

CERTIFICATE OF INSPECTION

DATE August 6, 1982

City of Portland Housing Inspections Division Department of Urban Development Tel: 775-5451 Ext. 311 - 312

James & Patricia Virgilio 585 Forest Avenue Portland, Maine 04101

Re: Premises located at 37 High St., Portland, Me. 40-C-15 WE/PLSNT

Dear Mr. & mrs. Virgilio:

An inspection of the above referred premises was recently completed by Code Enforcement Officer Marge Schmuckal

Although the structure does not meet the minimum standards as described in the Housing Code, it has been determined that no  $\underline{\text{major}}$  code deficiencies

Items included on the enclosed list should be corrected as part of your normal maintenance procedures in order to avoid extensive repairs in the future and to prolong the useful life of the building.

Thank you for your cooperation and your efforts to help us maintain decent, safe, and sanitary housing for all Portland residents.

Please do not hesitate to call this office if you have any questions regarding this notice.

> Sincerely yours, Joseph E. Gray, Jr., Director of Planning Urban Development

Lyle D. Noyes. Inspection Services Division

- Schmuckal (3)

Enclosure

# HOUSING INSPECTION REPORT

37 High St., Portland, Me. 40-C-15 WE/PLSNT NOHC - 5-27-81 Certificate of Inspection dated August 6, 1982 continued:

FIRST FLOOR REAR EXTERIOR - stairs - missing bottom railing.

.

.....

Ø.

## MITICE OF HOUSING CONDITIONS

CITY OF PORTLAND

DU

Department of Urban Development Housing Inspection Division 775-5457 - Ext. 3 1 - 318

Ch.-Blk.-Lot: 40-C-15 Location: 37 High Street

Project: NCP-PLSNT-WE Issued: May 27. 1981 Expires: August 27, 1981

James & Patricia Virgilio 585 Forest Avenue Portland, Maine 04101

774-2844 WOL

Dear Hr. & Hrs. Virgilio: 774-0825 home

As owner or agent, you are hereby notified that an examination was made of the premises at 37 High Street, Portland, Maine, by Code Enforcement Officer Marge Schmuckal. Violations of Municipal Codes relating to housing conditions were found as described in detail on the attached

In accordance with provisions of the above mentioned Codes, you are hereby requested to correct those defects on or before August 27, 1981. You may contact this office to arrange a satisfactory repair schedule if you are unable to make such repairs within the specified time. We will assume the repairs to be in progress if we do not hear from you within ten days from this date and, on reinspection within the time set forth above, will anticipate that the premises have been brought into compliance with Code Standards. Please contact this office i you have any questions regarding

Your cooperation will aid this Department in it's goal to maintain all Portland residents in decent, safe, and sanitary housing.

Very truly yours.

Coseph E. Gray, Jr., Director of Planning and Urban Development

Lyle D. Noyes, Inspection Services Division

Code Enforcement Officer - Schmuckal (3)

Attachments:

jmr

## HOUSING INSPECTION REPORT

OWNER: James & Patricia Virgilio CODE ENFORCEMENT OFFICER - Schmuckal 37 High St., Portland, Me. 40-C-15 NCP-WE/PLSNT Notice of Housing Conditions DATED: May 27, 1981 EXPIRES: August 27, 1981

ITEMS LISTED BELOW ARE IN VIOLATION OF "CHAPTER 307 OF THE MUNICIPAL CODES - MINIMUM STANDARDS FOR HOUSING" AND MUST BE CORRECTED.

	SEC.(S)
1 RIGHT 100: - WOTH Shinglos - sound flog day	Λ 3-a
0.1 - FIRST FLOOR RIGHT ROAF HALD - doo - missing laten assemb	1.y. 3-c
8.3 - FIRST FLOOR RIGHT ROAT MAN BOOK WILLOWS.	3-e
	3-a
FIRST PLOUN FRONT - porch - rotted smile	3-a
F PER MINDLE PATERIOL POOL DECKED GER	3-a
TOUR DEAD EVERTOR TOR - DIONER GIGING.	3-d
7. FIRST FLOOR REAF EXTERIOR Stairs - Worn treads	3-d
7. FIRST FLOOR REAR EXTERIOR - stairs - missing railing 4.	, ,
•	
FIRST FLOOR REAR	3-c
-9KITCHEN - window - broken - Blass.	3-c
10 BATHROOM - WINDOW - broken glass.	
TOOD WIDDIE	
FIRST FLOOR MIDDLE  1.1, KITCHEN - window - broken glass,	3-c
11. KITCHEN - WINGOW - B. OKE. BICOS.	
FIRST FLOOR FRONT	_
12. LIVING ROOM window - broken glass.	3-c
Fernando 1-1-1 in 11-1000	
SECOND FLOOR FRONT	8-e
SECOND FLOOR FRONT  63 -3. HITCHER - ceiling illegal extension cord.	0-e
V/	
SECOND FLOOR REAR	6-c
TITUE CON - IN - Illegal Diumping Choss Control	3-b
15. PICHT REAR BEDROOM - ceiling - broken plaster.	, ,

We suggest you contact the City of Portland Building Inspection Department. 389 Congress Street, Tel. 775-5451 to determine if any of the items listed above require a building or alteration permit.

FINSPECTION	RECOMMENDATIONS  LOCATION 37 H A PROJECT PLENTO
	Anus KAL OWNER JAMOS 150 g. Dio
NOTICE OF HO	ISING CONDITIONS HEARING NOTICE FINAL NOTICE Expired Issued Expired Issued Expired
1.77	21 2-27-21
A reinspecti	on was made of the above premises and I recommend the following action.
DATE	ALL VIOLATIONS HAVE BEEN CORRECTED
	SATISFACTORY Rehabilitation in Progress
	Time Extended To:
	Time Extended To:
	Time Extended To:  UNSATISFACTORY Progress Send "HEARING NOTICE"  "FINAL NOTICE"
	POST Dwelling Units
	U"SATISFACTORY Progress "LEGAL ACTION" To Be Taken
	INSPECTOR'S REMARKS:
£-4	Doi: 1 # 8
	INSTRUCTIONS TO INSPECTOR:



August 22, 1991

Paul and Susan Trusiani 25 Longwood Terrace Portland, ME 04102

, DU

Article V - 120 - The property is damaged, decayed, deteriorated, insanitary and unsafe (or vermin infested) in such a manner as to create a serious hazard to the health, safety and general welfare of the occupants or the public.

Therefore, you will not occupy, permit anyone to occupy, or rent the above mentioned without the written consent of the Health Officer or his agent, certifying that the conditions have been corrected.

Failure to comply with this order may result in a complaint being filed for prosecution in District Court.

Sincerely yours, Joseph E. Gray, Jr., Director of Planning & Urban Development

Code Enforcement Officer - High In

#### CITY OF PORTLAND HOUSING INSPECTION RELURT

OWNER: Paul and Susan Trusiani LOCATION: 37 High St. (40-C-15)

CODE EMPORCEMENT OFFICER: Hugh Irving


HOUSING CONDITIONS DATED: 8-22-91 EXPIRES: 9-22-91

ITEMS LISTED BELOW ARE IN VIOLATION OF ARTICLE V OF THE MUNICIPAL CODES, "HOUSING CODE", AND MUST BE CORRECTED ON OR BEFORE THE EXPIRATION DATE.

Please note that the violations listed below are for Apartment \$3, 1st floor.

VIOLATION LOCATION COL	DE.
1. Floor covering worn through Overall 108 - dangerous	8-2
2. Electric wires stick out of Liv/Rm, Bed/Rm 113 recepticle - dangerous	3
3. Elec. light switch defective Kitchen iii 4. *No smoke detector Overall	š
5. Hand sink pulled away from wall Bath/Rm Plumbing 111	L-4 .
7. Countertop loose Kitchen 108	3-2
8. Folding door broken, in disrepair Bath/Rm 108	3-3
9. Parts of Goor frame missing Door Entrance 108	3-3
10. Ceiling tale in disrepair Overall 108	3-3

<sup>\*</sup> Must be corrected immediately.





# CITY OF PORTLAND

DEPARTMENT OF PLANNING & URBAN DEVELOPMENT INSPECTION SERVICES DIVISION

NOTICE OF HOUSING CONDITIONS

DU: 6 CHART-BLUCK-LOT - 40-7-15 LOCATION: 33-37 Fign Street

DISTRICT: 3/8 ISSUED: October 18, 1938 EXPIRES: December 18, 1988

Paul & Susan Trusiani 25 Longwood Drive Portland, ME 04102

Dear Mr. & Mrs. Trusiani:

You are hereby notified, as owner or agent, that an inspection was made of 33-37 High Street eet by Code Enforcement
Violations of Article V of the Municipal Officer Hubert Irving Violations of Article V of the Municipal Ordinance (Hous, Code) were found as described in detail on the attached

In accordance with the provisions of the above mentioned Code, you are hereby o dered to correct those detects on or before December 18, 88 . If you are unable to make such repairs within the specified time, you may contact this office to arrange a satisfactory repair schedule. If we do not hear from you within ten (10) days from this date, we will assume the repairs to be in progress and, on re-inspection within the-time set-furth above, will anticipate that the premises have been brought into corpliance with the Housing Code Standards.

Please Note: You should consult the inspection Services Division to insure that any corrective action you undertake complies with the building, plumbing, electrical, zoning and other Article of the City Code.

Please contact this office if you have any questions regarding this order.

Your cooperation will aid this department in it's goal to maintain decent, safe, and sanitary housing for all of Portland's residents.

Very truly yours,

Joseph E. Cray, Jr., Director Planning & Urban De Pelopmen

Chief of Inspection

Hubert Irving (3/8) Code Enforcement Office

Attachments

189 CONGRESS STREET + POPTI &

a mangangangangangan kalanggan kalanggan kananggan kananggan sa mangan kananggan kananggan kananggan kananggan

#### HOUS INSPECTION REPORT

OWNER: Paul & Susan Trusiani LCCATION: 33-37 High Street 40-C-15

CODP ENFORCEMENT OFFICER: Hubert rving (3/8)

HOUSING CONDITIONS DATED: October 18, 1988 EXPIRES: December 18, 1988

ITEMS LISTED BELOW ARE IN VIOLATION OF ARTICLE V OF THE MUNICIPAL CODES, "HOUSING CODE", AND MUST BE CORRECTED ON OR BEFOR: THE EXPIRATION DATE.

	•	SEC.(S)
1.	EXTERIOR OVERALL - windows - cords missing.	108-3
2.	EXTERIOR OVERALL - combo/windows, damaged screens and windows.	108-3
3.		108-3
* 4.	1	109-4
* 5.		109-5
* 6.	EXTERIOR AND INTERIOR FIRST FLOOR FRONT APARIMENT - deteriorated,	
	dangerous fire escape.	116-2
* 7.	INTERIOR FIRST FLOOR OVERVLL - hallway - unsanitary, ar and deposits.	108-2
* 8.	INTERIOR OVERALL BASEMENT - clothing in storage on wet tasement floor.	109-4
* 9 <b>.</b>		114-1
*10.		114-2
*11.		109-4
12.		113
*13.	TOTAL TITLE STORY OF THE LICENT DESIGNATION OF THE STORY	
	facing building - fire hazard.	108-2
*14.		114-2
*15.	INFERIOR OVERALL - hallways - missing lights.	113
*16.	INTERIOR BASEMENT - missing furnace safety shut-off switch.	114-2
17.	INTERIOR FIRST FLOOR - basement door - no fire door	101

\*WHEN MAKING YOUR REPAIRS, FIRST PRIORITY IS TO BE GIVEN TO ITEMS WITH ASTERISKS AS THEY CONSTITUTE EXTREME HAZARDS TO THE PEALTH OR SAFETY OF THE OCCUPANIS OF THIS STRUCKURE.

م قائد

**建国现在中国国际** 10/2 CITY OF PORTLAND INSTECTION SERVICES DIVISION - HOUSING INSPECTION SCHEDULE Dist 8-3 C-B-L: 40-1 5 Legal Units: 6 Exist. Units: 6 Stories: 2 Stand. 1st: N.O.H.C. L.C.D. TRUSIANI-Violation CCDE VIOLATION DESCRIPTION LOCATION Ext. ove a late 0/14 mbo keri, democrat speros spero 108-3 017 s od anibare -Detriorated, Daugane 115-2 cof Chimney 114-1 14-2 by fury --109-4

(2).37.

suservines Division 2)Insp.Date 3)Insp Type 4)Proj.Code 5)Assr's:Chart 6)Bl. 7)Lot 8)Census:Tract 9)Blk. 10)Insp 11)Form No. 121Hous No. 13/Sec.H.No 17)St Design 15)Direct 16)StreetSN 20)Bldg's Rat. 19)Status 18)Owner or Agent: 5 Longwood 21) Address: 22) City and State: Foot Task Me 04/103 U 29)Bldg.Type 30)Stories ol)Const.Mat 32)O.B's 23)D.Units 24)Occ.D.U.'s 25)Rm Units 26)Occ.R.U.s 27)No.

33)C.H. 34)Pho 35)ZonedFor 36)Actual Land Use ccupants 28)Com'1 34)Pho OK w **/4** 37)D.D. 38)Lks.Ad.Bth.Fac 39+Disp. 40)Closing Date Cá. Viol 113 Cd. Viol. 108-2 INTERIOR - Structure EXTERIOR - Structure Lighting (Cotturnitius.) 113 EX/FO Foundation EW Elec. Wiring 108-2 7/11/ 108-2 108-2 EX/WA Walls FL Floors 108-2 Root RO IN/WA Walis 108-4 108-2 Porch PO CZ 108-4 Cellings 108-3 EX/SR IN/WI Stairs 108-4 Windows 108-3 Steps SP ĀS Airshafts 108-3 708-1 Doors DO ROR 108-3 108-1 Rent Rafters EX/WI Cons/MI. 109-5 Window SAN Sanitation 108-4 ĒÃ Eaves IN/SRW Stairways 108-1 108-4 TR Trim SRT Stair Tread: 111-4 108-5 EX/CH Chimney WSL <u>111-3</u> Wastelines 108 - 1GU Gutters Supply Lines SUL 108-1 114-1 RD Roof Drains ST Stacks 108-4 1.14--1 BU Bulkhead FU Flues 114-1 - SH Outbuildings GR VE Vents 114-1 YA Yard IN/CH 109-4 Heating Equip, Furnace - FU Spaceheater - SPH Chimney 114-2 2 Garbage GA 109-4 Bsmt. Sanitation Litter - LI 109-4 RU Rubbish 109-4 108-1  $\overline{\infty}$ Containers DMP 108-1 Dampness 113 DR BS/LI Drainage 109-5 Lighting TI3IN-CR-FL EL/PA Infestation Elec. Panel 109-5 108-2 RA BS/SR Rats 109-5 Stairs 108-2 IN/FO Other Foundation 116-2 108-2 Fire Escape Floor Joists 108-2 116-2 DE Dual Egress Carrying 'l'imbers 108-2 DW Driveways <u> 110-6</u> Bsmt. Dwelling Unit - BDU WΑ Walks FN

THE MANAGEMENT

连续流

機能は

会が多く

000

の意思

Remarks on reverse side

Fences

TRUSIANI-P-J & SUSAN 25 Longulos TERR - 775-6702 J. 56. 88. 260 in 39. Triggi. ं येव . कार्यमार्थ \$ Abestoss in basement must be removed on and apulated sty of Lie ed contractor ses pacializaing IN the work-"
If the condition of the abestoes is determined to be
use suitable to encapulating, it will be necessary to
assuitable to encapulating, it will be necessary to
have it reimoved with the 10 days of the date of this
report of the abestoes contractor will be required to
Notify the state of fice— A Please ALVANGE for for inspection not to Oct 20/88. Teamsts to be volified by your 24 hrs

Inspection Services Samuel P. Hollses



Planning and Urban Development Joseph E. Gray Jr. Director

June 09, 1994

CITY OF PORTLAND

TRUSIANI PAUL J 25 LONGWOOD TER PORTLAND ME 04102

Re: 37 High St CBL: 040- - C-015-001-01

Dear Mr. Trusiani:

We recently received a complaint and an inspection was made at the above referenced address. As a result of the inspection, you are hereby notified to correct the following substandard housing conditions:

1.	INT - 3PD FL; APT #6 - BATHROOM	113.50
	NO OUTLETS	113.30
2.	INT - 3RD FL; APT #6 - LIVING ROOM	100 00
	BROKEN LINOLEUM	108.20
3.	TIVE OND BY NEW HOLDS	
٠.		108.30
	INOPERABLE WINDOW	
4.	EXT - 3RD FL; APT #6 - LIVING ROOM	108.30
	NO SCREEN	
5.	INT - 3RD FL; APT #6 - STAIRS	108.40
	NO HANDRAIL	108.40
6.	· · · · · · · · · · · · · · · · · · ·	٠,
	INT - 3RD FL; APT #6 - STAIRS	108.40
7.	O GUARDRAIL	
7.	INT - 3RD FL; APT #6 - FIRE ESCAPE	108.20
	MISSING FLOOR BOARDS	100.20
8.	INT - THROUGHOUT -	
٠.		109.50
	COCKROACH INFE TATION	

PRIORITY VIOLATION NUMBER(S):

The above mentioned conditions are in violation of Article V of the Municipal Code of the City of Portland, Maine, and must be corrected within 30 days. Failure to comply with this order may result in a complaint being filed for prosecution in District Court.

Sincerely,

Tammy Myrson Code Enforcement Officer

Marge Schmuckal / Asst. Chief of Inspection Services

389 Congress Street · Portland, Maine 04101 · (207) 874-8704

pection Services âmuci P. Hoffses Chief



Planning and Urban Development Joseph E. Gray Jr. Director

CITY OF PORTLAND

June 09, 1994

TRUSIANI PAUL J 25 LONGWOOD TER PORTLAND ME 04102

> Re: 37 High St CBL: 040- - C-015-001-01

During a recent inspection of the property owned by you at the above referred address, it was noted that smoke detectors were inoperable in some locations (apt. #2; 1st fl.-rear and apt.#6; 3rd fl.).

25 MRSA 2464 required that approved smoke detectors be installed in each apartment in the immediate vicinity of the bedrooms. When activated, the detector shall provide an alarm suitable to warn the occupants within the individual unit. Failure to comply with this statute may result in a fine of up to \$500 for each violation.

Re-inspection of your property will be made in 24 hours. Lack of compliance will result in referral of the matter for legal action.

Loss control is a responsibility of your management. Our observations are intended to assist you. Recommendations are a result of conditions observed at the time of our visits. They do not necessarily include every possible at the time of our visits. loss potential code violation, or exception to good practice.

Sincerely,

Jammy Munson

Tammy Munson Code Enforcement Officer

Marge Schmuckal

Asst. Chief of Inspection Services

389 Congress Street · Portland, Maine 04101 · (207) 874-8704

Inspection Services P. Samuel Hoffses Chief



Planning and Urban Development Joseph E. Cray Jr. Director

### CITY OF PORTLAND

December 19, 1994

TRUSIANI PAUL J 25 LONGWOOD TER PORTLAND ME 04102

Re: 37 High St

CBL: 040- - C-015-001-01

Dear Mr. Trusiani:

You are hereby notified, as owner or agent, that <code>fn</code> inspection was made of the above referenced property. Violations of Article V of the Municipal reference (Housing Code) were found as described in detail on the attached

In accordance with the provisions of the above mentioned Code, you are hereby ordered to correct those defects within sixty (60) days. If you are unable to make such repairs within the specified time, you may contact this office to arrange a satisfactory repair schedule. If we do not hear from you within ten (10) days from this date, we will assume the repairs to be in progress and, on re-inspection within the time set forth above, will anticipate that the premises have been brought into compliance with the

Please Note: You should consult this department to insure that any corrective action you should undertake complies with the building, plumbing, electrical, zoning and other Articles of the City Code.

Please contact this office if you have any questions regarding this order.

Your cooperation will aid this department in it's goal to maintain decent, safe, and sanitary housing for all of Portland's residents. Sincerely,

lammy Munson Tammy Minson Code Enforcement Officer

Marge Schmuckal

Asst. Chief of Inspection Services

389 Congress Street • Portland, Maine 04101 • (207) 874-8704 • FAX 874-8716 • TTY 874-8936

#### HOUSING INSPECTION REPORT

Location: 37 High St Housing Conditions Date: December 19, 1994 Expiration Date: February 17, 1995

Items listed below are in violation of Article V of the Municipal Codes, "Housing Codes", and must be corrected before the expiration date:

	·	
1.	INT - 3RD FLR; APT #6 - BATHROOM HAS NO OUTLETS	113.50
2.	INT - 3RD FLR: APT #6 -	108.20
3.	LIVING ROOM HAS BROKEN LINOLEUM EXT - 3RD FLR; APT #6 - LIVING ROOM	
4.	WINDOW IS INOPERABLE	108.30
**	EXT - 3RD FLR; APT #6 - LIVING ROOM WINDOW HAS NO SCREEN	108.30
5.	INT - 3RD FLR: APT #6 -	108.40
6.	STAIRS HAVE NO HANDRAIL INT - 3RD FLR; APT #6 -	
7.	STAIRS HAVE NO GUARDRATT, WITH BALLISTEDS	108.40
	INT - 3RD FLR; APT #6 - FIRE ESCAPE IS MISSING FLOOR BOARDS	108.20
8.	INT - THOUGHOUT -	109.50
9.	COCKROACH INFESTATION INT - 1ST FLR; APT #3 - KITCHEN	
10.	INT - 1ST FLR; APT #3 - KITCHEN SINK IS DRIPPING INT - 1ST FLR; APT #3 - THROUGHOUT	111.40
, -		
11.	EXT - THROUGHOUT - WINDOW DANKS ARE CRACKED	108.30
12.	EXT - THROUGHOUT - WINDOW PANES ARE CRACKED EXT - THROUGHOUT - WINDOWS ARE INOPERABLE (SILICONED SHUT) INT - BASEMENT -	108.30
13.	WINDOWS ARE INOPERABLE (SILICONED SHUT) INT - BASEMUNT -	108.30
	STAIRS HAVE BROKEN TRWADS	108.40
14.	INT - BASEMENT - COVER THE OIL LINE WITH CONCRETE INT - BASEMENT -	114.30
15.	INT - BASEMENT -	100 20
16.	SLAB HAS AN OPEN HOLE	T00.50
	THERE APPEARS TO BE SOME FRIABLE ASTESTOS	116.60
7.	INT - BASEMENT - SLAB HAS AN OPEN HOLE INT - BASEMENT - THERE APPEARS TO BE SOME FRIABLE ASTESTOS INT - BASEMENT - STORAGE OF TOXIC MATERIALS INT - BASEMENT	116.10
18.	TILL DISCRIFFICAT	113.50
19:	JUNCTION BOX IS OPEN INT - BASEMENT -	113.30
70	THERE ARE LOOSE WIRES	113.50
20.	INT - IST FLR - THROUGHOUT - HALLS HAVE HOLES	108.20
21.	THERE ARE LOOSE WIRES INT - 1ST FLR - THROUGHOUT - HALLS HAVE HOLES INT - FRONT HALL - STAIRS ARE MISSING BALUSTERS INT - BEAD -	100 40
22.	STAIRS ARE MISSING BALUSTERS INT - REAR -	100.40
22	STAIRS HAVE LOOSE HANDRATTS	108.40
23.	EXT - FRONT - STAIRS HAVE ROTTED TREADS	108.40
24.	EXT - FIONT -	
	WINDOW IS BROKEN	108.30

PRIORITY VIOLATIONS: NUMBERS 7, 17, 24

Inspection Services Samuel P. Hoffses Chief

Inspection Services P. Samuel Hoffses Chief

Allrban Development

CITY OF PORTLAND

Re: 37 High St

CBL: 040- - C-015-001-01

Planning and Urban Development Joseph E. Gray Jr.

December 01

WONG FRANK

December 19, 1994

26 HILLIS PORTLAND

TRUSIANI PAUL J 25 LONGWOOD TER PORTLAND ME 04102

Dear Mr.

The Hous Developm

Dear Mr. Trusiani: referenc

Congrati propert Housing

During a recent inspection of the property owned by You at the above in apartment #3, first floor. Smoke detectors were missing/inoperable

Good me neighb

25 MR.SA 2464 required that approved smoke detectors be installed in each detector shall provide an alarm suitable to warn the occupants within the occupants within the each violation.

25 MR.SA 2464 required that approved smoke detectors be installed in each detector shall provide an alarm suitable to bedrooms. When activated, the of up to \$500 for each violation.

Please Sincer

Re-inspection of your property will be made in 24 hours. Lack of compliance

Kevij Code

Loss control is a responsibility of your management. Our observations are at the time of our Visits. They do not necessarily include every possible every possible Sincerely,

Tammy Mukson Code Enforcement Officer

Marge Schmuckal Asst. Chief of Inspection Services

389 Congress Street • Portland, Maine 04101 • (207) 87/-8704 • FAX 874-8716 • TTY 874-8936 

Inspection Services P. Samuel Hoffses Chief



Planning and Urban Development Joseph E. Gray Jr.

## CITY OF PORTLAND

December 19, 1994

TRUSIANI PAUL J 25 LONGWOOD TER PORTLAND ME 04102

Re: 37 High St CBL: 040- - C-015-001-01

Dear Mr. Trusiani:

You are hereby notified, as owner or agent, that an inspection was made of the above referenced property. Violations of Article V of the Municipal Ordinance (Housing Code) were found as described in detail on the attached

In accordance with the provisions of the above mentioned Code, you are hereby ordered to correct those defects within sixty (60) days. If you are unable to make such repairs within the specified time, you may contact this office to arrange a satisfactory repair schedule. If we do not hear from you within ten (10) days from this date, we will assume the repairs to be in progress and, on re-inspection within the time set forth above, will anticipate that the premises have been brought into compliance with the Housing Code Standards.

Please Note: You should consult this department to insure that any corrective action you should undertake complies with the building, plumbing, electrical, zoning and other Articles of the City Code.

Please contact this office if you have any questions regarding this order.

Your cooperation will aid this department in it's goal to maintain decent, safe, and sanitary housing for all of Portland's residents.

Sincerely,

Tammy Manson Code Enforcement Officer

Marge Schmuckal

Asst. Chief of Inspection Services

389 Congress Street · Portland, Maine 04101 · (207) 874-8704 · FAX 874-8716 · TTY 874-8936

#### HOUSING INSPECTION REPORT

Location: 37 High St Lousing Conditions Date: December 19, 1994 Expiration Date: February 17, 1995

Items listed below are in violation of Article V of the Municipal Codes, "Housing Codes", and must be corrected before the expiration date:

	•	
1.	INT - 3RD FLR; APT #6 - BATHROOM HAS NO OUTLETS	113.50
2.	INT - 3RD FLR; APT #6 -	
	LIVING ROOM HAS BROKEN LINOLEUM	108.20
3.	EXT - 3RD FLR; APT #6 - LIVING ROOM	•
	WINDOW IS INOPERABLE	108.30
4.	EXT - 3RD FLR: APT #6 - TIVING BOOM	
	WINDOW HAS NO SCREEN	108.30
5,	INT - 3RD FLR: APT #6 -	100.40
	STAIRS HAVE NO HANDRAIL	108.40
6.	INT - 3RD FLR; APT #6 -	100 40
	STAIRS HAVE NO GUARDRAIL WITH BALUSTERS	108.40
7.	INT - 3RD FLR; APT #6 -	108.20
8.	FIRE ESCAPE IS MISSING FLOOR BOARDS	
	INT - THOUGHOUT - COCKROACH INFESTATION INT - 1ST FLR; APT #3 - KITCHEN SINK IS DRIPPING	109.50
9.	TNO - 1 CO PID - 1 DO - 12	,
- Ŧ.	SINK IS DRIPPING	1.11.40
10.	INT - 1ST FLR; APT #3 - THROUGHOUT	108.20
,	CEILING TILES ARE DAMAGED	108.20
11.	EXT - THROUGHOUT -	
	WINDOW PANES ARE CRACKED	108.30
12.	EXT - THROUGHOUT -	108.30
		108.30
13.	THE - DESCRIENT -	108.30 108.40
	STAIRS HAVE BROKEN TREADS	108.40
<b>14.</b>	INT - BASEMENT -	114.30
15.	COVER THE OIL LINE WITH CONCRETE	114.30
13.	INT - BASEMENT -	114.30
16.	SLAB HAS AN OPEN FOLE INT - BASEMENT -	200120
17.	THERE APPEARS TO BE SOME FRIACLE ASTESTOS INT - BASEMENT -	*
	STORAGE OF TOXIC MATERIALS	116.10
18.	INT - BASEMENT -	1
٠,	JUNCTION BOX IS OPEN	113.50
19.	INT - BASEMENT -	
	THERE ARE LOOSE WIRES	113.50
20.	INT - 1ST FLR - THROUGHOUT -	100.00
21	HALLS HAVE HOLES	108.20
21.	INT - FRONT HALL -	108.40
22.	STAIRS ARE MISSING BALUSTERS	200.40
~~.		108.40
23.	STAIRS HAVE LOOSE HANDRAILS EXT - FRONT -	
	STAIRS HAVE ROTTED TREADS	108.40
24.	EXT - FRONT -	
	WINDOW IS BROKEN	108.30

PRIORITY VIOLATIONS: NUMBERS 7, 17, 24

Inspection Services
P. Samuel Hoffses
Chief



Planning and Urban Development Joseph E. Gray Jr. Director

#### CITY OF PORTLAND

December 19, 1994

TRUSIANI PAUL J 25 LONGWOOD TER PORTLAND ME 04102

Re: 37 High St

CBL: 040- - C-015-001-01

DU: 6

Lear Mr. Trusiani:

During a recent inspection of the property owned by you at the above referred address, it was noted that smoke detectors were missing/inoperable in apartment #3, first floor.

25 MRSA 2464 required that approved smoke detectors be installed in each apartment in the immediate vicinity of the bedrooms. When activated, the detector shall provide an alarm suitable to warn the occupants within the individual unit. Failure to comply with this statute may result in a fine of up to \$500 for each violation.

Re-inspection of your property will be made in 24 hours. Lack of compliance will result in referral of the matter for legal action.

Loss control is a responsibility of your management. Our observations are intended to assist you. Recommendations are a result of conditions observed at the time of our visits. They do not necessarily include every possible loss potential code violation, or exception to good practice.

Sincerely,

Taminy Murson

Code Enforcement Officer

Margo Schmuckal

Asst. Chief of Inspection Services

389 Congress Street • Portland, Maine 04101 • (207) 874-8704 • FAX 874-8716 • TTY 874-8936

Inspection Services
P. Samuel Hoffses
Chief



Planning and Urban Development Joseph E. Gray Jr. Director

# CITY OF PORTLAND

MAY 22, 1997

MR1-LTD PTSP 50 CONGRESS ST - SUI 417 BOSTON MA 02109

Re: 37 HIGH ST

CBL: 040- - C-015-001-01

DU: 6

#### Dear Sir:

We recently received a complaint, and an inspection was made at the abovereferenced address. As a result of the inspection, you are hereby notified to correct the following substandard housing conditions:

1. EXT - HALL - 108.30

WINDOWS ARE BROKEN
2. INT - APT #5 - KITCHEN
108.20

LINOLEUM IS DAMAGED

3. INT - APT #5 - KITCHEN

108.20

HALL DOOR & FRAME ARE DAMAGED

4. INT - APT #5 WIRING ABOVE SUSPENDED CEILING IS ILLEGAL
108.20

5. INT - APT #5 -CEILING TILES ARE WATER-DAMAGED

6. INT - OVERALL HARD-WIRED BATTERY-BACK/UP SMOKE DETECTORS ARE REQUIRED
IN EACH UNIT - PERMIT BY MASTER ELECTRICIAN

The above-mentioned conditions are in violation of Article V of the Municipal Code of the City of Portland, Maine, and must be corrected within thirty (30) days. Failure to comply with this order may result in a complaint being filed for prosecution in District Court.

Sincerely,

Arthur Rowe

Code Enforcement Officer

Tammy Munson

Code Enfc. Offr./ Field Supv.

Tammy Munson