

107 BRACKETT STREET

SHAW-WALKER

Full cut #920R - Full cut #920R - Full cut #920R - Full cut #920R



R6 RESIDENCE ZONE
CITY OF PORTLAND, MAINE
DEPARTMENT OF BUILDING INSPECTION
COMPLAINT

INSPECTION COPY

COMPLAINT NO. 61/31

Date Received May 15, 1961

Location:

107 Brackett St.

Location 107 Brackett Street

Use of Building _____

Owner's name and address Matthews Weiner, 68 Walton St.

Telephone _____

Tenant's name and address _____

Telephone _____

Complainant's name and address Fire Dept.

Telephone _____

Description: Rear shed in dangerous condition.

H

NOTES: Rear ell wall has settled nearly a foot. No foundation or sills. Should be repaired or rebuilt. NFC

10/5/61 - No really hazardous structural condition here - A.J.H.



(A) APARTMENT HOUSE ZONE
APPLICATION FOR PERMIT

PERMIT ISSUED
00158
FEB 6 1952
CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE
Class of Building or Type of Structure Second and third
Portland, Maine, January 28, 1952

The undersigned hereby applies for a permit to erect alter repair or remodel the following building 107 Brackett Street in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 107 Brackett Street Within Fire Limits? yes Dist. No. 4-4420
Owner's name and address Edward M. Perkins, 531 Westbrook St., So. Portland Telephone 4-4420
Lessee's name and address _____ Telephone _____
Contractor's name and address owner No. of sheets 3
Architect _____ No. families 3
Proposed use of building Apartment house Plans no Roofing _____
Last use _____ Specifications _____ Style of roof _____
Material brick and wood and No. stories 2 1/2 Heat _____
Other buildings on same lot _____ Estimated cost \$ 100. Fee \$ 50.

General Description of New Work

To cut in door between main part of house and ell on third floor to give access to rear stairway so that tenant on third floor will have two means of egress.
To partition off small hallway, probably 3' x 3', in main part of house where door is being cut in, partition to be covered with wallboard.

Chief's order 1/19/52 (as written owner)
Memo Sent to Fire Chief signed from 3rd floor

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. PERMIT TO BE ISSUED TO owner

See to Fire Dept. 1/29/52
Rec'd from Fire Dept. 2/5/52
RECEIVED IS WAREHOUSE

Details of New Work

Is any plumbing involved in this work? _____ Is any electrical work involved in this work? _____
Height average grade to top of plate _____ Height average grade to highest point of roof _____
Size, front _____ depth _____ solid or filled land? _____ earth or rock? _____
Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
Material of underpinning _____ Rise per foot _____ Height _____ Roof covering _____ Thickness _____
Kind of roof _____ Material of chimneys _____ of lining _____ Dressing or full size? _____ Kind of heat _____
No. of chimneys _____ Framing lumber—Kind _____ Sills _____ Girt or ledger board? _____ Size _____
Corner posts _____ Girders _____ Size _____ Columns under girders _____ Size _____
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet. _____
Joists and rafters: _____
On centers: _____
Maximum span: _____
If one story building with masonry walls, thickness of walls? _____
No. cars now accommodated on same lot _____, to be accommodated _____ number commercial cars to be accommodated _____
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

If a Garage

Miscellaneous

Will work require disturbing of any tree on a public street? no
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

APPROVED:

O.N. 2/6/52-AGS

INSPECTION COPY

Signature of owner

Edward M. Perkins

Cert. of Occupancy issued

SECTION

3-18-52 3 months since various treatments
done are very low. W. J. M. 11-3
4-10-53 - Work completed. W. J. M.



CITY OF PORTLAND, MAINE
Department of Building Inspection

To: Oliver T. Sanborn
Chief of the Fire Department

From: Warren McDonald
Insptr. of Bldgs.

(date) January 29, 1952

Location: 107 Brackett Street
Owner: Edward W. Perkins
Subject: Application for permit for
improvements at above location,
required by order of Chief of Fire
Department dated 1/10/52

While our two departments have done a good job of coordination under the Safety Ordinance--yours issuing the orders after inspection and ours issuing permits for improvements to be made,--

The confusion on the part of many people, who come in here, as to who has ordered them to do what,

The fact that on some jobs a permit has been issued, and the work done, only to have your inspector find that the situation did not then satisfy your order under the law,

And, the fact that you are permitted under the Building Code to exercise discretion as to details of means of egress in an existing building where there is no substantial increase in number of persons accommodated, while we must proceed under the precise terms of the Code unless deviation in this connection is approved by yourself--

leads me to the belief that each situation ought to be checked before any permits are issued, presumably by the inspector in your department who made the inspection on which the original order was based, to see:

1. If the work contemplated will completely satisfy the order.
- 2 To see, if possible, whether or not there may be some more economical way of satisfying the order, and, if so, to recommend that way to the owner.

To that end there is attached for your consideration applications for permits at the above location.

Remarks relating to this particular job:

Will the proposed alterations satisfy the requirements of your order of the above date?

Warren McDonald
Inspector of Buildings

45-F-10

SURVEY AND INVESTIGATION OF TENEMENT AND LODGING HOUSES
QUESTIONABLE AS TO LEGAL AND SAFE USE

1. Location *107 Brimblett St* Date Investigation Commenced *1/29/52*
2. References: Complaints Appl. BP Inq. ---
3. Present Owner and Address *Edward M. Perkins, 531 West 100th St S. Port.*
4. Present Lessee and Address
5. Building Permit Record: *1943 - dem. ell; 1944 dem. gas; 1947 const. platform; 1947 dem. gas; 1949 oil burner; 1951 roof.*

Assessors' Record

6. Survey 1924: Owner *Richard V. & Nora L. Haney* No. tenants *2*
No. rooms *10*; Class of Use *Dwelling*
7. Assessors' change record since 1924 *1936 J. Thomas Haney; 1939 Marie Harding & Acceptance Corp; 1942 John MacIntire NLR; 1947 Arthur L. Haney & Son, Inc.*

Arthur L. Haney & Son, Inc.

City Directory Record

- 1926 *1/29/52* 1939 *Edward D. Douglass; John A. Mahon; Mrs. Caroline Forbes*
1927 *Probable owner the* 1940 *John Mahon; Mary E. Cowling*
1928 *illegally from lot to* 1941 *Vacant*
1929 *three families, but in 1942*
1930 *only one family on floor* 1943
1931 *and for R.C. requirement* 1944 *Fredrick F. Othage; Thas Lewis; John H. Hill*
1932 *applying for lot to lot* 1945 *Thas Lewis; Henry Kennedy; Bertha M. Houghton*
1933 *safety condenser like* 1946 *Thas Lewis; Harold Thomas*
1934 *care of it - A.J.D.* 1947 *Thas Lewis; Harold Thomas; Arthur L. Haney & Son, Inc.*
1935 1948
1936 1949
1937 1950
1938 *Mrs. Caroline Forbes* 1951
Mrs. Laura J. McDonald

CONCLUSIONS

*Reck Control - 1943 - 2nd floor 4 rooms; 1943 - 3rd floor 3 rooms
1944 - 1st floor 4 rooms*



FILL IN AND SIGN WITH INK
APPLICATION FOR PERMIT FOR
HEATING, COOKING OR POWER EQUIPMENT

Portland, Maine,

Nov 7, 1947

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE
The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 107 Brackett St

Use of Building dwelling

No. Stories 10

New-Building Existing

Name and address of owner of appliance Arthur Harrelson, Jr., 70 1/2 100 St

Telephone 3 818 7

Installer's name and address

General Description of Work

To install oil burner in steam boiler

IF HEATER, OR POWER BOILER

Location of appliance or source of heat Basement

Type of floor beneath appliance concrete

Kind of fuel

If wood, how protected?

Minimum distance to wood or combustible material, from top of appliance or casing top of furnace

From sides or back of appliance

From top of smoke pipe

Other connections to same flue

Rated maximum demand per hour

Size of chimney flue

If gas fired, how vented?

IF OIL BURNER

Name and type of burner Leath Newcomb EM 2

Does oil supply line feed from top or bottom of tank? yes

Will operator be always in attendance? no

Type of floor beneath burner concrete

Number and capacity of tanks 275 gallon

Location of oil storage Basement

If two 275-gallon tanks, will three-way valve be provided?

How many tanks fire proofed?

Will all tanks be more than five feet from any flame?

Total capacity of any existing storage tanks for furnace burners

IF COOKING APPLIANCE

Location of appliance

Type of floor beneath appliance

If wood, how protected?

Minimum distance to wood or combustible material from top of appliance

From top of smoke pipe

From front of appliance

Other connections to same flue

Size of chimney flue

If so, how vented?

Rated maximum demand per hour

Is hood to be provided?

If gas fired, how vented?

MISCELLANEOUS EQUIPMENT OR SPECIAL INFORMATION

Amount of fee enclosed? 2.00 (\$1.00 for one heater, etc., 50 cents additional for each additional heater, etc., in same building at same time.)

APPROVED:

OK 11-8-49. Rm.

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Gould-Farmer Co. of Maine, Inc.

Signature of Installer by S. J. Peter

INSPECTION COPY

Permit No. 49/1940 12-30

Location 107 Brackett St.

Owner Arthur Harrison, Jr.

Date of permit 11/9/49

Approved [Signature] NOT COMPLETE

NOTES 2-3-60 [Signature]

1. Flue Pipe

2. Vent Pipe

3. Kind of Heat

4. Burner Rating & Supports

5. Make & Type

6. Stack Co.

7. Height

8. Windward

9. Windward

10. Valve

11. Capacity

12. Tank Size & Support

1. Tank Location

2. All Other

3. Instruction Card

12-5-49 [Signature]

12-29-49 [Signature]

[Signature]



APPLICATION FOR PERMIT

Class of Building or Type of Structure Third Class
Portland, Maine, Sept. 9, 1947

02273
SEP 9 1947

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to ~~rebuild~~ demolish the following building structure as shown on the plans and specifications, if any, submitted herewith and the following specifications:

Location 107 Bru Kett Street Within Fire Limits? Dist. No.
Owner's name and address F. R. Wardwell, 22 School Street Telephone none
Lessee's name and address Telephone
Contractor's name and address Owner Telephone
Architect Specifications Plans No of sheets
Proposed use of building No. families
Last use 3-car garage No. families
Material wood No. stories 1 Heat Style of roof Roofing
Other buildings on same lot Dwelling house Fee \$.50
Estimated cost \$

General Description of New Work

To demolish one-story 3-car garage 15' x 30'
(No sewer connection)

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

Details of New Work

Is any plumbing involved in this work? Is any electrical work involved in this work?
Height average grade to top of plate Height average grade to highest point of roof
Size, front depth No. stories solid or filled land? earth or rock?
Material of foundation Thickness, top bottom cellar
Material of underpinning Height Thickness
Kind of roof Rise per foot Roof covering
No. of chimneys Material of chimneys of lining Kind of heat fuel
Framing lumber—Kind Dressed or full size?
Corner posts Sills Girt or ledger board? Size
Girders Size Columns under girders Size Max. on centers
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
Joists and rafters: 1st floor 2nd 3rd roof
On centers: 1st floor 2nd 3rd roof
Maximum span: 1st floor 2nd 3rd height?
If one story building with masonry walls, thickness of walls?

If a Garage

No. cars now accommodated on same lot to be accommodated number commercial cars to be accommodated
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building?

Miscellaneous

Will work require disturbing of any tree on a public street? no
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed?

APPROVED:

Signature of owner

F. R. Wardwell

INSPECTION COPY

Permit No. 47/2273

Location 107 Brackett St.

Owner J. P. Hardwell

Date of permit 9/9/47

No. of closing-in _____

Inspn. ch. _____

Final No. _____

Final Inspn. 10/17/47

Cert. of Occupancy issued none

NOTES

10/7/47 - all work done
E.S.

Memorandum from Department of Building Inspection, Portland, Maine

107 Brackett Street--Construction of side platform without
roof for and by Arthur L. Harradon, Jr.

9/3/47

Permit is issued subject to the following:

A center cedar foundation post is to be used under the outside sill midway between the rear wall of the main house and the corner foundation post of the platform.

The 2x6 floor joists are to be supported against the building on no less than 2x3 nailing strips, spiked to the frame of the building; and at the other end upon the 4x6 sill, either upon the top of the sill or upon no less than 2x3 nailing strip spiked to the inside of the sill.

Judging from our atlas, which is not to be relied upon as be accurate, there is not enough space between the building and the side lot line of the next house to allow the 5-foot wide platform and 10 feet between it and the side lot line--that being shown on your sketch. This 10 feet is the least distance allowed from the side lot line to the new work by the Zoning ordinance in the Apartment House Zone where the property is located, so you should be governed accordingly. This existing open space does not hold out to approximately 15 feet in width.

Wlaci/S

(Signed) Warren McDonald
Inspector of Buildings



(A) APARTMENT BUILDING ZONE
APPLICATION FOR PERMIT

Class of Building or Type of Structure Third Class
Portland, Maine, Sept. 2, 1947

SEP 3 1947

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to ~~erect~~ alter ~~repairs~~ ~~and~~ ~~install~~ the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 107 Brackett Street Within Fire Limits? yes Dist. No. 3
Owner's name and address Arthur L. Harradon, Jr., 107 Brackett St. Telephone 4-9628
Lessee's name and address Telephone
Contractor's name and address owner Telephone
Architect Specifications Plans yes No of sheets 1
Proposed use of building Tenement No. families 3
Last use " No. families 3
Material of frame No. stories 2 1/2 Heat Style of roof Roofing
Other buildings on same lot barn Fee \$.50
Estimated cost \$ 50

General Description of New Work

To construct 5'x13' platform rear of building.

2.5 x 6 x 45 = 675

4 x 6 on 10.5 x 10 = 2169

INSPECTION NOT COMPLETED

NOTIFICATION BEFORE LATHING
OR CLOSING-IN IS WAIVED

CERTIFICATE OF OCCUPANCY
REQUIREMENT IS

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

Details of New Work

Is any plumbing involved in this work? Is any electrical work involved in this work?
Height average grade to top of plate Height average grade to highest point of roof
Size, front depth No. stories solid or filled land? earth or rock?
Material of foundation cedar posts at least 4' below grade Thickness, top bottom cellar
Material of underpinning Height Thickness
Kind of roof none Rise per foot Roof covering Kind of heat fuel
No. of chimneys Material of chimneys of lining Dressed or full size?
Framing lumber—Kind second-hand 6" upright Size
Corner posts Sills 4x6 Girt or ledger board? Max. on centers
Girders Size Columns under girders Size Max. on centers
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
Joists and rafters: 1st floor 2x6 2nd 3rd roof none
On centers: 1st floor 16" 2nd 3rd 1 roof
Maximum span: 1st floor 5' 2nd 3rd height?

If a Garage

No. cars now accommodated on same lot to be accommodated number commercial cars to be accommodated
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building?

Miscellaneous

Will work require disturbing of any tree on a public street? no
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes
Permit Issued with Memo

APPROVED:

Signature of owner

Mrs. A. L. Harradon, Jr.


INSPECTION COPY

Permit No. 47/2197
 Location 107 Brackett St
 Owner Arthur L. Harradon
 Date of permit 9/3/47
 Notif. closing-in _____
 Inspn. closing-in _____
 Final Notif. _____
 Final Inspn. _____
 Cert. of Occupancy issued _____

INSPECTION NOT COMPLETED
 11/29/48

NOTES

2/24/47 - 2x5 mlls.
 2x5 joists which
 lay on side and lay over
 both mlls. 22" dia.



11/29/48 - Lack of time to
 make further inspection
 Sd



APPLICATION FOR PERMIT

Class of Building or Type of Structure Third Class

Permit No. 1303

DEC 30 1944

Portland, Maine, December 30, 1944

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect alter install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 107 Frackett Street Within Fire Limits? yes Dist. No. 3
Owner's or Lessee's name and address Alice McIntire, York Village Telephone _____
Contractor's name and address T. P. Sweetland, 794 Congress St. Telephone 2-2268
Architect _____ Plans filed _____ No. of sheets _____
Proposed use of building _____ No. families _____
Other buildings on same lot _____ Fee \$.50
Estimated cost \$ _____

Description of Present Building to be Altered

Material _____ No. stories _____ Heat _____ Style of roof _____ Roofing _____
Last use 2 car garage No. families _____

General Description of New Work

To demolish 1 story frame building

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

Details of New Work

Is any plumbing work involved in this work? _____
Is any electrical work involved in this work? _____ Height average grade to top of plate _____
Size, front _____ depth _____ No. stories _____ Height average grade to highest point of roof _____
To be erected on solid or filled land? _____ earth or rock? _____
Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
Material of underpinning _____ Height _____ Thickness _____
Kind of roof _____ Rise per foot _____ Roof covering _____
No. of chimneys _____ Material of chimneys _____ of lining _____
Kind of heat _____ Type of fuel _____ Is gas fitting involved? _____
Framing lumber--Kind _____ Dressed or full size? _____
Corner posts _____ Sills _____ Sirt or ledger board? _____ Size _____
Material columns under girders _____ Size _____ Max. on centers _____
Studs (outside walls and carrying partitions) 2x4-16" O. C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.
Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____
Total number commercial cars to be accommodated _____
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

above work require removal or disturbing of any shade tree on a public street? no
there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Signature of owner By: T. P. Sweetland

NON COPY

Permit No. 44/1303

Location 107 Brickett St

Owner Alice McIntire

Date of permit 12/30/44

Notif. closing-in

Inspn. closing-in

Final Notif.

Final Inspn.

Cert. of Occupancy issued Lapsch

NOTES

1645 7:10 AM
Extracted from Permit
B-13-45 from Permit
9-25-45 for change
Time

~~9-25-45 permit~~

NO RA - 110 T

STARTED PERMIT

LAPSON Ed



APPLICATION FOR PERMIT

PERMIT ISSUED
0618

Class of Building or Type of Structure Second-third

Permit No. 0618
JUN 21 1942

Portland, Maine, June 21, 1942

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to ~~erect~~ alter ~~install~~ the following building structure ~~equipment~~ in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 107 Brackett Street Within Fire Limits? yes Dist. No. 3
Owner's or Lessee's name and address John McIntyre, York Village Telephone
Contractor's name and address P. C. Sweetland, 721 Congress St. Telephone 2-2122
Architect Plans filed No. of sheets
Proposed use of building dwelling house No. families 2
Other buildings on same lot
Estimated cost \$

Description of Present Building to be Altered

Material brick No. stories 2 1/2 Heat Style of roof
Last use dwelling house No. families 2

General Description of New Work

To demolish from all end. 12 x 12 on rear of building

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

Details of New Work

Is any plumbing work involved in this work?
Is any electrical work involved in this work? Height average grade to top of plate
Size, front depth No. stories Height average grade to highest point of roof
To be erected on solid or filled land? earth or rock?
Material of foundation Thickness, top bottom cellar
Material of underpinning Height Thickness
Kind of roof Rise per foot Roof covering
No. of chimneys Material of chimneys of lining
Kind of heat Type of fuel Is gas fitting involved?
Framing lumber—Kind Dressed or full size?
Corner posts Sills Girt or ledger board? Size
Material columns under girders Size Max. on centers
Studs (outside walls and carrying partitions) 2x4-16" O. C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.
Joists and rafters: 1st floor 2nd 3rd roof
On centers: 1st floor 2nd 3rd roof
Maximum span: 1st floor 2nd 3rd roof
If one story building with masonry walls, thickness of walls? height?

If a Garage

No. cars now accommodated on same lot to be accommodated
Total number commercial cars to be accommodated
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building?

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

SECTION COPY

Signature of owner By John McIntyre

John McIntyre

P. C. Sweetland



Location, Ownership and detail must be correct, complete and legible.

Separate application required for every building.

Plans must be filed with this application.

Application for Permit for Alterations, etc.

To the

Portland, May 12, 1922 192

INSPECTOR OF BUILDINGS:

The undersigned applies for a permit to alter the following described building:—

Location 107 Brackett Street Ward 6 in fire-limits? no
Name of Owner or Lessee, A. T. Haney Address 151 Spring Street
" " Contractor, John Brown " 126 Payson Street
" " Architect

Descrip-
tion of
Present
Bldg.

Material of Building is wood Sty of Roof, pitch Material of Roofing, shingle
Size of Building s. 16ft feet long; 15ft feet wide. No. of Stories, 1
Cellar Wall is constructed of piers is inches wide on bottom and batters to inches on top.
Underpinning is is inches thick; is feet in height.
Height of Building 12ft Wall, if Brick; 1st, 2d, 3d, 4th, 5th
What was Building last used for? shed No. of Families?
What will Building now be used for? private garage

DETAIL OF PROPOSED WORK

Cut in door for private garage for one car, pyrene fire extinguisher,
all to comply with the building ordinance

Estimated Cost \$ 50.

IF EXTENDED ON ANY SIDE

Size of Extension, No. of feet long? ; No. of feet wide? ; No. of feet high above sidewalk?
No. of Stories high? ; Style of Roof? ; Material of Roofing?
Of what material will the Extension be built? Foundation?
If of Brick, what will be the thickness of External Walls? inches; and Party Walls inches.
How will the extension be occupied? How connected with Main Building?

WHEN MOVED, RAISED OR BUILT UPON

No. of Stories in height when Moved, Raised, or Built upon? Proposed Foundations.
No. of feet high from level of ground to highest part of Roof to be?
How many feet will the External Walls be increased in height? Party Walls.

IF ANY PORTION OF THE EXTERNAL OR PARTY WALLS ARE REMOVED

Will an opening be made in the Party or External Walls? in Story.
Size of the opening? How protected?
How will the remaining portion of the wall be supported?

Signature of Owner or
Authorized Representative.

Address

A. T. Haney

PERMIT MUST BE OBTAINED BEFORE BEGINNING WORK