208-210 STATE STREET

## ALWAYS PREVENT FIRE ALL WAYS

FRANK M. HOBERTY, JR

HARGLO E TRAHEY



CIRCCIOR

HARRY & ROLLING ROTOSSIG THATEIBEA

CHARLES F. ROGAN

## Insurence Department DIVISION OF STATE FIRE PREVENTION AUGUSTA, MAINE 04330

June 23, 1970

Mr. Alan Levenso.. 187 Middle Street Fortland, Kaino

### Dear Sire

## Re: 100ms - 208-210 State Street - Portland

A recent inspection of your property by a Supervising State Fire Inspector revealed the existence of conditions which are in violation of the laws pertaining to fire and structural safety.

Accordingly, the following steps are to be taken to remedy these conditions:

- Remove chain lock from front door.
- Stairways to be enclosed with 4 hour fire resistant material and to be cut off with self-closing h hour fire registant doors at each level.
- Doors to attic to be 4 hour fire resistant with self closers.
- Prorgancy lights to be provided for third floor.
- Illuminated exit signs on separate circuit and exterior lights connected on the zame circuit with separate switch to be provided.
- 6. Provide second exit for third floor by a walk-down rire escape to the ground. This to be Class A type.
- 7. Repeit broken plaster in cellar and cellar stairway.
- 8. Boiler moon to have 5/8" fire core cheetrock edded to interior walls.
- 9. Boiler room coiling to be made one hour fire resistant.
- 10. Door to callus to be made one hour fire regulatant with self closer,

Please advise this office within ten days of the action which you propose to take.

By direction of the Insurance Commissioner Charle of Bogan

Director

MIRICAG. cas Chief Joseph Cremo

Portland Building Inspector

## APARTMENT HOUSE ZONE



PPLICATION FOR PERMIT	NAO SOS
ilding or Type of Structure Second Class	ľ

§ 952

CITY of PORTLAND

Portland, Maine, December 26, 1951 To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

			install the following b <b>initings</b> tructum ng Ordinance of the City of Portland	caquipment
	C. Tannon and one with Miles Piet.	HAGWINY SPECIACORORES		
Location 206-16	cox State Street	Withi	n Fire Limita? <u>yes</u> Dist. No	0
Owner a mante and addi	ressDlsters_of_6	BECV605 Stevene Aven	10 //11 1	
Ecoce a name and addi-	'ess			
contractor a mante and	address L. S. Hould	os Co., 247 biddle Str	eat m	000-
431 CHIALCUL		C		
Last use	- 1		No. families No. families	
ATACCTICITION AND THE PARTY OF	io. stories	itStyle of roof	D C	
A serior partornings out stilling	: 10t		Roomg	
Estimated cost \$		Description of New V	Fee \$1.00	)
for whose protection for whose protection for the foll signal structure and located and located perature will not so place, conveniently lesilencing switch, if silent position when the following as to operation out of order.  3-6" I rotectowire gone it sunderstood that this	ch tone, strength intended—current ength, to operate an 14 gauge steel not less than 6" below 40 degrees ocated to permit provided, will be a alarm is not so and testing of s	of signal, number and by dry batteries of content of at least content or well-seasoned wood nor more than 6' above for allowed that alar so arranged that alar unding. Installer will ystem and there and how the season of the se	rom any wall or partition r, if any, allpublic and r, if any, allpublic and nd atteched garage, if an location as to arous. It apacity to ring all angs ne year, installed in subset of the state of the state of the state of the state of the right of the estimate system frequently will sound if switch is a fasten to control bex for the secure servicing if the secure servicing if the state of the secure servicing if the state of the state of the secure servicing if the state of the secure servicing if the secure servicing is substituted in the secure servicing if the secure servicing is substituted in the secure servicing in the secure servicing is substituted in the secure servicing in the secure servicing is substituted in the secure servicing in the secure servicing is substituted in the secure servicing in the secure servicing is substituted in the secure servicing in the secure servicing is substituted in the secure servicing in the secure servicing is substituted in the secure servicing in the secure	y, MARKAS  1 persons simultaneou stantial hinged door ce where tem astened in Alarm throam to ull instruc- system gets
Is any plumbing involved	l in this work?	Is any electrical s	work involved in this1-2	
resem average grade to	rob or blate		sta blobace malue of t	
preci montemana (IC)	pinNo. sto	riessolid or filled land	D	
minterial of loungation		. Thickness, top hot	om collan	
***accitat of differ pittining	***************************************	Height	T11.1.1	
azura or reor	Kise per loot	Roof covering		
Tro. or citimiteys	Material of chimi	neys of lining	Kind of book to	I
r raming minoch-Find"		Dressed or full size	6م	
COLUCT DOSTS	SilisGir	t or ledger board?	C!	* Whitenessan
Orucis	:Columns u	nder girders Sta	Man	
orads (outside waits and (	carrying partitions) 2x4	l-16" O. C. Bridging in every	floor and flat roof span over 8 fee	·+
joists and raiters:	ist lloor	, 2nú	3rd roof _	
On centers:	IST HOOF.	, 2nd	3rdroof	
Maximum span:	19t HOOT		lr/l	
11 of a story building with	masonry walls, thickness	ess of walls?		***************************************
		If a Garage		,
No. cars now accommodat Will automobile repairing	ted on same lot, to be done other than mir	be accommodatednumber	r commercial cars to be accommod. tored in the proposed building?	ited
	<del></del>			*************************
PROVED:	o		Miscellaneous	
1/2/50FOQ	<u> </u>	Will work require disturb	ing of any tree on a public street?_	no
wind is stant	Marian.	Will there be in charge	of the above work a person contri	etent to
. Critist.	withing.	see that the State find observed? vas	City requirements pertaining the	reto are
		Sisters of Mercy E. S. Boulos Co.		į

Signature of owner by:

A. F. Bruch

INSPECTION COPY

NOTES	Cert.	inal	Tina.	nspn	Notii.	Date 1	Owner		
	Cert. of Occupancy issued	inal Inspn	Tinal Notif,	nspn. closing-in	Notif. closing-in	3	,  ª	10	••
	cupa	2	ļ.,	ing-in	ng-in	mit	1000	;	
	ncy is					{	Alexander of	, 52/	
	sucd	17.5				1			<i>)-2</i>
		1,				2	8 K		-28-52
		8				7	36	E	۲
		17	}			() )	12.5		
		\				1	2 E	,	
	ı	ł	ı	1	1	. ,	1	10	
									-
					<del></del>				_
							<del></del>		
									•
	_	<del></del>						<del></del>	-
									•
		—							•
									- -
		<b></b>	<del>-</del>						-
		<b>-</b>							-
			<del></del> -						-
									-
									•
									-
									-
		<b></b>							
	. <del></del>								-
						<del></del> -			-
							<del></del>		
		<del></del>							-
									-
									-
			<b></b>	<u>.</u>	<del></del> -				-
									-
									4
									-
									<del>-</del>

if fill congress treat-I AF 206-Ald Ataba Streat-I AF 216 (tate Streat-I (Fire Alarm Systems)

Aminary 2, 10.2

247 Midle Street Fortland, Zainn

Copies to 1 Siveter of Utres 605 Stavens Avame Canal of the Fire Coportaint

Dentlemon:

Thron pendits are being issued berwith for the installation of the fire above system in the buildings at 661 congress street. By 212 state street. In each case the symbothes cally for the installation of three falses from going in table or och floor, probabilings at 306-212 state street and 214 state direct, in the case of the case then one section to each trivet and 214 states direct, where there is easy to a floor pay he needed to adoptedly some that some than pants of the tableting. He are not aware of whether you have taken the part in a posterior of the building. He are not aware of whether you have taken to make the part have not done not appear that it is done to be acceptable on the installations is absorbed in order that it is done to go you contain as to suche for the location of goily after installations have completed may be avoided.

Very truly yours,

lumbactor of Soffkinia

AJS/C

MEMORANDUM FROM DEPARTMENT OF BUILDING INSPECTION, PORTLAND, MAINE
200-210 State Street-Installation of automatic fire alors system for Sisters of
Merc, by a. S. Boulos Company, installers

When such a system has been installed, the owner and lessee of the building arc responsible for keeping the system in working order at all times so that the system may always be on guard to warn the occupants of the building in case a fire starts. To discharge this responsibility and to have good assurance that he will not be held either financially or criminally liable in case of injury or loss of life in his building due to fire, it is my belief that the owner and lessee must see to it that the alarm system is tested every twenty-four hours. This may be done by merely precuing very briefly the test button to see if the bells ring loud and clear.

Most of these systems have dry batteries for their power, and the batteries will deteriorate in time so that they will not ring the alarm bells satisfactorily, if at all. If the batteries are used briefly by this test every day, they will last longer than when tested less frequently.

Because this is a safety device whenever it is found that the bells do not ring loud and clear or any other defect appears in the system, the owner or his agent should notify immediately some predetermined party who has agreed in advance to come at once and service the system, whether day or night, Sundays or holidays.

It is recommended that the name of such a party and the address and telephone number be posted permanently on or in the control box of the system.

WMcD/H CC: Sisters of Mercy EC5 Sisterans Avenue (Signed) WARREN MIDONALD
INSPECTOR OF BUILDINGS



# (G) GENERAL BUSINESS ZONE Application for Permit for Alterations and Miscellaneous Structures

CLASS OF BUILDING OR TYPE OF STRUCTURE 2nd

To the INSPECTOR OF	BUILDINGS, PORTLA	Portland, . ND, ME.	Maine, Janur	17/27 19 10 11 10 2 UE
The understaned been	hu annlies for a nermit to	alter the following d	escribed building	according to the following
The undersigned here specifications, the Laws of the	he State of Maine, and the	erect the following d Building Ordinance	lescribed structure of the City of	Portland: 8 1927
Location 208-212	State Street	Ward6	Within F	ire Limits? Dist :1
Owner's name and addre	ss? Rt. Rev	Joan Murray 307	Cumporlard	Avenuo
Contractor's name and add	dress? F vi Cw	n inglum 4 Son 1	81 Jt to St	reet , P 5380
Architect's name and add	ress?			
Last use of building ? Auro	Hing house & hospi-	tal	No. Families	1
Proposed use of building	**			
,	Description of	f Present Bui	lding	
Material brick No	of Stories 2	Style of RoofP	itch	Roofing shingle
	General Descr	iption of New	Work	
Build passageway bel	woon present hospit	al and residence	as por pla	ns
				CIFIC! " "CIM
			1,1	1. F. 4. 10211
			1, 47	HILBARITORING TH
No gas fitting inclu	ided in this posmit		100	11.2.1
		Framing Men	nbers	
Corner posts?	Sills ?	Rafters or roof beam	s?	_on center?
Material and size of colun				/
Ledger board used ?	_			•
Girders 6" x 8" or larger.				
be all one piece in cross se				omo tha corner posts win
Floor timbers:	1st floor	, 2nd	, 3rd	, 4th
On centers:	1st floor	, 2nd	, 3rd	, 4th
Span:	1st floor	, 2nd	, 3rd	, 4th
-	If 1st or 2nd	Class Constru	ction	
External walls } thickness	( 1st story	, 2nd story		
Party walls thickness	1st story	, 2nd story		
•	Other Details	s New Constru	iction	
To be erected on solid or				
Material of foundation?_	Thick	mess, top?	bo	ttom ?
Material of underpinning	۷۷۵ مر	er 4 ft. high ?	thi	ckness?
Kind of roof (pitch, hip,				
No. of new chimneys?				
2101 01 11011 1111111111111111111111111	/	civate Garage		
No. cars now accommodat	-		to be accomm	ndated ?
Other buildings on same				
Distance from nearest pre	cent building to propes	ed garage?	٧	
All parts of garage, in				
*				mes. ws of adjoining property.
Garage.wiii.te.at.least		cellaneous	nearest windo	ws_or_acifoning_property
35701 .1. 1	<del></del>		_1_ 1 <sub>~</sub> .	ata a ma
Will the above construction				
Plans filed as part of this		***************************************		
Estimated total cost \$				?
Signature of owner	or authorized representa	ilive?		† h

Permit No. 27 Lotif. Closing in-Inspin Closing in . Final Cotif -



## City of Portland.

3305

خام ما≛ حام	Hilly (1/ 191).	1
To the Inspector	Buildings of the City of Portland:	
The under	gued respectfully makes application for a permit to erect enlarge	
a building on	Male street , at number 20 f	وبر
to be	stories high 2/14" feet long,	
16.4	feet wide; also an addition to be stories	
high,	feet long, ieet wide, and to	4
be used as a	Jacque	
The material to be	used in the erection enlargement of said building is to be as follows:	
Exterior wans to	e made of	
Roof to be made	i State	
Gutters to be mad	of Mutal	
Cornices to be ma	e of forth	
Bay windows to 1	mare of	
The builder is	be made of Callery Genderess Museum	,
	Address	•
The owner is	Address	,
Table de forte ferrous acceptantes sousse se Table de	desired and the second of the	
Management broad name in the c	tine to an antine it or consiste directional a paring of a to a face of the constant time can antition is specific.	
Fare man in manusimen a ma	A THE RESIDENCE OF THE STREET	· . '
Total man and a series m	Consider marrial man and a series of the ser	,
ing. B	(Applicant to sign here Miliam H. Bradford	•
-T <sub>3-1</sub>	OFFICE OF	
	INSPECTOR OF BUILDINAS,	
£11.	CITY OF PORTLAND,	,
f <sup>n</sup> j <sup>e</sup> z <sup>e</sup>	10-11 A. 85. 4-8.9. 88	
The above petition	as granted the	در '  او الم

208, State St.