

844 CONGRESS STREET

STAMP-OUTER

Full cut #920R - Half pt. #252R - Full cut #9203R - Full cut #8206R



## APPLICATION FOR PERMIT

Class of Building or Type of Structure \_\_\_\_\_

Portland, Maine, May 5, 1973

PERMIT ISSUED

MAY 8 1973

00474

CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 844 Congress St. Within Fire Limits? \_\_\_\_\_ Dist. No. \_\_\_\_\_  
Owner's name and address Portland Glass - 832 Congress St. Telephone \_\_\_\_\_  
Lessee's name and address \_\_\_\_\_ Telephone \_\_\_\_\_  
Contractor's name and address Ralph Romano, 55 Frederick St. Telephone \_\_\_\_\_  
Architect \_\_\_\_\_ Specifications \_\_\_\_\_ Plans \_\_\_\_\_ No. of sheets \_\_\_\_\_  
Proposed use of building \_\_\_\_\_ No. families \_\_\_\_\_  
Last use dwelling No. families 1  
Material \_\_\_\_\_ No. stories \_\_\_\_\_ Heat \_\_\_\_\_ Style of roof \_\_\_\_\_ Roofing \_\_\_\_\_  
Other buildings on same lot \_\_\_\_\_  
Estimated cost \$ \_\_\_\_\_ Fee \$ 10.

### General Description of New Work

To demolish 2½ story frame dwelling. Gas Company was called. Sewer will be closed under supervision of Public Works Dept.

5/4/73  
5/7/73

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. **PERMIT TO BE ISSUED TO** contractor

### Details of New Work

Is any plumbing involved in this work? \_\_\_\_\_ Is any electrical work involved in this work? \_\_\_\_\_  
Is connection to be made to public sewer? \_\_\_\_\_ If not, what is proposed for sewage? \_\_\_\_\_  
Has septic tank notice been sent? \_\_\_\_\_ Form notice sent? \_\_\_\_\_  
Height average grade to top of plate \_\_\_\_\_ Height average grade to highest point of roof \_\_\_\_\_  
Size, front \_\_\_\_\_ depth \_\_\_\_\_ No. stories \_\_\_\_\_ solid or filled land? \_\_\_\_\_ earth or rock? \_\_\_\_\_  
Material of foundation \_\_\_\_\_ Thickness, top \_\_\_\_\_ bottom \_\_\_\_\_ cellar \_\_\_\_\_  
Kind of roof \_\_\_\_\_ Rise per foot \_\_\_\_\_ Roof covering \_\_\_\_\_  
No. of chimneys \_\_\_\_\_ Material of chimneys \_\_\_\_\_ of lining \_\_\_\_\_ Kind of heat \_\_\_\_\_ fuel \_\_\_\_\_  
Framing Lumber—Kind \_\_\_\_\_ Dressed or full size? \_\_\_\_\_ Corner posts \_\_\_\_\_ Sills \_\_\_\_\_  
Size Girder \_\_\_\_\_ Columns under girders \_\_\_\_\_ Size \_\_\_\_\_ Max. in centers \_\_\_\_\_  
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.  
Joists and rafters: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
On centers: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
Maximum span: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
If one story building with masonry walls, thickness of walls? \_\_\_\_\_ height? \_\_\_\_\_

### If a Garage

No. cars now accommodated on same lot \_\_\_\_\_, to be accommodated \_\_\_\_\_ number commercial cars to be accommodated \_\_\_\_\_  
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? \_\_\_\_\_

### APPROVED:

O.K. 5/8/73

### Miscellaneous

Will work require disturbing of any tree on a public street? \_\_\_\_\_  
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Portland Glass Co.

CS 301

INSPECTION COPY

Signature of owner by:

Albert Romano

Permit No. 23/474  
Location 844 Congress St.  
Owner Richard Wilson  
Date of permit 5/8/73  
Notif. closing-in \_\_\_\_\_  
Inspn. closing-in \_\_\_\_\_  
Final Notif. \_\_\_\_\_  
Final Inspn. \_\_\_\_\_  
Cert. of Occupancy issued \_\_\_\_\_  
Staking Out Notice \_\_\_\_\_  
Form Check Notice \_\_\_\_\_

NOTES

5/17/73  
Renovated  
OK.

Handwritten notes and signatures on lined paper, including a large 'X' mark.

CITY OF PORTLAND, MAINE  
DEPARTMENT OF BUILDING INSPECTION

May 4, 1973

Portland Glass Co.  
832 Congress St.

With relation to permit applied for to demolish a dwelling  
at 844 Congress St. it is unlawful  
to commence demolition work until a permit has been issued from  
this department.

Section 1 of the Ordinance for rodent and vermin control  
provides: "It shall be unlawful to demolish any building or  
structure unless provision is made for rodent and vermin  
eradication. No permit for the demolition of a building or  
structure shall be issued by the Building Inspection Department  
until and unless provisions for rodent and vermin eradication  
have been carried out under supervision of a pest control  
operator registered with the Health Department.

The building permit for demolition cannot be issued until the  
provisions of this section have been satisfied. It is the  
obligation of owner or demolition contractor or both to take  
up with the Health Department the matter of complying with this  
section, being prepared to inform that department what registered  
pest control operator is to be employed.

Very truly yours,

R. Lovell Brown  
Director

Eradication of this building has been completed.

Contractor:

Ralph Romano

80 Frederick St.

*Re: rodent eradication by City of Portland*  
*5/17/73*  
Sent to Health Dept 5/14/73  
Rec'd from Health Dept 5/17/73

Addr: 844 Congress St. PERMIT NUMBER **0076**

By

Type of Bldg.

- Addr: 844 Congress St. PERMIT NUMBER **0076**

Addr: 844 Congress St. PERMIT NUMBER **0076**

2nd floor

~~CONFIDENTIAL - 4411484 E. 10010~~  
~~CONFIDENTIAL - 4411484 E. 10010~~

Plant: Walter Co. Date: 3 Nov 1972

NEW YORK 1/21/13

1	STAYC	1	2.00
---	-------	---	------

SECRET

\_\_\_\_\_

CH 11

SURFACE

\_\_\_\_\_

	DATE	TIME	PLACES	
	1968	0700	1000	

INVESTIGATION OF THE  
SOURCES OF THE

TOYOTA SALES

\_\_\_\_\_

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100	101	102	103	104	105	106	107	108	109	110	111	112	113	114	115	116	117	118	119	120	121	122	123	124	125	126	127	128	129	130	131	132	133	134	135	136	137	138	139	140	141	142	143	144	145	146	147	148	149	150	151	152	153	154	155	156	157	158	159	160	161	162	163	164	165	166	167	168	169	170	171	172	173	174	175	176	177	178	179	180	181	182	183	184	185	186	187	188	189	190	191	192	193	194	195	196	197	198	199	200	201	202	203	204	205	206	207	208	209	210	211	212	213	214	215	216	217	218	219	220	221	222	223	224	225	226	227	228	229	230	231	232	233	234	235	236	237	238	239	240	241	242	243	244	245	246	247	248	249	250	251	252	253	254	255	256	257	258	259	260	261	262	263	264	265	266	267	268	269	270	271	272	273	274	275	276	277	278	279	280	281	282	283	284	285	286	287	288	289	290	291	292	293	294	295	296	297	298	299	300	301	302	303	304	305	306	307	308	309	310	311	312	313	314	315	316	317	318	319	320	321	322	323	324	325	326	327	328	329	330	331	332	333	334	335	336	337	338	339	340	341	342	343	344	345	346	347	348	349	350	351	352	353	354	355	356	357	358	359	360	361	362	363	364	365	366	367	368	369	370	371	372	373	374	375	376	377	378	379	380	381	382	383	384	385	386	387	388	389	390	391	392	393	394	395	396	397	398	399	400	401	402	403	404	405	406	407	408	409	410	411	412	413	414	415	416	417	418	419	420	421	422	423	424	425	426	427	428	429	430	431	432	433	434	435	436	437	438	439	440	441	442	443	444	445	446	447	448	449	450	451	452	453	454	455	456	457	458	459	460	461	462	463	464	465	466
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----

WASH DC

\_\_\_\_\_

TOTAL	1	2.00
-------	---	------

Building and Inspection Services Dept.: Plumbing Inspection



MAINE PRINTING CO. PORTLAND

CITY OF PORTLAND  
HEALTH DEPARTMENT  
HOUSING DIVISION



Loc. 842 Congress St.  
Loc w/1 S Misc.  
Bldg x Fire x Elec x Other x  
Issued November 8, 1967  
Expires December 8, 1967

Mr. Daniel F. Quirk  
261 State Street  
Portland, Maine

Dear Sir:

On October 31, 1967 an examination was made of the premises located  
at 12 Congress Street, Portland, Maine.

Non-compliance with the ordinances relating to housing conditions was found as detailed below.

In accordance with the provisions of the above ordinance, you are hereby ordered to correct these defects according to specifications within the time limits allowed. Failure to comply with this notice will necessitate legal action.

Some repairs or improvements required will necessitate permits which are to be obtained from the Building Inspector, Health, Fire or other City Departments. These must be obtained before the work is started.

If any additional information is desired, visit or telephone the Housing Supervisor at this Office, Tel. 774-8221, extension 226. Kindly notify this office as soon as all corrections have been completed.

Very truly yours,  
John R. Davy, M. D.  
Health Director

By \_\_\_\_\_  
Housing Supervisor

**VIOLATIONS & SPECIFICATIONS**

## Responsibility of Owner or Agent      \*\* Responsibility of Occupant

**STRUCTURAL**

Repair and put in good order all dilapidated and hazardous parts of the structure as follows:

- a. Repair or replace the loose, worn, and deteriorated parts of the front and rear porches including the steps.
- b. Have all sides of the foundation pointed.
- c. Replace the missing bricks for all sides of the foundation.
- d. Determine the reason and remedy the condition which causes the holes in the foundation.
- e. Replace the missing clapboards for all sides of the structure.
- f. Replace the broken window panes in all of the windows throughout the structure including the cellar.
- g. Repair or replace the defective rear exit door.
- h. Replace the missing drainpipe on the right and left sides of the structure.
- i. Repair or replace the defective rear exit doors on the second and third floors.
- j. Repair or replace the loose, cracked, and missing plaster on the walls and ceilings in all of the halls throughout the structure.
- k. Replace the missing balusters for the front and rear stairways.
- l. Repair or replace the loose, worn, deteriorated, and hazardous parts

STRUCTURAL continued

- l. of the cellar stairway.
- m. Repair or replace the loose and worn treads on the cellar stairway.
- n. Repair or replace the loose, cracked, and missing plaster on the walls and ceilings in the kitchen, bathroom, right bedroom, and living room on the first floor.
- o. Determine the reason and remedy the condition which causes the walls to leak in the right bedroom on the first floor.
- p. Determine the reason and remedy the condition which causes the ceilings to leak in the kitchen and the right bedroom on the first floor.
- q. Determine the reason and remedy the condition which causes the paint to peel on the living room ceiling on the first floor.
- r. Putty the loose window panes in all of the windows throughout the first floor apartment.
- s. Repair or replace the loose, cracked, and missing plaster on the walls and ceilings in the kitchen, living room, and bedrooms on the second floor.
- t. Repair or replace the loose, worn, and deteriorated parts of the rear porch on the second floor.
- u. Repair or replace the loose, cracked, and missing plaster on the living room walls on the third floor.
- v. Determine the reason and remedy the condition which causes the kitchen ceiling on the third floor to leak.
- w. Determine the reason and remedy the condition which causes the water to seep through the cellar floor near the center waste line.

PLUMBING

Check and have repaired all defective plumbing and plumbing fixtures throughout the structure.

- a. Correct the condition at the fixture that causes a cross connection at the bathtub in the first floor apartment.
- b. Determine the reason and remedy the condition which causes the trap under the kitchen sink on the second floor to leak.
- c. Determine the reason and remedy the condition which causes the oil to leak from the kitchen stove in the third floor apartment.

We suggest that the plumbing throughout the structure be checked by a competent licensed plumber.

HEATING

- a. Supply a topping for the chimney.

ELECTRICAL

Check and have repaired all defective electric wiring and electrical equipment throughout the structure.

- a. Install adequate artificial illumination in the halls.
- b. Repair or replace the defective fixtures in the kitchen and the bedroom on the second floor.
- c. Replace the missing cover plate for the switch in the kitchen on the first floor.
- d. Repair or replace the defective cover plate in the bathroom on the first floor.

NUISANCES AND UNSANITARY CONDITIONS

- a. Accomplish a general clean-up of the yard by removing and properly disposing of all garbage and rubbish.
- b. Provide suitable, sufficient, water-tight, tightly covered metal garbage and rubbish containers to receive the accumulation of garbage and rubbish during the intervals between collections.
- c. Rid the premises of all infestation (mice, cockroaches). We suggest that you procure the services of a competent pest control operator registered with this Department to do the work.

842 Congress Street continued

NUISANCES AND INSANITARY CONDITIONS continued

- d. Remove the bed spring from the rear hall on the first floor.
- e. Accomplish a general clean-up of the cellar.

The above mentioned conditions are in violation of Chapter 307 of the Municipal Code and must be corrected on or before December 8, 1967.





# RESIDENCE ZONE APPLICATION FOR PERMIT

Class of Building or Type of Structure Third Class  
Portland, Maine, May 21, 1963

PERMIT ISSUED  
00564  
MAY 22 1963  
CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 844 Congress Street Within Fire Limits? \_\_\_\_\_ Dist. No. \_\_\_\_\_  
Owner's name and address Myron Finkelman, 19 Spruce St. Telephone \_\_\_\_\_  
Lessee's name and address \_\_\_\_\_ Telephone \_\_\_\_\_  
Contractor's name and address owner Telephone \_\_\_\_\_  
Architect \_\_\_\_\_ Specifications \_\_\_\_\_ Plans \_\_\_\_\_ No. of sheets \_\_\_\_\_  
Proposed use of building Dwelling No. families 2  
Last use \_\_\_\_\_ " \_\_\_\_\_ No. families 2  
Material frame No. stories 2 1/2 Heat \_\_\_\_\_ Style of roof \_\_\_\_\_ Roofing \_\_\_\_\_  
Other buildings on same lot \_\_\_\_\_  
Estimated cost \$ 1000. Fee \$ 5.00

## General Description of New Work

To Repair after Fire to former condition without alterations and without change of use but if conditions in the areas of repair are found to be dangerously sub-standard of Building Code requirements, both Building Dept. and owner will be notified immediately.

Cause of Fire - smoking in chair - fire was in April  
No structural damage

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. PERMIT TO BE ISSUED TO owner

## Details of New Work

Is any plumbing involved in this work? \_\_\_\_\_ Is any electrical work involved in this work? \_\_\_\_\_  
Is connection to be made to public sewer? \_\_\_\_\_ If not, what is proposed for sewage? \_\_\_\_\_  
Has septic tank notice been sent? \_\_\_\_\_ Form notice sent? \_\_\_\_\_  
Height average grade to top of plate \_\_\_\_\_ Height average grade to highest point of roof \_\_\_\_\_  
Size, front \_\_\_\_\_ depth \_\_\_\_\_ No. stories \_\_\_\_\_ solid or filled land? \_\_\_\_\_ earth or rock? \_\_\_\_\_  
Material of foundation \_\_\_\_\_ Thickness, top \_\_\_\_\_ bottom \_\_\_\_\_ cellar \_\_\_\_\_  
Kind of roof \_\_\_\_\_ Rise per foot \_\_\_\_\_ Roof covering \_\_\_\_\_  
No. of chimneys \_\_\_\_\_ Material of chimneys \_\_\_\_\_ of lining \_\_\_\_\_ Kind of heat \_\_\_\_\_ fuel \_\_\_\_\_  
Framing Lumber—Kind \_\_\_\_\_ Dressed or full size? \_\_\_\_\_ Corner posts \_\_\_\_\_ Sills \_\_\_\_\_  
Size Girder \_\_\_\_\_ Columns under girders \_\_\_\_\_ Size \_\_\_\_\_ Max. on centers \_\_\_\_\_  
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.  
Joists and rafters: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
On centers: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
Maximum span: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
If one story building with masonry walls, thickness of walls? \_\_\_\_\_ height? \_\_\_\_\_

## If a Garage

No. cars now accommodated on same lot \_\_\_\_\_, to be accommodated \_\_\_\_\_ number commercial cars to be accommodated \_\_\_\_\_  
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? \_\_\_\_\_

APPROVED:

O.N. - 5/22/63 - ags

## Miscellaneous

Will work require disturbing of any tree on a public street? no  
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

CS 301

INSPECTION COPY

Signature of owner

Myron Finkelman

P.H.

NOTES

6-12-63 Broomfield cop. 8/11  
 9-17-63 Working  
 Five place training?  
 4-22-63 same. 4D  
 12-26-63 Completed 4D

Permit No.	13/541
Location	144th Ave. N.E.
Owner	Walter B. Bickelmeier
Date of permit	5/21/63
Notif. closing-in	
Final Notif.	
Final Inspn.	
Cert. of Occupancy issued	
Safety Out Notice	
Form Check Notice	

# APPLICATION FOR PERMIT

Class of Building or Type of Structure ..... Intero Class

Portland, Maine, August 1, 1950

PERMIT TO ISSUE  
01343  
AUG 14 1977  
CITY of PORTLAND

*To the* INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 34 Congress Street Within Fire Limits? yes Dist. No. 4  
Owner's name and address Byron Finkelman, 19 Spruce St. Telephone \_\_\_\_\_  
Lessee's name and address \_\_\_\_\_ Telephone \_\_\_\_\_  
Contractor's name and address E. Bishop, 15 Gray St. Telephone \_\_\_\_\_  
Architect \_\_\_\_\_ Specifications \_\_\_\_\_ Plans no No. of sheets \_\_\_\_\_  
Proposed use of building Dwelling No. families 1  
Last use " No. families 1  
Material Frame No. stories 2 Heat \_\_\_\_\_ Style of roof pitch Roofing \_\_\_\_\_  
Other buildings on same lot \_\_\_\_\_  
Estimated cost \$ 100. 10/10/12 Fee \$ 50.

### General Description of New Work

- General Description of New Work**
- ✓ Change from 1 family to 2 family dwelling
  - ✓ To partition off existing ~~first floor~~ <sup>second floor</sup> ~~first floor~~ <sup>second floor</sup> - 2x4, 16" J.C. plasterboard both sides
  - ✓ To divide existing ~~closet~~ <sup>entr</sup> on ~~second~~ <sup>first</sup> floor to provide new bathroom. 2x8 studs, 16" J.C. plasterboard - existing window
  - ✓ No finished rooms on third floor - not to be used for living quarters.

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. **PERMIT TO BE ISSUED TO** Myron Finkelman

### Details of New Works

Is any plumbing involved in this work? \_\_\_\_\_ Is any electrical work involved in this work? \_\_\_\_\_

Height average grade to top of plate \_\_\_\_\_ Height average grade to highest point of roof \_\_\_\_\_

Size, front \_\_\_\_\_ depth \_\_\_\_\_ S. stories \_\_\_\_\_ solid or filled land? \_\_\_\_\_ earth or rock? \_\_\_\_\_

Material of foundation \_\_\_\_\_ Thickness, top \_\_\_\_\_ bottom \_\_\_\_\_ cellar \_\_\_\_\_

Material of underpinning \_\_\_\_\_ Height \_\_\_\_\_ Thickness \_\_\_\_\_

Kind of roof \_\_\_\_\_ Rise per foot \_\_\_\_\_ Roof covering \_\_\_\_\_

No. of chimneys \_\_\_\_\_ Material of chimneys \_\_\_\_\_ of lining \_\_\_\_\_ Kind of heat \_\_\_\_\_ fuel \_\_\_\_\_

Framing lumber—Kind \_\_\_\_\_ Dressed or full size? \_\_\_\_\_

Corner posts \_\_\_\_\_ Sills \_\_\_\_\_ Girt or ledger board? \_\_\_\_\_ Size \_\_\_\_\_

Girders \_\_\_\_\_ Size \_\_\_\_\_ Columns under girders \_\_\_\_\_ Size \_\_\_\_\_ Mat. on centers \_\_\_\_\_

Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.

Joists and rafters: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_

On centers: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_

Maximum span: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_

If one story building with masonry walls, thickness of walls? \_\_\_\_\_ height? \_\_\_\_\_

### If a Garage

No. cars now accommodated on same lot \_\_\_\_\_, to be accommodated \_\_\_\_\_ number commercial cars to be accommodated \_\_\_\_\_  
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? \_\_\_\_\_

**APPROVED:**

### Miscellaneous

Will work require disturbing of any tree on a public street? no  
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

**INSPECTION COPY**

*Signature of owner*

NOTES

*\* 2nd Floor*

Permit No. 521 1393  
Location 641' (Cargano St.)  
Owner Myra Winkelman  
Date of Permit 8/14/50  
Notif. closing in 8/16/50  
Inspn. closing in 8-21-50 *OK*  
Final Notif.  
Final Insp.  
Ct. of Occupancy Issued

INSPECTION NOT COMPLETED

APPROVED FOR THE CITY OF NEW YORK  
By *[Signature]*  
Inspector



FILL IN COMPLETELY AND SIGN WITH INK

APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIPMENT

February 25, 1935

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

Portland, Maine,

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 844 Congress Street

Use of Building

Dwelling house

Name and address of owner Ernest N. Leavitt, 844 Congress St.

Ward 7

Contractor's name and address Halverson Bros 9-15 Union St.

Telephone 3-4751

General Description of Work

To install Oil Burning Equipment in connection with existing steam heat

IF HEATER, POWER BOILER OR COOKING DEVICE

Is heater or source of heat to be in cellar? yes If not, which story \_\_\_\_\_ Kind of Fuel Oil

Material of supports of heater or equipment (concrete floor or what kind) concrete

Minimum distance to wood or combustible material, from top of boiler or casing top of furnace, \_\_\_\_\_

from top of smoke pipe \_\_\_\_\_ from front of heater \_\_\_\_\_ from sides or back of heater \_\_\_\_\_

Size of chimney flue \_\_\_\_\_ Other connections to same flue \_\_\_\_\_

IF OIL BURNER

Name and type of burner Timken Silent Automatic Labeled and approved by Underwriters' Laboratories? yes

Will operator be always in attendance? \_\_\_\_\_ Type of oil feed (gravity or pressure) gravity

Location oil storage basement No. and capacity of tanks 1 - 275 gal.

Will all tanks be more than seven feet from any flame? yes How many tanks fireproofed? \_\_\_\_\_

Amount of fee enclosed? 1.00 (\$1.00 for one heater, etc., 50 cents additional for each additional heater, etc., in same building at same time.)

INSPECTION COPY

Signature of contractor

By

Halverson Bros

383



Ward 7 Permit No. 35/209  
Location 844 Congress St.  
Owner Ernest R. Leavitt  
Date of permit 2/25/35.  
Post Card sent 2/26/35  
Notif. for insp. None  
Approval Tag issued 3/9/35. O.R.  
Oil Burner Check List (date) 3/9/35.

1. Kind of heat Steam
2. Label ✓
3. Anti-siphon ✓
4. Oil storage ✓
5. Tank distance ✓
6. Vent pipe ✓
7. Fill pipe ✓
8. Gauge ✓
9. Rigidity ✓
10. Feed safety ✓
11. Pipe sizes and material ✓
12. Control valve ✓
13. Ash pit vent ✓
14. Temp. or pressure safety ✓
15. Instruction card ✓
16.

NOTES