

271 BRACKETT STREET

SHAKESPEARE

1800 BRACKETT STREET, BOSTON, MASS. 02108



**APPLICATION FOR PERMIT**  
**DEPARTMENT OF BUILDING INSPECTIONS SERVICES**  
**ELECTRICAL INSTALLATIONS**

Date Jan. 30, 1981  
 Receipt and Permit number A 66814

To the CHIEF ELECTRICAL INSPECTOR, Portland, Maine:

The undersigned hereby applies for a permit to make electrical installations in accordance with the laws of Maine, the Portland Electrical Ordinance, the National Electrical Code and the following specifications:

LOCATION OF WORK: 269-271 Brackett St.  
 OWNER'S NAME: Cliff Roberts ADDRESS: Brook Rd. Falmouth

	FEES
<b>OUTLETS:</b>	
Receptacles _____ Switches _____ Plugmold _____ ft. TOTAL _____	
<b>FIXTURES: (number of)</b>	
Incandescent _____ Fluorescent _____ (not strip) TOTAL _____	
Strip Fluorescent _____ ft. _____	
<b>SERVICES:</b>	
Overhead <input checked="" type="checkbox"/> Underground _____ Temporary _____ TOTAL amperes <u>200</u>	<u>3.00</u>
METERS: (number of) <u>1</u>	<u>.50</u>
<b>MOTORS: (number of)</b>	
Fractional _____	
1 HP or over _____	
<b>RESIDENTIAL HEATING:</b>	
Oil or Gas (number of units) _____	
Electric (number of rooms) _____	
<b>COMMERCIAL OR INDUSTRIAL HEATING:</b>	
Oil or Gas (by a main boiler) _____	
Oil or Gas (by separate units) _____	
Electric (number of) _____ Over 20 kws _____	
<b>APPLIANCES: (number of)</b>	
Ranges _____ Water Heaters _____	
Cook Tops _____ Disposals _____	
Wall Ovens _____ Dishwashers _____	
Dryers _____ Compactors _____	
Fans _____ Others (denote) _____	
TOTAL _____	
<b>MISCELLANEOUS: (number of)</b>	
Branch Panels _____	
Transformers _____	
Air Conditioners Central Unit _____	
Separate Units (windows) _____	
Signs 20 sq. ft. and under _____	
Over 20 sq. ft. _____	
Swimming Pools Above Ground _____	
In Ground _____	
Fire/Burglar Alarms Residential _____	
Commercial _____	
Heavy Duty Outlets, 220 Volt (such as welders) 30 amps and under _____	
over 30 amps _____	
Circus, Fairs, etc. _____	
Alterations to wires _____	
Repairs after fire _____	
Emergency Lights, battery _____	
Emergency Generators _____	
	INSTALLATION FEE DUE: _____
FOR ADDITIONAL WORK NOT ON ORIGINAL PERMIT _____	DOUBLE FEE DUE: _____
FOR REMOVAL OF A "STOP ORDER" (304-16.b) _____	TOTAL AMOUNT DUE: <u>3.50</u>

**INSPECTION:**  
 Will be ready on \_\_\_\_\_, 19\_\_; or Will Call   
 CONTRACTOR'S NAME: Jon Hodgdon  
 ADDRESS: 80 Maple Ave. Scarborough  
 TEL.: \_\_\_\_\_  
 MASTER LICENSE NO.: 3906 SIGNATURE OF CONTRACTOR  
 LIMITED LICENSE NO.: \_\_\_\_\_ *Jon Hodgdon*

INSPECTOR'S COPY — WHITE  
 OFFICE COPY — CANARY  
 CONTRACTOR'S COPY — GREEN



CITY OF PORTLAND, MAINE  
FIRE DEPARTMENT



JOSEPH R. CREMO  
CHIEF

FIRE PREVENTION BUREAU  
380 CONGRESS STREET  
PORTLAND, MAINE

March 11, 1971

Mr. Clifton C. Roberts  
141 Gray Road  
Falmouth, Maine 04105

Re: 269-271 Brackett Street  
Portland, Maine

Dear Mr. Roberts:

A recent inspection of your property by a fire inspector from the Portland Fire Department, Fire Prevention Bureau, revealed the existence of conditions which are in violation of the laws pertaining to fire and structural safety.

Accordingly, the following steps are to be taken to remedy these conditions:

Provide an approved second means of egress for the 2nd and 3rd floor of the 269 side at the above address.

Provide an approved second means of egress for the 3rd floor of the 271 side at the above address.

Before any work is started a permit must be obtained from the Office of Building Inspection and posted on the premises where the work is being done.

Please advise this office within ten days of the action which you propose to take.

By Direction of Chief of Fire Department

Copy: Legal Department  
Building Inspector ✓  
File

CERTIFIED MAIL R.P.R. #619158

*Joseph R. Cremo*

CITY OF PORTLAND, MAINE  
FIRE DEPARTMENT



JOSEPH R. CREMO  
CHIEF

FIRE PREVENTION BUREAU  
380 CONGRESS STREET  
PORTLAND, MAINE

March 11, 1971

Mr. Clifton C. Roberts  
141 Gray Road  
Falmouth, Maine 04105

Re: 269-271 Brackett Street  
Portland, Maine

Dear Mr. Roberts:

A recent inspection of your property by a fire inspector from the Portland Fire Department, Fire Prevention Bureau, revealed the existence of conditions which are in violation of the laws pertaining to fire and structural safety.

Accordingly, the following steps are to be taken to remedy these conditions:

Provide an approved second means of egress for the 2nd and 3rd floor of the 269 side at the above address.

Provide an approved second means of egress for the 3rd floor of the 271 side at the above address.

Before any work is started a permit must be obtained from the Office of Building Inspection and posted on the premises where the work is being done.

Please advise this office within ten days of the action which you propose to take.

By Direction of Chief of Fire Department

Copy: Legal Department  
Building Inspector ✓  
File

CERTIFIED MAIL R.R. #619158

*Joseph R. Cremo*

RECEIVED  
MAR 1 1971  
DEPT. OF BLDG. INSP.  
CITY OF PORTLAND

**PERMIT TO INSTALL PLUMBING**

49

Date Issued 3-1-63 **PORTLAND PLUMBING INSPECTOR**

By J. P. Welch

APPROVED FIRST INSPECTION

Date 3-1-63

By JOSEPH P. WELCH

APPROVED FINAL INSPECTION

Date 3-5-1963

By JOSEPH P. WELCH

By  COMMERCIAL  
 RESIDENTIAL  
 SINGLE  
 MULTI FAMILY  
 NEW CONSTRUCTION  
 REMODELING

Address 271 Brackett Street PERMIT NUMBER

Installation For: William H. Gailey

Owner of Bldg. William H. Gailey

Owner's Address: 271 Brackett Street

Plumber: Portland Gas Light Company Date: 3-1-63

NEW	REPL	PROPOSED INSTALLATIONS	NUMBER	FEE
		SINKS		
		LAVATORIES		
		TOILETS		
		BATH TUBS		
		SHOWERS		
		DRAINS		
		HOT WATER TANKS	1	\$ 2.00
		TANKLESS WATER HEATERS		
		GARBAGE GRINDERS		
		SEPTIC TANKS		
		HOUSE SEWERS		
		ROOF LEADERS (Conn. to house drain)		
			<b>TOTAL</b>	<b>\$ 2.00</b>

PORTLAND HEALTH DEPT. PLUMBING INSPECTION



FILL IN AND SIGN WITH INK

### APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIPMENT

Portland, Maine October 29, 54

PERMIT NUMBER  
01000

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 271 Brackett St No. of Building Dwelling No. Stories 1  New Building  Existing

Name and address of owner of appliance W. H. Taylor 271 Brackett St

Installer's name and address Gould-Farmer Co. 31 Maine St Telephone 38187

#### General Description of Work

To install oil burner in steam heating coils

#### IF HEATER, OR POWER BOILER

Location of appliance \_\_\_\_\_ Any burnable material in floor surface or beneath? \_\_\_\_\_

If so, how protected? \_\_\_\_\_ Kind of fuel? \_\_\_\_\_

Minimum distance to burnable material, from top of appliance or casing top of furnace \_\_\_\_\_

From top of smoke pipe. \_\_\_\_\_ From front of appliance \_\_\_\_\_ From sides or back of appliance \_\_\_\_\_

Size of chimney flue \_\_\_\_\_ Other connections to same flue \_\_\_\_\_

If gas fired, how vented? \_\_\_\_\_ Rated maximum demand per hour \_\_\_\_\_

Will sufficient fresh air be supplied to the appliance to insure proper and safe combustion? \_\_\_\_\_

#### IF OIL BURNER

Name and type of burner Silent Glow 1200 Labeled by underwriter's laboratories? Yes

Will operator be always in attendance? No Does oil supply line feed from top or bottom of tank? Bottom

Type of floor beneath burner concrete Size of vent pipe 1 1/4

Location of oil storage Basement Number and capacity of tanks one 275

Low water shut off \_\_\_\_\_ Make Watts No. 877

Will all tanks be more than five feet from any flame? Yes How many tanks enclosed? None

Total capacity of any existing storage tanks for furnace burners None

#### IF COOKING APPLIANCE

Location of appliance \_\_\_\_\_ Any burnable material in floor surface or beneath? \_\_\_\_\_

If so, how protected? \_\_\_\_\_ Height of Legs, if any \_\_\_\_\_

Skirting at bottom of appliance? \_\_\_\_\_ Distance to combustible material from top of appliance? \_\_\_\_\_

From front of appliance \_\_\_\_\_ From sides and back \_\_\_\_\_ From top of smokepipe \_\_\_\_\_

Size of chimney flue \_\_\_\_\_ Other connections to same flue \_\_\_\_\_

Is hood to be provided? \_\_\_\_\_ If so, how vented? \_\_\_\_\_ Forced or gravity? \_\_\_\_\_

If gas fired, how vented? \_\_\_\_\_ Rated maximum demand per hour \_\_\_\_\_

#### MISCELLANEOUS EQUIPMENT OR SPECIAL INFORMATION

Amount of fee enclosed 2.00 (\$2.00 for one heater, etc.. 50 cents additional for each additional heater, etc., in same building at same time.)

APPROVED:

*[Signature]*

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? Yes

Gould-Farmer Co. of Maine, Inc.

Signature of Installer

*[Signature]*

INSPECTION COPY



1112

- 1 Full Pipe
- 2 Vent Pipe
- 3 Kind of Heat
- 4 Barrier, Radius & Supports
- 5 Name & Label
- 6 Stack Control
- 7 Height of Control
- 8 Remote Control
- 9 Pipe Support & Section
- 10 Vent Support
- 11 Cap or Closure
- 12 Tank Height & Supports
- 13 Tank Distance

NOTES

Permit No. 577/1931  
Location 271 Broadbent St.  
Owner Donald Hammond Co.  
Date of permit 11/1/54  
Approved

- 4 Oil Gauge
- 5 Instruction Card
- 5 Low Water Shut off

--	--



(A) APARTMENT HOUSE ZONE  
APPLICATION FOR PERMIT

Class of Building or Type of Structure Third Class  
Portland, Maine, June 4, 1952

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect ~~and~~ <sup>erect</sup> the following building structure ~~erect~~ in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 271 Brackett Street Within Fire Limits? yes Dist. No. \_\_\_\_\_  
Owner's name and address W. H. Gailey, 271 Brackett Street Telephone 3-9467  
Lessee's name and address \_\_\_\_\_ Telephone \_\_\_\_\_  
Contractor's name and address Winfred W. Wiles, 12 Cragmore Ave., So. Portland Telephone \_\_\_\_\_  
Architect \_\_\_\_\_ Specifications \_\_\_\_\_ Plans yes No. of sheets 1  
Proposed use of building Apartment house No. families 3  
Last use \_\_\_\_\_ " " \_\_\_\_\_ No. families 3  
Material wood No. stories 2 1/2 Heat \_\_\_\_\_ Style of roof \_\_\_\_\_ Roofing \_\_\_\_\_  
Other buildings on same lot \_\_\_\_\_  
Estimated cost \$ 2607.260 Fee \$ 2.00

General Description of New Work

To erect wooden fire escape third floor level to ground on left hand side of building as per plan.

*6/30/53 - Mr. Gailey says they are not to do work - apt on 3rd floor is vacant and is not to be used. P.H. Chief's order 1/10/52 2nd floor required from 3rd floor. Refused 7/7/53*

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. **PERMIT TO BE ISSUED TO W. H. Gailey**

Details of New Work

Is any plumbing involved in this work? \_\_\_\_\_ Is any electrical work involved in this work? \_\_\_\_\_  
Is connection to be made to public sewer? \_\_\_\_\_ If not, what is proposed for sewage? \_\_\_\_\_  
Height average grade to top of plate \_\_\_\_\_ Height average grade to highest point of roof \_\_\_\_\_  
Size, front \_\_\_\_\_ depth \_\_\_\_\_ No. stories \_\_\_\_\_ solid or filled land? \_\_\_\_\_ earth or rock? \_\_\_\_\_  
Material of foundation \_\_\_\_\_ Thickness, top \_\_\_\_\_ bottom \_\_\_\_\_ cellar \_\_\_\_\_  
Material of underpinning \_\_\_\_\_ Height \_\_\_\_\_ Thickness \_\_\_\_\_  
Kind of roof \_\_\_\_\_ Rise per foot \_\_\_\_\_ Roof covering \_\_\_\_\_  
No. of chimneys \_\_\_\_\_ Material of chimneys \_\_\_\_\_ of lining \_\_\_\_\_ Kind of heat \_\_\_\_\_ fuel \_\_\_\_\_  
Framing lumber—Kind \_\_\_\_\_ Dressed or full size? \_\_\_\_\_  
Corner posts \_\_\_\_\_ Sills \_\_\_\_\_ Girt or ledger board? \_\_\_\_\_ Size \_\_\_\_\_  
Girders \_\_\_\_\_ Size \_\_\_\_\_ Columns under girders \_\_\_\_\_ Size \_\_\_\_\_ Max. on centers \_\_\_\_\_  
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.  
Joists and rafters: \_\_\_\_\_ 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
On centers: \_\_\_\_\_ 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
Maximum span: \_\_\_\_\_ 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
If one story building with masonry walls, thickness of walls? \_\_\_\_\_ height? \_\_\_\_\_

If a Garage

No. cars now accommodated on same lot \_\_\_\_\_, to be accommodated \_\_\_\_\_ number commercial cars to be accommodated \_\_\_\_\_  
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? \_\_\_\_\_

APPROVED: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Miscellaneous

Will work require disturbing of any tree on a public street? no  
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

INSPECTION COPY

Signature of owner

*William H. Gailey*

4

Permit No. 521

Location 271 Brackett St.

Owner J. J. Seidley

Date of permit 1/5/57

Notif. closing-in

Inspn. closing-in

Final Notif.

Final Inspn.

Cert. of Occupancy issued

NOTES

Handwritten notes in the top section of the lined area.

Main body of the document containing multiple columns of horizontal lines for notes.

AP 271 Brackett Street

June 20, 1952

Mr. W. H. Galley,  
271 Brackett Street,  
Portland, Maine

c.c. Mr. Winfred W. Wiles,  
12 Cragmore Avenue,  
South Portland, Maine

Dear Mr. Galley:-

We are unable to issue a permit for construction of a proposed fire escape on the side of your building at 271 Brackett Street, as indicated on the plan filed with the application for permit, for the following reasons:-

- 1 - The stairway, which is shown constructed of wood, is only 24" wide, whereas a minimum width of 30" is specified by the Building Code for a wooden fire escape.
- 2 - The pitch of the stairway is too steep. Wooden stairs are required to have steps so constructed that the height from top of one tread to top of the next is not over 8½" and the width of tread is required to be not less than 9", not counting the nosing.
- 3 - There is no indication as to the size and thickness of the metal angles and other members which make up the brackets and drop ladder, nor of the diameter of the bolts fastening the brackets to the building, which in the case of the top fastenings are required to extend through the wall of the building.

While there is no objection to constructing the fire escape partly of wood and partly of steel, if you desire to take advantage of the steeper and narrower stairway allowed for metal fire escapes, it is necessary that all parts of the fire escape be constructed of metal according to the specification of Section 303-g of the Building Code.

Very truly yours,

Harven McDonald  
Inspector of Buildings

AJS/G

FILL IN COMPLETELY AND SIGN WITH INK

Permit No. 1537 ISSUED



# APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIPMENT

SEP 28 1932

Portland, Maine, \_\_\_\_\_

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications: dwelling house

Location 271 Brackett Street Use of Building \_\_\_\_\_ Ward 7

Name and address of owner Harold H. Baker, 271 Brackett St. Telephone 8-2408

Contractor's name and address Cutler & Cutler, Inc. 186 Federal St.

## General Description of Work

To install Oil Burning Equipment

### IF HEATER, POWER BOILER OR COOKING DEVICE

Is heater or source of heat to be in cellar? yes If not, which story \_\_\_\_\_ Kind of Fuel concrete

Material of supports of heater or equipment (concrete floor or what kind) \_\_\_\_\_

Minimum distance to wood or combustible material, from top of boiler or casing top of furnace, \_\_\_\_\_

from top of smoke pipe \_\_\_\_\_, from front of heater \_\_\_\_\_ from sides or back of heater \_\_\_\_\_

### IF OIL BURNER

Name and type of burner Williams Oil-O-Matic Labeled and approved by Underwriters' Laboratories? yes

Will operate or be always in attendance? basement Type of oil feed (gravity or pressure) gravity

Location oil storage five No. and capacity of tanks 1 - 275 gal.

Will all tanks be more than seven feet from any flame? yes How many tanks fireproofed? \_\_\_\_\_

Amount of fee enclosed? 1.00 (\$1.00 for one heater, etc., 50 cents additional for each additional heater, etc., in same building at same time.)

Signature of contractor

*[Handwritten Signature]*

INSPECTION COPY

CERTIFICATE OF OCCUPANCY  
REQUIREMENT IS WAIVED

1537

Ward 7 Permit No. 32/1537.  
 Location 271 Brackett St.  
 Owner Harold H. Baker  
 Date of permit 9/28/32.  
 Notif. closing-in \_\_\_\_\_  
 Inspn. closing-in \_\_\_\_\_  
 Final Notif. \_\_\_\_\_  
 Final Inspn. 10/20/32  
 Cert. of Occupancy issued None

NOTES

1. Kind of heat Steam
2. Label ✓
3. Anti-siphon —
4. Oil storage ✓
5. Tank distance ✓
6. Vent pipe ✓
7. Fill pipe ✓
8. Gauge ✓
9. Rigidity ✓
10. Feed safety ✓
11. Pipe sizes & material ✓
12. Control valve ✓
13. Air pressure vent ✓
14. Trip or pressure safety ✓
15. Insulation ✓
16. \_\_\_\_\_



Location, Ownership and detail must be correct, complete and legible.  
 Separate application required for every building.  
 Plans must be filed with this application.

## Application for Permit for Alterations, etc.

To the

Portland, Me., January 21, 1940

INSPECTOR OF BUILDINGS:

The undersigned applies for a permit to alter the following described building:—

Location ..... 271 Brackett Street ..... Ward 6 ..... in fire limit? no  
 Name of Owner or Lessee, Mrs. Eva A. Fox ..... Address 271 Brackett Street  
 " " Contractor, F S Crosby ..... " Waterville, Me  
 " " Architect, ..... " .....  
 Material of Building is wood ..... Style of Roof, pitch ..... Material of Roofing, shingle .....  
 Size of Building is 30ft ..... feet long; ..... 26ft ..... feet wide. No. of Stories, 3 .....  
 Cellar Wall is constructed of stone ..... inches wide on bottom and batters to ..... inches on top.  
 Underpinning is brick ..... is ..... inches thick; is ..... feet in height.  
 Height of Building 32ft ..... Wall, if Brick; 1st, ..... 2d, ..... 3d, ..... 4th, ..... 5th, .....  
 What was Building last used for? ..... dwelling ..... No. of Families? 1 .....  
 What will Building now be used for? ..... dwelling (one family) .....

**Descrip-  
tion of  
Present  
Bldg.**

PERMIT MUST BE OBTAINED BEFORE BEGINNING WORK

### Detail of Proposed Work

Build addition 11x11 feet to be used as closed in porch with asphalt  
 roof all to comply with the building ordinance  
 .....  
 .....  
 ..... Estimated Cost \$ 125.

### If Extended On Any Side

Size of Extension, No. of feet long? .....; No. of feet wide? .....; No. of feet high above sidewalk? .....  
 No. of Stories high? .....; Style of Roof? .....; Material of Roofing? .....  
 Of what material the Extension be built? ..... Foundation? .....  
 If of Brick, what will be the thickness of External Walls? ..... inches; and Party Walls ..... inches.  
 How will the extension be occupied? ..... How connected with Main Building? .....

### When Moved, Raised or Built Upon

No. of Stories in height when Moved, Raised, or Built upon? ..... Proposed Foundations .....  
 No. of feet high from level of ground to highest part of Roof to be? .....  
 How many feet will the External Walls be increased in height? ..... Party Walls .....  
 .....  
 .....

### If Any Portion of the External or Party Walls Are Removed

Will an opening be made in the Party or External Walls? ..... in ..... Story.  
 Size of the opening? ..... How protected? .....  
 How will the remaining portion of the wall be supported? .....

Signature of Owner or  
 Authorized Representative .....  
 Address F S Crosby, Waterville

27 Brackett St



1914

Application for Permit for Alterations

Plans must be filed with the Department of Buildings and approved for each portion. Overhead and flag must be covered.

PERMIT GRANTED  
Jan 21 1924

Permit filled out by .....  
Permit number .....  
Location 271 Brackett

FINAL REPORT

Has the work been completed in accordance with this application and plans filed and approved? ..... 102.....

Law been violated? ..... Doc. No. .... of 102.....

Nature of violation? .....

Table with multiple columns and rows, containing faint text and numbers, possibly a schedule or list of items.

Violation removed, when? ..... 102.....

Estimated cost of alterations, etc. \$.....

Inspector of Buildings

PERMIT MUST BE OBTAINED BEFORE BEGINNING WORK

102 Brackett St

ANSWER MUST BE OBTAINED BEFORE BEGINNING WORK





CITY OF PORTLAND, MAINE

389 CONGRESS STREET  
PORTLAND, MAINE 04101  
(207) 775-5451

DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

P. SAMUEL HOFFSES, CHIEF  
INSPECTION SERVICES DIVISION

Date: February 22, 1989

Elliot Silverman  
P. O. Box 17682  
Portland, ME 04101

Re: Smoke Detectors

Dear Mr. Silverman:

During a recent inspection of the property owned by you at 271 Brackett Street, Portland, Maine, it was noted that smoke detectors were missing/inoperable in some locations.


25 MRSA 2464 requires that approved smoke detectors be installed in each apartment in the immediate vicinity of the bedrooms. When actuated, the detector shall provide an alarm suitable to warn the occupants within the individual unit. Failure to comply with this statute may result in a fine of up to \$500 for each violation.

Re-inspection of your property will be made in ten (10) days. Lack of compliance will result in referral of the matter for legal action.

Loss control is a responsibility of your management. Our observations are intended to assist you. Recommendations are a result of conditions observed at the time of our visits. They do not necessarily include every possible loss potential code violation, or exception to good practice.

Sincerely yours,

Joseph E. Gray, Jr., Director  
Planning & Urban Development

By:   
P. Samuel Hoffses  
Chief of Inspection Services

Joseph Torres, Housing Inspector  
Code Enforcement Officer

cc: Lt. James P. Collins, Fire Prevention Bureau

jmr

*mailed*



## CITY OF PORTLAND

DEPARTMENT OF PLANNING & URBAN DEVELOPMENT  
INSPECTION SERVICES DIVISION

February 22, 1989

Elliot Silverman  
P. O. Box 17682  
Portland, ME 04101

Re: 271 Brackett Street 54-G-16, 17

Dear Sir:


We recently received a complaint and an inspection was made by Code Enforcement Officer: Joseph Torres of the property owned by you at 271 Brackett Street, Portland, Maine. As a result of the inspection, you are hereby ordered to correct the following substandard housing conditions:

1. INTERIOR SECOND FLOOR, APT. #2 - HALLWAY - smoke detector missing. 2464

The above mentioned conditions are in violation of Article V of the Municipal Code of the City of Portland, Maine, and must be corrected on or before March 4, 1989.

Failure to comply with this order may result in a complaint being filed for prosecution in District Court.

Sincerely yours,  
Joseph E. Gray, Jr., Director of  
Planning & Urban Development

By   
F. Samuel Morris  
Chief of Inspection Services

Joseph Torres, Housing Inspector

jmr