

299-301 BRACKETT STREET

SHAW-WALKER

Full cut # 920R - Half cut # 9202R - Tjira # 9203R - Full cut # 9209R

CITY OF PORTLAND, MAINE

Application for Permit to Install Wires

Permit No. 58354
 Issued 12/1/69
 Portland, Maine Dec 1 1969

To the City Electrician, Portland, Maine:

The undersigned hereby applies for a permit to install wires for the purpose of conducting electric current, in accordance with the laws of Maine, the Electrical Ordinance of the City of Portland, and the following specifications:

(This form must be completely filled out — Minimum Fee \$1.00)

Owner's Name and Address Thomas Laughlin Tel.

Contractor's Name and Address J. E. Edwards Tel.

Location 299-301 Crescent St Use of Building

Number of Families Apartments Stores Number of Stories

Description of Wiring: New Work Additions Alterations

Pipe Cable Metal Molding BX Cable Plug Molding (No. of feet)

No. Light Outlets Plugs Light Circuits Plug Circuits

FIXTURES: No. Fluor. or Strip Lighting (No feet)

SERVICE: Pipe Cable Underground No. of Wires 3 Size 4/0-3/0

METERS: Relocated Added Total No. Meters 7

MOTORS: Number Phase H. P. Amps Volts Starter

HEATING UNITS: Domestic (Oil) No. Motors Phase H.P.

Commercial (Oil) No. Motors Phase H.P.

Electric Heat (No. of Rooms)

APPLIANCES: No. Ranges Watts Brand Feeds (Size and No.)

Elec. Heaters Watts

Miscellaneous Watts Extra Cabinets or Panels

Transformers Air Conditioners (No. Units) Signs (No. Units)

Will commence 19... Ready to cover in 19... Inspection 19...

Amount of Fee \$ 2.00

Signed J. E. Edwards

DO NOT WRITE BELOW THIS LINE

SERVICE METER GROUND

VISITS: 1 2 3 4 5 6

7 8 9 10 11 12

REMARKS:

INSPECTED BY J. W. Herbert
(SEAL)

LOCATION *Braz. Kraft ST 299-301*
 INSPECTION DATE *12/3/69*
 WORK COMPLETED *12/3/69*
 TOTAL NO. INSPECTIONS *1*
 REMARKS:

FEEES FOR WIRING PERMITS EFFECTIVE JULY 31, 1963

WIRING

1 to 30 Outlets \$ 2.00
 31 to 60 Outlets 3.00
 Over 60 Outlets, each Outlet05
 (Each twelve feet or fraction thereof of fluorescent lighting or
 any type of plug molding will be classed as one outlet).

SERVICES

Single Phase 2.00
 Three Phase 4.00

MOTORS

Not exceeding 50 H.P. 3.00
 Over 50 H.P. 4.00

HEATING UNITS

Domestic (Oil) 2.00
 Commercial (Oil) 4.00
 Electric Heat (Each Room)75

APPLIANCES

Ranges, Cooking Tops, Ovens, Water Heaters, Disposals, Built-in
 Dishwashers, Dryers, and any permanent built-in appliance — each
 unit 1.50

MISCELLANEOUS

Temporary Service, Single Phase 1.00
 Temporary Service, Three Phase 2.00
 Circuses, Carnivals, Fairs, etc. 10.00
 Meters, relocate 1.00
 Distribution Cabinet or Panel, per unit 1.00
 Transformers, per unit 2.00
 Air Conditioners, per unit 2.00
 Signs, per unit 2.00

ADDITIONS

5 Outlets, or less 1.00
 Over 5 Outlets, Regular Wiring Rates

299-301 Brackett Street

Feb. 14, 1972

Allen Googins
Rehabilitation Specialist
684 Congress Street, P.O. Box 911

Dear Mr. Googins:

These inside rooms referred to in your letter to Ronald H. Johnston on Feb. 3, 1972 are an existing condition. therefore the only feasible way that we can see that the intent of the Building Code is met in some aspects is to require that these rooms will not have any doors on the door opening or the doors to be provided must have louvres within the door, on this basis we can go along with the use of these rooms.

Very truly yours,

A. Allan Soule
Assistant Director

AAS:m



CITY OF PORTLAND, MAINE
 DEPARTMENT OF BUILDING INSPECTION
COMPLAINT

Location:
 299 Brackett St.

INSPECTION COPY

COMPLAINT NO. 63/71

Date Received October 18, 1971

Location 299 Brackett St.

Owner's name and address Roland Johnstone - Westbrook, Maine Use of Building _____ Telephone _____


Tenant's name and address _____ Telephone _____

Complainant's name and address William Wallace - same Telephone _____

Description: Lights for front & rear hallways do not work. Telephone _____
Ceiling dangerous.

NOTES:

10/25/71 Leaks when raining in front
 Back hallway lights do not work.
 other tenants said both hallways are
 lighted up at sun down. P.M. Cup
 Mr. Wallace is on 3rd floor - light is
 in the rear of the property. The
 Bull turned out.



CITY OF PORTLAND, MAINE
MEMORANDUM

DATE: 12-7-71

TO: Lyle D. Noyes, Housing Inspector Supervisor
FROM: R. Lovell Brown, Director of Building & Inspection Services
SUBJECT: In reference to 299-301 Brackett Street

Pertaining to the venting of the inside room at the above address, we feel that inasmuch as the owner has agreed to remove the door to that room and the condition is an existing one we will waive any additional venting requirements.

R. Lovell Brown

RLB:m

cc to: Joseph Oliver, Housing Department - Health Dept.



FILL IN AND SIGN WITH INK

APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIPMENT

Portland, Maine, March 12, 1970

PERMIT 231
CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.
The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 301 Brackett St. Use of Building 6 Man. No. Stories 6 New Building Existing "Existing"
Name and address of owner of appliance Thomas Laugelin, 90 High St. Telephone
Installer's name and address M. & H. Oil Co., 161 E. St. John St.

General Description of Work

To install forced hot water heating system and oil burning equipment in place of 2 hot air furnaces and 1 steam boiler to heat entire building.

IF HEATER, OR POWER BOILER

Location of appliance basement Any burnable material in floor surface or beneath? no
If so, how protected? Kind of fuel? oil
Minimum distance to burnable material, from top of appliance or casing top of furnace over 4'
From top of smoke pipe 3' From front of appliance over 4' From sides or back of appliance over 4'
Size of chimney flue 8x8 Other connections to same flue no Rated maximum demand per hour
If gas fired, how vented? no Will sufficient fresh air be supplied to the appliance to insure proper and safe combustion? no

IF OIL BURNER

Name and type of burner American Standard Labeled by underwriters' laboratories? yes
Will operator be always in attendance? Does oil supply line feed from top or bottom of tank? bottom
Type of floor beneath burner concrete Size of vent pipe 1 1/2"
Location of oil storage basement Number and capacity of tanks No.
Low water shut off Make How many tanks enclosed? No.
Will all tanks be more than five feet from any flame? yes Total capacity of any existing storage tanks for furnace burners 2 - 275 gal.

IF COOKING APPLIANCE

Location of appliance Any burnable material in floor surface or beneath?
If so, how protected? Height of Legs, if any
Skirting at bottom of appliance Distance to combustible material from top of appliance?
From front of appliance From sides and back
Size of chimney flue Other connections to same flue From top of smokepipe
Is hood to be provided? If so, how vented? Forced or gravity?
If gas fired, how vented? Rated maximum demand per hour

MISCELLANEOUS EQUIPMENT OR SPECIAL INFORMATION

Amount of fee enclosed? 2.00 \$2.00 for one heater, etc., \$1.00 additional for each additional heater, etc., in same building at same time

APPROVED:

3/12/70

O.H. McCall

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

M & H. Oil Co.

By:

M & H Oil Co. Hubbert

Signature of Installer

CS 300

INSPECTION COPY

LOCATION 301 BRACKET ST.

V - Verify

INSPECTION DATE 3/5/75 116W

	V	OK
1 FILL PIPE		✓
2 VENT PIPE		✓
3 RED PLATE EMERGENCY SWITCH		✓
4 NUMBER & CAPACITY OF TANKS <u>2-275</u>	✓	3/8
5 TANK RIGIDITY & SUPPORT		✓
6 TANK DISTANCE		✓
7 VENT ALARM		✓
8 FUEL GAUGE		✓
9 FIREMATIC FUEL VALVES		✓
10 BURNER RIGIDITY & SUPPORT		✓
11 PIPING SUPPORT & PROTECTION		✓
12 NAME & LABEL		✓
13 PRIMARY SAFETY CONTROL		✓
14 LIMIT CONTROL		✓
15 LOW WATER CUT-OFF		✓
16 SERVICE SWITCH		✓
17 CONDUIT OR GREENFIELD		✓
18 THERMAL CUT-OFF SWITCH		✓
19 PRESSURE RELIEF VALVE		✓
20 DRAFT REGULATOR		✓
21 ADEQUATE VENTILATION	✓	4/37
22 ANY INDICATION OF OIL LEAKS		✓
23 KIND OF HEAT <u>HOT WATER</u>		✓
24 INSTRUCTION CARD	✓	
25 TANKLESS HOT WATER HEATER		✓
26 TEMPERING VALVE		✓
27 PRESSURE RELIEF VALVE		✓
28 CONDITION OF CHIMNEY <u>HAS LOOSE BRICKS</u>	✓	✓
29 NUMBER & TYPE OF CONNECTIONS TO CHIMNEY		✓
30 FIRESTOPPING		✓
31 STACK DISTANCE TO COMBUSTIBLE MATERIAL		✓

301 Brackett Street

March 24, 1970

cc to: Thomas Laughlin
90 High Street

M & H Oil Company
161 R. St. John Street
Portland, Maine

Gentlemen:

Upon inspection of the above job on March 24, 1970, the following omissions were found:

1. No red plate emergency switch installed at head of stairs.
2. No draft regulator.
3. No instruction card.
4. Chimney has loose bricks placed in opening, this must be cemented.

It is important that correction of these conditions be made before April 7, 1970.

If additional information relative to the above is desired, please phone Inspector Malcolm Ward at 774-8221, extension 234, any weekday but Saturday between 8:00 and 9:00 A. M.

Very truly yours,

Malcolm Ward
Field Inspector

MW:m

301 Drackett St.

April 9, 1970

B & H Oil Company
161 Rear St. John Street

cc to: Thomas Laughlin
90 High Street

Gentlemen:

Upon inspection of the above job on April 8, 1970 the following conditions were not corrected as per our letter of March 24, 1970.

1. No red plate emergency switch.
2. No draft regulator.
3. No instruction card.
4. Loose bricks in chimney.

It is important that correction of these conditions be made before April 22, 1970, and notification be given this office of readiness for another inspection.

Very truly yours,

Malcolm Ward
Building Inspection Department

EW:m

Re: 299-301 Brackett St

March 11, 1970

Dear Mr. Turner Service
913 Congress St.

Gentlemen:

As per our conversation the other day it was understood that you would be in on Monday, March 9th to file the permit for installation at 299-301 Brackett St. As of this date this has not been done.

The owner of the building is concerned because if anything should happen to this furnace he would be unable to collect his insurance because of the lack of a permit.

A permit is always needed before any installation are made. If this permit is not applied for on or before March 15, 1970, we will have to turn the matter over to the Corporation Counsel.

Very truly yours,

E. Lovell Brown
Director

301 Brackett St.

April 29, 1970

cc to: Thomas Laughlin
90 High Street

M & H Oil Company
161 St. John Street
Gentlemen:

Upon inspection of the above job on April 27, 1970
the following omissions were found:

1. No red plate emergency switch installed at head
of cellar stairs.
2. Instruction card not permanently posted near the
assembly as our letter of March 24, 1970 stated
and also letter of April 9, 1970.

It is important that the above conditions be fully
corrected before May 6, 1970 to avoid action against you for
violation of law without further notice.

Very truly yours,

Malcolm Ward
Building Inspection Department

MHW

STRUCTURAL - continued

First Floor 299 Side

- a. The windows in the kitchen which are not weathertight.
- b. The sink in the kitchen - needs caulking.
- c. The missing plaster on the walls in the living room.
- d. The windows in the living room which are not weathertight.
- e. The missing plaster on the walls in the bathroom.
- f. The cracked plaster on the ceiling in the dining room.
- g. The missing plaster on the walls in the front bedroom.
- h. The missing door in the front bedroom.

Second Floor 299 Side

- a. The windows in the kitchen which are not weathertight.
- b. The cracked and loose plaster on the ceiling and walls in the middle bedroom on the third floor.


ELECTRICAL

- a. The defective light switch in the first floor rear hall at 299.
- b. Install a main ground wire.
- c. The defective ceiling light fixture in the bathroom on the second floor at 301.
- d. Install one duplex convenience outlet in the living room at 299.

HEATING

- a. Have the entire heating system checked by a competent heating specialist.

The above mentioned conditions are in violation of Chapter 307 of the Municipal Code of the City of Portland and must be corrected on or before October 24, 1969.



CITY OF PORTLAND
HEALTH DEPARTMENT
HOUSING DIVISION



Loc. 299-301 Brackett St.
Loc w/S
Bldg Fire ELEC
Issued Sept. 15, 1969
Expires October 24, 1969

Mr. Thomas A. Laughlin
90 High Street
Portland, Maine 04101

Dear Sir:
On September 16, 1969 an examination was made of the premises located
at 299-301 Brackett Street, Portland, Maine

Non-compliance with the ordinances relating to housing conditions was found as detailed below.
In accordance with the provisions of the above ordinance, you are hereby ordered to
correct these defects according to specifications within the time limits allowed. Failure to
comply with this notice will necessitate legal action.

Some repairs or improvements required will necessitate permits which are to be ob-
tained from the Building Inspector, Health, Fire or other City Departments. These must be ob-
tained before the work is started.

If any additional information is desired, visit or telephone the Housing Supervisor at
this Office, Tel. 774-8221, extension 226. Kindly notify this office as soon as all corrections
have been completed.

Very truly yours,
Health Director

By _____
Housing Supervisor

VIOLATIONS & SPECIFICATIONS

Responsibility of Owner or Agent ** Responsibility of Occupant
Repair and put in good order all dilapidated and hazardous parts of the structure as follows:

STRUCTURAL

- a. The missing front porch railing at 299.
- b. The rear left porch.
- c. The foundation - needs pointing and bricks are missing.
- d. The missing and broken clapboards on the exterior walls.
- e. The broken cellar windows.
- f. The roof - shows signs of leakage and the shingles are curling.
- g. The broken window in the attic at 301
- h. The broken window in the front door at 301.
- i. The missing parts of the downspouts at the front of the structure.
- j. The defective sidewalk at 301.
- k. The rear door at 301 which is not weathertight.
- l. The front and rear door at 299 which are not weathertight.
- m. The missing plaster on the walls in the rear hall at 301.
- n. The loose stair rails in the rear hall at 301.

CITY OF PORTLAND, MAINE
MEMORANDUM

DATE: Sept 30, 1969

TO: Captain Geisler - Fire Prevention

FROM: Allan Soule

SUBJECT: 299-301 Brackett St.

I will be sending a letter out with this permit mentioning the wiring that you brought up as well as the lock and doors to the rear stairs at the second floor level. I will also mention the holes in the cellar floor as well as the chimney and clean out doors and the closing up of the opening on the third floor in the chimney on the left hand side. I will also put it in the letter about the condition of the two rear porches on each side and again state that plywood will not be allowed in the stairway of public halls. If there is anything that I've forgotten let me know and I will put it in the letter also.

299-301 Brackett Street

Oct. 3, 1969

Thomas A. Laughlin
90 High Street

Dear Mr. Laughlin:

Building permit to change the use of this building from 4-family to 6-family apartment building without alterations is being issued subject to plans received with the application and in compliance with the Building Code restrictions as follows:

1. Doors of the second floor level at both 299 and 301 Brackett Street in the rear are to be removed so that the upper apartments will have unobstructed egress straight to the outside.
2. All openings in the cellar floor are to be filled in with concrete.
3. All chimneys within this building are to be checked out before they are put into use. In the 301 section the opening in the chimney in the proposed third floor apartment, if not to be used, is to be filled in with masonry.
4. The two porches on the rear on each side that have all broken treads and railings, etc. must be replaced with adequate boarding.
5. Only incombustible material allowed on the front and rear hallways and stairways that serves as a public means of egress for the families on the upper floor.
6. The Fire Department requires that new wiring be installed throughout these buildings.

Very truly yours,

A. Allan Soule
Assistant Director Building Inspection Department

AAS:m

CITY OF PORTLAND, MAINE
MEMORANDUM

DATE: Sept 30, 1969

TO: Captain Carber - Fire Prevention

FROM: Allan Soule

SUBJECT: 299-301 Brackett St.

I will be sending a letter out with this permit mentioning the wiring that you brought up as well as the lock and doors to the rear stairs at the second floor level. I will also mention the holes in the cellar floor as well as the chimney and clean out doors and the closing up of the opening on the third floor in the chimney on the left hand side. I will also put it in the letter about the condition of the two rear porches on each side and again state that plywood will not be allowed in the stairway of public halls. If there is anything that I've forgotten let me know and I will put it in the letter also.

Allan Soule
Assistant Director

RECEIVED

OCT-2 1969

DEPT. OF BLDG. INSP.
CITY OF PORTLAND



FILL IN AND SIGN WITH INK

APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIPMENT

Portland, Maine, October 4, 1966

PERMIT 00968 OCT 4 1966 CITY of PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 301 Erackett St. Use of Building Apt. Bldg. (duplex) No. Stories 2 1/2 New Building Existing " Name and address of owner of appliance Thomas A Laughlin, 90 High St. Installer's name and address N A Bruns Inc. 235 Franklin St. Telephone

General Description of Work

To install Oil burning equipment in connection with existing gravity hot water heat (conversion from coal-fired heat) 1st. floor (used burner)

IF HEATER, OR POWER BOILER

Location of appliance Any burnable material in floor surface or beneath? If so, how protected? Kind of fuel? Minimum distance to burnable material, from top of appliance or casing top of furnace From top of smoke pipe From front of appliance From sides or back of appliance Size of chimney flue Other connections to same flue If gas fired, how vented? Rated maximum demand per hour Will sufficient fresh air be supplied to the appliance to insure proper and safe combustion?

IF OIL BURNER

Name and type of burner Eastern oil-gun type Labelled by underwriters' laboratories? yes Will operator be always in attendance? Does oil supply line feed from top or bottom of tank? bottom Type of floor beneath burner concrete Size of vent pipe 1 1/2" Location of oil storage basement Number and capacity of tanks 275 gal. Low water shut off Make No. Will all tanks be more than five feet from any flame? yes How many tanks enclosed? Total capacity of any existing storage tanks for furnace burners

IF COOKING APPLIANCE

Location of appliance Any burnable material in floor surface or beneath? If so, how protected? Height of Legs, if any Skirting at bottom of appliance? Distance to combustible material from top of appliance? From front of appliance From sides and back From top of smoke pipe Size of chimney flue Other connections to same flue Is hood to be provided? If so, how vented? Forced or gravity? If gas fired, how vented? Rated maximum demand per hour

MISCELLANEOUS EQUIPMENT OR SPECIAL INFORMATION

Amount of fee enclosed? 2.00 (\$2.00 for one heater, etc., \$1.00 additional for each additional heater, etc., in same building at same time.)

APPROVED:

O.K. 10-4-66 [Signature]

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

N A Bruns Inc.

CR 300

INSPECTION COPY

Signature of Installer by: N. B. Bruns

71

PERMIT TO INSTALL PLUMBING NOV 6 - 1969 864

Date Issued Nov. 4, 1969
 Portland Plumbing Inspector
 By: ERNOLD R. GOODWIN

App. First Insp. NOV 10 1969
 By: ERNOLD R. GOODWIN
 CHIEF PLUMBING INSPECTOR

App. Final Insp. DEC 19 1969
 By: ERNOLD R. GOODWIN
 CHIEF PLUMBING INSPECTOR

- Type of Bldg.
- Commercial
 - Residential
 - Single
 - Multi Family
 - New Construction
 - Remodeling

Address: 299 & 301 Franklin St. ~~NOV PERMIT NUMBER~~
 Installation For: dwelling
 Owner of Bldg.: Thomas Laphlin DEC 4 - 1969
 Plumber: Reuben Kete Date: 11/4/69

NEW	REPL.		NO.	FEE
		SINKS	6	10.60
2	4	LAVATORIES	2	1.20
2		TOILETS	3	1.80
2	1	BATH TUBS	2	1.20
2		SHOWERS		
		DRAINS FLOOR SURFACE		
		HOT WATER TANKS		
		TANKLESS WATER HEATERS		
		GARBAGE DISPOSALS		
		SEPTIC TANKS		
		HOUSE SEWERS		
		ROOF LEADERS		
		AUTOMATIC WASHERS		
		DISHWASHERS		
		OTHER		
			TOTAL 13	14.80

Building and Inspection Services Dept.: Plumbing Inspection



R6 RESIDENCE ZONE

APPLICATION FOR PERMIT

Class of Building or Type of Structure Third Class

Portland, Maine, September 25, 1969

PERMIT ISSUED

OCT 6 1969

CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 299-301 Brackett St.

Owner's name and address Thomas A Laughlin, 90 High St. Within Fire Limits? _____ Dist. No. _____

Lessee's name and address _____ Telephone 773-5507

Contractor's name and address _____ Telephone _____

Architect _____ Specifications _____ Plans yes Telephone _____

Proposed use of building _____ No. of sheets 1

Last use _____ " " _____ No. families 6

Material frame No. stories 3 Heat _____ Style of roof _____ No. families 4

Other buildings on same lot _____ Roofing _____

Estimated cost \$ _____ Fee \$ 2.00

General Description of New Work

TO CHANGE USE OF BUILDING FROM 4-FAMILY TO 6-FAMILY APARTMENT BUILDING, NO ALTERATIONS AS PER PLAN.

Sent to Fire Dept. 10/1/69
Rec'd from Fire Dept. 10/2/69

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. **PERMIT TO BE ISSUED TO** owner

Details of New Work

Is any plumbing involved in this work? _____ Is any electrical work involved in this work? _____

Is connection to be made to public sewer? _____ If not, what is proposed for sewage? _____

Has septic tank notice been sent? _____ Form notice sent? _____

Height average grade to top of plate _____ Height average grade to highest point of roof _____

Size, front _____ depth _____ No. stories _____ solid or filled land? _____ earth or rock? _____

Material of foundation _____ Thickness, top _____ bottom _____ cellar _____

Kind of roof _____ Rise per foot _____ Roof covering _____

No. of chimneys _____ Material of chimneys _____ of lining _____ Kind of heat _____ fuel _____

Framing Lumber-Kind _____ Dressed or full size? _____ Corner posts _____ Sills _____

Size Girder _____ Columns under girders _____ Size _____ Max. on centers _____

Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.

Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____

On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____

Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____

If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____ number commercial cars to be accommodated _____

Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will work require disturbing of any tree on a public street? no

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Thomas A. Laughlin

APPROVED:

Eric O. Wood Deputy Chief
O.K. - 10/6/69 - Allen W. Little

CS 201

INSPECTION COPY

Signature of owner

by:

Thomas A. Laughlin

LOCATION *Brac Kett St. 301*
 INSPECTION DATE *12/10/66*
 WORK COMPLETED *12/10/66*
 TOTAL NO. INSPECTIONS *1*
 REMARKS:

FEEES FOR WIRING PERMITS EFFECTIVE JULY 31, 1963

WIRING

1 to 30 Outlets (including switches) \$ 2.00
 31 to 60 Outlets (including switches) 3.00
 Over 60 Outlets, each Outlet (including switches)05
 (Each twelve feet or fraction thereof of fluorescent lighting or
 any type of plug molding will be classed as one outlet).

SERVICES

Single Phase 2.00
 Three Phase 4.00

MOTORS

Not exceeding 50 H.P. 3.00
 Over 50 H.P. 4.00

HEATING UNITS

Domestic (Oil) 2.00
 Commercial (Oil) 4.00
 Electric Heat (Each Room)75

APPLIANCES

Ranges, Cooking Tops, Ovens, Water Heaters, Disposals, Dish-
 washers, etc. — Each Unit 1.50

TEMPORARY WORK (Limited to 6 months from date of permit)

Service, Single Phase 1.00
 Service, Three Phase 2.00
 Wiring, 1-50 Outlets 1.00
 Wiring, each additional outlet over 5002
 Circuses, Carnivals, Fairs, etc. 10.00

MISCELLANEOUS

Distribution Cabinet or Panel, per unit 1.00
 Transformers, per unit 2.00
 Air Conditioners, per unit 2.00
 Signs, per unit 2.00

ADDITIONS

5 Outlets, or less 1.00
 Over 5 Outlets, Regular Wiring Rates

CITY OF PORTLAND, MAINE

Application for Permit to Install Wires

To the City Electrician, Portland, Maine:

The undersigned hereby applies for a permit to install wires for the purpose of conducting electric current, in accordance with the laws of Maine, the Electrical Ordinance of the City of Portland, and the following specifications:

Portland, Maine
 Permit No. 55249
 Issued Oct. 11, 1966

(This form must be completely filled out - Minimum Fee, \$1.00)

Owner's Name and Address Mr. Laughlin
 Contractor's Name and Address N. A. Burns Jr. Portland
 Location 301 Stack St
 Number of Families _____
 Description of Wiring: New Work _____

Use of Building _____
 Stores _____
 Additions _____
 Alterations _____

Pipe _____ Cable _____
 No. Light Outlets _____
 Metal Molding _____
 Flugs _____
 Light Switches _____
 Cable _____
 Underground _____
 H. P. _____ Amps _____
 No. Motors _____
 No. Motors _____
 Phase _____
 Phase _____

FIXTURES: No. _____
 SERVICE: Pipe _____
 METERS: Relocated _____
 MOTORS: Number _____
 HEATING UNITS: Domestic (Oil) _____
 Commercial (Oil) _____
 Electric Heat (No. of Rooms) _____
 No. Ranges _____
 Elec. Heaters _____
 Miscellaneous _____
 Transformers _____
 Will commence _____
 Amount of Fee \$ 7.00

Fluor. or Strip Lighting (No. feet) _____
 Plug Molding (No. feet) _____
 Plug Circuits _____
 No. of Wires _____
 Total No. Meters _____
 Volts _____
 Starter _____
 H.P. _____
 H.P. _____
 Brand Feeds (Size and No.) _____
 Extra Cabinets or Panels _____
 Signs (No. Units) _____
 Inspection _____

Signed N. A. Burns Jr.
N. A. Burns Jr.

DO NOT WRITE BELOW THIS LINE

19 _____
 19 _____
 19 _____

SERVICE _____
 VISITS: 1 _____
 7 _____
 2 _____
 8 _____
 3 _____
 9 _____
 4 _____
 10 _____
 5 _____
 11 _____
 6 _____
 12 _____
 GROUND _____

REMARKS: _____

INSPECTED BY J. W. Hubert
 (OVER)

CE 88A



APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIPMENT

Portland, Maine, September 16, 1964

PERMIT ISSUED
1964

SEP 17 1964

CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, Room 205, 225
once with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 299 Brackett St. Use of Building Dwelling, 2 Fam. No. Stories 2
Name and address of owner Theodore Sweetland, 209 Spring St. New Building Existing
Installer's name and address Harris Oil Co., 202 Commercial St. Telephone

General Description of Work

To install oil-fired furnace gravity warm air heat (in place of coal-fired furnace) 1st floor
and to install oil-burning equipment in connection with existing steam heat for 2nd floor (conversion)

IF HEATER, OR POWER BOILER

Location of appliance basement Any burnable material in floor surface or beneath? no
If so, how protected? Kind of fuel? oil
Minimum distance to burnable material, from top of appliance or casing top of furnace 22 23" From sides or back of appliance 3"
From front of appliance 4" From top of smoke pipe 21" From front of appliance 21"
Size of chimney flue 8x8 Other connections to same flue none Rated maximum demand per hour
If gas fired, how vented? none
Will sufficient fresh air be supplied to the appliance to insure proper and safe combustion? yes

IF OIL BURNER

Name and type of burner Homart & Nail (45 gal.) Labeled by underwriters' laboratories? yes
Will operator be always in attendance? Does oil supply line feed from top or bottom of tank? bottom
Type of floor beneath burner concrete Size of vent pipe 1 1/2" each
Location of oil storage basement Make McDonnell-Miller Number and capacity of tanks 2-27 1/2 gal.
Low water shut off yes How many tanks enclosed? No. 67
Will all tanks be more than five feet from any flame? yes
Total capacity of any existing storage tanks for furnace burners none

IF COOKING APPLIANCE

Location of appliance Any burnable material in floor surface or beneath?
If so, how protected? Height of Legs, if any
Skirting at bottom of appliance? Distance to combustible material from top of appliance?
From front of appliance From sides and back From top of smokepipe
Size of chimney flue Other connections to same flue Forced or gravity?
Is hood to be provided? If so, how vented? Rated maximum demand per hour
If gas fired, how vented?

MISCELLANEOUS EQUIPMENT OR SPECIAL INFORMATION

Amount of fee enclosed 3.00 (\$2.00 for one heater, etc., \$1.00 additional for each additional heater, etc. in same building at same time.)

APPROVED: *OK 9.17.64*

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? Yes

Signature of Installer By: *[Signature]* Harris Oil Co.

INSPECTION COPY

P.K.

PERMIT TO INSTALL PLUMBING *out*

11532

PERMIT NUMBER

Date Issued 6-18-62

PORTLAND PLUMBING INSPECTOR

By J. P. Nelson

APPROVED FIRST INSPECTION

Date 7-10-62

By *[Signature]*

APPROVED FINAL INSPECTION

Date JUL 10 1962

By JOSEPH P. WELCH

- TYPE OF BUILDING
- COMMERCIAL
- RESIDENTIAL
- SINGLE
- MULTI-FAMILY
- NEW CONSTRUCTION
- REMODELING

Address		301 Brackett Street	
Installation For:		Mrs. Margaret P. Fournier	
Owner of Bldg.		Mrs. Margaret B. Fournier	
Owner's Address:		301 Brackett Street	
Plumber:		Portland Gas Light Company	
		Date:	6-18-62
NEW	REPL.	PROPOSED INSTALLATIONS	NUMBER
		SINKS	
		LAVATORIES	
		TOILETS	
		BATH TUBS	
		SHOWERS	
		DRAINS	
		HOT WATER TANKS	1
		TANKLESS WATER HEATERS	
		GARBAGE GRINDERS	
		SEPTIC TANKS	
		HOUSE SEWERS	
		ROOF LEADERS (Conn. to house drain)	
			FEE
			\$ 2.00
TOTAL			\$ 2.00

PORTLAND HEALTH DEPT. PLUMBING INSPECTION

CITY OF PORTLAND, MAINE
HEALTH DEPARTMENT



ROBERT A. VANADEN, M.D., M.P.H.
SALUBRITY SUPERVISOR

BUSINESS PLUMBING LICENSES
MASTER PLUMBING LICENSE
JOURNEYMAN PLUMBING LICENSES

This notice is to all persons holding such licenses in the City of Portland. The City Council adopted a new chapter, 413, of the Municipal Code which became effective in September 1961. This new chapter sets up regulations regarding the licensing of Plumbers in the City of Portland. It also re-established the Plumbers Examining Board.

The Plumbers Examining Board is composed of:
Mr. Nelson A. Tripp, Chairman
Mr. Donald O. McCubrey
Mr. Martin Bartley
Mr. Joseph P. Welch, Plumbing Inspector, Secretary

The classification of Business Plumbing License is discontinued. The only licenses issued now are Master Plumber and Journeyman.

Fees:
Master Plumber \$20.
Journeyman Plumber 3.

No new "limited" plumbers licenses will be issued. All such "limited" licenses in effect on the date of the adoption of this ordinance will be renewed if application is made annually.

All licenses will be renewed through the Health Department Office. Please make checks payable to the City of Portland. Remember licenses expire July 31st. of each year and must be renewed annually as outlined under Section 15 of Chapter 413, the Municipal Code.

Norman M. Winch
Norman M. Winch, P.E.,
Public Health Engineer

HAINE PRINTING CO., PORTLAND

CITY OF PORTLAND
HEALTH DEPARTMENT
HOUSING DIVISION



Mr. Chester H. Libby,
c/o A. C. Libby Co.,
415 Congress St., Room 211,
Portland, Maine

Loc. 299 Brackett St.
Loc w/i S
Bldg X Fire X Elec X Other
Issued August 2, 1957
Expires September 2, 1957

RECEIVED
AUG 5 1957
OFFICE OF BUILDING INSPECTION
CITY OF PORTLAND
Housing Division

Dear Sir: On August 28, 1957 an examination was made of the premises located at 299 Brackett St., Portland, Maine

Non-compliance with the ordinances relating to housing conditions was found as detailed below. In accordance with the provisions of the above ordinance, you are hereby ordered to correct these defects according to specifications within the time limits allowed. Failure to comply with this notice will necessitate legal action. Some repairs or improvements required will necessitate permits which are to be obtained from the Building Inspector, Health, Fire or other City Departments. These must be obtained before the work is started. If any additional information is desired, visit or telephone the Housing Supervisor at this Office, telephone 4-1431, extension 226. Kindly notify this office as soon as all corrections have been completed.

Very truly yours,
Edward W. Colby, M.D.
Health Director
By *James E. Whitton*
Housing Supervisor

VIOLATIONS & SPECIFICATIONS

Responsibility of Owner or Agent ** Responsibility of Occupant

#	Violations & Specifications	Responsibility
1	STRUCTURAL REPAIRS Repair or replace the loose, worn, dilapidated and hazardous parts of the structure as follows: a) Repair or replace the loose, worn and hazardous treads on the back hall stairway. b) Repair or replace the loose clapboards. c) Repair or replace the missing lower front half drain pipe. d) Repair or replace the loose & worn out treads on the ceiling stairway. e) Repair or replace the loose, worn out treads on the outside rear porch and stairway. f) Repair or replace the loose, cracked or missing plaster in the bath, toilet and bedrooms of the first floor apartment; the back hall and the kitchen, living room and bedroom of the second floor apartment. g) Putty the loose window panes and tighten the loose window sashes throughout the structure.	##
2	MECHANICAL Repair or replace the defective trap in the kitchen of the first floor apartment. Replace the safety valve on the hot water tank in the second floor apartment.	**
3	ELECTRICAL EQUIPMENT Check and have repaired all defective wiring and electrical equipment throughout the structure. Install convenient outlets in all the rooms where there is a dangerous excessive use of extension cords. Particular attention is directed to the kitchen, bath, toilet and pantry of the first floor apartment and the living room and bedrooms of the second floor apartment.	**

(CONTINUED)

MAINE PRINTING CO., PORTLAND

CITY OF PORTLAND
HEALTH DEPARTMENT
HOUSING DIVISION



Loc.	299 B Wash St.
Bldg	w/i S
Fire	
Elec	
Other	
Issued	August 2, 1957
Expires	September 2, 1957

Dear Sir: On 299 B Wash St. - Continued

an examination was made of the premises located at _____ in accordance with the provisions of the above ordinance, you are hereby ordered to correct these defects according to specifications within the time limits allowed. Failure to comply with this notice will necessitate legal action. Some repairs or improvements required will necessitate permits which are to be obtained from the Building Inspector, Health, Fire or other City Departments. These must be obtained before the work is started. If any additional information is desired, visit or telephone the Housing Supervisor at this Office, telephone 4-1431, extension 226. kindly notify this office as soon as all corrections have been completed.

Very truly yours,
Edward W. Colby, M.D.
Health Director
By Lawrence J. Martin
Housing Supervisor

VIOLATIONS & SPECIFICATIONS

- # Responsibility of Owner or Agent
- ** Responsibility of Occupant

RODENT & INSANITARY CONDITIONS

All the premises of all infestation (rats, mice). If you are unable to do it yourself, we suggest that you procure the services of a pest control operator registered with this Department.

The above mentioned conditions are in violation of the City Ordinance "Minimum Standards for Continued Occupancy" and must be corrected as of before September 2, 1957.

RECEIVED
AUG 5 1957
DEPT. OF BLD'G. INSP.
CITY OF PORTLAND

APARTMENT HOUSE PERMIT APPLICATION FOR PERMIT

Class of Building or Type of Structure Third Class APR 13 1932
Portland, Maine, April 15, 1932

INSPECTOR OF BUILDINGS, PORTLAND, ME.
The undersigned hereby applies for a permit to erect alter install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith the following specifications:

Location 289-301 Brackett Street Ward 415 Within Fire Limits? yes Dist. No. 5
Owner's or Lessee's name and address A. O. Libby Co., 415 Congress Street Telephone 1-0617
Contractor's name and address G. A. Marland & Sons, 10 Edwards Street Telephone 1-0617
Plans filed no No. of sheets 4
No. families 4

Proposed use of building Tenement House Fee \$ 50.
Other buildings on same lot _____
Estimated cost \$ 50.

Description of Present Building to be Altered
Material frame No. stories 2 1/2 Heat steam Style of roof _____ Roofing _____
Last use Tenement No. families 4

General Description of New Work
To rebuild two rear chimneys from attic floor up.

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by the heating contractor.

CLAIM BY NAME OF OCCUPANT
RESPONSE BY OCCUPANT IS WAITED
OR CLOSING-IN IS WAIVED

Details of New Work
Size, front _____ depth _____ No. stories _____ Height average grade to top of plate _____
To be erected on solid or filled land? _____ earth or rock? _____

Material of foundation _____ Thickness, top _____ bottom _____
Material of underpinning _____ Height _____ Thickness _____

Kind of Roof _____ Rise per foot _____ Roof covering _____ of lining none
No. of chimneys 2 Material of chimneys brick Is gas fitting involved? _____

Kind of heat _____ Type of fuel _____ Size _____
Corner posts _____ Sills _____ Girt or ledger board? _____
Material columns under girders _____ Size _____ Max. on centers _____

Studs (outside walls and carrying partitions) 2x4-16" O. C. Girders 6x8 or larger. Bridging in every floor and flat roof
span over 8' feet. Sills and corner posts all one piece in cross section.
Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
Maximum span: 1st floor _____, 2nd _____, 3rd _____, height? _____

If one story building with masonry walls, thickness of walls? _____
No. cars now accommodated on same lot _____, to be accommodated _____
Total number commercial cars to be accommodated _____

Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____
Miscellaneous _____
Will above work require removal or disturbing of any shade tree on a public street? no

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes
Signature of owner E. A. Marland
A. O. Libby Co.

INSPECTION COPY

1630 2/4

Ward _____ Permit No. 38/451

Location 299-301 Brackett St.

Owner A.C. Libby Co.

Date of permit 4/13/38

Notif. closing-in _____

Inspn. closing-in _____

Final Notif. _____

Final Inspn. 4/23/38 C.D.C.

Cert. of Occupancy issued None

NOTES

~~Work O.K. along roof,
could see nothing
inside. A.C.~~



Location, Ownership and detail must be correct, complete and legible.
 Separate application required for every building.
 Plans must be filed with this application.

Application for Permit for Alterations, etc.

To the INSPECTOR OF BUILDINGS: *Portland*, *May 26, 1922* 192

The undersigned applies for a permit to alter the following described building:—
 Location *299 Brackett Street* in fire-limits? *no*
 Name of Owner or Lessee, *A. C. Libby* Address *Masonic Building*
 " Contractor, *Cobb & Webster* " *105 Preble Street*
 " Architect *Cobb & Webster* Ward, *7*
 Description of Present Bldg. Material of Building is *wood* Style of Roof, *pitch* Material of Roofing, *asphalt*
 Size of Building is *60ft.* feet long; *45ft.* feet wide. No. of Stories, *2 1/2*
 Cellar Wall is constructed of *stones* is *45ft.* inches wide on bottom and batters to *2 1/2* inches on top.
 Underpinning is *brick* is *2d,* inches thick; is *3d,* feet in height. *4th,* inches on top.
 Height of Building *30ft.* Wall, if Brick; 1st, *dwelling* 2d, *same* 3d, *same* 4th, *same*
 What was Building last used for? *dwelling* No. of Families? *8*
 What will Building now be used for? *same*

REPORT

PERMIT MUST BE OBTAINED BEFORE BEGINNING WORK

DETAIL OF PROPOSED WORK

*Build dormer window on roof with asphalt shingles
 all to comply with the building ordinance*

IF EXTENDED ON ANY SIDE

Size of Extension, No. of feet long? _____; No. of feet wide? _____; Estimated Cost \$ *250.*
 No. of Stories high? _____; Style of Roof? _____; No. of feet high above sidewalk? _____
 Of what material will the Extension be built? _____; Material of Roofing? _____
 If of Brick, what will be the thickness of External Walls? _____; Foundation? _____
 How will the extension be occupied? _____; How connected with Main Building? _____ inches.

WHEN MOVED, RAISED OR BUILT UPON

No. of Stories in height when Moved, Raised, or Built upon? _____; Proposed Foundations _____
 No. of feet high from level of ground to highest part of Roof to be? _____; Party Walls _____
 How many feet will the External Walls be increased in height? _____

IF ANY PORTION OF THE EXTERNAL OR PARTY WALLS ARE REMOVED

Will an opening be made in the Party or External Walls? _____; How protected? _____ in _____ Story.
 Size of the opening? _____
 How will the remaining portion of the wall be supported? _____

Signature of Owner or Authorized Representative *Cobb & Webster*
 Address *105 Preble St*

CITY OF PORTLAND, MAINE

Application for Permit to Install Wires

Permit No. 58429
 Issued 1/7/70
 1970

Portland, Maine Jan 7

To the City Electrician, Portland, Maine:

The undersigned hereby applies for a permit to install wires for the purpose of conducting electric current, in accordance with the laws of Maine, the Electrical Ordinance of the City of Portland, and the following specifications:

(This form must be completely filled out - Minimum Fee, \$1.00)

Owner's Name and Address Thomas J. Laughlin Tel. _____
 Contractor's Name and Address J. W. Cassidy Tel. _____
 Location 301 Brackett St Use of Building apart
 Number of Families 6 Apartments 6 Stores 3 Number of Stories _____
 Description of Wiring: New Work Additions _____ Alterations _____

Pipe _____ Cable _____ Metal Molding BX Cable _____ Plug Molding (No. of feet) 450
 No. Light Outlets 30 Plugs 15 Light Circuits 4 Plug Circuits _____
 FIXTURES: No. _____ Undergound _____ Floor or Strip Lighting (No. feet) _____
 SERVICE: Pipe _____ Cable _____ Added _____ Total No. Meters _____
 METERS: Relocated _____ Phase _____ H. P. _____ Amps _____ Volts _____ Starter _____
 MOTORS: Number _____ Domestic (Oil) _____ No. Motors _____ Phase _____ H.P. _____
 HEATING UNITS: Commercial (Oil) _____ No. Motors _____ Phase _____ H.P. _____
 Electric Heat (No. of Rooms) _____

APPLIANCES: No. Ranges _____ Watts _____ Brand Feeds (Size and No.) _____
 Elec. Heaters _____ Watts _____
 Miscellaneous _____ Watts _____ Extra Cabinets or Panels _____
 Transformers _____ Air Conditioners (No. Units) _____ Signs (No. Units) _____
 Will commence Dec 1969 Ready to cover in _____ Inspection Jan 7 1970
 Amount of Fee \$ 4.95 Signed James W. Cassidy

DO NOT WRITE BELOW THIS LINE

	METER	GROUND	
SERVICE	1	2	3
VISITS:	4	5	6
	7	8	9
	10	11	12
REMARKS:			

INSPECTED BY J. W. Cassidy
 (OVER)

LOCATION *Brackett St 301*
 INSPECTION DATE *1/27/20*
 WORK COMPLETED *1/27/20*
 TOTAL NO. INSPECTIONS *1*
 REMARKS:

FEEES FOR WIRING PERMITS EFFECTIVE JULY 31, 1968

WIRING		
1 to 30 Outlets		\$ 2.00
31 to 60 Outlets		3.00
Over 60 Outlets, each Outlet05
(Each twelve feet or fraction thereof of fluorescent lighting or any type of plug molding will be classed as one outlet).		
SERVICES		
Single Phase		2.00
Three Phase		4.00
MOTORS		
Not exceeding 50 H.P.		3.00
Over 50 H.P.		4.00
HEATING UNITS		
Domestic (Oil)		2.00
Commercial (Oil)		4.00
Electric Heat (Each Room)75
APPLIANCES		
Ranges, Cooking Tops, Ovens, Water Heaters, Disposals, Built-in Dishwashers, Dryers, and any permanent built-in appliance — each unit		1.50
MISCELLANEOUS		
Temporary Service, Single Phase		1.00
Temporary Service, Three Phase		2.00
Circuses, Carnivals, Fairs, etc.		10.00
Meters, relocate		1.00
Distribution Cabinet or Panel, per unit		1.00
Transformers, per unit		2.00
Air Conditioners, per unit		2.00
Signs, per unit		2.00
ADDITIONS		
5 Outlets, or less		3.00
Over 5 Outlets, Regular Wiring Rates		



APPLICATION FOR PERMIT
DEPARTMENT OF BUILDING INSPECTIONS SERVICES
ELECTRICAL INSTALLATIONS

Date Jan 10 1983
 Receipt and Permit-number A 92526

To the CHIEF ELECTRICAL INSPECTOR, Portland, Maine:

The undersigned hereby applies for a permit to make electrical installations in accordance with the laws of Maine, the Portland Electrical Ordinance, the National Electrical Code and the following specifications:

LOCATION OF WORK: 298 Brackett St.

OWNER'S NAME: Mrs. Dunbar ADDRESS: Lives there

FEES

OUTLETS: A. L.

Receptacles _____ Switches _____ Plugmold _____ ft. TOTAL _____

FIXTURES: (number of)

Incandescent _____ Fluorescent _____ (not strip) TOTAL _____

Strip Fluorescent _____ ft. _____

SERVICES:

Overhead Underground _____ Temporary _____ TOTAL amperes 100 3.00

METERS: (number of) 1 _____ .50

MOTORS: (number of)

Fractional _____

1 HP or over _____

RESIDENTIAL HEATING:

Oil or Gas (number of units) _____

Electric (number of rooms) _____

COMMERCIAL OR INDUSTRIAL HEATING:

Oil or Gas (by a main boiler) _____

Oil or Gas (by separate units) _____

Electric Under 20 kws _____ Over 20 kws _____

APPLIANCES: (number of)

Ranges _____

Cook Tops _____

Wall Ovens _____

Dryers X _____

Fans _____

Water Heaters _____

Disposals _____

Dishwashers _____

Compactors _____

Others (denote) _____

TOTAL _____

1.50

MISCELLANEOUS: (number of)

Branch Panels _____

Transformers _____

Air Conditioners Central Unit _____

Separate Units (windows) _____

Signs 20 sq. ft. and under _____

Over 20 sq. ft. _____

Swimming Pools Above Ground _____

In Ground _____

Fire/Burglar Alarms Residential _____

Commercial _____

Heavy Duty Outlets, 220 Volt (such as welders) 30 amps and under _____

over 30 amps _____

Circus, Fairs, etc. _____

Alterations to wires _____

Repairs after fire _____

Emergency Lights, battery _____

Emergency Generators _____

INSTALLATION FEE DUE: _____

FOR ADDITIONAL WORK NOT ON ORIGINAL PERMIT DOUBLE FEE DUE: _____

FOR REMOVAL OF A "STOP ORDER" (304-16.b) DOUBLE FEE DUE: _____

TOTAL AMOUNT DUE: 5.00

INSPECTION:

Will be ready on 1-12-83, 1983; or Will Call _____

CONTRACTOR'S NAME Bill Cagnon - Seabee Electric

ADDRESS: 58 Victor Rd.

TEL.: 774-4880

MASTER LICENSE NO.: _____

LIMITED LICENSE NO.: 3014

SIGNATURE OF CONTRACTOR: [Signature]

INSPECTOR'S COPY — WHITE

OFFICE COPY — CANARY

CONTRACTOR'S COPY — GREEN

