279-281-283 Prackett Street 5'- F 25

LONGESQ IS

SUANIA SU

CL.BC

### CERTIFICATE OF INSPECTION

DATE August 10, 1982

City of Portland Housing Inspections Division Department of Urban Development Tel: 775-5451 Ext. 311 - 312

Mr. Clifton Roberts 56 Brook Road Falmouth, Maine 04105

Re: Premises located at 279-281-283 Brackett St., Portland, Me. 54-F-43 WE

Dear Mr. Roberts:

An inspection of the above referred premises was recently completed by Code Enforcement Officer  $\underline{\mathsf{Merlin}\ \mathsf{Leary}}$ 

Although the structure does not meet the minimum standards as described in the Housing Code, it has been determined that no  $\underline{\text{major}}$  code deficiencies exist at this time.

Items included on the enclosed list should be corrected as part of your normal maintenance procedures in order to avoid extensive repairs in the future and to prolong the useful life of the building.

Thank you for your cooperation and your efforts to help us maintain decent, safe. and sanitary housing for all Portland residents.

Please do not hesitate to call this office if you have any questions regarding this notice.

Sincerely yours, Joseph E. Gray, Jr., Director of Planning Urban Development

cer - Leary (5)

Enclosure

State and the second

### HOUSING INSPECTION REPORT

OWNER: Mr. Clifton Roberts

CODE ENFORCEMENT OFFICER - Leary (5)

2/9-281-283 Brackett St., Portland, Me. 54-F-43 WE NCHC - 5-26-77 Certificate of Inspection dated August 10, 1982 continued:

THIRD FLOOR BATHROOM - 283 Brackett - lavatory missing.
THIRD FLOOR FRONT - 281 Brackett - missing lavatory, flush toilet and a tub or shower.
THIRD FLOOR FRONT - 283 Brackett - missing lavatory, flush toilet and a tub or shower.
BATHROOM - missing lavatory, flush toilet and a tub or shower.

# ADMINISTRATIVE HEARING DECISION

City of Portla Department of Housing Inspe Telephone: 7	Neighborhood Conservation Neighborhood Conservation Ctions Division 75-5451 - Ext. 448 358
Wr. Clifton Ro 56 Brook Road Falmouth, Mai	
Dear Mr. Ro	berts:  eby notified that a reinspection and your request for additional time
referred p	remises resulted in the decision noted below.  piration time extended to 12/28/79 in order to complete the work in progress of correct the remaining five (5) Housing Code Violations as shown on attached ist.  Southern modified as follows
please r dates, In Atte	notify this office if all violations are corrected before the above mentioned notify this office if all violations are corrected before the above mentioned so that a "Certificate of Compliance" may be issued.  Very truly yours, Joseph E. Gray, Jr., Director Neighborhood Conservation  berts. Owner  Lyle L. Nayes,
<u> </u>	Lyle 1. Noyes,  Chief of Housing Inspections

dld

,

درس

279-281-283 Brackett Street, Fortland, Maine NCP-WE 54-F-43
Remaining Housing Code Violations to be corrected within time extension granted on attached "Administrative Hearing Decision":

- 1. THIRD FLOOR BATHROOM 283 Brackett install lavatory at the 3rd floor bathroom at 283 Brackett Street.
- 281 Brackett THIRD FLOOR FRONT

  PATHROOM install a private 3 piece bathroom consisting of a lavatory, flush toilet and a tub or shower.

3. BRACKETT - THIRD FLOOR REAR

3. BATHROOM install a private 3 piace buthroom constating of a layersky, Flush tollet

4. BATHROOM - install a private 3 piece bathroom consisting of a lavatory, flush toilet and a tub or shower.

5. BATHROOM - install a private 3 piece bakhroom consisting of a lavatory, flush toilet and a tub or shower for this dwelling unit.

REINSPECTION RECUMMENDATIONS LOCATION 229 PROJECT 10 INSPECTUR NOTICE OF HOUSING CONDITIONS HEARING NUTICE housei Expired FINAL NUTICE Expired Expired 5-26-27 A relpspection was made of the above premises and I recommend the following action: ALL VIOLATIONS HAVE BEEN CORRECTED COTAL Send " CERTIFICATE OF COMPLIANCE" P.617 SATISFACTORY Rehabilitation in Progress 3-12-16 1119 Time Extended To Time Extended To Time Extended To UNSATISFACTURY Progress Send "HEARING NOTICE" "FINAL NOTICE" "NOTICE TO VACATE" POST Entire PUST Dwelling Units UNSATISFACTORY Progress Request "LEGAL ACTION" Be Taken 7-30-50 777 F 6-8.2 14. INSTRUCTIONS TO INSPECTOR:

i yangi

翸

CBBS - FIR

#### NOTICE OF HOUSING CONDITIONS

CITY OF PORTLAND, MAINE

Department of Planning & Urban Development Inspection Services Division Tel. 775-5451 - Ext. 311 - 346

James W. Bell c/o Hogan Company P. O. 8054 Portland, ME 04104 DU 12 Legal - Found 14

CH. 54 BLK. F LOT 43

LOCATION.279-281-283 Brackett

PROJECT: District 5 ISSUED: April 14, 1987 EXPIRES: June 14, 1987

Dear' Mr. Bell:

You are hereby notified, as owner or agent, that an inspection was made of the premises at <a href="https://example.com/279-281-283">279-281-283</a> Brackett Street by Code Enforcement Officer Merlin Leary Violations of Article V of the Municipal Ordinance (Housing Code) were found as described in detail on the attached "Housing Inspection Report".

In accordance with the provisions of the above-mentioned Code, you are hereby ordered to correct those defects on or before \_\_\_\_June 14, 1987 \_\_\_. If you are unable to make such repairs within the specified time, you may contact this office to arrange a satisfactory repair schedule. If we do not hear from you within ten (10) days from this date, we will assume the repairs to be in progress and, on re-inspection within the time set forth above, will anticipate that the premises have been brought into compliance with the Housing Code Standards.

Please Note: You should consult the inspection Services Division to insure that any corrective action you undertake complies with the building, plumbing, electrical, zoning and any other Article of the City Code.

Please contact this office if you have any questions regarding this order.

Your cooperation will aid this department in it's goal to maintain decent, safe, and sanitary housing for all of Portland's residents.

Very truly yours,

Joseph E. Gray, Jr., Director Planning & Urban Development

r. Samuel Hoffshir Chief of Inspection Services

Melli Leau

Code Enforcement Officer - Merlin Leary (5)

Attachments

im

jmr

## HOUSING INSPECTION REPORT

OWNER: James W. Bell

LOCATION: 279-281-283 Brackett Street

54-F-43

CODE ENFORCEMENT OFFICER: Merlin Leary (5)

HOUSING COMDITIONS DATED: April 14, 1987

EXPIRES: June 14, 1987

ITEMS LISTED BELOW ARE IN VIOLATION OF ANTICLE V OF THE MUNICIPAL CODES, "HOUSING CODE", AND MUST BE CORRECTED ON OR BEFORE THE EXPIRATION DATE.

		SEC.(S)
1.	INTERIOR FIRST FLOOR, APT. #1 - RIGHT REAR BEDROOM - window - missing	
	counterpalance cords.	108-3
2.	INTEPIOR FIRST FLOOR, APT. #1 - RIGHT REAR BEDROOM - ceiting - missing	100 5
	tiles.	108-3
<b>*</b> 3.	INTERIOR FIRST FLOOR, AFT. #1 - LEFT REAR BEDROOM - ceiling - buckled.	108-3
* 4.	EXTERIOR FIRST FLOOR, APT. #1 - RIGHT REAR - door - broken glass	108-3
<b>*</b> 5.	INTERIOR FIRST FLOOR, APT. #1 - LIVING ROOM & BEDROOM - illegal wiring	
_	(extension cords).	113-5
6.	The state of the s	
<i>*</i> 7.	fixture.	113-5
8.	THE THE PARTY OF THE PROPERTY	111
9.	THE THE PARTY OF THE TAXABLE PROPERTY.	25 MRSA
۶.	INTERIOR SECOND FLOOR, APT. # - KITCHEN - window - missing counter-	
10.	balance cord.	108-3
11.	INTERIOR THIRD FICOR, APT. #12 - HATHROOM - missing toilet and sink.	111-1
	window - missing counterparance.	108-3
12.	INTERIOR THIRD FLOOR, APT. #18 - KITCHEN - window - loose sash.	108-3
*13.	INTERIOR THIPD FLOOR, APT. #18 & #19 - BATTEROOM IN HALL - sharing	
3.4	facilities.	111-1
14.	The strong stron	108-2
	CELLAR - asbestos.	116-6
*16.	CELLAR - loose and hanging wires.	113-5

\*WHEN MAKING YOUR REPAIRS, FIRST PRIORITY IS TO BE GIVEN TO ITEMS WITH ASTERISKS, AS THEY CONSTITUTE EXTREME HAZARDS TO THE HEALTH OR SAFETY OF THE OCCUPANTS OF THIS STRUCTURE.



JOSEPH E MODONOUGH

April 14, 1987

James W. Bell c/o Hogan Company P. O. 8054 Portland, ME 04104

Re: Smoke Detectors

Dear Mr. Bell:

During a recent inspection of the property owned by you at 279-281-283 Brackett St., it was noted that smoke detectors were missing in the following areas:

INTERIOR - SECOND FLOOR, APT. #4 - missing.

25 MRGA \$246 requires that approved smoke detectors be installed in each of the above listed areas. Failure to comply with this statute may result in a fine of up to \$500 for each violation.

Perinspection of your property will be made in ten (10) days. Lack of compliance it result in reserval of the matter for legal action.

Sincerely yours, Joseph E. McDonough Chief of the Fire Department City of Portland

Merlin Leary Code Enforcement Officer (5)

cc: Lt. James Collins, Fire Prevention Bureau

jmr

109 MIDDLE STREET . PORTLAND MAINE 04101 . TELEPHONE (207) 775-6361



JOSEPH & GRAY, JR DIRECTO' OF PLANNING AND URBAN DEVELOPMENT

April 14, 1987

James W. Bell c/o Hogan Company P. O. 8054 Portland, ME 04104

Re: 279-281-283 Brackett Street 54-F-43

Dear Sir:

A recent inspection was made by Code Enforcement Officer Merlin Leary
of the property owned by you at 279-281-283 Brackett St., Portland, Maine. As a
result of the inspection, you are ordered to correct the following conditions
that exist: Unlawful Change of Use

103.2 Change in use: It shall be unlawful to make any change in the use or occupancy of any structure or portion thereof which would subject it to any special provisions of this code without approval of the building official, and the building official's certification that such structure meets the intent of the provisions of law governing building construction for the proposed new use and occupancy, and that such change does not result in any greater hazard to public safety or welfare.

The above mentioned conditions are in violation of Section 103.2 of the 1984 BOCA Building Code, and must be corrected on or before May 9, 1987

Failure to comply with this order will result in a complaint being filed for prosecution in District Court.

Please contact this office if you have any questions regarding this notice.

Chief of Inspection Services

Enforcement Officer - Merlin Leary (5)

PSH/ jmr

# CITY OF PORTLAND INSPECTION STRVICES DIVISION - HOUSING INSPECTION SCHEDULE

Insp. Date	:_4_	9-F)	Compl	aint	5 year Fire Inspector	s Name M Leary	0ist
Property A	ddress:	279-	281-	ZF3	Breckett C-B-L: 54-	F-43 Legal Units://2 Exist. Units:///S	tories:3
Owner or A	gent 7	James togen	WBe	0.08	054 Portland 04	Stand. 1st: N.O.H.C. L	.O.D.
Violation No.	Ext.	Int.	F1.	Apt.	LOCATION	VIOLATION DESCRIPTION	CODE
	_ DAC!	X	1	#/	Right war bedroom White		10F-3
2		X	/	#/	Right ween bedroom ceiling	11	10f-3
¥-7		X	/	#/	Left war hedrown	Buckled Ceiline	108-2
£4	У		/	#/	Right tran Door	Broken Giess	10F-3
* 5		X	1	#/	Ziving room & Bodio		1/3-5
6		X	. /	#/	Living toom ceiling	Missing light fixture	113-5
* 7		X	1	#/	Bathroom Toilet	Backing Un.	101
P		X	2	#4	Aprit m + 1 +	Missing Detector	MRSA
9		\(\forall \)	2	#	Kitchen Windon	Missing Constrabalised	101-3
18	,	1/2	3	#12	Horrings , '	Missing Toiletty Sink	111-1
1/		Ϋ́	3	#18	KitchenWinden	Hissing Counter balane	10F-3
12		\ \ X	3	#18	Kitchen Windon.	Genso Sor &	105-3
* 13		Ý	3	产,79	Rathroom in Hell	Sharing Pakilities	111-1
14		X	• 1	\$74	ShowerStell	Teeling Print	105-7
713		- (	<u> </u>		Cellar:	Aspestes	116-6
#16			ź	7	Celter	Loosed Herry & Wires	113-5
							Later Carlot and Later to

- A DESCRIPTION OF THE PARTY OF

28	SENDER: Complete item	
PS Form 381 July 1986	Put your address in the "RE" reverse side. Failure to do this being returned to you. The revous the name of the purson of the pu	will prevent this card from turn receipt fee will provide silvered to and the date of the following services are
988 7.47-	1. [] Show to whom, data a	nd address of delivery.
<b>747-845</b>	2. C nestricted Delivers	
5	3. Article Aduressed to:	
١	Hogan Co.	
1	P.O. Box 8054	
İ	Fortland, ME 04	LUA
f	4. Type of Service:	Article Number
	☐ Fiegistered ☐ Inrured ☐ CGD ☐ Exp.ress Mail	224 191
	Always obtain signature of ec DATE DELIVERED.	dressed or agent und
إير	5. Signature - Addressee	· · · · · · · · · · · · · · · · · · ·
; -	× //	
	6. Signe ore Agent	<u></u>
-	Garage Salivery	Q MAN 3
DOMESTIC RETURN RECEIPT	E. Addressea'c c + (ONL	Y IS reclusived and the paid in



DEPARTMENT OF PLANNING & URBAN DEVELOPMENT INSPECTION SERVICES DIVISION

May 8, 1987

Hogan Company P. O. Box 8054 Portland, ME 04104

Re: 279 Brackett Street

Dear Sir:

We recently received a complaint and an inspection was made by Code Enforcement
Officer Merlin Leary of the property owned by you at 279 Brackett Street'
Portland, Maine. As a result of the inspection, you are hereby ordered to correct the following substandard housing conditions:

\* 1. RIGHT REAR - porch - broken treads. 108-4 \* 2. RIGHT REAR - porch - missing. 108-4

Failure to comply with this order may result in a complaint being filed for prosecut. on in District Court.

Sincerely yours, Joseph E. Gray, Jr., Director of Planning & Urban Development

Chief of Inspection Services

Officer - Merlin Leary (5)

the market

Appropriate the Reading of the Daniel P 032 224 377 RECEIPT FOR CERTIFIED MAIL NO INSURANCE COVERAGE PROVIDE NOT FOR INTERNATIONAL MAIL (See Reverse) Sent to

James Bell
Street and No
306 Congress St.
P.O., State and ZIP Code
Portland, MF. 04
Postage Certified Fee Special Delivery Fee 3 **Fastricted Delivery Fee** Leary Housing



THEMPOLIEVED MARRY & DMINNALS TO THEMPSE INSPECTION SERVICES DIVISION

September 14, 1987

Mr. James Bell 306 Congress Street Portland, ME 04101

Re: 279 Brackett Street, Apt. #3

Dear Mr. Bell:

We recently received a complaint and an inspection was made by Code Enforcement Officer <u>Merlin Leary</u> of the property owned by you at <u>279 Brackett St., Apt. #3</u>, Portland, Maine. As a result of the inspection, you are hereby ordered to correct the following substandard housing conditions:

- REAR PORCH wall missing light fixture. 1'3-5
  BATHROOM toilet backing up. 111-4
  KITCHEN & LIVING ROOM floors holes. 108-2

The above mentioned conditions are in violation of A-ticle V of the Municipal Code of the City of Portland, Maine, and must be corrected on or before September 15, 1987 for item #2, October 14, 1987 for items #1 & #3.

Failure to comply with this order may result in a complaint being filed for prosecution in District Court.

Sincerely yours, Joseph E. Gray, Jr., Director of

Chief of Inspection Services

imr

389 CONGRESS STREET . PORTLAND MAINE 04101 . TELEPHONE (207) 775-5451

Sept 9 1417



JOSEPH E. McDONOUGH FIRE CHIEF

April 14, 1987

James W. Bell c/o\_Hegan Company P. O. 8054 Portland, ME 04104

Re: Smoke Detectors

Dear Mr. Bell:



During a recent inspection of the property owned by you at 279-281-283 Brackett St., it was noted that smoke detectors were missing in the following areas:

INTERIOR - SECOND FLOOR, APT. #4 - missing.

25 MRSA §2464 requires that approved smoke detectors be installed in each of the above listed areas. Failure to comply with this statute may result in a fine of up to \$500 for each violation.

Re-inspection of your property will be made in ten (10) days. Lack of compliance will result in referral of the matter for legal action.

Sincerely yours, Joseph E. McDonough Chief of the Fire Department City of Portland

Merlin Leary , Code Enforcement Officer (5)

cc: Lt. James Collins, Fire Prevention Bureau

jnx

109 MIDDLE STREET . PORTLAND, MAINE 04101 . TELEPHONE (207) 775-6361



DEPARTMENT OF PLANNING & URBAN DEVELOPMENT INSPECTION SERVICES DIVISION

January 7, 1988

Mr. James Bell 306 Congress Street Portland, ME 04101

Re: 279 Brackett Street

Dear Mr. Bell:

We recently received a complaint and an inspection was made by Code
Enforcement Officer Merlin Leary of the property owned by you
at 279 Brackett Street, Portland, Maine. As a result of the
inspection, you are hereby ordered to correct the following substandard
housing conditions:

\* 1. INTERIOR 3RD. FL., APT. #12 - left rear window - broken glass. 108-3
\* 2. INTERIOR 3RD. FL., AFT. #12 - kitchen sink - leaking hot atter faucet. 111-3

The above mentioned conditions are in violation of  $Article\ V$  of the Municipal Code of the City of Portland, Maine, and must be corrected on or before February 7, 1987

Failure to comply with this order may result in a complaint being filed for prosecution in District Court.

Sincerely yours, Joseph E. Gray, Jr., Director of Planning & Urban Development

Code Enforcement Officer (5)

389 CONGRESS STREET . PORTLAND MAINE 04101 . TELEPHONE -207) 775-5451

# CITY OF PORTLAND INSPECTION SERVICES DIVISION - HOUSING INSPECTION SCHEDULE

Insp. Date	: <u>12</u>	31-17	Compl	aint_/	5 year	_FireInspec	tor's Name	Lezy	Dist.
Property A	Address	279	Bi	م مرار د	HS+	C-B-1,:	Leg	al Units:Exist. Unit	s: <u>/3</u> Stories:
		Mr J.	- 	5 B	Port by	I, m	S	tand. lst:N.O.H.C.	L.O.D.
Violation No.	Ext.	I .	F1.	Apt.	LOCATION		VIOLATION DE	SCRIPTION	CODE
12		X	3	12	Kızıchi	Window	Lezku	Glass , fe hot water fe	108-3
							,		
									र्ग है जूर्य कर्म है जूर्य कर्म है
									<u> </u>
	1			37.78		dopatories en e			

Cm.F.



## CITY OF PORTLAND

DEPARTMENT OF PLANNING & URBAN DEVELOPMENT INSPECTION SERVICES DIVISION

January 7, 1988

Mr. James Bell 306 Congress Street Portland, ME 04101

Re: 279 Brackett Street

Dear Mr. Bell:

We recently received a complaint and an inspection was made by Code

Enforcement Officer Merlin Leary of the property owned by you at 279 Brackett Street, Portland, Maine. As a result of the at 279 Brackett Street , Portland, Maine. As a result of inspection, you are hereby ordered to correct the following ubstandard housing conditions:

\*-1. INTERIOR 3RD FI., APT. #12 - left rear window -- broken glass -- 108-3 -- \* 2. INTERIOR-3RD FI., APT. #12 - kitchen-sink -- leaking-hot-water-faucet.

The above mentioned condition. re in violation of Article V of the Municipal Code of the City of cortland, Maine, and must be corrected on or before February 7, 1987

Failure to comply with this order may result in a complaint being filed for prosecution in District Court.

> Sincerely yours, Joseph E. Gray, Jr., Director of Planning & Urban Development

Merlin Leary Code Enforcement Officer (5)

389 CONGRESS STREET . PORTLAND MAINE 04101 . TELEPHONE -2071 775-5451



DEPARTMENT OF PLANNING & URBAN DEVELOPMENT INSPECTION SERVICES DIVISION

December 19, 1988

Bell Properties 306 Congress Street Fortland, ME 04101



Re: 279 Brackett Street, Apt. #6

Dear Sir:

TO THE PARTY OF

We recently received a complaint and an inspection was made by Code Enforcement Officer Merlin Leary of the property owned by you at 270 Brackett St., Apt. #6, Portland, Maine. As a result of the inspection, you are hereby ordered to correct the following substandard bounded conditions:

- 1. Missing-counterbalance cords in the bedroom-window. 108-3
  2. Missing tiles in the living-room-and the bedroom ceilings. 108-2
  3. Missing battery in the smoke detector. 25-MFSA 2464.

4. Missing switch-cover-on-the living room wall. 113-5

Failure to comply with this order may result in a complaint being filed for prosecution in District Court.

Sincerely yours, Joseph E. Gray, Jr., Director of Planning & Urban Development

Merlin Leary (5)
Code Enforcement Office

inspection services



DEPARTMENT OF PLANNING & URBAN DEVELOPMENT INSPECTION SERVICES DIVISION

December 14, 1989

c -- F.

James Bell Branden Group 306 Congress Street Portland, ME 04101

Re: 279 Brackett Street - 54-F-43

Dear Sir:

We recently received a complaint and an inspection was made by Code

Enforcement Officer Marland Wing of the property owned by you at 279 Brackett Street Portland, Maine. As a result of the inspection, you are hereby ordered to correct the following substandard housing conditions:

- Bedroom closet ceiling missing plaster. 108-2 Bedroom wall missing switch plate. 113

- Kitchen cockroaches.
  Living Room w ndow broken glass. 108-3
  Cellar enclose oil line, cellar floor. 114-2
  Hall walls missing switch covers. 113
  Hall 2nd. Floor loose switch. 113

The above mentioned conditions are in violation of Article  $\boldsymbol{V}$  of the Municipal Code of the City of Portland, Maine, and must be corrected on or before January 14, 1990

Failure to comply with this order may result in a complaint being filed for prosecution in District Court.

Sincerely yours, Joseph E. Gray, Jr., Director of Planning & Urban Development

389 CONGRESS STREET • PORTLAND, MAINE 04101 • TELEPHONE (207) 874-8300

為

Browlow Group

279 Brackett St.

1. Missing plaster Bedivon Noset ceiling 188-2

2. Missing Switch plate. Bedivon Wall post 113

3, Cockrouches in Kitchen

4. Broken I lass living voor

5. Enclose oil line cellar Floor 114-2



DEPARTMENT OF PLANNING & URBAN DEVELOPMENT
INSPECTION SERVICES DIVISION
December 5, 1989

James Jell c/O Brenden Group 306 Congress Street Portland, Maine 04101

Re: 279 Brackett St. Apt. #4
54-F-43

Dear :ir:

white with a state of the state

We recently received a complaint and an inspection was made by Code
Enforcement Officer <u>Merlin Leary</u> of the property owned by you
at <u>279 Brackett St. Apt. #4</u>, Portland, Maine. As a result of the
inspection, you are hereby ordered to correct the following substandard
housing conditions:

Missing storm in the bedroom window.

Hanging light fixture on the kitchen ceiling

113-5

Failure to comply with this order may result in a complaint being filed for prosecution in District Court.

Sincerely yours, Joseph E. Gray, Jr., Director of Planning & Urban Development

Chief of Inspection Services

Merlin Leary, Code Enforcement Officer

### CITY OF PORTLAND, MAINE



389 CONGRESS STREET PORTLAND, MAINE 04101 (207) 874-8300

DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

P. SAMUEL HOFFSES, CHIEF INSPECTION SERVICES DIVISION

May 17, 1990

R.M.S. Property Management 75 Market Street Portland, ME 04101

Re: 279-283 Brackett St.

Dear Sir:

We recently recieved a complaint and an inspection was made by Code Enforcement Officer Marland Wing of the property owned by you at 279-283 Brackett Street, Portland, Maine. As a result of the inspection, you are hereby to correct the following substandard housing conditions: ,Portland,

- Missing hand rails front exterior stairs. 108-4 Exposed oil line cellar floor. 1.4-2

- 1. Missing hand rails front exterior stairs. 108-4
  2. Exposed oil line cellar floor. 1 4-2
  3. Trash & debris in cellar. 109-4
  4. Loose and exposed wiring overall cellar. 113
  5. Missing switch cove s front hall walls. 113
  6. Loose hand rail left fron hall stairs. 108-4
  7. Loose plaster 2nd. Floor Front hall ceiling. 108-2
  8. Worn stair treads front hall stairs. 108-4
  9. Broken doors leading to grantments. 108-3
  10. Cockroaches throughout building. 109-5 (See

The above mentioned conditions are in violation of Article V of the Municipal Code of the City of Portland, Maine, and must be corrected on or before \_\_June 17, 1990.

Failure to comply with this order may result in a complaint being filed for prosecution in District Court.

Sincerely,

Chief of Inspection Serv.

Marland Wing,

Code Enforcement Officer (5)

imr

A COMMENT OF STREET

#### HOUSING INSPECTION REPORT

OWNER: R.M.S. Property Management

LOCATION: 279-283 Brackett St. 54-F-43

CODE ENFORCEMENT OFFICER: Marland Wing (5)

HOUSING CONDITIONS DATED: May 17, 1990

EXPIRES: June 17, 1990

I FEMS LISTED BFLOW ARE IN VIOLATION OF ARTICLE V OF THE MUNICIPAL CODES, "HOUSING CODE", AND MUST BE CORRECTED ON OF BEFORE THE EXPIRATION DATE.

SEC.(S)

Continued From Page #1:

Leaking faucet - bathroom tub -- 2nd. Floor Left Apt.
 Loose toilet seat - 2nd. Floor Left Apt.

111-3

111-3

and another similar side .

## CITY OF PORTLAND, MAINE



389 CONGRESS STREET PORTLAND, MAINE 04101 (207)874-8300

DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

P. SAMUEL HOFFSES, CHIEF INSPECTION SERVICES DIVISION

June 11, 1990

R.S.M. Property Management 75 Market Street Portland, ME 04101

Re: 279-283 Brackett Street 54-F-43

Dear Sir:

We recently recieved a complaint and an inspection was made by Code

Enforcement Officer Marland Wing of the
property owned by you at 279-283 Brackett Street Portland,
Maine. As a result of the inspection, you are hereby to correct the
following substandard housing conditions:

- No. smoke detector, Apt. #2 1sc. Floor Rear.
   Friable asbestos in cellar.

Failure to comply with this order may result in a complaint being filed for prosecution in District Court.

Marland Wing (5)

Sincerely,

Chief of Inspection Serv.

.... was ended the



### CITY OF PORTLAND, MAINE

389 CONGRESS STREET PORTLAND, MAINE 04101 (207) 775-5451

**DEPARTMENT OF PLANNING & URBAN DEVELOPMENT** 

P. SAMUEL HOFFSES, CHIEF INSPECTION SERVICES DIVISION

Date: June 11, 1990

R.S.M. Property Management 75 Market Street Purtland, ME 04101

Re: Smoke Detectors

Dear Sir:

During a recent inspection of the property owned by you at 279-283 Brackett St., Portland, ME, , it was noted that smoke detectors were missing/inoperable in some locations.

25 MRSA 2464 requires that approved smoke detectors be installed in each apartment in the immediate vicinity of the bedroom. When actuated, the detector shall provide an alarm suitable to warn the occupants within the individual unit. Failure to comply with this statute may result in a fine of up to \$500 for each violation.

Re-inspection of your property will be made in ten (24) hrs.. Lack of compliance will result in referral of the matter-for legal action.

Loss control is a responsibility of your management. Our observations are intended to assist you. Recommendations are a result of conditions observed at the time of our visits. They do not necessarily include every possible loss potential code violation, or exception to good practice.

Sincerely yours,

Chief of Inspection Services

Marland Wing (5) Code Enforcement Officer

cc: Lt. James P. Collins, Fire Prevention Bureau

Letter of Defects R.S.A. Posperty Management 175 Market St Bot Hand, Me 24101 LOC: 279-283 Brackett St. Coday & Ho smike detector in Art.

He 2 lot Floor Rear

30 days 2. Fijoble as bestos in cellar. material and the second and the second

dress 29283 BEFARELE St.						INSPECTION SERVICES DIVISION													
						Owner's Ad 27 W1	idress in R <b>d</b>	Fal	mout	ı, 1:	E	0410	)5						
		MERS DE	CKEELS	· ·					LOT NO	D.	NC	. UNITS		1			1		
er	v	en Ray												DIST.					
TYP		DATE	iNS	P. NO		T		ART INSP	STOP INSP.		TAL TIM			3					
32		12-2-91		l		$\perp$	9	:15	9:25		41200		L						
_		<u></u>						541	- F-4	3									1 4
				Т		Γ-		UILAPIDATED B		×					ITEM				61
-+		ONTAINERS		$\vdash$		١.	-	LUMBER, STOC				X			SAN.	NO. PONSIB	III ITV		۲
-		AINER COVERED		+-1		12		PI UMBING AND	SEWAGE					-	<del></del>	VNER	,,,,,,		7
-		SE CONTAINED		Ä		3	_	WEEDS				$\vdash$				NANT			L
	OUT T	OO EARLY LATE		1-		ENV. HAZARD	<u> </u>	RODENT PROC	ring				- 1						╀
	JUNK			+-		Z	-	TXTERIOR				X	ļ	<u></u>	<del> </del>				┾
		APPLIANCES		X			-	INTERIOR						┸-				CORRE	
	-	RUBBLE						VIOL	ATIONS									BY	
EM O.																			
	_				.+10	n	of	the above	property	reves	iled a	n ex	ces	3716	<u>-</u>				
		A rec	cont 10	aher								1.1.	* h ***		hour				
		accui	nulatio	B 0	£ tr	.98	h,	debris, a	nd miscel	Laneou	is ru	ore	CHE						
	-	the	side un	d r	ear	ye	rde												
							• at	traction/	harborage	and	16 a	viol	atio	u o	ft	16			
_	$\perp$																	1	
								City of Po										12-1	3-
		This	debri	e mi	ıst	be	re	moved with	nin 10 day	99.								+	
	-																		
						_												1	
																		-	
	l																	1	
-																			
																		1	
	}								<u> </u>									1	
	i																	+	
_																			
																		1	
								·····											
																		1	
	. –	1																	
_		<del> </del>										*							
		-																	

INSPECTOR OWNER

Inspection Services Samuel P. Hoffses Chief

Planning and Urban Development Joseph E. Gray Jr. Director

June 4, 1991

CITY OF PORTLAND

Ken Ray 14 Edef Rd Cumberland, Maine 04021

> Re: 279 Brackett St. Apt. #3 54-F-43

Dear Sir:

We recently received a complaint and an inspection was made by Code Enforcement Officer Marland Wing of the property owned by you at 279 Brackett St. Portland, ME, Portland, Maine. As a result of the inspection, you are hereby ordered to correct the following substandard housing conditions:

Holes in kitchen floor

108-2

Rid the premises of mice and cockroaches

109-5

The above mentioned conditions are in violation of Article V of the Municipal Code of the City of Portland, Maine, and must be corrected on or before July 4, 1991

Failure to comply with this order may result in a complaint being filed for prosecution in District Court.

Sincerely yours, Joseph E. Gray, Director of Planning &

Chief of Inspection Services

Code Enforcement Officer - Merland Wing

389 Congress Street · Portland, Maine 04101 · (207) 874-8704



Planning and Urban Development Joseph E. Gray Jr. Director

# CITY OF PORTLAND

February 3, 1992

Inspection Services Samuel P. Hoffses

Chief

Ken Ray 14 Edes Rd Cumberland, ME 04021

Re: 279 Brackett St/Apt #3 CBL #: 054-F-043 : טם

A re-inspection of the premises noted above was made on January 15, 1992, by Code Enforcement Officer Kathleen Lowe.

This is to verify that you have complied with our request to correct the violation(s) of the Municipal Code relating to housing conditions as described in our "Letter of Defects" dated June 4, 1991.

Thank you for your cooperation and your efforts to help us maintain decent, safe and sanitary housing for all Portland residents.


In order to aid in the preservation of Portland's existing housing inventory, it shall be the policy of this department to interpret to each resident building at least once every five years, although a property is subject to re-inspection at any time during the said five-year period.

Sincerely,

Kathleen Lowe Code Enforcement Officer Chief of Inspection

289 Congress Street · Portland, Maine 04101 · (207) 874-8704

LOD-Substnd. Hsg. Conds.





Planning and Urba'ı Development Joseph E. Gray Jr. Director

### CITY OF PORTLAND

July 30, 1992

Kenneth Ray 27 Winn Rd. Falmouth, ME 04105

re: 279-281 Brackett St. CBL #: 54-F-43 D U: 12

Dear Mr. Ray:

We recently received a complaint, and an inspection was made by Code Enforcement Officer Kathy Lowe of the property owned by you at 279-281 Brackett Portland, Maine. As a result of the inspection, you are hereby requested to correct the following substandard housing conditions:

Apt.3 Bathroom #1 leaking plumbing (to be corrected by 8/10/92) damaged floor no ventilation Apt.3 Bathrrom #1 Apt.3 Bathroom #1 4.. Apt.3 Bathroom #2 no ventilation Apt.3 Bathroom #2 damaged floor Apt.3 Bathroom #2 remove carpeting

The above-mentioned conditions are in violation of Article V or the Municipal Code of the City of Portland, Maine; and must be corrected on or before 8/31/92. Failure to comply with this order may result in a complaint being filed for prosecution in District Court.

Sincerely,

Kathleen Lowe Code Enforcement Officer

Chief Inspection Services

389 Congress Street · Portland, Maine 04101 · (207) 874-8704

<b>5</b>		
	P 032 224 902	æ:
	NO INSURANCE COVERAGE PROVICED NOT FOR INTERNATIONAL MAIL (See Reverse)	27º Brackett
984-446-01	ont to Mr James Pell Side Congress St. Po State and JPP Code 04101	ett St.
S.0.P.O.	Postage \$	
*	Certified Fee Special Delivery Fee	Leary
	Restricted Delivery Fee	1 '
1	Return receipt showing to whom and Date Delivered  Return receipt snowing to whom,	Housing
1 6	Return receipt snowing to whom Date, and Address of Delivery  TOTAL Postage and Fees	•
,	Return receipt services of Delivery Date, and Address of Delivery TOTAL Postage and Fees Postmark or Date	
ę l	₽\	1

٠, • ﴿		- <b>,</b> '*
SENDER: Complete items Pur your audress in the "RETL reverse slidt. Failure to do this being returned to 5-10. The ren you ther you of the person to delivery, for wider, nat legs th available. Commit pratmenter if for carrictels) inquested.	JAN TO" space on the will prevent this card from urn receipt foe will provide allowed to and the dote of the following services are	279 Bracket
1. [] Show to whom, date an 2. [] Postricted Delivery.	id address of delivery.	St
3. Article Addressed to: Mr. James Bell 30% Congress St. Portland, FE 041	స్త <sup>స</sup> 101	M. Leary
4. Type of Service:  ☐ Registered ☐ traumed ☐ Contified ☐ COD	Article Number	- Housing
Always obtale Sontiture of at DATE DELIVERED.  5. Dignature - Accordances	diessay or agent and	
Ponto of Calman		
B: Addresses () by dress ()	भागे प्रजास कवा का प्रवास स्थान	
The state of the s	<b>《大学》</b>	

- 11.11



## CITY OF PORTLAND

DEPARTMENT OF PLANNING & URBAN DEVELOPMENT INSPECTION SERVICES DIVISION

July 19, 1988

Mr. James Bell 306 Congress Street Portland, ME 04101

Re: 279 Brackett Street

Dear Mr. Bell:

We recencly received a complaint and an inspection was made by Code
Enforcement Officer Merlin Leary of the property owned b,
at 279 Brackett Street , Portland, Maine. As a result of
inspection, you are hereby ordered to correct the following substandard
Yousing conditions:

1. Lack of hot water. 111-3

Failure ro comply with this order may result in a complaint being filed for prosecution in District Court.

Sincerely yours, Joseph E. Gray, Jr., Direct Planning & Urban Development

P. Samuel 1997 Services

Merlin Leary - Code Enforcement Offices (5)

imr

189 CONGRESS STREET . . . PORT AND MAIN F. 1905 . .

7-18-16 Ne 209 Brockett 1

e J.H



## CITY OF PORTLAND

DEPARTMENT OF PLANNING & U BAN DEVELOPMENT INSPECTION SERVICES DIVISION

JK MA

July 19, 1988

Mr. James Bell 306 Congress Street Portland, ME 04101

Re: 279 Brackett Street

Dear Mr. Bell:

We recently received a complaint and an inspection was made by Code

Enforcement Officer Merlin Leary of the property owned by you at 279 Brackett Street , Portland, Maine. As a result of the inspection, you are hereby ordered to correct the following substandard housing conditions:

1. Lack of hot Water. 111-3



Failure to comply with this order may result in a complaint being filed for prosecution in District Cour $\ .$ 

Sincerely yours, Joseph E. Gray, Jr., Director of Planning & Urban Development

P Samuel distincts
Chief of Laspection Services

Merlin Leary - Code Enforcement Officer (5)

389 CONGRESS STREET . PORTLAND MAINE 14101 . TELEPHING DATABLE . .

. es .es .es Sellier

**是一門** 

, RE	CEIPT	FOR IRANCE (	CERTIF COVERAGE RNATION Reverse	PROVIDE AL MAIL	AIL D	Pe: 279 Brackett
* US.G.P.O. 1984-48-01	set and 106 CO. Sta. PORT pstage ertified special Restrict to who	Fee Delivery Receipt m _nd D receipt and Add	Fee  ME  Fee  Showing ata Deliveration of Deli	livery	\$	cett St., Apt. #6 M. Leary - Lousing



## CITY OF PORTLAND

DEPARTMENT OF PLANNING & URBAN DEVELOPMENT INSPECTION SERVICES DIVISION

September 6, 1988

Bell Properties 306 congress Street Portland, Maine 04101

Re: 279 Brackett Street, Apt. #6

Dear Sir:

We recently received a complaint and an inspection was made by Code Enforcement Officer Merlin Leary of the property owned by you at 279 Brackett St., Apt. #6, Portland, Maine. As a result of the inspection, you are hereby ordered to correct the following substandard housing conditions:

- \* 1. Leaking conditions on the living room ceiling. 108-2 2. Missing tiles or the kitchen and living room ceiling. 108-2
  - Missing switch cover on the living room wall. 113-5
     Broken panels on the hall door. 108-3

The above mentioned conditions are in violation of Article V of the Municipal Code of the City of Portland, Maine, and must be corrected on or before October 6, 1988.

Failure to comply with this order may result in a complaint being filed for prosecution in District Court.

> Sincerely yours, Joseph E. Gray, Jr., Director of Planning & Urban Development

P. Samuel Mottsey Chief of Inspection Services

Merlin Leary (5) Code Enforcement Officer

USQ.P.O.

Re: 279 Brackett St M. Leary	
SEMDER: Complete Items 1 and 2 when additional s end 4. Put your address in the "RETURN TO" Space on the reve card from being returned to your To	era elde. Enilure en de able will averme able.
delivered to and the date of deliver. For additional tens to possible for additional tens to possible for additional services.  1. O Show to whom delivered, date, and at freezae's uddrest for charge!	Will 20wide you the name of the person the following carviose are evallable. Consult
3. Article Addressed to:	4. Article Number
Bell Properties 306 Congress St. Fortland. ME 04101	225 (vA1 T, pic of Sanuthet: ☐ Registated ☐ Insu. ☐ Contified ☐ COD ☐ Express Mail
	Always obtain algorature of exdresses or exercise DELIVERED.
5. Signature – Addressee  X  S. Signature Agent  X  7. Date of Delivery	8. After a Hadres (ONLY if regular)
1 2 0 8K	

PS Farm 3811, Mar. 1987 + U.S.Q.PO 1987-178-268 DOMESTIC RETURN RECEIPT

N 'var - Housing

小儿



# CITY OF PORTLAND

DEPARTMENT OF PLANNING & URBAN DEVELOPMENT INSPECTION SERVICES DIVISION

December 19, 1988

Bell Properties 306 Congress Street Portland, ME 04101

Re: 279 Brackett Street, Apt. #6

Dear Sir:

We recently received a complaint and an inspection was made by Ccde
Enforcement Officer Merlin Leary of the property owned by you
at 279 Brackett St., Apt. #6, Portland, Maine. As a result of the
inspection, you are hereby ordered to correct the following substandard
housing conditions:

- Missing counterbalance cords in the bedroom window. 108-3 Missing tiles in the living room and the bedroom ceilings. 108-2 Missing battery in the smcke detector. 25 MRSA 2464. Missing switch cover on the living room wall. 113-5

Failure to comply with this order may result in a complaint being filed for

Sincerety yours, Joseph E. Gray, Jr., Director of Planning & Uthan Development

Merlin Leary (5) Code Enforcement Office



Planning and Urban Development Joseph E. Gray Jr. Director

### CITY OF PORTLAND

October 21, 1992

Occupant 279 Brackett St/Apt #2 Portland, ME 04102

Re: 279-283 Brackett St/Apt 2 CDL #: 054-F-043 DU:

Dear Occupant of Apartment 2,

A recent inspection of the apartment that you are now occupying, found that it does not meet the requirements of Article V (Housing Code) of the City of Portland Municipal Code and is hereby declared unfit for human occupation.

The owner, Ken Ray, has been notified of the above mentioned condition and has been directed to take immediate steps to vacate the room.

Sincerely,

Kathy Lowe Code Enforcement Officer

Chief of Inspection Services



Planning and Urban Development Joseph E. Gray Jr. Director

#### CITY OF PORTLAND

October 21, 1992

Ken Ray 25 Winn Rd Falmouth, ME 04105

> Re: 279-283 Brackett St/Apt 2 CBL #: 054-F-043

Dear Mr. Ray,

As owner or agent of the property located at the above referred address, you are hereby notified that as the result of a recent inspection, the occupied apartment (#2) is hereby declared unfit for human occupancy.

The above mentioned apartment is to be vacated, and kept vacant, so long as the following conditions continue to exist thereon.

#### Article v Section 6-120

(3) Properties which, because of their general condition, state of the premises, number of occupants, or location, are so insanitary, unsafe, over rowded or otherwise dangerous or detrimental that they create a serious menace to the occupants or the public.

Therefore, you will not occupy, permit anyone to occupy, or rent the above mentioned apartment without the written consent of the Health Officer or his agent, certifying that the conditions have been corrected.

You are also hereby ordered to make the above mentioned apartment of the property safe and secure so that no danger to life or property or fire hazard shall exist thereon. This can be accomplished by boarding up doors and wisdows and other openings at all levels of the structure. You are ordered to do this immediately or we will have no choice but to refer this matter to the Corporation Counsel for legal action as the law allows.

Sincerely,

Kathy Lowe

Code Enforcement Officer

P. Samuel Hoffdes Chief of Inspection Services



Planning and Urban Development Joseph E. Gray Jr. Director

### CITY OF PORTLAND

January 19, 1993

Kenneth Ray 27 Winn Rd Falmouth, ME 04105

> Re: 279-283 Brackett St CBL: 054-F-043 DU: 12

Dear Mr. Ray,

As owner or agent of the property located at the above referred address, you are hereby notified that as the result of a recent inspection, the occupied apartment #10 is hereby declared until for human occupancy.

The above mentioned mourtment is to be vacated, and kept vacant so long as the following conditions a continue to exist thereon.

Arricle v .. 9-120

(1) Prope. As which are either damaged, decayed, dilapidated, insanitary, unsafe, or vermin-infested in such a manner as to create a serious hazard to the health, safety, and general welfare of the occupants or the public.

Therefore, you will not occupy, permit anyone to occupy, or rent the above mentioned apartment without the written consent of the Health Officer or his/her agent, certifying that the conditions have been corrected.

Sincerely,

Kathleen A. Lowe

Code Enforcement Officer

P. Samuel Hoffses

Chief of Inspection Services



Planning and Urban Development Joseph E. Gray Jr. Director

## CITY OF PORTLAND

January 19, 1993

Tenant (Apt #10) 279 Brackett St Portland, ME 04102

> Re: 279-283 Brackett St CBL #: 054-F-043 DU: 12

Dear Tenant,

A recent inspection of the apartment (#10) that you are now occupying, found that it does not meet the requirements of Article V (Housing Code) of the City of Portland Municipal Code and is hereby declared unfit for human occupation.

The owner, Kenneth Ray, has been notified of the above mentioned condition and has been directed to take immediate steps to vacate the apartment.

Sincerely,

Kathleen A. Lowe

Code Enforcement Officer

P. Samuel Hoffses

Chief of Inspection Services



Planning and Urban Development Joseph E. Gray Jr. Director

## CITY OF PORTLAND

June 24, 1993

Lalumierre Scott P & Kenneth S 27 Winn Rd Falmouth Me 04105

> Re: 279 Brackett St CBL: 054- - F-043-001-01 DU: 12

Dear Sirs,

This is to inform you, as owner or agent of the property located at the above referred address, that we have released the apartments numbered 2 and 10 from posting.

Therefore, you may rent this dwelling unit to others or occupy them yourself.

If any additional information is desired, visit or call this office.

sincerely,

Kathleen Lowe

Code Enforcement Officer

P. Samuel Hoffses Chief of Inspection Services



Planning and Urban Development Joseph E. Gray Jr. Director

### CITY OF PORTLAND

Novembe 16, 1994

RAY KENNETH S 502 STEVENS AVE PORTLAND ME 04103

> Re: 279 Brackett St CBL: 054- - F-043-001-01 DU: 13

Dear Mr. Ray:

During a recent inspection of the property owned by you at the above referred address, it was noted that the smoke detector was inoperable in apartment #7.

25 MRSA 2464 required that approved smoke detectors be installed in each apartment in the immediate vicinity of the Ledrooms. When activated, the detector shall provide an alarm sultable to warn the occupants within the individual unit. Failure to comply with this statute may result in a fine of up to \$500 for each violation.

Re-inspection of your property will be made in 24 hours. Lack of compliance will result in referral of the matter for legal action.

Loss control is a responsibility of your management. Our observations are intended to assist you. Recommendations are a result of conditions observed at the time of our visits. They do not necessarily include every possible loss potential code violation, or exception to good practice.

Sincerely,

Amy/Lirpson Code Enforcement Officer Marge Schmuckal

Asst. Chief of Inspection Services

389 Congress Street • Portland, Maine (4101 • (207) 874 8704 • FAX 874-8716 • ITY 874-8936