

PERMIT # _____	PORTLAND BUILDING PERMIT APPLICATION	DATE <u>7/24/87</u>	PERMIT ISSUED JUL 27 1987 City of Portland
I. GENERAL INFORMATION			
Location/address of construction <u>420 Brackett Street</u>			
1. Owner's name <u>Shirley Barber</u>	Tel: <u>839-3489</u>		
Address <u>3 Ottawa Woods Road, Scarsdale, NY 10574</u>			
2. Lessee's name _____	Tel. <u>772-4066</u>		
Address _____			
3. Contractor's name <u>William Barber</u>	Tel. _____	<u>90</u>	
Address _____			
4. Is this a legally recorded lot? yes _____ no _____			

II. DESCRIPTION OF WORK:
to remodel kitchen as per plans

III. BUILDING DIMENSIONS: length _____ width _____ square footage _____ height _____ #stories _____	
IV. ZONE <u>R-6</u>	Street frontage _____ Zoning board approval: no <input type="checkbox"/> yes <input type="checkbox"/> date _____
Setbacks: front _____ back _____ side _____ side _____	Planning board approval: no <input type="checkbox"/> yes <input type="checkbox"/> date _____
V. REVIEW REQUIRED: variance _____ other _____	
site plan _____ subdivision _____ shore _____ floodplain mgmt _____	Number of off-street parking spaces: _____ enclosed _____ outdoors _____
VI. FEES:	
base fee _____	other fees _____
subdivision fee _____	late fee _____
site plan review fee _____	TOTAL <u>\$30.00</u>

VII. DETAILS OF WORK		
1. WATER SUPPLY: <input type="checkbox"/> public <input type="checkbox"/> private	7. ELECTRICAL: service entrance size _____ # smoke detectors _____	8. CHIMNEY: # flues _____ material _____ # fireplaces _____
2. SEWER: <input type="checkbox"/> public <input type="checkbox"/> private, type _____	9. FRAMING: floor joists _____ size _____ max. on center _____ ceiling joists _____ rafters _____ studs _____ wall studs _____	
3. HEAT: type _____ fuel _____	10. If 1-story building w/masonry walls: wall thickness _____ height _____	11. BEDROOM WINDOWS: height _____ width _____ sill height _____ egress window? yes <input type="checkbox"/> no <input type="checkbox"/>
4. FOUNDATION: type _____ thickness _____ footing _____		
5. ROOF: type _____ pitch _____ covering _____ load _____		
6. PLUMBING: SPRINKLER SYSTEM? yes <input type="checkbox"/> no <input type="checkbox"/>		
VIII. OFFICE USE: TAX MAP # _____ LOT # _____ VALUE/STRUCTURE _____ PERMIT EXPIRATION _____		IX. NEW OR PHASED SUBDIVISION REFERENCE: Name _____ Lot _____ Block _____
CODE: _____ If other, explain: _____ Seasonal Condominium Apartment		
X. PROPOSED USE: <u>004 - 3 Family</u>		
XI. PAST USE: _____		
XII. OWNERSHIP: PUBLIC <input checked="" type="checkbox"/> PRIVATE <input type="checkbox"/>		
XIII. EST. CONSTRUCTION COST: <u>2,000</u>	XIV. GR. SQ. FT. OF LOT BUILDING _____	

COMPLETE XV AND XVI ONLY IF THE NUMBER OF UNITS WILL CHANGE		
XV. RESIDENTIAL BUILDINGS ONLY: BEDROOMS		XVI. # RESIDENTIAL UNITS:
# NEW DWELLING UNITS WITH:	1 BDRM. 2 BDRMS 3 BDRMS	# NEW DWELLINGS _____
# EXISTING DWELLING UNITS WITH:		# EXISTING DWELLINGS _____
		TOTAL RESIDENTIAL UNITS _____

APPROVALS BY: _____ DATE _____	MISCELLANEOUS
BUILDING INSPECTION: PLAN EXAMINED _____	Will work require disturbing of any tree on a public street? _____
ZONING: <u>O.R. McFarlane July 24, 1987</u>	Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? _____
C.E.O. _____	
FIRE DEPT: _____	

NOTE TO APPLICANT: Separate permits are required by the installers and subcontractors of heating, plumbing, electrical, and mechanicals.

District No. <u>5</u>	XVII. SIGNATURE OF APPLICANT: <u>[Signature]</u> PHONE # _____
	TYPE NAME OF ABOVE: <u>William Barber</u> 1 2 3 4

White - GPCOS Green - Applicant Yellow - Assessor Pink - Office File Gold - Field Inspector

M. Kearney

NOTES

9-16-87 This permit at pgh 4
Interior kitchen. Unloading pen
with new roof, ceiling & lighting
1-27-89 Dph, & all completed
with budget.

Permit No.	
Location	280 Biscotti
Owner	
Date of permit	
Approved	
Dwelling	
Garage	
Alteration	

~~[Large Xed-out section]~~

~~[Large Xed-out section]~~

BARBER
 220 BRACKET ST. MAP 55-B-38
 Kitchen Remodel

	Materials Estimate	LABOR Est.
GUT TO STUDS		
NEW SUB FLOOR 10 Sheets Plywood	\$ 120	⊖
4 New windows	\$ 320	⊖
New dry wall (17 sheets)	\$ 100	⊖
Rewire outlets + ceil/light (have all materials left over from other jobs)	\$ 0	⊖
Plumb for kitchen sink (have leftover materials)	\$ 50	⊖
10' L shaped new cabinets	\$ 800	⊖
Suspended ceiling	\$ 250	⊖
elec heat registers + + stats	\$ 150	⊖
Chapboards (replace damaged as needed)	\$ 100	⊖

RECEIVED


JUL 24 1987

DEPT. OF BUILDING INSPECTIONS
 CITY OF PORTLAND


MAP SKETCH ADDENDUM

Borrower/Client	William Barber		
Property Address	220 Brackett St.	55-B-38	Zip Code 04102
City	Portland	County Cumberland	State Me.
Lender			

BUILDING SKETCH




LOCATION MAP [*SUBJECT PROPERTY]



OVER FOR PHOTO ATTACHMENTS

SKETCH ADDENDUM

Borrower/Client	BARBER		
Property Address	220 Brackett St.	Map	55-13-38
City	County	State	Zip Code
Lender			



RECEIVED
 JUL 24 1987
 DEPT. OF BUILDING INSPECTIONS
 CITY OF PORTLAND

- | | | |
|---|---|--|
| <p>Plumbing
 ↓
 new sink
 remove old sink
 remove old radiator
 and tie off</p> | <p>Electrical
 outlets + switches
 bsbd registers
 thermostats ↑
 relocate stove outlet
 (2) ceiling lights
 middle of kit + Bkfst area</p> | <p>Carpentry
 level floor
 new subfloor
 4 new windows hi part dble
 new wall board over
 celotex insulating board
 replace siding as needed</p> |
|---|---|--|

- Gut out
- new windows
- wall board
- suspended ceiling
- approx 10' new L shaped cabinets

NOTICE OF HOUSING CONDITIONS

CITY OF PORTLAND, MAINE

Department of Planning & Urban Development
Inspection Services Division
Tel. 775-5451 - Ext. 311 - 346

Ms. Shirley Barber
220 Brackett Street
Portland, ME 04102

DU 3

CH. 55 BLK. B LOT 38

LOCATION: 220 Brackett Street

PROJECT: MCP-WE
ISSUED: October 9, 1986
EXPIRES: December 9, 1986

Dear Ms. Barber:

You are hereby notified, as owner or agent, that an inspection was made of the premises at 220 Brackett Street by Code Enforcement Officer Merlin Leary. Violations of Article V of the Municipal Ordinance (Housing Code) were found as described in detail on the attached "Housing Inspection Report".

In accordance with the provisions of the above-mentioned Code, you are hereby ordered to correct those defects on or before Dec. 9, 1986. If you are unable to make such repairs within the specified time, you may contact this office to arrange a satisfactory repair schedule. If we do not hear from you within ten (10) days from this date, we will assume the repairs to be in progress and, on re-inspection within the time set forth above, will anticipate that the premises have been brought into compliance with the Housing Code Standards.


Please Note: You should consult the inspection Services Division to insure that any corrective action you undertake complies with the building, plumbing, electrical, zoning and any other Article of the City Code.

Please contact this office if you have any questions regarding this order.

Your cooperation will aid this department in its goal to maintain decent, safe, and sanitary housing for all of Portland's residents.

Very truly yours,

Joseph E. Gray, Jr., Director
Planning & Urban Development

By: 
P. Samuel Hopkins
Chief of Inspection Services

Code Enforcement Officer - Merlin Leary (5)

Attachments

jmr

HOUSING INSPECTION REPORT

OWNER: Ms. Shirley Barber

LOCATION: 220 Brackett St. 35-B-38 WE

CODE ENFORCEMENT OFFICER: Merlin Leary (5)

HOUSING CONDITIONS DATED: October 9, 1986

EXPIRES: December 9, 1986

ITEMS LISTED BELOW ARE IN VIOLATION OF ARTICLE V OF THE MUNICIPAL CODES, "HOUSING CODE", AND MUST BE CORRECTED ON OR BEFORE THE EXPIRATION DATE.

	<u>SEC.(S)</u>
* 1. RIGHT CELLAR - windows - broken glass.	108-3
2. SECOND FLOOR REAR HALL - wall - broken shingles.	108-2
* 3. SECOND FLOOR REAR HALL - stairway - missing safety rail.	108-4
<u>FIRST FLOOR</u>	
* 4. LIVING ROOM - ceiling - missing light fixture.	113-5
<u>SECOND FLOOR</u>	
* 5. SMOKE DETECTOR - missing. (ten days)	25 MRSA 2464

*WHEN MAKING YOUR REPAIRS, FIRST PRIORITY IS TO BE GIVEN TO ITEMS WITH ASTERISKS, AS THEY CONSTITUTE EXTREME HAZARDS TO THE HEALTH OR SAFETY OF THE OCCUPANTS OF THIS STRUCTURE.



CITY OF PORTLAND, MAINE
Department of Building Inspection

Certificate of Occupancy

LOCATION 226 Brackett St.

Issued to Shirley Barber

Date of Issue July 10, 1989

This is to certify that the building, premises, or part thereof, at the above location, built — altered — changed as to use under Building Permit No. 89/2053, has had final inspection, has been found to conform substantially to requirements of Zoning Ordinance and Building Code of the City, and is hereby approved for occupancy or use, limited or otherwise, as indicated below.

PORTION OF BUILDING OR PREMISES

Entire

APPROVED OCCUPANCY

3 unit Apartments

Limiting Conditions:

None

This certificate supersedes
certificate issued

Approved:

7/10/89
(Date)

Inspector

Inspector of Buildings

Notice: This certificate identifies lawful use of building or premises, and ought to be transferred from owner to owner when property changes hands. Copy will be furnished to owner or lessee for one dollar.

PERMIT # 00205 CITY OF Portland BUILDING PERMIT APPLICATION MAP # _____ LOT# _____

Please fill out any part which applies to job. Proper plans must accompany form.

Owner: Shirley Barber 554-9147
 Address: P.O. Box. 10525 N.S. 04104
 LOCATION OF CONSTRUCTION 220 Brackett St.
 CONTRACTOR: _____ SUBCONTRACTORS: _____
 ADDRESS: _____

Est. Construction Cost: _____ Type of Use: _____
 Past Use: _____
 Building Dimensions L _____ W _____ Sq. Ft. _____ # Stories: _____ Lot Size: _____
 Is Proposed Use: _____ Seasonal _____ Condominium _____ Apartment _____
 _____ Conversion - Explain Change of Use to Legalize 3 family Letter attached

COMPLETE ONLY IF THE NUMBER OF UNITS WILL CHANGE
 Residential Buildings Only:
 # Of Dwelling Units _____ # Of New Dwelling Units _____

Foundation:
 1. Type of Soil: _____
 2. Set Backs - Front _____ Rear _____ Side(s) _____
 3. Footings Size: _____
 4. Foundation Size: _____
 5. Other _____

Floor:
 1. Sills Size: _____ Sills must be anchored.
 2. Girder Size: _____
 3. Lally Column Spacing: _____ Size: _____
 4. Joists Size: _____ Spacing 16" O.C.
 5. Bridging Type: _____ Size: _____
 6. Floor Sheathing Type: _____ Size: _____
 7. Other Material: _____

Exterior Walls:
 1. Studding Size _____ Spacing _____
 2. No. windows _____
 3. No. Doors _____
 4. Header Sizes _____ Span(s) _____
 5. Bracing: Yes _____ No _____
 6. Corner Posts Size _____
 7. Insulation Type _____ Size _____
 8. Sheathing Type _____ Size _____
 9. Siding Type _____ Weather Exposure _____
 10. Masonry Materials _____
 11. Metal Materials _____

Interior Walls:
 1. Studding Size _____ Spacing _____
 2. Header Sizes _____ Span(s) _____
 3. Wall Covering Type _____
 4. Fire Wall if required _____
 5. Other Materials _____

For Official Use Only	
Date: <u>March 29, 1989</u>	Subdivision: Yes / No _____
Inside Fire Limits: _____	Name: _____
Blgd Code: _____	Lot: _____
Time Limit: _____	Block: _____
Estimated Cost: _____	Permit Expiration: _____
Value/Structure: <u>60</u>	Ownership: _____ Public _____ Private _____
Fee: _____	

Ceiling:
 1. Ceiling Joists Size: _____
 2. Ceiling Strapping Size _____ Spacing _____
 3. Type Ceilings: _____
 4. Insulation Type _____
 5. Ceiling Height: _____

Roof:
 1. Truss or Rafter Size _____ Span _____
 2. Sheathing Type _____ Size _____
 3. Roof Covering Type _____
 4. Other _____

Chimneys:
 Type: _____ Number of Fire Places _____

Heating:
 Type of Heat: _____

Electrical:
 Service Entrance Size: _____ Smoke Detector Required Yes _____ No _____

Plumbing:
 1. Approval of soil test if required Yes _____ No _____
 2. No. of Tubs or Showers _____
 3. No. of Flushes _____
 4. No. of Lavatories _____
 5. No. of Other Fixtures _____

Swimming Pools:
 1. Type: _____
 2. Pool Size: _____ Square Footage _____
 3. Must conform to National Electrical Code and State Law.

Zoning:
 District: _____ Street Frontage Req: _____ Provided _____
 Required Setbacks: Front _____ Back _____ Side _____

Review Required:
 Zoning Board Approval: Yes _____ No _____ Date: _____
 Planning Board Approval: Yes _____ No _____ Date: _____
 Conditional Use: _____ Variance _____ Site Plan _____ Subdivision _____
 Shore and Floodplain Mgmt _____ Special Exception _____
 Other (Explain) _____
 Date Approved: 5-9-89

Permit Received By: Latin

PERMIT ISSUED WITH LETTER
 Signature of Applicant: _____ Date: 3/20/89
 Signature of CEO: _____ Date: 3-25-89

Inspection Dates: _____

BUILDING PERMIT REPORT

ADDRESS: 220 Brackett St. DATE: 10/may/89
REASON FOR PERMIT: Change of use from 2 to 3
Family apartment's
BUILDING OWNER: Shirley Barber
CONTRACTOR: 11
PERMIT APPLICANT: 11
APPROVED: *3*4*5*6*7* DENIED: _____

CONDITION OF APPROVAL OR DENIAL:

- 1.) Before concrete for foundation is placed, approvals from Public Works and Inspection Services must be obtained.
- 2.) Precaution must be taken to protect concrete from freezing.
- *3.) All vertical openings shall be enclosed with construction having a fire rating of at least one(1) hour, including fire doors with self-closers
- *4.) Each apartment shall have access to two(2) separate, remote and approved means of egress. A single exit is acceptable when it exits directly from the apartment to the building exterior with no communications to other apartment units.
- *5.) The boiler shall be protected by enclosing with one(1) hour fire rated construction including fire doors and ceiling, or by placing over the boiler, two(2) residential sprinkler heads supplied from the domestic water.
- *6.) Every sleeping room below the fourth story in buildings of Use Groups R and I-1 shall have at least one operable window or exterior door approved for emergency egress or rescue. The units must be operable from the inside opening without the use of separate tools. Where windows are provided as a means of egress or rescue, they shall have a sill height not more than 44 inches (1118 mm) above the floor. All egress or rescue windows from sleeping rooms must have minimum net clear openings of 5.7 square feet (0.53m²). The minimum net clear opening height dimension shall be 24 inches (610 mm). The minimum net clear opening width dimension shall be 20 inches (508 mm).
- 7.) In addition to any automatic fire alarm system required by Sections 1018.3.5, a minimum of one single station smoke detector shall be installed in each guest room, suite of sleeping area in buildings of Use Groups R-1 and I-1 and in dwelling units in the immediate vicinity of the bedrooms in buildings of Use Group R-2 or R-3. When actuated, the detector shall provide an alarm suitable to warn the occupants within the individual unit (see Section 1717.3.1).

In buildings of Use Groups R-1 and R-2 which have basements, an additional smoke detector shall be installed in the basement. In buildings of Use Group R-3, smoke detectors shall be required on every story of the dwelling unit, including basements.

In dwelling units with split levels, a smoke detector installed on the upper level shall suffice for the adjacent lower level provided the lower level is less than one full story below the upper level. If there is an intervening door between the adjacent levels, a smoke detector shall be installed on both levels.

All detectors shall be installed in an approved location. Where more than one detector is required to be installed within an individual dwelling unit, the detectors shall be wired in such a manner that the actuation of one alarm will actuate all the alarms in the individual unit.

- 8.) Private garages located beneath rooms in buildings of Use Groups R-1, R-2, R-3 or I-1 shall have walls, partitions, floors and ceilings separating the garage space from the adjacent interior spaces constructed of not less than 1-hour fireresistance rating. Attached private garages shall be completely separated from the adjacent interior spaces and the attic area by means of 1/2-inch gypsum board or equivalent applied to the garage side. The sills of all door openings between the garage and adjacent interior spaces shall be raised not less than 4 inches (102 mm) above the garage floor. The door opening protectives shall be 1 3/4-inch solid core wood doors or approved equivalent.
- 9.) A guardrail system located near the open side of deck or elevated walking surfaces shall be constructed. Guards in buildings of Use Group R-3 shall be not less than 36 inches in height. Open guards shall have intermediate rails, balusters or other construction such that a sphere with a diameter of 6 inches cannot pass through any opening.
- 10.) Section 25-135 of the Municipal Code for the City of Portland states: "No person or utility shall be granted a permit to excavate or open any street or sidewalk from the time of November 15 of each year to April 15 of the following year.
- 11.) The builder of a facility to which Section 4594-C of the Maine State Human Rights Act, Title 5 M.R.S.A. refers, shall obtain a certification from a design professional that the plans of the facility meet the standards of construction required by this section. Prior to commencing construction of the facility, the builder shall submit the certification to the Division of Inspection Services.

Sincerely,

P. Samuel Hoffses
Chief of Inspection Services


/el
11/16/88

RECEIVED
MAY 17 1983
DEPT. OF BLDG. INSP.
CITY OF PORTLAND

PERMIT ISSUED
WITH LETTER

Existing Secondary EXIT
TO BE CLOSED off THROUGH
2x4 FRAMING AND ~~Sheetrock~~ plywood


PROPOSED
SECONDARY EXIT
(4x4' platform
based on 4"x4"
posts secured in
concrete with
36" stairway
also secured
to ground)



Stairs Platform
Existing Primary EXIT TO OUTSIDE

220 Brackett St,
Portland Maine
owner Shirley Barber
MAP 55-B-38



RECEIVED
MAR 2 0 1989
DEPT. OF BUILDING INSPECTIONS
CITY OF PORTLAND




MAP 55-B-38
1" = 50'

Borrower/Client: **BARBER**
 Property Address: **2-20 BRACKETT STREET**
 City: **ROSELAND, N.J.** County: **ESSEX COUNTY** State: **N.J.** Zip Code: **07068**
 Lender: _____

First Floor



Second Floor



THIRD FLOOR

X - smoke detectors

Lt. Garroway
Portland Fire Dept.
Congress St.
Portland, Maine

RE: 220 Brackett St. (BARBER)

Dear. Lt. Garroway:

Per our discussion, I've enclosed the revised plans which are as follows:

1 hour fire rated doors at: A,B,C,D,E,F,G
door A will be an inswing.
B and C are the changes we discussed.

Construct interior staircase between third floor sunporch to second floor sunporch at H (exact location to be field determined by contractor)

Install new exterior door at I.

Reconstruct existing exterior stairs at J to accommodate new door.

Close off existing interior stairwell K+L. 5/8 firerated wallboard on each side of stud wall.

Remove existing outside stairs at M. Check if demo permit is required.

Wood jambs on firerated doors provided the contractor's rough openings provide for a tight fit without large gaps.

Exterior stairs per code specs provided.


20 minute firerated door to the cellar stairs at O.

2 fast acting residential sprinkler heads over boiler.

Hardwired smoke detectors in locations approximate to locations marked by X.
wall or ceiling mount but no closer than 4" from ceiling/wall juncture.

Sincerely:

Bill Barber



Mr. William Giroux
Portland Dept. of Zoning
City Hall
Portland, Maine

Dear Mr. Giroux:

In June of 1983 I purchased the 3 unit apt. building at 220 Brackett St. At the time of the purchase FHA required that code enforcement inspect the building to be sure it met current standards. Because of this the sellers had to install an outside staircase to serve as the emergency exit for the second floor. At this point I thought we had a legal building, but recently we had an appraisal done to obtain refinancing and the appraiser indicated that the property was only a legal 2 unit based on the records on microfilm and that a certificate of occupancy was never issued for the third unit. Based on my husband's conversation with you, we are applying for a "change of use" from a 2 unit to a three unit. Please note that there will not be any changes to the existing foundation or structure in any way, the building was built approx. 1874, from what we could determine the property appears to have been in use as a three unit since the 1960s, the lot size of 4500 sq.ft. meets current space requirements, there are 3 separate updated 100amp electric services, and three full baths. As you requested, I've enclosed a plot plan with the building outlined, this is as close to scale as possible. Please let me know if you have any further questions or requirements so that we can resolve this as quickly as possible and bring our building back to legal status.

Sincerely:


Shirley Barber
Shirley Barber

F.O. Box. 10525
Portland, Maine 04104
Tel: 854-9147 (work) between 8:30 to 5:30

DEPT. OF BUILDING INSPECTIONS
CITY OF PORTLAND

MAR 2 0 1989

RECEIVED



B PERMIT # 002052 CITY OF Portland BUILDING PERMIT APPLICATION MAP # _____ LOT# _____

Please fill out any part which applies to job. Proper plans must accompany form.

Owner: Shirley Barber 854-9147
 Address: P.O. Box. 10525 DTS 04104

LOCATION OF CONSTRUCTION 220 Brackett St.

CONTRACTOR: _____ SUBCONTRACTORS: _____

ADDRESS: _____

Est. Construction Cost: _____ Type of Use: _____

Past Use: _____

Building Dimensions L _____ W _____ Sq. Ft. _____ # Stories: _____ Lot Size: _____

Is Proposed Use: _____ Seasonal _____ Condominium _____ Apartment _____

Conversion - Explain Change of Use to Legalize 3 family

COMPLETE ONLY IF THE NUMBER OF UNITS WILL CHANGE Letter attached

Residential Buildings Only: _____
 # Of Dwelling Units _____ # Of New Dwelling Units _____

Foundation:

1. Type of Soil: _____
2. Set Backs - Front _____ Rear _____ Side(s) _____
3. Footings Size: _____
4. Foundation Size: _____
5. Other _____

Floor:

1. Sills Size: _____ Sills must be anchored.
2. Girder Size: _____
3. Lally Column Spacing: _____ Size: _____
4. Joists Size: _____ Spacing 16" O.C.
5. Bridging Type: _____ Size: _____
6. Floor Sheathing Type: _____ Size: _____
7. Other Material: _____

Exterior Walls:

1. Studding Size _____ Spacing _____
2. No. windows _____
3. No. Doors _____
4. Header Sizes _____ Span(s) _____
5. Bracing: Yes _____ No _____
6. Corner Posts Size _____
7. Insulation Type _____ Size _____
8. Sheathing Type _____ Size _____
9. Siding Type _____ Weather Exposure _____
10. Masonry Materials _____
11. Metal Materials _____

Interior Walls:

1. Studding Size _____ Spacing _____
2. Header Sizes _____ Span(s) _____
3. Wall Covering Type _____
4. Fire Wall if required _____
5. Other Materials _____

For Official Use Only	
Date <u>March 9, 1989</u>	Subdivision: Yes / No _____
Inside Fire Limits _____	Name _____
Eng Code _____	Lot _____
Time Limit _____	Block _____
Estimated Cost _____	Permit Expiration _____
Value/Structure <u>25,110</u>	Ownership: Public _____ Private _____
Fee _____	

Colling:

1. Ceiling Joists Size: _____
2. Ceiling Strapping Size _____ Spacing _____
3. Type Ceiling: _____
4. Insulation Type _____
5. Ceiling Height: _____

Roof:

1. Truss or Rafter Size _____
2. Sheathing Type _____
3. Roof Covering Type _____
4. Other _____

Chimneys:

Type: _____ Number of Fire Places: _____

Heating:

Type of Heat: _____

Electrical:

Service Entrance Size: _____ Smoke Detector Required Yes _____ No _____

Plumbing:

1. Approval of soil test if required Yes _____ No _____
2. No. of Tubs or Showers _____
3. No. of Flushes _____
4. No. of Lavatories _____
5. No. of Other Fixtures _____

Swimming Pools:

1. Type: _____
2. Pool Size _____ x _____ Square Footage _____
3. Must conform to National Electrical Code and State Law.

Zoning:

District _____ Street Frontage Req. _____ Provided _____

Review Required:

Required Setbacks: Front _____ Back _____ Side _____ Side _____

Zoning Board Approval: Yes _____ No _____ Date: _____

Planning Board Approval: Yes _____ No _____ Date: _____

Conditional Use: _____ Variance _____ Site Plan _____ Subdivision _____

Shore and Floodplain Mgmt _____ Special Exception _____

Other (Explain) _____

Date Approved _____

Permit Received By Latini

Signature of Applicant [Signature] Date 3/20/89

Signature of CEO _____ Date _____

Inspection Dates (5) MW