


134 CLARK STREET



SHAMROCK

Full cut # 9201 - Half cut # 9202 - Third cut # 9203 - Fifth cut # 9205



FILL IN AND SIGN WITH INK

### APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIPMENT

Portland, Maine, Sept. 19, 1962

**PERMIT ISSUED**  
01190  
IN 1962

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 134 Clark St. Use of Building Dwelling No. Stories 1 1/2 New Building Existing "  
 Name and address of owner of appliance William G Gorey, 134 Clark St.  
 Installer's name and address Randall & McAllister 84 Commercial St. Telephone

#### General Description of Work

To install Oil-fired steam heating system and oil burning equipment (in place of coal-fired steam heating system) (replacement) (conversion)

#### IF HEATER, OR POWER BOILER

Location of appliance Basement Any burnable material in floor surface or beneath?  no  
 If so, how protected? Kind of fuel? oil  
 Minimum distance to burnable material, from top of appliance or casing top of furnace 3'  
 From top of smoke pipe 3' From front of appliance over 4' From sides or back of appliance over 3'  
 Size of chimney flue 12" Other connections to same flue none  
 If gas fired, how vented? Rated maximum demand per hour  
 Will sufficient fresh air be supplied to the appliance to insure proper and safe combustion?  yes

#### IF OIL BURNER

Name and type of burner Thatcher gun type Labeled by underwriters' laboratories?  yes  
 Will operator be always in attendance? Does oil supply line feed from top or bottom of tank? bottom  
 Type of floor beneath burner concrete Size of vent pipe 1 1/2"  
 Location of oil storage basement Number and capacity of tanks 269-11000  
 Low water shut off  yes Make McD-Miller No. 269  
 Will all tanks be more than five feet from any flame?  yes How many tanks enclosed?  
 Total capacity of any existing storage tanks for furnace burners

#### IF COOKING APPLIANCE

Location of appliance Any burnable material in floor surface or beneath?  
 If so, how protected? Height of Legs, if any  
 Skirting at bottom of appliance? Distance to combustible material from top of appliance?  
 From front of appliance From sides and back From top of smokepipe  
 Size of chimney flue Other connections to same flue  
 Is hood to be provided? If so, how vented? Forced or gravity?  
 If gas fired, how vented? Rated maximum demand per hour

#### MISCELLANEOUS EQUIPMENT OR SPECIAL INFORMATION

Amount of fee enclosed? 2.00 (\$2.00 for one heater, etc., \$1.00 additional for each additional heater, etc. in same building at same time.)

**APPROVED**  
9.19.62 [Signature]

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed?  yes

Randall & McAllister

IS 300

INSPECTION COPY

Signature of Installer BY: [Signature]

7-M.



082/952

February 2, 1936

Mr. A. G. Libby  
12 Monument Square  
Portland, Maine

Dear Sir:

Referring to alterations in your building at 124 Clark Street, we find that the gutters and conductors on one side of the house have been fixed so that water therefrom does not run upon the public sidewalk, but on the other side of the house the downspout has not been fixed, so that now the water from the roof does run approximately directly upon the public sidewalk.

We have had this matter of roof drainage of this building on our books for a long time, and you must be quite aware that such a condition is in violation of the Ordinance of the City of Portland.

Will you not have this work completed on or before February 15, 1936 so that no water from the roof of the building will run upon the public sidewalk?

Very truly yours,

Inspector of Buildings,

AM/ED

CITY OF PORTLAND, MAINE  
DEPARTMENT OF BUILDING INSPECTION

March 28, 1972

City of Portland

With relation to permit applied for to demolish a dwelling  
at 13 1/2 Clark St. it is unlawful  
to commence demolition work until a permit has been issued from this  
department.

Section 6 of the Ordinance for rodent and vermin control provides:  
"It shall be unlawful to demolish any building or structure unless  
provision is made for rodent and vermin eradication. No permit for the  
demolition of a building or structure shall be issued by the Building  
Inspection Department until and unless provisions for rodent and vermin  
eradication have been carried out under supervision of a pest control  
operator registered with the Health Department.

The building permit for demolition cannot be issued until the  
provisions of this section have been satisfied. It is the obligation  
of owner or demolition contractor or both to take up with the Health  
Department the matter of complying with this section, being prepared  
to inform that department what registered pest control operator is to  
be employed.

Very truly yours,

R. Lovell Brown  
Director

Eradication of this building has been completed.

Contractor:

Ralph Romano Jr. Inc.

55 Frederick St.

3-30-72

*No evidence of rodent activity*  
*Spill 2* *[Signature]*

Sent to Health Dept. 3/28/72  
Rec'd from Health Dept. 3/31/72

CITY OF PORTLAND, MAINE  
DEPARTMENT OF PUBLIC WORKS  
DEMOLITION OF BUILDINGS

A building will be demolished at # 134 Clark St.  
on \_\_\_\_\_.

The Contractor is Ralph Romano Jr. Inc.  
55 Frederick St.

The owner is: City of Portland

3/29/72 The Contractor and Sewer Division have been notified  
of sealing the drain before the building can be demolished.

DEPARTMENT OF PUBLIC WORKS

PHILIP E. MULLIN

3/28/72  
3/31/72  
Sent to Health Dept.  
Rec'd from Health Dept.



# APPLICATION FOR PERMIT

Class of Building or Type of Structure \_\_\_\_\_

Portland, Maine, March 28<sup>th</sup> 1972

PERMIT ISSUED

Max 31 1

033.3

CITY of PORTLAND ME

To the INSPECTOR OF BUILDINGS, PORTLAND MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 134 Clark St. Within Fire Limits? \_\_\_\_\_ Dist. No. \_\_\_\_\_

Owner's name and address City of Portland ( PRA ) Telephone \_\_\_\_\_

Lessee's name and address \_\_\_\_\_ Telephone \_\_\_\_\_

Contractor's name and address Ralph Romano Jr., Inc., 55 Frederick St. Telephone \_\_\_\_\_

Architect \_\_\_\_\_ Specifications \_\_\_\_\_ Plans \_\_\_\_\_ No. of sheets \_\_\_\_\_

Proposed use of building \_\_\_\_\_ No. families \_\_\_\_\_

Last use dwelling No. families 1

Material \_\_\_\_\_ No. stories 2 Heat \_\_\_\_\_ Style of roof \_\_\_\_\_ Roofing \_\_\_\_\_

Other buildings on same lot \_\_\_\_\_

Estimated cost: \$ \_\_\_\_\_ Per \$ 10. \_\_\_\_\_

### General Description of New Work

To demolish existing 2 story frame dwelling. Sewer to be closed under supervision of Public Works Dept. Gas company was called.

Sent to Health Dept. 3/28/72  
Rec'd from Health Dept. 3/31/72

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. **PERMIT TO BE ISSUED TO Contractor**

### Details of New Work

1. any plumbing involved in this work? \_\_\_\_\_ Is any electrical work involved in this work? \_\_\_\_\_

Is connection to be made to public sewer? \_\_\_\_\_ If not, what is proposed for sewage? \_\_\_\_\_

Has septic tank notice been sent? \_\_\_\_\_ Form notice sent? \_\_\_\_\_

Height average grade to top of plate \_\_\_\_\_ Height average grade to highest point of roof \_\_\_\_\_

Size, front \_\_\_\_\_ depth \_\_\_\_\_ No. stories \_\_\_\_\_ solid or filled land? \_\_\_\_\_ earth or rock? \_\_\_\_\_

Material of foundation \_\_\_\_\_ Thickness, top \_\_\_\_\_ bottom \_\_\_\_\_ cellar \_\_\_\_\_

Kind of roof \_\_\_\_\_ Rise per foot \_\_\_\_\_ Roof covering \_\_\_\_\_

No. of chimneys \_\_\_\_\_ Material of chimneys \_\_\_\_\_ of lining \_\_\_\_\_ Kind of heat \_\_\_\_\_ fuel \_\_\_\_\_

Framing Lumber—Kind \_\_\_\_\_ Dressed or full size? \_\_\_\_\_ Corner posts \_\_\_\_\_ Sills \_\_\_\_\_

Size Girder \_\_\_\_\_ Columns under girders \_\_\_\_\_ Size \_\_\_\_\_ Max. on centers \_\_\_\_\_

Studs (outside walls and carrying partitions) 2x4-16" O. C Bridging in every floor and flat roof span over 8 feet.

Joists and rafters: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_

On centers: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_

Maximum span: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_

If one story building with masonry walls, thickness of walls? \_\_\_\_\_ height? \_\_\_\_\_

### If a Garage

No. cars now accommodated on same lot \_\_\_\_\_, to be accommodated \_\_\_\_\_ number commercial cars to be accommodated \_\_\_\_\_

Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? \_\_\_\_\_

APPROVED:

O.K. E.S. 3/31/72

### Miscellaneous

Will work require disturbing of any tree or public street? \_\_\_\_\_

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? Yes

CS 301

INSPECTION COPY

Signature of owner

By:


Ralph Romano, Jr. Inc.

[Signature]

Permit No. 72/335  
Location: 134 Alcott St.  
District: City of Portland  
Date of permit: 3/1/72  
Notif. closing-in:  
Inspr. closing-in:  
Final Notif.:  
Final Inspn.:  
Cert. of Occupancy issued:  
~~Issuing Off. Name~~ JRW  
Form Check Notice

NOTES

3/31/72 Gandy  
4/20/72 Revolutionary  
JRW







(B) LIMITED BUSINESS ZONE  
APPLICATION FOR PERMIT

Permit No. **0951**  
ISSUED  
JUL 2 1932

Class of Building or Type of Structure Trid. Class

Portland, Maine. July 3, 1932

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

I hereby apply for a permit to erect, alter, install the following building structure, equipment in accordance with the Building Code of the City of Portland, plans and specifications, if any, attached hereto and the following specifications:

Location - 134 Clark Street Ward 7 Within Fire Limit? yes Dist. No. 7

Owner's or lessor's name and address - A. G. Libby, 12 Monument Sq. Telephone 4675

Contractor's name and address - Conner Telephone \_\_\_\_\_

Architect's name and address \_\_\_\_\_

Proposed use of building - dwelling house No. families 2

Other buildings on same lot \_\_\_\_\_

Plans filed as part of this application? no No. of sheets \_\_\_\_\_

Estimated cost \$ 500. Fee \$ 75

Description of Present Building to be Altered

Material wood No. stories 2 Heat \_\_\_\_\_ Style of roof \_\_\_\_\_ Roofing \_\_\_\_\_

Last use dwelling house No families 2

General Description of New Work **INSPECTION NOT COMPLETED**

To put bearing partition over about 2 1/2' to enlarge existing dining room, first floor, and same on second floor to enlarge sleeping room  
To remove one existing front brick chimney (last 2 1/2'),  
To put in one new window, front, first and second floors,  
To put in one new window, front, first and second floors,  
To install a bathroom in existing room, first hall, second floor, existing window for  
To install a chimney down to cellar floor, providing tile floor lining and cast iron cleanout

**CERTIFICATE OF OCCUPANCY REQUIREMENT IS WAIVED**

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

Details of New Work

Height average grade to top of plate \_\_\_\_\_

Size: front \_\_\_\_\_ depth \_\_\_\_\_ No. stories \_\_\_\_\_ Height average grade to highest point of roof \_\_\_\_\_

To be erected on solid or filled land? \_\_\_\_\_ earth or rock? \_\_\_\_\_

Material of foundation \_\_\_\_\_ Thickness, top \_\_\_\_\_ bottom \_\_\_\_\_

Material of underpinning \_\_\_\_\_ Height \_\_\_\_\_ Thickness \_\_\_\_\_

Kind of Roof \_\_\_\_\_ Rise per foot \_\_\_\_\_ Roof covering \_\_\_\_\_

No. of chimneys \_\_\_\_\_ Material of chimneys \_\_\_\_\_ of lining \_\_\_\_\_

Kind of heat \_\_\_\_\_ Type of fuel \_\_\_\_\_ Is gas fitting involved? \_\_\_\_\_

Corner posts \_\_\_\_\_ Sills \_\_\_\_\_ Girt or ledger board? \_\_\_\_\_ Sire \_\_\_\_\_

Material columns undergirders \_\_\_\_\_ Size \_\_\_\_\_ Max. on centers \_\_\_\_\_

Study (outside walls and carrying partitions) 2x4-16" O. C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.

Joists and rafters: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_

On centers: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_

Maximum span: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_

If one story building with masonry walls, thickness of walls? \_\_\_\_\_ height? \_\_\_\_\_

If a Garage

No. cars now accommodated on same lot \_\_\_\_\_ to be accommodated \_\_\_\_\_

Total number commercial cars to be accommodated \_\_\_\_\_

Will automobile repairs be done other than minor repairs to cars habitually stored in the proposed building? \_\_\_\_\_

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Signature of owner A. G. Libby  
By R. D. Herrick

INSPECTION COPY

