

194 Danforth Street

NDP-REHAB II



SHAW-WALKER

#8503-1R

REQUEST FOR SERVICE

PORTLAND HEALTH DEPARTMENT

DATE RECEIVED	7/14/72	BY	Jim	DISTRICT	Leary
REQUEST BY	NAME	7			
	ADDRESS	194 Waverly St.			
OWNER	NAME	Sam Waverly			
	ADDRESS				
CONDITIONS	ADDRESS	194 Waverly St.			
Room is split in two & the main room is (State Room) Someone has lived in the room before					
COMMENTS					
to be taken care of					
SPECIAL INSTRUCTIONS					
DIVISION					
PRIORITY					
	SANITATION	ROUTINE	URGENT	HOUSING	NURSING
				SPECIAL	
			REPORT TO	BY	DATE

JUSTIFIED

Inspection Services
P. Sanner: Hoffman
Chief

JUNE 07, 1998

MOSER JEREMY
194 DANFORTH ST
PORTLAND ME 04102

Inspection Services
P. Sanner: Hoffman
Chief
CITY OF PORTLAND

JUNE 07, 1998

MOSER JEREMY
194 DANFORTH ST
PORTLAND ME 04102
DU: 4

Planning and Urban Development
Joseph B. Gray Jr.
Director

CITY OF PORTLAND

Dear Mr. Moser:

Re: 194 DANFORTH ST
CPI: 057- K 006

The Housing Inspections Division of the Department of Planning and Urban Development has recently completed an overall inspection of the above-referred property.

Dear Mr. Moser:

Congratulations are extended to you for the general condition of your property which was found to meet the standards established by the City's Housing Code. We did, however, note the following items that could cause future problems:

1) INT - OVERALL - 113.75
HARD-WIRED BATTERY-BACKUP SMOKE DETECTORS ARE REQUIRED IN EACH UNIT
Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.
Sincerely,
113.50
HARD-WIRED BATTERY-BACKUP SMOKE DETECTORS ARE REQUIRED IN EACH UNIT

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.
Sincerely,
Amy Fowers
Code Enforcement Officer
Tammy Munson
Code Enfc. Off. / Field Supv.

Amy Fowers
Code Enforcement Officer
Tammy Munson
Code Enfc. Off. / Field Supv.

