



APPLICATION FOR PERMIT

PERMIT ISSUED

JUL 9 1981

632

CITY OF PORTLAND

B.O.C.A. USE GROUP ... B.O.C.A. TYPE OF CONSTRUCTION ... ZONING LOCATION ... PORTLAND, MAINE, July 8, 1981

To the DIRECTOR OF BUILDING & INSPECTION SERVICES, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect, alter, repair, demolish or install the following building, structure, equipment or change use in accordance with the Laws of the State of Maine, the Portland B.G.C.A. Building Code and Zoning Ordinance of the City of Portland with plans and specifications, if any, submitted herewith and the following specifications:

LOCATION ... 5-7 Cherry St. ... Five District #1 [] #2 []
1. Owner's name and address ... Wabbon, Farrin-Attenzia ... same ... Telephone ... Not known
2. Lessee's name and address ... Telephone ...
3. Contractor's name and address ... G. L. Trynor Co. ... 18 State St. ... Gorham ... Telephone ... 839-2212
4. Architect ... Specifications ... Plans ... No. of sheets ...
Proposed use of building ... multi family with fire escape ... No. families ... 3
Last use ... No. families ...
Material ... No. stories ... Heat ... Style of roof ... Roofing ...
Other buildings on same lot ...
Estimated contractual cost \$... 400 ... Fee \$... 15.00 ...

FIELD INSPECTOR—Mr. ... GENERAL DESCRIPTION

This application is for: @ 775-5451
Dwelling ... Ext. 234 To erect fire escape to serve from 3 to 2 floors as per plans. 2 sheets of plans. 2
Garage ...
Masonry Bldg. ... Stamp of Special Conditions
Metal Bldg. ...
Alterations ...
Demolitions ... HOLD WILL PICK UP PERMIT
Change of Use ...
Other ...

NOTE TO APPLICANT Separate permits are required by the installers and subcontractors of heating, plumbing, electrical and mechanicals.

PERMIT IS TO BE ISSUED TO 1 [] 2 [] 3 [x] 4 []

Other: ...

DETAILS OF NEW WORK

Is any plumbing involved in this work? ... Is any electrical work involved in this work? ...
Is connection to be made to public sewer? ... If not, what is proposed for sewage? ...
Has septic tank notice been sent? ... Form notice sent? ...
Height average grade to top of plate ... Height average grade to highest point of roof ...
Size, front ... depth ... No. stories ... solid or filled land? ... earth or rock? ...
Material of foundation ... Thickness, top ... bottom ... cellar ...
Kind of roof ... Rise per foot ... Roof covering ...
No. of chimneys ... Material of chimneys ... of lining ... Kind of heat ... fuel ...
Framing Lumber—Kind ... Dressed or full size? ... Corner posts ... Sills ...
Size Girder ... Columns under girders ... Size ... Max. on centers ...
Studs (outside walls and carrying partitions) 2x4-16" O. C Bridging in every floor and flat roof span over 8 feet.
Joists and rafters: 1st floor ... 2nd ... 3rd ... roof ...
On centers: 1st floor ... 2nd ... 3rd ... roof ...
Maximum span: 1st floor ... 2nd ... 3rd ... roof ...
If one story building with masonry walls, thickness of walls? ... height? ...

IF A GARAGE

No. cars now accommodated on same lot ... to be accommodated ... number commercial cars to be accommodated ...
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? ...

APPROVALS BY: DATE MISCELLANEOUS
BUILDING INSPECTION—PLAN EXAMINER ... Will work require disturbing of any tree on a public street? ..
ZONING: ...
BUILDING CODE: ... Will there be in charge of the above work a person competent
Fire Dept.: ... to see that the State and City requirements pertaining thereto
Health Dept.: ... are observed? ..
Others: ...

Signature of Applicant Owen M. Estier Phone # ... same
Type Name of above G. L. Trynor Co. ... 1 [] 2 [] 3 [x] 4 []


FIELD INSPECTOR'S COPY

2A

Other ... and Address ...

Permit No 81/632
Location 5-7 Cherry St
Owner Wabbon-Farhin
Date of permit 7-9-81
Approved _____

NOTES
16-82 work completed



2234

CITY OF PORTLAND, MAINE Application for Permit to Install Wires

Permit No. **57337**

Issued **11-14-68**

Portland, Maine **Nov. 15**, 19 **68**

To the City Electrician, Portland, Maine:

The undersigned hereby applies for a permit to install wires for the purpose of conducting electric current, in accordance with the laws of Maine, the Electrical Ordinance of the City of Portland, and the following specifications:

(This form must be completely filled out — Minimum Fee, \$1.00)

Owner's Name and Address *John Wellen* Tel. _____
 Contractor's Name and Address *United Electric Corp.* Tel. *854-5377*
 Location *5 Cherry St.* Use of Building *Residence*
 Number of Families *3* Apartments _____ Stores _____ Number of Stories *2 1/2*
 Description of Wiring: New Work Additions _____ Alterations _____

Pipe Cable Metal Molding _____ BX Cable _____ Plug Molding (No. of feet) _____
 No. Light Outlets _____ Plugs _____ Light Circuits _____ Plug Circuits _____
 FIXTURES: No. _____ Fluor. or Strip Lighting (No. feet) _____
 SERVICE: Pipe _____ Cauce Underground _____ No. of Wires *3* Size *2/4 1/2*
 METERS: Relocated Added *1* Total No. Meters *3*
 MOTORS: Number _____ Phase _____ H. P. _____ Amps _____ Volts _____ Starter _____
 HEATING UNITS: Domestic (Oil) _____ No. Motors _____ Phase _____ H.P. _____
 Commercial (Oil) _____ No. Motors _____ Phase _____ H.P. _____
 Electric Heat (No. of Rooms) _____

APPLIANCES: No. Ranges _____ Watts _____ Brand Feeds (Size and No.) _____
 Elec. Heaters _____ Watts _____
 Miscellaneous _____ Watts _____ Extra Cabinets or Panels _____
 Transformers _____ Air Conditioners (No. Units) _____ Signs (No. Units) _____
 Will commence *2 1/2* 19 _____ Ready to cover in _____ 19 _____ Inspection *Will call* 19 _____
 Amount of Fee \$ *2.00*

Signed *Robert D. Young*

DO NOT WRITE BELOW THIS LINE

SERVICE <input checked="" type="checkbox"/>	METER	GROUND <input checked="" type="checkbox"/>
VISITS: 1 _____ 2 _____ 3 _____ 4 _____ 5 _____ 6 _____		
7 _____ 8 _____ 9 _____ 10 _____ 11 _____ 12 _____		
REMARKS:		

INSPECTED BY *FW [Signature]*
(OVER)

LOCATION *Cherry St 5*
 INSPECTION DATE *12/5/68*
 WORK COMPLETED *12/5/68*
 TOTAL NO. INSPECTIONS *1*
 REMARKS:

FEEES FOR WIRING PERMITS EFFECTIVE JULY 31, 1963

WIRING

1 to 30 Outlets	\$ 2.00
31 to 60 Outlets	3.00
Over 60 Outlets, each Outlet	.05
(Each twelve feet or fraction thereof of fluorescent lighting or any type of plug molding will be classed as one outlet).	

SERVICES

Single Phase	2.00
Three Phase	4.00

MOTORS

Not exceeding 50 H.P.	3.00
Over 50 H.P.	4.00

HEATING UNITS

Domestic (Oil)	2.00
Commercial (Oil)	4.00
Electric Heat (Each Room)	.75

APPLIANCES

Ranges, Cooking Tops, Ovens, Water Heaters, Disposals, Built-in Dishwashers, Fryers, and any permanent built-in appliance — each unit	1.50
---------------------------------------------------------------------------------------------------------------------------------------	------

MISCELLANEOUS

Temporary Service, Single Phase	1.00
Temporary Service, Three Phase	2.00
Circuits, Carriways, Fairs, etc	10.00
Meters, relocate	1.00
Distribution Cabinet or Panel, per unit	1.00
Transformers, per unit	2.00
Air Conditioners, per unit	2.00
Signs, per unit	2.00

ADDITIONS

5 Outlets, or less	1.00
Over 5 Outlets, Regular Wiring Rates	

PERMIT TO INSTALL PLUMBING

14225

PERMIT NUMBER

Date Issued: 7-10-64
PORTLAND PLUMBING INSPECTOR
 By: J. P. Welch
 Address: 5 Cherry Street
 Installation For: John Pellerin
 Owner of Bldg: John Pellerin
 Owner's Address: Same
 Plumber: Portland Gas Light Company Date: 7-10-64

APPROVED FIRST INSPECTION	NEW	REPL	PROPOSED INSTALLATIONS	NUMBER	FEE
			SINKS		
			LAVATORIES		
			TOILETS		
			BATH TUBS		
			SHOWERS		
			DRAINS		
			HOT WATER TANKS	1	\$ 2.00
			TANKLESS WATER HEATEPS		
			GARBAGE GRINDERS		
			SEPTIC TANKS		
			HOUSE SEWERS		
			ROOF LEADERS (Conn to house drain)		

Date: 7-23-64
 By: J. P. Welch
 APPROVED FINAL INSPECTION
 Date: JOSEPH P. WELCH
CHIEF PLUMBING INSPECTOR

- By: TYPE OF BUILDING
- COMMERCIAL
 - RESIDENTIAL
 - SINGLE
 - MULTI FAMILY
 - NEW CONSTRUCTION
 - REMODELING

PORTLAND HEALTH DEPT. PLUMBING INSPECTION TOTAL ► \$ 2.00

3



FILL IN AND SIGN WITH INK

APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIPMENT

Portland, Maine, November 3, 1955

PERMIT ISSUED 02037 NOV 3-1955 CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location . 5 Cherry St. Use of Building dwelling No. Stories 2 Building Existing "
Name and address of owner of appliance J. LaChance, 5 Cherry St.
Installer's name and address Ballard Oil & Equipment, 135 Marginal Way. Telephone 2-1991.

General Description of Work

To install gravity hot water boiler for oil-firing on present radiation system replacement

IF HEATER, OR POWER BOILER

Location of appliance basement Any burnable material in floor surface or beneath? no
If so, how protected? Kind of fuel? oil
Minimum distance to burnable material, from top of appliance or casing top of furnace 32"
From top of smoke pipe 20" From front of appliance over 4' From sides or back of appliance over 3'
Size of chimney flue 8x8 Other connections to same flue none
If gas fired, how vented? Rated maximum demand per hour 1.0GPH
Will sufficient fresh air be supplied to the appliance to insure proper and safe combustion? yes

IF OIL BURNER

Name and type of burner Ballard Labelled by underwriters' laboratories? yes
Will operator be always in attendance? NO Does oil supply line feed from top or bottom of tank? bottom
Type of floor beneath burner concrete Size of vent pipe 1 1/2"
Location of oil storage basement Number and capacity of tanks 1-275 gal.
Low water shut off Make No.
Will all tanks be more than five feet from any flame? yes How many tanks enclosed? none
Total capacity of any existing storage tanks for furnace burners none

IF COOKING APPLIANCE

Location of appliance Any burnable material in floor surface or beneath?
If so, how protected? Height of Legs, if any
Skirting at bottom of appliance? Distance to combustible material from top of appliance?
From front of appliance From sides and back From top of smokepipe
Size of chimney flue Other connections to same flue
Is hood to be provided? If so, how vented? Forced or gravity?
If gas fired, how vented? Rated maximum demand per hour

MISCELLANEOUS EQUIPMENT OR SPECIAL INFORMATION

Amount of fee enclosed? 2.00 (\$2.00 for one heater, etc., 50 cents additional for each additional heater, etc., in same building at same time.)

APPROVED

Handwritten signature and date 11/3/55

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? YES

Ballard Oil & Equipment

Signature of Installer By: [Handwritten Signature]

INSPECTION COPY

C17-254-1M-MAR22

1-2-56 A3
 Permit No. 55/2057
 Location 5 Cherry St.
 Owner J. La Chance
 Date of permit 11/3/55
 Approved 1-2-56 DMH

1-18-56 but at large
DMH

NOTES

- 1 Fuel Type
- 2 Vent Pipe
- 3 Kind of Heat
- 4 Burner Rigidity & Support
- 5 Name & Label
- 6 Stack Control
- 7 High Limit Control
- 8 Remote Control
- 9 Piping Support & Protection
- 10 Valves in Supply Line
- 11 Capacity of Tanks
- 12 Tank Rigidity & Support
- 13 Tank Inspection
- 14 Oil Gauge
- 15 Instruction Card
- 16 Low Water Shut off

1
 2
 3
 4
 5
 6
 7
 8
 9
 10
 11
 12
 13
 14
 15
 16
 17
 18
 19
 20
 21
 22
 23
 24
 25
 26
 27
 28
 29
 30
 31
 32
 33
 34
 35
 36
 37
 38
 39
 40
 41
 42
 43
 44
 45
 46
 47
 48
 49
 50

Permit No. 55/2057
 Date of Issue 11/3/55
 Issued by DMH

DMT



FILL IN AND SIGN WITH INK

APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIPMENT

PERMIT ISSUED
01978
OCT 31 1952
CITY OF PORTLAND

Portland, Maine, 10/31/52

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 5 Cherry St. Use of Building Dwelling No. Stories 2 New Building
Existing
Name and address of owner of appliance Joseph Falucho
Installer's name and address Falucho Oil Co Telephone 42671

General Description of Work

To install Replace old boiler with a new forced Hot Water Boiler and Oil Burner

IF HEATER, OR POWER BOILER

Location of appliance Basement Any burnable material in floor surface or beneath? Concrete
If so, how protected? _____ Kind of fuel? Oil
Minimum distance to burnable material, from top of appliance or casing top of furnace 3 ft.
From top of smoke pipe 10m ^{with shield} From front of appliance 10 ft. From sides or back of appliance 10-15 ft.
Size of chimney flue 8 X 10 Other connections to same flue No
If gas fired, how vented? _____ Rated maximum demand per hour _____
Will sufficient fresh air be supplied to the appliance to insure proper and safe combustion? _____

IF OIL BURNER

Name and type of burner Fluidheat Pressure Labelled by underwriter's laboratories? Yes
Will operator be always in attendance? No Does oil supply line feed from top or bottom of tank? Bottom
Type of floor beneath burner Concrete
Location of oil storage Basement Number and capacity of tanks 1 - 75
If two 275-gallon tanks, will three-way valve be provided? _____
Will all tanks be more than five feet from any flame? Yes How many tanks fire proofed? _____
Total capacity of any existing storage tanks for furnace burners None

IF COOKING APPLIANCE

Location of appliance _____ Any burnable material in floor surface or beneath? _____
If so, how protected? _____ Kind of fuel? _____
Minimum distance to wood or combustible material from top of appliance _____
From front of appliance _____ From sides and back _____ Front top of smokepipe _____
Size of chimney flue _____ Other connections to same flue _____
Is hood to be provided? _____ If so, how vented? _____ Forced or gravity? _____
If gas fired, how vented? _____ Rated maximum demand per hour _____

MISCELLANEOUS EQUIPMENT OR SPECIAL INFORMATION

Amount of fee enclosed? _____ (\$2.00 for one heater, etc., 50 cents additional for each additional heater, etc., in same building at same time.)

APPROVED:
DR 10-31-52: [Signature]

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? Yes

Signature of Installer

[Signature]
[Signature]

INSPECTION COPY

12.9
11.25 11.17

Permit No. 52/1978 12/17
 Location 5 Cherry St
 Owner Joseph P. Chance
 Date of permit 10/31/52
 Approved 12-22-52 J.P. 119 W

NOTES

11-18-52 Vent pipe 18"
 In defect - 1 of broken
 pipes
 12-22-52 Vent - vent changed
 Call of install an
 in said vent want
 in - changed to 2 1/2"
 10 - removed chimney
 bank

- 1 Full Pipe
- 2 Vent Pipe
- 3 Kind of Heat
- 4 Burner Height & Support
- 5 Name of
- 6 Stack Control
- 7 High Limit Control
- 8 Remot. Control
- 9 1. Reg. no. for
- 10 Valve
- 11 Capacity
- 12 Tank height & diameter
- 13 Tank Distance
- 14 Oil Usage
- 15 Instruction Card
- 16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

52

53

54

55

56

57

58

59

60

61

62

63

64

65

66

67

68

69

70

71

72

73

74

75

76

77

78

79

80

81

82

83

84

85

86

87

88

89

90

91

92

93

94

95

96

97

98

99

100

101

102

103

104

105

106

107

108

109

110

111

112

113

114

115

116

117

118

119

120

121

122

123

124

125

126

127

128

129

130

131

132

133

134

135

136

137

138

139

140

141

142

143

144

145

146

147

148

149

150

151

152

153

154

155

156

157

158

159

160

161

162

163

164

165

166

167

168

169

170

171

172

173

174

175

176

177

178

179

180

181

182

183

184

185

186

187

188

189

190

191

192

193

194

195

196

197

198

199

200



Permit No. _____

APPLICATION FOR PERMIT TO REPAIR BUILDING

Third Class Building

Portland, Maine, November 25, 1928

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.
The undersigned hereby applies for a permit to repair the following described building in accordance with the
Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 7 Cherry Street Ward 7 Within fire limits? No Dist. No. _____
Owner's name and address Martha J. Patterson, 66 Branchell St. Telephone 8327
Contractor's name and address Chas. Howan, 949 Congress St. Telephone _____
Use of building Dwelling house 2 families
No. stories 2 1/2 Height _____ ft., Gross area _____ sq. ft., Style of roof _____
Type of present roof covering _____

General Description of New Work

To repair after fire to former condition No alterations

Around snake pipe in basement

If Roof Covering is to be Repaired or Renewed

When last repaired? _____ Area then repaired _____ sq. ft.
Are repairs or renewal due to damage by fire? Yes If so, what area damaged? _____ sq. ft.
Area of roof to be repaired now? _____ No. plies _____
Type of roofing to be used _____
Trade name and grade of roof covering to be used _____
Estimated cost \$ 6. Fee \$.25

Signature of owner By Martin J. Patterson

INSPECTION COPY

9201

Ward 7 Permit No. 27535
 Location Cherry St.
 Owner Martha Cottler
 Date of permit 11/2/58
 Notif. closing-in _____
 Inspn. closing-in _____
 Final Notif. _____
 Final Inspn. _____
 Cert. of Occupancy issued _____

APPLICATION FOR PERMIT TO REPAIR SURFING

NOTES

~~(This is a duplicate)~~

(Duplicate)

If the work is not completed by the date shown on the permit, the permit will be automatically cancelled.

INDUSTRIAL CODE

Department of Public Works

11/2/58
 Inspector



LIMITED BUSINESS ZONE APPLICATION FOR PERMIT

Permit No. _____

Class of Building or Type of Structure third

Portland, Maine, Aug. 25, 1911

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to ~~erect~~ alter ~~with~~ the following building ~~structure~~ ~~equipment~~ in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any submitted herewith and the following specifications.

Location 5 Cherry St. Within Fire Limits? _____ Dist. No. _____
 Owner's or Lessee's name and address Dr. Herbert J. Patterson Esq., 66 Bramhall St. Telephone _____
 Contractor's name and address W. D. Graham 5 Cherry St. Telephone 2-3070
 Architect _____ Plans filed _____ No. of sheets _____
 Proposed use of building dwelling No. families 2
 Other buildings on same lot _____
 Estimated cost \$ 10. Est. \$ 25

Description of Present Building to be Altered

Material frame No. stories 2 1/2 Heat hot water Style of roof pitch Roofing asphalt
 Last use dwelling No. families 2

General Description of New Work

to cut in new cellar window (side) 22" x 35" for more light

NOTIFICATION BEFORE LETTERS
ON RECORD IN 15 10000

CERTIFICATE OF OCCUPANCY
MENTIONED IN 15 10000

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of _____

Details of New Work

Is any plumbing work involved in this work? no
 Is any electrical work involved in this work? no Height average grade to top of plate _____
 Size, front _____ depth _____ No. stories _____ Height average grade to highest point of roof _____
 To be erected on solid or filled land? _____ earth or rock? _____
 Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
 Material of underpinning _____ Height _____ Thickness _____
 Kind of roof _____ Rise per foot _____ Roof covering _____
 No. of chimneys _____ Material of chimneys _____ of lining _____
 Kind of heat _____ Type of fuel _____ Is gas fitting involved? _____
 Framing lumber—Kind _____ Dressed or full size? _____
 Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____
 Material columns under girders _____ Size _____ Max. on centers _____
 Studs (outside walls and carrying partitions) 2x4-16" O. C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.
 Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
 On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
 Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
 If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____
 Total number commercial cars to be accommodated _____
 Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no
 Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes
 Signature of owner Dr. Herbert J. Patterson Esq.

INSPECTION COPY

Wilford D. Graham

25

Permit No. 411213
 Location 5 Chimney St.
 Owner D. Herbert Patterson lot
 Date of permit 8/25/41
 Notif. closing-in _____
 Inspn. closing-in _____
 Final Notif. _____
 Final Inspn. 9/24/41
 Cert. of Occupancy issued Done

NOTES

NO REVISIONS REQUIRED

C
P.

CITY OF PORTLAND, MAINE

389 CONGRESS STREET
PORTLAND, MAINE 04101
(207) 874-8300



DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

P. SAMUEL KOFFSES, CHIEF
INSPECTION SERVICES DIVISION

7 Cherry Street, Apt 7

8 December 1989

Felix Atienza
PO Box 109
Gorham ME 04038

Dear Mr Atienza:


We recently received a complaint and an inspection was made by Code Enforcement Officer Merle Leary of the property owned by you at 7 Cherry Street, Portland, Maine. As a result of the inspection, you are hereby ordered to correct the following substandard housing conditions:


Interior - Front Bedroom - windows missing cords	108-3
Interior - Kitchen - windows missing cords	108-3
Interior - Rear Bedroom - missing storm window	108-3
Interior - Bathroom - provide ventilation	112
Interior - Front Hall - broken glass in window	108-3

The above mentioned conditions are in violation of Article V of the Municipal Code of the City of Portland, Maine, and must be corrected on or before 1/8/90.

Failure to comply with this order may result in a complaint being filed for prosecution in District Court.

Sincerely yours,
Joseph E Gray, Jr
Director of Planning & Urban Development


P. Samuel Koffses
Chief of Inspection Services


Merle Leary
Code Enforcement Officer

/bm

923927

Permit # 923927 City of Portland BUILDING PERMIT APPLICATION Fee \$50. Zone _____ Map # _____ Lot# _____
Please fill out any part which applies to job. Proper plans must accompany form.

Owner: Felix Y. Atienza Phone # 929-8598
Address: RR3; Box 109-Gorham, ME 04038
LOCATION OF CONSTRUCTION 5-7 Cherry St
Contractor: Dana Louis Sub. _____
Address: _____ Phone # _____
Est. Construction Cost: \$6000 Proposed Use 3-fam- after fire
Past Use 3-fam
of Existing Res. Units _____ # of New Res Units _____
Building Dimensions L _____ W _____ Total Sq Ft _____
Stories: _____ # Bedrooms _____ Lot Size: _____
Is Proposed Use: Seasonal _____ Condominium _____ Conversion _____
Explain Conversion Repairs after fire - 1st floor

For Official Use Only
Date 7/13/92 Subdivision: _____
Name JUL 16 1992
Inside Fire Limits _____ Lot # _____
Bldg Code _____ Ownership: _____ Public _____ Private _____
Time Limit _____
Estimated Cost \$6000
Zoning: R-6
Street Frontage Provided _____ Back _____ Side _____
Provided Setbacks: Front _____
Review Required:
Zoning Board Approval Yes _____ No _____ Date _____
Planning Board Approval Yes _____ No _____ Date _____
Conditional Use: _____ Variance _____ Site Plan _____ Subdivision _____
Shoreland Zoning Yes _____ No _____ Floodplain Yes _____ No _____
Special Exception _____
Other: WPA 7-15-92 **HISTORIC PRESERVATION**
Not in District nor Landmark
Does not require review.

Foundation:
1. Type of Soil _____
2. Set Backs - Front _____ Rear _____ Side(s) _____
3. Footings Size _____
4. Foundation Size _____
5. Other _____

Floor: Sills must be anchored.
1. Sills Size _____
2. Girder Size _____
3. Lally Column Spacing _____ Size: _____
4. Joists Size: _____ Spacing 16" O C
5. Bridging Type _____ Size: _____
6. Floor Sheathing Type: _____ Size: _____
7. Other Material: _____

Exterior Walls:
1. Studding Size _____ Spacing _____
2. No. windows _____
3. No. Doors _____
4. Header Sizes _____ Span(s) _____
5. Bracing: Yes _____ No _____
6. Corner Posts Size _____
7. Insulation Type _____ Size _____
8. Sheathing Type _____ Size _____
9. Siding Type _____ Weather Exposure _____
10. Masonry Materials _____
11. Metal Materials _____

Interior Walls:
1. Studding Size _____ Spacing _____
2. Header Sizes _____ Spacing _____
3. Wall Covering Type _____
4. Fire Wall if required _____
5. Other Materials _____

White - Tax Assessor

Ceiling:
1. Ceiling Joists Size _____ Spacing _____
2. Ceiling Strapping Size _____
3. Type Ceilings _____
4. Insulation Type _____
5. Ceiling Height _____
Roof:
1. Truss or Rafter Size _____
2. Sheathing Type _____
3. Roof Covering Type _____
Chimneys: Type _____ Number of Fire Places _____
Heating: Type of Heat _____
Electrical: Service Entrance Size _____ Smoke Detector Required Yes _____ No _____
Plumbing: Yes _____ No _____
1. Approval of soil test if required _____
2. No. of Tubs or Showers _____
3. No. of Flushes _____
4. No. of Lavatories _____
5. No. of Other Fixtures _____

Swimming Pools:
1. Type: _____ Square Footage _____
2. Pool Size _____
3. Must conform to National, State and Local Codes and State Law.

Permit Received By LOUIS E. ...
Signature of Applicant Felix Y. Atienza II
CEO's District _____
Date 7-13-92

PERMIT ISSUED
WITH REQUIREMENTS

PERMIT ISSUED
WITH REQUIREMENTS
CONTINUED TO REVERSE SIDE
Ivory P...

Mr. Wing

923927

Permit # _____ City of Portland BUILDING PERMIT APPLICATION Fee \$55. Zone _____ Map # _____ Lot # _____

Please fill out any part which applies to job. Proper plans must accompany form.

Owner: Felix Y. Atienza Phone # 929-8397
 Address: RRD; Box 109-Gorham, ME 04038
 LOCATION OF CONSTRUCTION 5-7 Cherry St
 Contractor: Dana Louis Sub: _____
 Address: _____ Phone # _____
 Est. Construction Cost: \$6000 Proposed Use: 3-fam= after fire
 Past Use: 3-fam
 # of Existing Res. Units _____ # of New Res. Units _____
 Building Dimensions L _____ W _____ Total Sq. Ft. _____
 # Stories: _____ # Bedrooms _____ Lot Size: _____
 Is Proposed Use: Seasonal _____ Condominium _____ Conversion _____
 Explain Conversion Repairs after fire - 1st floor

PERMIT ISSUED
 For Official Use Only
 Date: 7/13/92 Subdivision: _____
 Inside Fire Limits: _____ Name: _____
 Bldg Code: _____ Lot: _____
 Time Limit: _____ Ownership: **CITY OF PORTLAND**
 Estimated Cost: \$6000

Zoning: R-10
 Street Frontage Provided: _____
 Provided Setbacks: Front _____ Back _____ Side _____
 Review Required:
 Zoning Board Approval: Yes _____ No _____ Date: _____
 Planning Board Approval: Yes _____ No _____ Date: _____
 Conditional Use: _____ Variance _____ Site Plan _____ Subdivision _____
 Shoreland Zoning Yes _____ No _____ Floodplain Yes _____ No _____
 Special Exception _____ **HISTORIC PRESERVATION**
 Other (Explain) WPA 7-15-92 Not in District nor Landmark

Foundation:
 1. Type of Soil: _____
 2. Set Backs - Front _____ Rear _____ Side(s) _____
 3. Footings Size: _____
 4. Foundation Size: _____
 5. Other _____

Ceiling:
 1. Ceiling Joists Size: _____ Require Review.
 2. Ceiling Strapping Size _____ Spacing _____
 3. Type Ceilings: _____
 4. Insulation Type _____ Act: Approved
 5. Ceiling Height: _____ Approved with Conditions.

Floor:
 1. Sills Size: _____ Sills must be anchored.
 2. Girder Size: _____
 3. Lally Column Spacing: _____ Size: _____
 4. Joists Size: _____ Spacing 16" O.C.
 5. Bridging Type: _____ Size: _____
 6. Floor Sheathing Type: _____ Size: _____
 7. Other Material: _____

Roof:
 1. Truss or Rafter Size _____ Date Span 7-13-92
 2. Sheathing Type _____ Sign Size: PLM/jas
 3. Roof Covering Type _____

Exterior Walls:
 1. Studding Size _____ Spacing _____
 2. No. windows _____
 3. No. Doors _____
 4. Header Sizes _____ Span(s) _____
 5. Bracing: Yes _____ No _____
 6. Corner Posts Size _____
 7. Insulation Type _____ Size _____
 8. Sheathing Type _____ Size _____
 9. Siding Type _____ Weather _____
 10. Masonry Materials _____
 11. Metal Materials _____

Chimneys:
 Type: _____ Number of Fire Places _____
 Heating:
 Type of Heat: _____
 Electrical:
 Service Entrance Size: _____ Smoke Detector Required Yes _____ No _____
 Plumbing:
 1. Approval of soil test if required Yes _____ No _____
 2. No. of Tubs or Showers _____
 3. No. of Flushes _____
 4. No. of Lavatories _____
 5. No. of Other Fixtures _____

Interior Walls:
 1. Studding size _____ Spacing _____
 2. Header Sizes _____ Span(s) _____
 3. Wall Covering Type _____
 4. Fire Wall if required _____
 5. Other Materials _____

Swimming Pools:
 1. Type _____ **PERMIT ISSUED WITH REQUIREMENTS** Square Footage _____
 2. Pool Size _____
 3. Must conform to National Code and State Law.

PERMIT ISSUED WITH REQUIREMENTS

PERMIT ISSUED WITH LETTER

Received By Louise E. Chase
 Signature of Applicant [Signature] Date 7-13-92
 CEO's District Felix Y. Atienza II

CONTINUED TO REVERSE SIDE
 Ivory Tag - CEO WPA W1079

White - Tax Assessor

PLOT PLAN



FEES (Breakdown From Front)

Base Fee \$ 50-
 Subdivision Fee \$ _____
 Site Plan Review Fee \$ _____
 Other Fees \$ _____
 (Explain) _____
 Late Fee \$ _____

Type	Inspection Record	
		Date
_____	_____	____/____/____
_____	_____	____/____/____
_____	_____	____/____/____
_____	_____	____/____/____
_____	_____	____/____/____

COMMENTS

*7/15/97 Inspected lot 2nd + 3rd floor needs fire doors
 went over it with owner agreed they need to escape
 3rd floor egress problem - missing*

CERTIFICATION

Fire doors installed out with Fire Dept.

I hereby certify that I am the owner of record of the named property, or that the proposed work is authorized by the owner of record and that I have been authorized by the owner to make this application as I as authorized agent and I agree to conform to all applicable laws of this jurisdiction. In addition, if a permit for work described in this application is issued, I certify that the code official or the code official's authorized representative shall have the authority to enter areas covered by such permit at any reasonable hour to enforce the provisions of the code(s) applicable to such permit.

SIGNATURE OF APPLICANT

[Handwritten Signature]

ADDRESS

PHONE NO.

929-8598

RESPONSIBLE PERSON IN CHARGE OF WORK, TITLE

PHONE NO

BUILDING PERMIT REPORT

DATE: 7-15-92
ADDRESS: 5-7 Cheng St
REASON FOR PERMIT: make repairs after fire
BUILDING OWNER: Kelie Y. Assenza TR
CONTRACTOR: Dann Lewis
PERMIT APPLICANT: owner
APPROVED: Yes DENIED: →


CONDITIONS OF APPROVAL OR DENIAL

1. All vertical openings shall be enclosed with construction having a fire rating of at least (1)/(2) hour - including fire doors with self closers and fire exit hardware.
2. Each apartment shall have access to two separate, remote and approved means of egress. A single exit is acceptable when it exits directly from apartment to the building exterior with no communications to other apartment units.
3. Each apartment shall be equipped with approved single station smoke detectors powered by the house current. The detectors shall be located in an area which will provide protection for sleeping areas and shall be interconnected within the living unit. An additional smoke detector shall be provided in the sleeping room(s). When activated, the detectors shall initiate an alarm in that sleeping room.
4. The boiler or furnace shall be protected by enclosing with one hour fire rated construction including fire doors and ceiling or by providing automatic extinguishment. Sprinkler piping serving not more than six sprinklers may be connected to a domestic water supply system having a capacity sufficient to provide 0.15 gpm, per square foot of floor throughout the entire area. An INDICATING shut-off valve shall be installed in an accessible location between the sprinkler and the connection to the domestic water supply. Minimum pipe size shall be 3/4 inch copper or 1 inch steel. Maximum coverage area of a residential sprinkler is 144 square feet per sprinkler.
5. Comply with letter of Complaint from the Fire Dept Sent on 7-15-92 See attached copy

RECEIVED

JUL 13 1992

DEPT OF BUILDING INSPECTIONS
CITY OF PORTLAND



Minor Fire damage to
2nd Cellar stairway opening.
Ok'd by M. Wing

Inspection Services
P. Samuel Hoffses
Chief



Planning and Urban Development
Joseph E. Gray Jr.
Director

SEPTEMBER 05, 1996

CITY OF PORTLAND

ATIENZA FELIX Y JR
RR 3 BOX 109
GORHAM ME 04038

Re: 5-7 CHERRY ST
CBL: 065- - A-006-001-01
DU: 3

Dear Mr. Atienza:

You are hereby notified, as owner or agent, that an inspection was made of the above-referenced property. Violations of Article V of the Municipal Ordinance (Housing Code) were found as described in detail on the attached "Housing Inspections Report".

In accordance with the provisions of the above-mentioned Code, you are hereby ordered to correct those defects within sixty (60) days. If you are unable to make such repairs within the specified time, you may contact this office to arrange a satisfactory repair schedule. If we do not hear from you within ten (10) days from this date, we will assume the repairs to be in progress and, on reinspection within the time set forth above, will anticipate that the premises have been brought into compliance with the Housing Code Standards.

Please Note: You should consult this department to insure that any corrective action you should undertake complies with the building, plumbing, electrical, zoning and other Articles of the City Code.

Please contact this office if you have any questions regarding this order.

Your cooperation will aid this department in its goal to maintain decent, safe, and sanitary housing for all of Portland's residents.

Sincerely,

Marland Wing
Code Enforcement Officer

Tammy Munson
Code Enfc Offr / Field Supv.

HOUSING INSPECTION REPORT

Location: 5-7 CHERRY ST
Housing Conditions Date: September 5, 1996
Expiration Date: November 4, 1996

Items listed below are in violation of Article V of the Municipal Codes, "Housing Codes", and must be corrected before the expiration date:

1. EXT - REAR PORCH - 108.40
SUPPORTS ARE SAGGING
2. EXT - REAR PORCH - 108.40
BOARDS ARE ROTTED
3. EXT - REAR PORCH - 108.40
STAIRS HAVE A BROKEN TREAD
4. INT - CELLAR - 109.40
THERE IS AN ACCUMULATION OF MISCELLANEOUS DEBRIS
5. INT - 3RD FLR - FRONT HALL 108.40
STAIRS ARE MISSING A HANDRAIL
6. INT - 2ND FLR - FRONT HALL 113.50
CEILING HAS A LOOSE LIGHT FIXTURE
7. EXT - 2ND FLR - REAR PORCH 108.40
DECK HAS A BROKEN SAFETY RAIL
8. INT - 2ND FL - APT #2 - KITCHEN 108.20
CEILING HAS A POSSIBLE LEAK
9. INT - 2ND FL - APT #2 - DINING ROOM 108.30
WINDOW HAS A BROKEN SCREEN
10. INT - 2ND FL - APT #2 - REAR BEDROOM 108.20
WALL HAS LOOSE PLASTER
11. INT - 2ND FL - APT #2 - KITCHEN 113.50
CEILING HAS AN INOPERATIVE LIGHT FIXTURE
12. INT - 2ND FL - APT #2 - LIVING ROOM 108.30
WINDOW IS MISSING COUNTER-BALANCE CORDS