

CERTIFICATE

0 F

COMPLIANCE

May 21, 1970

CITY OF PORTLAND Health Department - Housing Division Tel. 774-8221 Ext. 226

Mr. Donald Kirkpatrick 41 Bowdoin Street Portland, Maine 04102

Re: Premises located at 41 Bondoin Street, Portland, Maine

Dear Mr. Kirkpotrick:

A re-inspection of the premises nated above was made on May 21, 1970 by the Housing Inspection Division.

This is to certify that you have complied with our request to correct the violations of Municipal Codes relating to housing conditions described in our Notice of Housing Conditions dated May 28, 1909

Thank you for your cooperation and your efforts to help us maintain decent, safe and sanitary housing for all Portland residents.

Please feel free to call on us if we can be of further service to you.

Very truly yours,

Arthur A. Hughson, CPH, MPH Health Director

By Housing Inspection Supervisor

GITY OF PORTLAND HEALTH DEPARTMENT HOUSING DIVISION



Loc. 41 Bowdoin Street Loc w/1 S Bldg X Fire Elec Other X Issued May 20, 1969 Expires June 28, 1969

Mr. Donald Kirkpatrick 41 Bowdoin Street Portland, dine 04102

May 21, 1969

Offici 7731741

an examination was made of the premises located

41 Bowdoin Street, Portland, Maine

Non-compliance with the ordinances relating to housing conditions was found as detailed below. In accordance with the provisions of the above ordinance, you are hereby ordered to correct these defects according to specifications within the time limits allowed. Failure to comply with this notice will necessitate legal action.

Some repairs or improvements required will necessitate permits which are to be obtained from the Building Inspector, Health, Fire or other City Departments. These must be obtained before the work is started.

If any additional information is desired, visit or telephone the Housing Supervisor at this Office, Tel. 774-8221, extension 226. Kindly notify this office as soon as all corrections

Very truly yours, Health Director

Housing Supervisor

VIOLATIONS & SPECIFICATIONS

Responsibility of Owner or Agent ** Responsibility of Occupant

STRUCTURAL Put in good order all deteriorated end hazardous parts of the atructure as follows: Repair CA Replace -

The losse, wern, deteriorated and hazardous parts of the outside purches.

Incluses, worn or missing drainpipes and gutter at the rear of the structure.

The worn, deteriorated fascia board and trim at the rear of the garage. In the rear of the garage.

In the cellarway.

In losse, cracked or missing plaster on the wall in the cellarway.

Incloses, cracked or missing plaster on the celling of the dining room,

living room and left rear bedroom.

Voint up the loose joints on the foundation around the cellar window cosing.

-00-

theck and have repaired all defective plumbing and plumbing fixtures throughout the

Determine the record and recedy the condition which causes the drain to leak in the second floor bothroom.

nuistaces And insanitary compilions

a. Aid the premises of all infestation. We suggest that you procure the services of a competent pest control operator registered with this Department to do

The above mentioned conditions are in violation of Chapter 307 of the Municipal Code of the City of Portland and must be corrected on or before June 28, 1969.

RECEIVED

MAY 29 1969

Bramhall Hill Neighborhood Conservation Program

41 Bowdoln Street - continued

As a result of our inspection, the following items were found to be inclpient violations — they are not violations at this ${\mathbb N}^2$, but could become true violations in possibly a year or two.

a. Slight cracks in exterior stucco siding.
 b. We suggest that you make the exterior trim of the structure weathertight and watertight by valuting or any other suitable means.

Owner Address Owner Address DATE REMARKS 9-23-69 11-7-69 2-6-70