

PERMIT TO INSTALL PLUMBING  
 Great Diamond Island  
 Address **83-A-F 1,2,3 Bay Ave.** PERMIT NUMBER **0519**

Date Issued \_\_\_\_\_  
 Portland Plumbing Inspector  
 By **ERNOLD R GOODWIN**

App. First Insp. \_\_\_\_\_  
 Date \_\_\_\_\_  
 By \_\_\_\_\_  
 App. Final Insp. \_\_\_\_\_  
 Date \_\_\_\_\_  
 By \_\_\_\_\_

- Type of Bldg.
- Commercial
  - Residential
  - Single
  - Multi Family
  - New Construction
  - Remodeling

NEW	REPL		QTY	FEE
		SINKS		
		LAVA CRIES		
		TOILETS		
		BATH TUBS		
		SHOWERS		
		DRAINS FLOOR SURFACE		
		HOT WATER TANKS		
		TANKLESS WATER HEATERS		
		GARBAGE DISPOSALS		
1		SEPTIC TANKS & leaching	1	25.00
		HOUSE SEWERS		
		ROOF LEADERS		
		AUTOMATIC WASHERS		
		DISHWASHERS		
		OTHER		
		base fee		3.00
			TOTAL	28.00

Building and Inspection Services Dept. Plumbing Inspection

MAINE DEPARTMENT OF HEALTH AND WELFARE  
APPLICATION FOR PRIVATE SEWAGE DISPOSAL PERMIT

NAME: Portland (For system discharging into less than 1000 gallons per day)

STREET, ROAD, ETC.: 111 West 1st Street, Portland, ME

OWNER'S ADDRESS: 111 West 1st Street, Portland, ME 04101

OWNER'S NAME: William F. H. H.

OWNER'S SIGNATURE: William F. H. H.

DATE: 11-15-76

PERMIT NO.: 0519

DATE: 11/15/76

SITE OF LOT: 44,222

TOTAL AREA: 8 Sq Feet

TYPE OF ZONING: Residential

IF YOU PLAN TO USE A PREVIOUS SUBDIVISION APPROVAL IN THE COURSE OF THIS INVESTIGATION, PLEASE ADVISE ONE OF THE FOLLOWING:

Dead restriction re private sewage disposal

Copy of the subdivision soil report

Soil report from a State Agency

APPLICANT'S ADDRESS: 111 West 1st Street, Portland, ME

APPLICANT'S SIGNATURE: William F. H. H.

DATE: 11-15-76

LOT NO.: 03A-F

1, 2, 3

THIS IS NOT A PERMIT; THE FORM WHEN COMPLETED MUST BE PRESENTED TO THE LOCAL PLUMBING INSPECTOR TO OBTAIN A PERMIT.

PAGE 1 OF 2

**SITE INVESTIGATION** Show location, pits and/or borings on sketch on page 2, and refer to completed sample form and Chapter 4 of the Code, II.

Soil Profile No.	Soil Profile No.	Soil Profile No.	Soil Profile No.
1	2	1a	1b
Organic strata 0" 1st strata 13" 2nd strata 10" to 12" 5th coarse 4 1/2"	Organic strata 0" 1st strata 18" FSL 2nd strata 18" FSL 3rd strata 18" FSL	Organic strata 0" 1st strata 16" 2nd strata 18" FSL 3rd strata 18" FSL	Organic strata 0" 1st strata 16" 2nd strata 18" FSL 3rd strata 18" FSL
Total Depth of observation hole inches: <u>56"</u> Max. Ground water table: <u>16"</u> Impervious layer, etc.: <u>None Evident</u>	Total Depth of observation hole inches: <u>48"</u> Max. Ground water table: <u>92"</u> Impervious layer, etc.: <u>None Evident</u>	Total Depth of observation hole inches: <u>48"</u> Max. Ground water table: <u>92"</u> Impervious layer, etc.: <u>None Evident</u>	Total Depth of observation hole inches: <u>48"</u> Max. Ground water table: <u>92"</u> Impervious layer, etc.: <u>None Evident</u>

Soil Group & Condition per Table 9-1 of the Code, II: C-8

Soil Group & Condition per Table 9-1 of the Code, II: C-3

Soil Group & Condition per Table 9-1 of the Code, II: C-3

Soil Group & Condition per Table 9-1 of the Code, II: C-3

**PRIVATE-SEWAGE DISPOSAL SYSTEM PROPOSED** Show location of system and details on sketch on page 2, and refer to completed sample form.

Soil Group & Condition per Table 9-1 of the Code, II: C-8

Soil Group & Condition per Table 9-1 of the Code, II: C-3

Soil Group & Condition per Table 9-1 of the Code, II: C-3

Soil Group & Condition per Table 9-1 of the Code, II: C-3

**PROPERTY/LOT LOCATION MAP**

**FOR THE USE OF THE PERMIT ONLY**

Application is denied for following reasons, position of the Code II are cited:

General info.  System Proposed,  Site Investigation,  Cross-Section,  Statement,  Section 23,  Section 45 and 55, Table 9-1 Group,  System Proposed,  Section 43, 49, 99, Table 9-1,  Site Investigation,  Indenture,  Modifications are necessary,  Use Stations  43  44  48  07,  Miscellaneous  Application for permit is approved  with condition specified,  comply with Section  without condition,  Signed DP William F. H. H. Date 11/15/76 HHE-200 7174

**SEWERAGE SYSTEM**

Combined System

Separated System—Type of human waste disposal system to be used:

Sewer Vent Fly

Open Fly

Closed Toilet

Incinerator Toilet

Other: \_\_\_\_\_

Other, describe \_\_\_\_\_

**SEWERAGE SYSTEM**

Combined System

Separated System

Sewer Tank

Arched Tank

Manufacturer—None

Model No. \_\_\_\_\_

Sew in gallons \_\_\_\_\_

**SEWERAGE SYSTEM**

Trench System

Bed Slope \_\_\_\_\_

Length \_\_\_\_\_

Width \_\_\_\_\_

Non-damage System

Holding Tank Site \_\_\_\_\_

Gal. \_\_\_\_\_

Manufacturer \_\_\_\_\_

**SEWERAGE SYSTEM**

Trench System

Bed Slope \_\_\_\_\_

Length \_\_\_\_\_

Width \_\_\_\_\_

Non-damage System


Holding Tank Site \_\_\_\_\_

Gal. \_\_\_\_\_

Manufacturer \_\_\_\_\_

DUPLICATE - To be retained by the Plumbing Inspector  
MAINE DEPARTMENT OF HEALTH AND WELFARE  
APPLICATION FOR PRIVATE SEWAGE DISPOSAL PERMIT  
(For systems disposing of less than 2000 gallons per day)

Town: Deer Island Street, Road, etc.: 1000 1/2 St Owner of place: Michael J. Leves  
If of "Water Body, Great Pond": None



Subsurface Absorption Area Cross-section

Scale: Vertical - 1" = 5' or 5'  
Horizontal - 1" = 20' or 25'

Statement: (no permit may be issued unless applicant certifies that all information and plans submitted by the applicant, I also understand that issuance of a permit is contingent upon the information and plans submitted by the applicant, I also understand that the permit is valid for a six (6) month period, approval given by the Administrative Authority of its agent.

Date: X 11/13/74 Signature: Robert G. [Signature]  
Applicant: [Signature]  
Owner: X [Signature]

MHE-200 774

# CITY OF PORTLAND, MAINE

## Application for Permit to Install Wires

Permit No. 59059  
 Issued 7/10/22  
 Portland, Maine 1922

To the City Electrician, Portland, Maine:  
 The undersigned hereby applies for a permit to install wires for the purpose of conducting electric current, in accordance with the laws of Maine, the Electrical Ordinance of the City of Portland, and the following specifications:

(1) form must be completely filled out - Minimum Fee, \$1.00  
 Contractor's Name and Address Mrs. Sylvia B. G. Gidycz / 7 Portland / 1922  
 Location 1001 Broadway / 2nd Floor / Use of Building  
 Number of Families 1 Apartments 1 Stores 0 Number of Stories 2  
 Description of Wiring: New Work Plumbing Alterations 0

Pipe 0 Cable 0 Metal Molding 0 BX Cable 0 Plug Molding (No. of feet) 0  
 No. Light Outlets 0 Plugs 0 Light Circuits 0 Plug Circuits 0  
 FIXTURES: No. 0 Underground 0 Floor or Strip Lighting (No. feet) 0 No. of Wires 3 Size 12  
 SERVICE: Pipe 0 Cable 0 Added 0 Total No. Meters 0  
 METERS: Relocated 0 H. P. 0 Amps 0 Volts 0 Starter 0  
 MOTORS: Number 0 Phase 0 No. Motors 0 Phase 0 H.P. 0  
 HEATING UNITS: Domestic (Oil) 0 No. Motors 0 Phase 0 H.P. 0  
 Commercial (Oil) 0  
 Electric Heat (No. of Rooms) 0 Brand Feeds (Size and No.) 0  
 APPLIANCES: No. Ranges 0 Warts 0 Extra Cabinets or Panels 0  
1 Elec. Heaters 0 Warts 0 4500  
 Miscellaneous 0  
 Transformers 0 Air Conditioners (No. Units) 0 Signs (No. Units) 0  
 Will commence July ready to cover in 19 Inspection July 14 1922  
 Amount of Fee \$ 3 Signed E E Carter

DO NOT WRITE BELOW THIS LINE

SERVICE	METER	GROUND
VISITS: 1	2	3
2	3	4
3	4	5
4	5	6
5	6	7
6	7	8
7	8	9
8	9	10
9	10	11
10	11	12
11	12	13
12	13	14
13	14	15
14	15	16
15	16	17
16	17	18
17	18	19
18	19	20
19	20	21
20	21	22
21	22	23
22	23	24
23	24	25
24	25	26
25	26	27
26	27	28
27	28	29
28	29	30
29	30	31
30	31	32
31	32	33
32	33	34
33	34	35
34	35	36
35	36	37
36	37	38
37	38	39
38	39	40
39	40	41
40	41	42
41	42	43
42	43	44
43	44	45
44	45	46
45	46	47
46	47	48
47	48	49
48	49	50
49	50	51
50	51	52
51	52	53
52	53	54
53	54	55
54	55	56
55	56	57
56	57	58
57	58	59
58	59	60
59	60	61
60	61	62
61	62	63
62	63	64
63	64	65
64	65	66
65	66	67
66	67	68
67	68	69
68	69	70
69	70	71
70	71	72
71	72	73
72	73	74
73	74	75
74	75	76
75	76	77
76	77	78
77	78	79
78	79	80
79	80	81
80	81	82
81	82	83
82	83	84
83	84	85
84	85	86
85	86	87
86	87	88
87	88	89
88	89	90
89	90	91
90	91	92
91	92	93
92	93	94
93	94	95
94	95	96
95	96	97
96	97	98
97	98	99
98	99	100

REMARKS: \_\_\_\_\_  
 INSPECTED BY \_\_\_\_\_ (OVER)