

NEW ISLAND AVENUE PEAKS ISLAND
84-C-9





APPLICATION FOR PERMIT

Class of Building - Type of Structure Third Class
Portland, Maine, June 8, 1937

PERMIT ISSUED
00421
JUN 9 1937
CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location New Island Ave., Peaks Island (84-C-9) Within Fire Limits? _____ Dist. No. _____

Owner's name and address Daniel Tuttle, 5 Tremont St., So. Port. Telephone 772-4059
former owner Lopez

Lessee's name and address _____ Telephone _____

Contractor's name and address CMR Telephone _____

Architect _____ Specifications _____ No. of sheets _____

Proposed use of building Cottage No. families _____

Last use _____ No. families _____

Material frame No. stories _____ Heat _____ Style of roof _____ Roofing _____

Other buildings on same lot _____

Estimated cost \$ 200. Fee \$ 3.00

General Description of New Work

To change out ~~fix~~ existing cedar post foundation under front porch to concrete block foundation down to ledge

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. **PERMIT TO BE ISSUED TO owner**

Details of New Work

Is any plumbing involved in this work? _____ Is any electrical work involved in this work? _____

Is connection to be made to public sewer? _____ If not, what is proposed for sewage? _____

Has septic tank notice been sent? _____ Form notice sent? _____

Height average grade to top of plate _____ Height average grade to highest point of roof _____

Size, front _____ depth _____ No. stories _____ so'd or filled land? _____ earth or rock? _____

Material of foundation _____ Thickness, top _____ bottom _____ cellar _____

Kind of roof _____ Rise per foot _____ Roof covering _____

No. of chimneys _____ Material of chimneys _____ of lining _____ Kind of heat _____ fuel _____

Framing Lumber--Kind _____ Dressed or full size? _____ Corner post _____ Sills _____

Size Girder _____ Columns under girders _____ Size _____ Max. on centers _____

Studs (outside walls and carrying partitions); 2x4-16" O. C Bridging in every floor and flat roof span over 8 feet.

Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____

On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____

Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____

If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____ number commercial cars to be accommodated _____

Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

APPROVED:

C. H. 618167 - R. H. H.

Miscellaneous

Will work require disturbing of any tree on a public street? No _____

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? Yes

INSPECTION COPY

Signature of owner Daniel Tuttle

ph

Under
Island Ave. (84-c-9)

Permit No. 67/441

Location Mar. Club in front of Club

Owner Harold Little

Date of permit 6/9/67

Notif. closing-in

Inspn. closing-in

Final Notif.

Final Inspn.

Cert. of Occupancy issued

Staking Out Notice

Form Check Notice

NOTES

7-8-67 Excavation to
ledge. Right side footing
in RD
9-15-67 Completed RD

X