

CITY OF PORTLAND, MAINE
MEMORANDUM

TO: Arthur Rowe, Environmental Health Inspector
FROM: Ernold Goodwin, Chief of Plumbing Inspections
SUBJECT: Malfunction of Cesspool, Peaks Island

DATE: 8-9-82

Upon your request to investigate a malfunction of a cesspool at the residence of Ruth W. Craig, Whitehead Street, Peaks Island, Lot 84-N-37 of the City Assessors lot plan.

On Friday afternoon, August 6, 1982 I made 3 calls to this property to talk with the owner of this property on my second call I left my calling card requesting a call from her to help solve this malfunction situation. I did find that the sewage from her residence coming to the top of the ground at the right hand side of building the approximately 3/4 of the length of the building. This can be remedied by covering properly a cover over same and 6" to 8" of soil or gravel over same.

As it is now this is definately a health hazard to the owner as well as the neighbors.

Ernold Goodwin, R.S.
Chief of Plumbing Inspections

File

Peaks Island

Whitehead 84 N 37