

OAKLAND AVE., PEAKS ISLAND

84-2-6



APPLICATION FOR PERMIT

PERMIT ISSUED
Permit No. 0429

Class of Building or Type of Structure Third Class

MAY 18 1944

Portland, Maine, May 16, 1944

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect alter install the following building structure equipment in accordance with the Laws of the State of Maine the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location: Oakland Avenue, Peaks Island Within Fire Limits? no Dist. No. _____
 Owner's or Lessee's name and address: Marie O. Farr, 261 Brackett St. Telephone 2-9178
 Contractor's name and address: J. J. J. J. Telephone _____
 Architect: _____ Plans filed no No. of sheets _____
 Proposed use of building: Cottage "Glen" No. families _____
 Other buildings on same lot: none
 Estimated cost \$ 30. Fee \$.50

Description of Present Building to be Altered

Material wood No. stories 1 1/2 Heat _____ Style of roof _____ Roofing _____
 Last use cottage No. families _____

General Description of New Work

To glass in existing rear porch
 Piazza existing with roof over same prior to Dec. 5, 1938
 More than half of the area of the vertical enclosing walls will consist of window sash or glass area of doors

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

Details of New Work

Is any plumbing work involved in this work? _____
 Is any electrical work involved in this work? _____ Height average grade to top of plate _____
 Size, front _____ depth _____ No. stories _____ Height average grade to highest point of roof _____
 To be erected on solid or filled land? _____ earth or rock? _____
 Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
 Material of underpinning _____ Height _____ Thickness _____
 Kind of roof _____ Rise per foot _____ Roof covering _____
 No. of chimneys _____ Material of chimneys _____ of lining _____
 Kind of heat _____ Type of fuel _____ Is gas fitting involved? _____
 Framing lumber--Kind _____ Dressed or full size? _____
 Corner posts _____ Sills _____ Girt or ledger _____ Size _____
 Material columns under girders _____ Size _____ Max. on centers _____
 Studs (outside walls and carrying partitions) 2x4-10" O. C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 7 feet. Sills and corner posts all one piece in cross section.
 Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
 On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
 Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
 If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____
 Total number commercial cars to be accommodated _____
 Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no
 Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes
 Signature of owner By Marie O. Farr

INSPECTION COPY

48292



APPLICATION FOR PERMIT

PERMIT ISSUED
Permit No. 0007

Class of Building or Type of Structure Third Class

MAY 7 1941

Portland, Maine, May 7, 1941

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect alter install the following building ~~and~~ equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted, herewith and the following specifications:

Location Oakland Avenue, Peck's Island Within Fire Limits? no Dist. No. _____

Owner or Lessee's name and address Elizabeth W. Lyons, 20 Pine St. Lewiston Telephone _____

Contractor's name and address H. W. Stephenson, Elizabeth St. Peck's Telephone 2622

Architect _____ Plans filed no No. of sheets _____

Proposed use of building Cottage No. families _____

Other buildings on same lot _____ Fee \$ 25

Estimated cost \$0 _____

Description of Present Building to be Altered

Material wood No. stories 2 Heat _____ Style of roof _____ Roofing _____

Last use Cottage No. families _____

General Description of New Work

To cut in two small windows in westerly gable end, second floor.

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

Details of New Work

CERTIFICATE OF NON-APPLICABILITY OF REQUIREMENTS IS WAIVED

Is any plumbing work involved in this work? _____

Is any electrical work involved in this work? _____ Height average grade to top of plate _____

Size, front _____ depth _____ No. stories _____ Height average grade to highest point of roof _____

To be erected on solid or filled land? _____ earth or rock? _____

Material of foundation _____ Thickness top _____ bottom _____ cellar _____

Material of underpinning _____ Height _____ Thickness _____

Kind of roof _____ Rise per foot _____ Roof covering _____

No. of chimneys _____ Material of chimneys _____ of lining _____

Kind of heat _____ Type of fuel _____ Is gas fitting involved? _____

Framing lumber—Kind _____ Dressed or full size? _____

Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____

Material columns under girders _____ Size _____ Max. on centers _____

Studs (outside walls and carrying partitions) 2x4-16 C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.

Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____

On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____

Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____

If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____ to be accommodated _____

Total number commercial cars to be accommodated _____

Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Signature of owner _____

Elizabeth W. Lyons
by *David P. Lyons*

INSPECTION COPY

Permit No. 41607

Location: Oakland Ave. Pealer

Owner: Elizabeth W. Lyons

Date of permit: 5/7/41

Notif. closing-in

Inspn. closing-in

Final Notif.

Final Inspn. 8/4/41. OK

Cert. of Occupancy issued *[Signature]*

NOTES

