

MAPLE ST., PEAKS ISLAND

65-F-20



(A) APARTMENT HOUSE ZONE  
APPLICATION FOR PERMIT

Class of Building or Type of Structure Third Class

Portland, Maine, Sept. 13, 1947

PERMIT 155040  
02343

SEP 15 1947

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE.

The undersigned hereby applies for a permit to ~~erect~~ alter ~~or~~ ~~rebuild~~ ~~or~~ ~~reconstruct~~ the following building ~~structure~~ ~~equipment~~ ~~or~~ ~~improvement~~ in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location Maple Street, Peaks Island Within Fire Limits? no Dist. No. \_\_\_\_\_  
Owner's name and address Ernest Vourgarakis, Maple St., Peaks Island Telephone 2-59-5  
Lessee's name and address \_\_\_\_\_ Telephone \_\_\_\_\_  
Contractor's name and address Owner Telephone \_\_\_\_\_  
Architect \_\_\_\_\_ Specifications \_\_\_\_\_ Plans \_\_\_\_\_ No. of sheets \_\_\_\_\_  
Proposed use of building Dwelling house No. families 1  
Last use \_\_\_\_\_ " " No. families 1  
Material wood No. stories 2 Heat \_\_\_\_\_ Style of roof \_\_\_\_\_ Roofing \_\_\_\_\_  
Other buildings on same lot none Fee \$ 1.00  
Estimated cost \$ 350

INSPECTION NOT COMPLETED General Description of New Work

To enclose existing one-story side and front piazza.  
Piazza existing with roof over same prior to Dec. 5, 1938. More than half of the area  
of the vertical enclosing walls will consist of window sash or glass area of doors.

NOTIFICATION BEFORE LATHING  
OR CLOSING-IN IS WAIVED

CERTIFICATE OF OCCUPANCY  
REQUIREMENT IS WAIVED

85-F-20

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

Details of New Work

Is any plumbing involved in this work? \_\_\_\_\_ Is any electrical work involved in this work? \_\_\_\_\_  
Height average grade to top of plate \_\_\_\_\_ Height average grade to highest point of roof \_\_\_\_\_  
Size, front \_\_\_\_\_ depth \_\_\_\_\_ No. stories \_\_\_\_\_ solid or filled land? \_\_\_\_\_ earth or rock? \_\_\_\_\_  
Material of foundation \_\_\_\_\_ Thickness, top \_\_\_\_\_ bottom \_\_\_\_\_ cellar \_\_\_\_\_  
Material of underpinning \_\_\_\_\_ Height \_\_\_\_\_ Thickness \_\_\_\_\_  
Kind of roof \_\_\_\_\_ Rise per foot \_\_\_\_\_ Roof covering \_\_\_\_\_  
No. of chimneys \_\_\_\_\_ Material of chimneys \_\_\_\_\_ of lining \_\_\_\_\_ Kind of heat \_\_\_\_\_ fuel \_\_\_\_\_  
Framing lumber—Kind \_\_\_\_\_ Dressed or full size? \_\_\_\_\_  
Corner posts \_\_\_\_\_ Sills \_\_\_\_\_ Girt or ledger board? \_\_\_\_\_ Size \_\_\_\_\_  
Girders \_\_\_\_\_ Size \_\_\_\_\_ Column under girders \_\_\_\_\_ Size \_\_\_\_\_ Max. on centers \_\_\_\_\_  
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.  
Joists and rafters: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
On centers: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
Maximum span: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, height? \_\_\_\_\_  
If one story building with masonry walls, thickness of walls? \_\_\_\_\_

If a Garage

No. cars now accommodated on same lot \_\_\_\_\_, to be accommodated \_\_\_\_\_ number commercial cars to be accommodated \_\_\_\_\_  
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? \_\_\_\_\_

Miscellaneous

Will work require disturbing of any tree on a public street? no  
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

APPROVED:

Signature of owner

Ernest Louis Vourgarakis

INSPECTION COPY

Permit No. 47/2343

Location Maple St. Peaks Island

Owner Ernest Youngsackis

Date of permit 9/15/47

Notif. closing-in

Inspn. closing-in

Final Notif.

Final Inspn.

Cert. of Occupancy issued

NOTES

INSPECTION NOT COMPLETED



Permit No. 12291  
**PERMIT ISSUED**  
**APPLICATION FOR PERMIT TO REPAIR BUILDING**

Third Class Building

SEP 21 1940

Portland, Maine, September 21, 1940

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to repair the following described building in accordance with the  
Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location Seaboard Avenue, Peaks Island Within fire limits? no Dist. No. \_\_\_\_\_  
Owner's name and address Mrs. G. Waldron Smith, Peaks Island Telephone \_\_\_\_\_  
Contractor's name and address Henry S. Horr, Peaks Island Telephone 167-4  
Use of building Cottage  
No. stories 1 1/2 Style of roof pitch Type of present roof covering asphalt roofing

**General Description of New Work**

To cover all roof

**If Roof Covering is to be Repaired or Renewed**

Is any plumbing work involved in this work? \_\_\_\_\_ Is any electrical work involved in this work? \_\_\_\_\_  
Are repairs or renewal due to damage by fire? no If so, what area damaged? \_\_\_\_\_ sq. ft.  
Area of roof to be repaired now? all roof \_\_\_\_\_ sq. ft.  
Type of roofing to be used asphalt roofing Class C Und. Lb. No. plies \_\_\_\_\_  
Trade name and grade of roof covering to be used Class C Und. Lb.  
Estimated cost \$ \_\_\_\_\_ Fee \$ .50

Signature of owner By: Mrs. G. Waldron Smith

INSPECTION COPY

779/24

Permit No. 40/1391

Location Seashore Dr, Sealbeach

Owner Mr. H. Walden Smith

Date of permit 9/21/40

Notif. closing-in

Inspn. closing-in

Final Notif

Final Inspn.

Cert. of Occupancy issued None

NOTES



(A) APAR 111

ZONE 11111 ISSUED

Permit No. 0281  
JAN 24 1932

## APPLICATION FOR PERMIT

Class of Building or Type of Structure Third ClassPortland, Maine, March 24, 1932

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to ~~erect~~ alter ~~install~~ the following building ~~structure~~ equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location Marle Street, Peaks Ward 1st, 2 Within Fire Limits? no Dist. No. \_\_\_\_\_  
Owner's name and address Mrs. O. Waldron On th, Peaks Telephone \_\_\_\_\_  
Contractor's name and address Z. H. Weaver Sargent Road, Peaks Telephone 222  
Architect's name and address \_\_\_\_\_  
Proposed use of building Cottage No. families \_\_\_\_\_  
Other buildings on same lot \_\_\_\_\_  
Plans filed as part of this application? no No. of sheets \_\_\_\_\_  
Estimated cost \$ 150. Fee \$ .75

## Description of Present Building to be Altered

Material wood No. stories 1 1/2 Heat \_\_\_\_\_ Style of roof \_\_\_\_\_ Roofing \_\_\_\_\_  
Last use Cottage No. families \_\_\_\_\_

## General Description of New Work:

To glass in one story front piazza

Piazza existing with roof over same prior to Dec. 6, 1926

NOTIFICATION BEFORE LATHING  
OR CLOSING IN IS WAIVED.CERTIFICATE OF OCCUPANCY  
REQUIREMENT IS WAIVED.

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

## Details of New Work

Size, front \_\_\_\_\_ depth \_\_\_\_\_ No. stories \_\_\_\_\_ Height average grade to top of plate \_\_\_\_\_  
To be erected on solid or filled land? \_\_\_\_\_ earth or rock? \_\_\_\_\_ Height average grade to highest point of roof \_\_\_\_\_  
Material of foundation \_\_\_\_\_ Thickness, top \_\_\_\_\_ bottom \_\_\_\_\_  
Material of underpinning \_\_\_\_\_ Height \_\_\_\_\_ Thickness \_\_\_\_\_  
Kind of Roof \_\_\_\_\_ Rise per foot \_\_\_\_\_ Roof covering \_\_\_\_\_  
No. of chimneys \_\_\_\_\_ Material of chimneys \_\_\_\_\_ of lining \_\_\_\_\_  
Kind of heat \_\_\_\_\_ Type of fuel \_\_\_\_\_ Is gas fitting involved? \_\_\_\_\_  
Corner posts \_\_\_\_\_ Sills \_\_\_\_\_ Girt or ledger board? \_\_\_\_\_ Size \_\_\_\_\_  
Material columns under girders \_\_\_\_\_ Size \_\_\_\_\_ Max. on centers \_\_\_\_\_  
Studs (outside walls and carrying partitions) 2x4-16" O. C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.  
Joists and rafters: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
On centers: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
Maximum span: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
If one story building with masonry walls, thickness of walls? \_\_\_\_\_ height? \_\_\_\_\_

## If a Garage

No. cars now accommodated on same lot \_\_\_\_\_, to be accommodated \_\_\_\_\_  
Total number commercial cars to be accommodated \_\_\_\_\_  
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? \_\_\_\_\_

## Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no  
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

INSPECTION COPY

Signature of owner Mrs. O. Waldron Smith  
G. E. O. Smith

7048A

Ward 32 Permit No. 32/381  
Location Maple St. Beach  
Owner Mrs. G. Walden Smith  
Date of permit 3/24/32  
Notif. closing-in \_\_\_\_\_  
Inspn. closing-in \_\_\_\_\_  
Final Notif. \_\_\_\_\_  
Final Inspn. 3/24/32  
Cert. of Occupancy issued None

NOTES

85  
7  
20  
3/24/32 - P.I.M. - A.J.S.

