

STERLING ST., PEAKS ISLAND

87-E-16



# APPLICATION FOR PERMIT

PERMIT BOARD

Permit No. 0311

MAY 2 1944

Class of Building or Type of Structure Third Class

Portland, Maine, May 2, 1944

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect alter install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 47-1/2 Sterling Street, Peaks Island Within Fire Limits? NO Dist. No. \_\_\_\_\_  
 Owner's or-Lessee's name and address Edna Ruth Straker, 7 Quincy St. Telephone 2-1718  
 Contractor's name and address CYRAC Telephone \_\_\_\_\_  
 Architect \_\_\_\_\_ Plans filed \_\_\_\_\_ No. of sheets \_\_\_\_\_  
 Proposed use of building \_\_\_\_\_ No. families \_\_\_\_\_  
 Other buildings on same lot Cottage  
 Estimated cost \$ \_\_\_\_\_ Fee \$ 1.00

### Description of Present Building to be Altered

Material wood No. stories 2 Heat \_\_\_\_\_ Style of roof \_\_\_\_\_ Roofing \_\_\_\_\_  
 Last use Cottage No. families \_\_\_\_\_

### General Description of New Work

To demolish building existing

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

### Details of New Work

Is any plumbing work involved in this work? \_\_\_\_\_  
 Is any electrical work involved in this work? \_\_\_\_\_ Height average grade to top of plate \_\_\_\_\_  
 Size, front \_\_\_\_\_ depth \_\_\_\_\_ No. stories \_\_\_\_\_ Height average grade to highest point of roof \_\_\_\_\_  
 To be erected on solid or filled land? \_\_\_\_\_ earth or rock? \_\_\_\_\_  
 Material of foundation \_\_\_\_\_ Thickness, top \_\_\_\_\_ bottom \_\_\_\_\_ cellar \_\_\_\_\_  
 Material of underpinning \_\_\_\_\_ Height \_\_\_\_\_ Thickness \_\_\_\_\_  
 Kind of roof \_\_\_\_\_ Rise per foot \_\_\_\_\_ Roof covering \_\_\_\_\_  
 No. of chimneys \_\_\_\_\_ Material of chimneys \_\_\_\_\_ of lining \_\_\_\_\_  
 Kind of heat \_\_\_\_\_ Type of fuel \_\_\_\_\_ Is gas fitting involved? \_\_\_\_\_  
 Framing lumber—Kind \_\_\_\_\_ Dressed or full size? \_\_\_\_\_  
 Corner posts \_\_\_\_\_ Sills \_\_\_\_\_ Girt or ledger board? \_\_\_\_\_ Size \_\_\_\_\_  
 Material columns under girders \_\_\_\_\_ Size \_\_\_\_\_ Max. on centers \_\_\_\_\_  
 Studs (outside walls and carrying partitions) 2x4-16" O. C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.  
 Joists and rafters: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 On centers: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 Maximum span: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 If one story building with masonry walls, thickness of walls? \_\_\_\_\_ height? \_\_\_\_\_

### If a Garage

No. cars now accommodated on same lot \_\_\_\_\_, to be accommodated \_\_\_\_\_  
 Total number commercial cars to be accommodated \_\_\_\_\_  
 Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? \_\_\_\_\_

### Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no  
 Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? YPS  
 Signature of owner Edna Ruth Straker

INSPECTION COPY

45430

Permit No. 44/351

Location Stirling St. Pecker

Owner Adam Straker

Date of permit 5/2/44

Notif closing-in


Inspn. closing-in

Final Notit

Final Inspn. 3/20/45: 036.

Cert. of Occupancy in None

NO...





Location, Ownership and detail must be correct, complete and legible.  
 Separate application required for every building.  
 Plans must be filed with this application.

## Application for Permit for Alterations, etc.

To the

Portland, September 25, 1923

INSPECTOR OF BUILDINGS:

The undersigned applies for a permit to alter the following described building:—

Location Sterling St., Peaks Island Ward 1 in fire-limits? no  
 Name of Owner or Lessee R. N. Bryant Address 147 Beacon Street  
 " " Contractor E. I. Sharpe " 55 Fessenden Street  
 " " Architect..... " ....."  
 Material of Building is wood Style of Roof pitch Material of Roofing shingle  
 Size of Building is 28ft feet long; 29ft feet wide. No. of Stories 2  
 Cellar Wall is constructed of posts is..... inches wide on bottom and batters to..... inches on top.  
 Underpinning is..... is..... inches thick; is..... feet in height.  
 Height of Building 20ft Wall, if Brick; 1st..... 2d..... 3d..... 4th..... 5th.....  
 What was Building last used for? cottage No. of families? 1  
 What will Building now be used for? cottage (one family)

Description of Present Bldg. CHIMNEY REPORT

### Detail of Proposed Work

build tile lined chimney, close up end of building, change partition, out in door  
all to comply with the building ordinance

Estimated Cost \$ 800.

### If Extended On Any Side

Size of Extension, No. of feet long?.....; No. of feet wide?.....; No. of feet high above sidewalk?.....  
 No. of Stories high?.....; Style of Roof?.....; Material of Roofing?.....  
 Of what material will the Extension be built?..... Foundation?.....  
 If of Brick, what will be the thickness of External Walls?..... inches; and Party Walls..... inches.  
 How will the extension be occupied?..... How connected with Main Building?.....

### When Moved, Raised or Built Upon

No. of Stories in height when Moved, Raised, or Built upon?..... Proposed Foundations.....  
 No. of feet high from level of ground to highest part of Roof to be?.....  
 How many feet will the External Walls be increased in height?..... Party Walls.....

### If Any Portion of the External or Party Walls Are Removed

Will an opening be made in the Party or External Walls?..... in..... Story.  
 Size of the opening?..... How protected?.....  
 How will the remaining portion of the wall be supported?.....

Signature of Owner or Authorized Representative.....

Address.....

*R. N. Bryant*  
147 Beacon St.

PERMIT MUST BE OBTAINED BEFORE BEGINNING WORK

✓  
Sterling St, Peaks

6000

87-8 E-16

## FINAL REPORT

.....192.....  
Has the work been completed in accordance with  
this application and plans filed and approved?

.....  
Law been violated? .....Doc. No.....of 192.....

Nature of violation? .....

.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....

### PERMIT GRANTED

.....Sept 25, 1923.....192.....  
Permit filled out by.....  
Permit number.....  
Location.....**Sterling St, Peaks**.....

Violation removed, when? .....192.....

Estimated cost of alterations, etc., \$.....

Inspector of Buildings.

СЪОБЩЕНИЕ МОСК



Location, Ownership and detail must be correct, complete and legible.  
 Separate application required for every building.  
 Plans must be filed with this application.

# Application for Permit for Alterations, etc.

Portland, September 25, 1923

To the

INSPECTOR OF BUILDINGS:

The undersigned applies for a permit to alter the following described building:—

Description of Present Bldg.

FINAL REPORT

Location Sterling St, Peaks Island Ward 1 in fire-limits? no  
 Name of Owner or Lessee R. N. Bryant Address 147 Beacon Street  
 " Contractor E. J. Sharpe " 55 Fessenden Street  
 " Architect \_\_\_\_\_  
 Material of Building is wood Style of Roof pitch Material of Roofing shingle  
 Size of Building is 28ft feet long; 29ft feet wide. No. of Stories 2  
 Cellar Wall is constructed of posts is \_\_\_\_\_ inches wide on bottom and batters to \_\_\_\_\_ inches on top.  
 Underpinning is \_\_\_\_\_ is \_\_\_\_\_ inches thick; is \_\_\_\_\_ feet in height.  
 Height of Building 20ft Wall, if Brick; 1st \_\_\_\_\_ 2d \_\_\_\_\_ 3d \_\_\_\_\_ 4th \_\_\_\_\_ 5th \_\_\_\_\_  
 What was Building last used for? cottage No. of families? 1  
 What will Building now be used for? cottage (one family)

### Detail of Proposed Work

put in foundation, build tiled lined chimney, change partitions, close up end of building  
all to comply with the building ordinance

Estimated Cost \$ 1400.

### If Extended On Any Side

Size of Extension, No. of feet long? \_\_\_\_\_; No. of feet wide? \_\_\_\_\_; No. of feet high above sidewalk? \_\_\_\_\_  
 No. of Stories high? \_\_\_\_\_; Style of Roof? \_\_\_\_\_; Material of Roofing? \_\_\_\_\_  
 Of what material will the Extension be built? \_\_\_\_\_ Foundation? \_\_\_\_\_  
 If of Brick, what will be the thickness of External Walls? \_\_\_\_\_ inches; and Party Walls \_\_\_\_\_ inches.  
 How will the extension be occupied? \_\_\_\_\_ How connected with Main Building? \_\_\_\_\_

### When Moved, Raised or Built Upon

No. of Stories in height when Moved, Raised, or Built upon? \_\_\_\_\_ Proposed Foundations \_\_\_\_\_  
 No. of feet high from level of ground to highest part of Roof to be? \_\_\_\_\_  
 How many feet will the External Walls be increased in height? \_\_\_\_\_ Party Walls \_\_\_\_\_

### If Any Portion of the External or Party Walls Are Removed

Will an opening be made in the Party or External Walls? \_\_\_\_\_ in \_\_\_\_\_ Story.  
 Size of the opening? \_\_\_\_\_ How protected? \_\_\_\_\_  
 How will the remaining portion of the wall be supported? \_\_\_\_\_

Signature of Owner or Authorized Representative \_\_\_\_\_  
 Address \_\_\_\_\_

R. N. Bryant  
147 Beacon Street

PERMIT MUST BE OBTAINED BEFORE BEGINNING WORK

✓  
Sterling St., Peaks

5000  
4  
87-E-16

## FINAL REPORT

..... 1923....  
Has the work been completed in accordance with  
his application and plans filed and approved?

.....  
Law been violated?..... Doc. No. .... of 1923....

Nature of violation?.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....

..... 1923....  
Violation removed, when? .....

Estimated cost of alterations, etc. \$.....

Inspector of Buildings.

---

### PERMIT GRANTED

..... Sept. 25, 1923..... 1923....

Permit filled out by.....

Permit number.....

**Sterling St, Peaks**

Location.....

.....

.....