

ENVIRONMENTAL RECORD FORM				PORTLAND HEALTH DEPARTMENT ENVIRONMENTAL HEALTH DIVISION			
Address Oaklawn Road & Oshawa Path Pks., Peaks Island				Owner's Address same - occupant			
Owner Covvy Johnson				BLOCK NO 12 90-E-4	PEOPLE	UNIT 5 6	
TYPE 7-2 E-1 100	DATE 9-14 6/14/84	INSP NO. 13 16 123	START INSP 2:30 P.M.	STOP INSP 3:00 P.M.	TOTAL TIME 17 19 1 hr	DIST. 20 7	CENSUS TRACT 21 2

CODE S - Satisfactory N - Not Applicable U - Unsatisfactory

REFUSE	21	CONTAINERS	5	HARBOR	31	DILAPIDATED BLDGS.	3	VER.	39	ITEMS	1
	24	CONTAINER CONST.	5		32	LUMBER, STOCK, MATERIALS	3		40	SAN. NO.	51
	25	CONTAINER COVERED	5		33	PLUMBING AND SEWAGE	10		41	H. 1+ BAITED LBS.	
	26	REFUSE CONTAINED	10		34	WEEDS	3		42	SURVEY	
	27	ANIMAL FEED	5		35	RODENT PROOFING	10		43	A	
	28	JUNK CAR	5		36	OTHER			44	B	
	29	JUNK APPLIANCES	3		37	EXTERIOR	12		45	C	
	30	MISC. RUBBLE	2		38	INTERIOR	15		46	D	

ITEM NO.	VIOLATIONS	CORRECT BY
	As the result of a complaint, an inspector made at the property listed above.	
	It was determined that there is a serious malfunction of the sub-surface waste disposal system on your property, evidenced by black wastewater on top of the ground.	
	This is a violation of the Municipal and State housing/plumbing codes, and all steps should be taken to correct this problem within 10 days, as it currently presents an immediate health hazard to occupants and the neighboring community.	6/14
	<i>[Signature]</i>	RS