

Ward 7 Permit No. 29/856

Location Pleasant Ave Alaska

Owner W. P. & C. C. Hurling

Date of permit 9/17/29

Notif. closing -

Inspn. closing in

Final Notif.

Final Inspn.

Cer. of Occupancy issued




NOTE: 11/9/29

B

10/15/29 - Partition
removed + fireplace
started. In view
next across chimney
are bolted up to wall
not be seen at this
time but look well
they are O.K. A.G.

11/7/29 - All work com-
pleted. A.G.

East of Pleasant Park



15 ft
20 ft
Pond

8 ft
10 ft
Pond



(A) APARTMENT HOUSE ZONE

APPLICATION FOR PERMIT

Class of Building or Type of Structure Third Class

Portland, Maine, June 7, 1929

PERMIT 1535
1032
Permit No. 1535
75710

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect ~~alter~~ erect ~~the~~ the following building ~~structure~~ structure equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location Extension of Pleasant Ave. Peaks Ward 1 Within Fire Limits? No Dist. No. _____

Owner's or Lessee's name and address W. R. & A. C. Sterling, Peaks Island Telephone _____

Contractor's name and address S. H. Weaver, Peaks Island Telephone _____

Architect's name and address _____

Proposed use of building 2 car garage No. families _____

Other buildings on same lot shed and summer hotel

Description of Present Building to be Altered

Material _____ No. stories _____ Heat _____ Style of roof _____ Roofing _____

Last use _____

General Description of New Work

To erect 2 car frame garage

NOTICE
NO WORK TO BE DONE BEFORE LATHING
CERTIFICATE OF OCCUPANCY
REQUIREMENT IS WAIVED

Details of New Work

Size, front 18' depth 20' No. stories 1 Height average grade to top of platf. 9'
Height average grade to highest point of roof 19.9'

To be erected on solid or filled land? solid earth or rock? earth

Material of foundation cedar posts Thickness, top _____ bottom _____

Material of underpinning _____ Height _____ Thickness _____

Kind of roof pitch Roof covering Asphalt shingles Class C End. Lab.

No. of chimneys 10 Material of chimneys _____ of lining _____

Kind of heat gas Type of fuel _____ Distance, heater to chimney _____

If oil burner, name and model _____

Capacity and location of oil tanks _____

Is gas fitting involved? no Size of service _____

Corner posts 4x4 Sills 4x5 Girt or ledger board? _____ Size _____

Material columns under girders _____ Size _____ Max. on centers _____

Studs (outside walls and carrying partitions) 2x1-16" O.C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.

Joists and rafters: 1st floor 4x4, 2nd _____, 3rd _____, roof 2x4

On centers: 1st floor _____, 2nd _____, 3rd _____, roof 24"

Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____

If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot none to be accommodated 2

Total number commercial cars to be accommodated none

Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? no

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no

Plans filed as part of this application? yes No. sheets 1

Estimated cost \$ 300. Fee \$ 75

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? Yes

INSPECTION COPY

Signature of owner

W. R. & A. C. Sterling

Wm. P. [Signature]

Armeda C. Sterling

CHIEF OF PERMITS

9465

Ward 1 Permit No. 29/10/29

Location Ext. Pleasant Hill

Owner W. P. + A. C. Sterling

Date of permit 6/10/29

Notif. closing-in _____

Insp. closing-in _____

Final Notif. _____

Final Inspn. _____

Cert. of Occupancy issued _____

NOTES

10/16/29 - garage built
90
a.g.





Location, Ownership and detail must be correct, complete and legible.
 Separate application required for every building.
 Plans must be filed with this application.

Application for Permit for Alterations, etc.

Portland, Me., April 22, 1924 10

To the
 INSPECTOR OF BUILDINGS:

The undersigned applies for a permit to alter the following described building:

Location ~~Pease~~ Pease Island ~~Pease Island~~ Pease Island Ward 1 in fire limits? no
 Name of Owner or Lessee, W. R. Sterling Address Pease Island
 " " Contractor, A J Comeau " 73 Anderson Street
 " " Architect,

Description of Present Bldg.

Material of Building is wood Style of Roof, Dutch Material of Roofing, shingle
 Size of Building is 100ft feet long; 50ft feet wide. No. of Stories, 2
 Cellar Wall is constructed of STONE is inches wide bottom and batters to inches on top.
 Underpinning is brick is inches thick; is feet in height.
 Height of Building 26ft Wall, if Brick; 1st, 2d, 3d, 4th, 5th
 What was Building last used for? hotel No. of Families?
 What will Building now be used for? hotel

Detail of Proposed Work

Build sun porch 10x18 feet one story high, build piazza 13x60 feet
all to comply with the building ordinance

Estimated Cost \$ 700.

If Extended On Any Side

Size of Extension, No. of feet long?; No. of feet wide?; No. of feet high above sidewalk?
 No. of Stories high?; Style of Roof?; Material of Roofing?
 Of what material will the Extension be built? Foundation?
 If of Brick, what will be the thickness of External Walls? inches; and Party Walls inches.
 How will the extension be occupied? How connected with Main Building?

When Moved, Raised or Built Upon

No. of Stories, height when Moved, Raised, or Built upon? Proposed Foundations
 No. of feet high from level of ground to highest part of Roof to be?
 How many feet will the External Walls be increased in height? Party Walls

If Any Portion of the External or Party Walls Are Removed

Will an opening be made in the Party or External Walls? in Story.
 Size of the opening? How protected?
 How will the remaining portion of the wall be supported?

Signature of Owner or Authorized Representative

Address

Alvin J. Crossman
73 Anderson St

Tel. 8337

PERMIT MUST BE OBTAINED BEFORE BEGINNING WORK

92-50

Trefethen Ldg Beach Pleasant Art

APPROVED FOR PERMIT FOR ALTERATIONS
APPROVED FOR PERMIT FOR ALTERATIONS
APPROVED FOR PERMIT FOR ALTERATIONS

APPROVED FOR PERMIT FOR ALTERATIONS

PERMIT GRANTED

Apr 22, 1924

Permit filled out by

Permit number

Location Trefethen Landing

FINAL REPORT

Has the work been completed in accordance with this application and plans filed and approved?

Law been violated? Dec No. of 192

Nature of violation?

Violation removed, when?

Estimated cost of alterations, etc. \$.....

Inspector of Buildings

PERMIT SHALL BE GRANTED SUBJECT TO THE



City of Portland.

2-10-1912

To the Inspector of Buildings of the City of Portland:

The undersigned respectfully makes application for a permit to erect enlarge a building on Peake Island street, at number Oceanic House to be stories high..... feet long, feet wide; also an addition to be 3 stories high,..... 43 feet long, 20 feet wide, and to be used as a Hotel.

The material to be used in the erection enlargement of said building is to be as follows:

Exterior walls to be made of Wood

Roof to be made of

Gutters to be made of

Cornices to be made of.....

Bay windows to be made of

Dormer windows to be made of Wood

The builder is L. J. Townsend Address 120 Sherman St.

The architect is

The owner is Mr. L. J. Sterling Address Peake Island

Concrete 16" bottom 12" top

8500

(Applicant to sign here) Louis A. Townsend

OFFICE OF
INSPECTOR OF BUILDINGS,
FOR THE
CITY OF PORTLAND.
OFFICE HOURS:
10:15 A. M. - 4:45 P. M.

The above petition was granted to e 10th day of Feb 191 2

✓
PERMIT NO. 2067

DATE OF ISSUE 2-14-62

LOCATION

Peabody and

Steering
Horse

APPLICATION APPROVED