

106 Bedford Street

115-B-5

  
SHAW-WALKER  
#8503-1R

November 16, 1977 ✓

Mr. Thomas H. Ayling, 111  
106 Bedford Street  
Portland, Maine 04102

Dear Mr. Ayling:

Re: 106 Bedford Street - 115-B-5  
NCF-Oakdale  
Neighborhood Conservation

The Housing Inspections Division of the Department of Neighborhood Conservation has recently completed an exterior inspection of your property in conjunction with the above referred program.

Congratulations are extended to you for the general conditions of your property which was found to meet the standards established by the City's Housing Code.

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely yours,  
Joseph E. Gray, Jr., Director  
Neighborhood Conservation

By Lyle D. Noyes  
Lyle D. Noyes,  
Chief of Housing Inspections

Inspector G. Bartlett  
G. Bartlett



