

69 Falrouth Street

117-A-15

SAWALKER

November 16, 1977 ✓

Robert S. & Alice B. Leighton
69 Falmouth Street
Portland, Maine 04103

Dear Mr. & Mrs. Leighton:

Re: 69 Falmouth Street - 117-A-15
NCP-Oakdale
Neighborhood Conservation

The Housing Inspections Division of the Department of Neighborhood Conservation has recently completed an exterior inspection of your property in conjunction with the above referred program.

Congratulations are extended to you for the general conditions of your property which was found to meet the standards established by the City's Housing Code. We did, however, note the following items that could cause future problems.

FRONT ROOF - missing shingles.
LEFT MIDDLE WALL - rafter.

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely yours,
Joseph E. Gray, Jr., Director
Neighborhood Conservation

by _____
Lyle D. Noyes,
Chief of Housing Inspections

Inspector G. Bartlett
G. Bartlett

