

105 Dartmouth Street 118-D-16



July 21, 1977

Lydia Minkin
105 Dartmouth Street
Portland, Maine 04102

Dear Ms. Minkin: Re: NCP-Oakdale Neighborhood Conservation Program
105 Dartmouth Street, Portland, Maine 118-D-16

The Housing Inspections Division of the Department of Neighborhood Conservation has recently completed an exterior inspection of your property in conjunction with the above referred program.

Congratulations are extended to you for the general conditions of your property, which was found to meet the standards established by the City's Housing Code. We did, however, note the following items that could cause future problems.

1. EXTERIOR ROOF- loose bricks and mortar.

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely yours,
Joseph E. Gray, Jr., Director
Neighborhood Conservation

By Lyle D. Noyes
Lyle D. Noyes,
Chief of Housing Inspections

Inspector G. Bartlett
G. Bartlett

OK-15-EY

STRUCTURE INSPECTION SCHEDULE

1) Instr. Name SAINT-GIT

[illegible]

