



R3 RESIDENCE ZONE

APPLICATION FOR PERMIT

Class of Building or Type of Structure Installation.....

Portland, Maine, November 27, 1963.....

PERMIT ISSUED

DEC 2 1963

CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 335 Brighton Ave. Within Fire Limits? Dist. No.
 Owner's name and address Osteopathic Hospital of Maine, 335 Brighton Ave. Telephone
 Lessee's name and address Telephone
 Contractor's name and address James A. McBrady, 169 Front St., So. Port. Telephone 799-7343
 Architect Specifications Plans yes No. of sheets 1
 Proposed use of building Hospital No. families
 Last use No. families
 Material No. stories Hea. Style of roof Roofing
 Other buildings on same lot
 Estimated cost \$..... Fee \$..... 5.00

General Description of New Work

To install gravity ventilator in kitchen of new wing as per plan
This ventilator is in connection with fans for ventilation of new addition.

Permit Issued with Letter

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. **PERMIT TO BE ISSUED TO** James A. McBrady

Details of New Work

Is any plumbing involved in this work? Is any electrical work involved in this work?
 Is connection to be made to public sewer? If not, what is proposed for sewage?
 Has septic tank notice been sent? Form notice sent?
 Height average grade to top of plate Height average grade to highest point of roof
 Size, front depth No. stories solid or filled land? earth or rock?
 Material of foundation Thickness, top bottom cellar
 Kind of roof Rise per foot Roof covering
 No. of chimneys Material of chimneys of lining Kind of heat fuel
 Framing Lumber—Kind Dressed or full size? Cor posts Sills
 Size Girder Columns under girders Size Max. on centers
 Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
 Joists and rafters: 1st floor 2nd 3rd roof
 O. centers: 1st floor 2nd 3rd roof
 Maximum span: 1st floor 2nd 3rd roof
 If one story building with masonry walls, thickness of walls? height?

If 1 Garage

No. cars now accommodated on same lot to be accommodated number commercial cars to be accommodated
 Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building?

APPROVED:

OK-12/5/63-ags

Miscellaneous

Will work require disturbing of any tree on a public street? NO
 Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? YES

Osteopathic Hospital
James A. McBrady

Signature of owner By: *Murray M. Dutton*

INSPECTION COPY

PH

NOTES

12-11-63 Phoned
architects for detail
of fire stopper

3-25-64 Completed @

X

Permit No. 63/1601

Location 335 Bingham Quay

Owner Deputy Registrar of Marine

Date of permit 17/6/64

Notif. closing-in

Inspn. closing-in

Final Notif.

Final Inspn.

of Occupancy issued

Staking Out Notice

Form Check Notice

Multiple sets of horizontal lines for notes and data entry, including a large 'X' mark in the upper section.

Memorandum from Department of Building Inspection, Portland, Maine

AP- 335 Brighton Avenue

Sept. 17, 1963

Paul B. McLellan Co.
52 Marginal Way

cc to: Osteopathic Hospital of Maine, Inc.
335 Brighton Avenue

Gentlemen:

Permit to construct a 1-story brick and concrete addition on rear of building 15'11" x 29'3" as per plan is being issued subject to the fire alarm system being extended from the kitchen into this new storage addition.

Very truly yours,

Gerald E. Mayberry
Deputy Building Inspection Director

GEM:m

CS-27

R3 RESIDENCE ZONE



APPLICATION FOR PERMIT

2nd. Class
Class of Building or Type of Structure
September 9, 1963
Portland, Maine

PERMIT ISSUED
SEP 17 1963
CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location: 335 Brighton Ave. Within Fire Limits? Dist. No.
Owner's name and address: Osteopathic Hospital of Maine, 335 Brighton Ave. Telephone
Lessee's name and address Telephone
Contractor's name and address: Paul B McLellan Co. 52 Marginal Way Telephone 772-5451
Architect Specifications Plans Yes No. of sheets 13
Proposed use of building: Hospital No. families
Last use No. families
Material No. stories Heat Style of roof Roofing
Other buildings on same lot
Estimated cost \$ 4,000.00 Fee \$ 8.00

General Description of New Work

To construct 1-story brick and concrete addition on rear of building 15'11" x 29'3" as per plan.

Permit Issued with Memo

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. PERMIT TO BE ISSUED TO contractor

Details of New Work

Is any plumbing involved in this work? Is any electrical work involved in this work?
Is connection to be made to public sewer? If not, what is proposed for sewage?
Has septic tank notice been sent? Form notice sent? YES
Height average grade to top of plate Height average grade to highest point of roof
Size, front depth No. stories solid or filled land? earth or rock?
Material of foundation concrete Thickness, top bottom cellar
Kind of roof Rise per foot Roof covering
No. of chimneys Material of chimneys of lining Kind of heat fuel
Framing Lumber-Kind Dressed or full size? Corner posts Sills
Size Girder Columns under girders Size Max. on centers
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
Joists and rafters: 1st floor, 2nd, 3rd, roof
On centers: 1st floor, 2nd, 3rd, roof
Maximum span: 1st floor, 2nd, 3rd, roof
If one story building with masonry walls, thickness of walls? height?

If a Garage

No. cars now accommodated on same lot, to be accommodated number commercial cars to be accommodated
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building?

APPROVED:
J. E. M. W. Orlino

Miscellaneous
Will work require disturbing of any tree on a public street? NO
Will there be in-charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? YES
Osteopathic Hospital of Maine Inc.
Paul B. McLellan Co.

INSPECTION COPY Signature of owner Paul B. McLellan

71

PERMIT TO INSTALL PLUMBING

10630

PERMIT NUMBER

Date Issued 9-6-61
 PORTLAND PLUMBING INSPECTOR
 By J. P. Welch

Address 335 Brighton Avenue
 Installation For: Osteopathic Hospital
 Owner of Bldg. Osteopathic Hospital
 Owner's Address Brighton Avenue
 Plumber: Fred J. De Waters Date: 7-6-61

APPROVED FIRST INSPECTION	NEW	REPL	PROPOSED INSTALLATIONS	NUM	FEE
Date <u>9-6-61</u>			SINKS		
By <u>J. P. Welch</u>			LAVATORIES		
APPROVED FINAL INSPECTION			TOILETS		
Date <u>9-7-61</u>			BATH TUBS		
By <u>Joseph P. Welch</u>			SHOWERS		
			DRAINS		
			HOT WATER TANKS		
			TANKLESS WATER HEATERS		
			GARBAGE GRINDERS		
			SEPTIC TANKS		
By <u>JOSEPH P. WELCH</u>	1		HOUSE SEWERS	1	\$ 2.00
<input type="checkbox"/> COMMERCIAL			ROOF LEADERS (Conn. to house drain)		
<input type="checkbox"/> RESIDENTIAL					
<input type="checkbox"/> SINGLE					
<input type="checkbox"/> MULTI FAMILY					
<input type="checkbox"/> NEW CONSTRUCTION					
<input type="checkbox"/> REMODELING					
TOTAL					\$ 2.00

PORTLAND HEALTH DEPT. PLUMBING INSPECTION

3

PERMIT TO INSTALL PLUMBING

Date Issued 6-17-63

PORTLAND PLUMBING INSPECTOR

By J. P. Welch

Address 315 Brighton Avenue
 Installation For: Catapathic Hospital
 Owner of Bldg. Catapathic Hospital
 Owner's Address: Catapathic Hospital

12931
 PERMIT NUMBER

Plumber: Fred J. Delaters

APPROVED FIRST INSPECTION

Date June 17 1963

By JOSEPH P. WELCH

APPROVED FINAL INSPECTION

Date June 20 1963

By JOSEPH P. WELCH

- TYPE OF BUILDING
- COMMERCIAL
 - RESIDENTIAL
 - SINGLE
 - MULTI FAMILY
 - NEW CONSTRUCTION
 - REMODELING

NEW	REPL	PROPOSED INSTALLATIONS	NUMBER PAID FEE	
		SINKS		
		LAVATORIES		
		TOILETS		
		BATH TUBS		
		SHOWERS		
		DRAINS		
		HOT WATER		
		TANKLESS WATER HEATERS		
		GARBAGE GRINDERS		
		SEPTIC TANKS		
		HOUSE SEWERS		
		ROOF LEADERS (Conn. to house drain)		\$ 2.00

PORTLAND HEALTH DEPT. PLUMBING INSPECTION

TOTAL ▶ \$ 2.00

PERMIT TO INSTALL PLUMBING

PERMIT NUMBER 1184

Address: 335 Brighton Ave

Date Issued: Dec 16, 1954
 PORTLAND PLUMBING INSPECTOR

Installation For: Owner of Bldg.: Osteopathic Hospital of Maine, Sear

Owner's Address: Same Date: Dec 14, 1954

By: Joseph R. Kelah

Plumber: Emil M. Anderson

APPROVED FIRST INSPECTION
 Date: 12/15/54

NEW		REP'L	PROPOSED INSTALLATIONS	NUMBER	FEE
	1		SINKS	1	1.00
			LAVATORIES		
			TOILETS		
			BATH TUBS		
			SHOWERS		
			DRAINS		
			HOT WATER TANKS	3	
			TANKLESS WATER HEATERS		
			GARBAGE GRINDERS		
			SEPTIC TANKS		
			HOUSE SEWERS		
			ROOF LEADERS (conn. to house drain)		
				1	1.00

APPROVED FINAL INSPECTION
 Date: 12/15/54

- By: [Signature]
- TYPE OF BUILDING
- COMMERCIAL
 - RESIDENTIAL
 - SINGLE
 - MULTI FAMILY
 - NEW CONSTRUCTION
 - REMODELING

PORTLAND HEALTH DEPT.

PLUMBING INSPECTION

Total

PERMIT TO INSTALL PLUMBING

PERMIT NUMBER 3387

Date Issued 8-13-56
 PORTLAND PLUMBING INSPECTOR

By J. P. Walsh
 APPROVED FIRST INSPECTION

Date Aug 13-56
 By J. P. Walsh
 APPROVED FINAL INSPECTION

Date Nov 6-56
 By J. P. Walsh

- TYPE OF BUILDING
- COMMERCIAL
 - RESIDENTIAL
 - SINGLE
 - MULTI FAMILY
 - NEW CONSTRUCTION
 - REMODELING

SM 12-53

Address: 995 Broadway

Installation For: Hospital

Owner of Bldg.:
 Owner's Address: Date:

Plumber: E. J. ... Date:

		PROPOSED INSTALLATIONS		NUMBER	FEE
NEW	REP'L				
			SINKS		
			LAVATORIES		
			TOILETS		
			BATH TUBS		
			SHOWERS		
			DRAINS		
			HOT WATER TANKS	3	
			TANKLESS WATER HEATERS		
			GARBAGE GRINDERS		
			SEPTIC TANKS		
			HOUSE SEWERS		
			ROOF LEADERS (conn. to house drain)		
				Total	752

PORTLAND HEALTH DEPT.

PLUMBING INSPECTION

PERMIT NUMBER 3989

PERMIT TO INSTALL PLUMBING

Address: 335 Brighton Ave.

Date Issued: 8-18-56

Installation For: Hospital

PORTLAND PLUMBING INSPECTOR

Owner of Bidg.:

Owner's Address:

By: J. J. Welch

Plumber: J. J. Welch Date: 8-18-56

APPROVED FIRST INSPECTION

Date: 11-14-56

By: J. J. Welch

APPROVED FINAL INSPECTION

Date: Mar. 18, 58

By: J. J. Welch

TYPE OF BUILDING

COMMERCIAL

RESIDENTIAL

SINGLE

MULTI FAMILY

NEW CONSTRUCTION

REMODELING

NEW	REP'L	PROPOSED INSTALLATIONS	NUMBER	FEES
29		SINKS	29	13.20
35		LAVATORIES	35	4.38
29		TOILETS	29	2.40
2		BATH TUBS	2	.24
2		SHOWERS	2	.24
13		DRAINS	13	1.56
1		HOT WATER TANKS	1	.12
2		TANKLESS WATER HEATERS	2	.24
2		GARBAGE GRINDERS	2	.24
4		SEPTIC TANKS	4	1.20
1		HOUSE DRAINERS	1	.12
5		ROOF LEADERS (conn. to sewer)	5	.60
5		Flts. br. up	5	.60
			Total	29.28

5M 12-53

PORTLAND HEALTH DEPT.

PLUMBING INSPECTION

PERMIT TO INSTALL PLUMBING
 PERMIT NUMBER 6291
 Address: 325 Boston Ave
 Installation For: Osterline Hotel

Date Issued: 4-14-58
 PORTLAND PLUMBING INSPECTOR

By: S. P. Walsh
 APPROVED FIRST INSPECTION

Date: Apr 14 58

By: J. B. Walsh
 APPROVED FINAL INSPECTION

Date: Apr 14 58

By: J. B. Walsh

TYPE OF BUILDING

- COMMERCIAL
- RESIDENTIAL
- SINGLE
- MULTI FAMILY
- NEW CONSTRUCTION
- REMODELING

Owner of Bldg.:
 Owner's Address: E. B. Quinlan Co.
 Plumber: F. B. Quinlan Co.
 Date: 4-14-58

NEW	REPL	S IKS	PROPOSED INSTALLATIONS	
			NUMBER	TEE
1		LAVATORIES	1	1
1		TOILETS	1	1
		BATH TUBS		
		SHOWERS		
		DRAINS		
		HOT WATER TANKS		
		TANKLESS WATER HEATERS	3	
		GARBAGE GRINDERS		
		SEPTIC TANKS		
		HOUSE SEWERS		
		ROOF LEADERS (conn. to house drain)		
			Total	5

PORTLAND HEALTH DEPT.

PLUMBING INSPECTION

PERMIT TO INSTALL PLUMBING

Date Issued: 6-17-63 PERMIT NUMBER 2910

Address: 335 Brighton Avenue

Installation For: Osteopathic Hospital

Owner of Bldg.: Osteopathic Hospital

Owner's Address: Same

Plumber: Fred J. Delabara Date: 6-17-63

APPROVED FIRST INSPECTION	NEW		PRE-POSED INSTALLATIONS	NUMBER	FEE
	NEW	REPL			
	8		SINKS	8	\$11.80
	22		LAVATORIES	22	19.20
Date: <u>Oct 17, 1963</u>	13		TOILETS	13	7.80
By: <u>JOSEPH E. WELCH</u>	1		BATH TUBS	1	.60
			SHOWERS		
APPROVED FINAL INSPECTION	7		DRAINS	7	4.20
Date: <u>Apr 13, 1964</u>	1		HOT WATER TANKS	1	.50
By: <u>JOSEPH E. WELCH</u>			TANKLESS WATER HEATERS		
			GARBAGE GRINDERS		
<input type="checkbox"/> TYPE OF BUILDING			SEPTIC TANKS		
<input type="checkbox"/> COMMERCIAL			HOUSE SEWERS		
<input type="checkbox"/> RESIDENTIAL			ROOF LEADERS (Conn. to house drain)		
<input type="checkbox"/> SINGLE	3		Other Fixtures		1.80
<input type="checkbox"/> MULTI FAMILY					
<input type="checkbox"/> NEW CONSTRUCTION					
<input type="checkbox"/> REMODELING					

TOTAL ▶ \$40.00

PORTLAND HEALTH DEPT. PLUMBING INSPECTION

U.S. 329-355 Brighton Ave.

March 26, 1964

Osteopathic Hospital of Maine
335 Brighton Avenue

cc to: James Saunders Associates
562 Congress Street
cc to: Paul B. McLellan Company
52 Marginal Way

Gentlemen:

Certificate of Occupancy authorizing use of new addition to your hospital is issued herewith subject to condition that provision is to be made on the premises for not less than 90 off-street parking spaces as required by the Zoning Ordinance. Finished grading is to be provided outside front and rear doors so that there will be no appreciable step down at these locations.

Very truly yours,

Albert J. Sears
Building Inspection Director

AJS:m

UF - 63/608 - 329-355 Brighton Ave.

June 20, 1963

James Saunders Associates,
562 Congress Street

cc to: Paul B. McLellan Co.
52 Marginal Way

cc to: Osteopathic Hospital of Maine
335 Brighton Ave.

Gentlemen:

On the basis of the information furnished as to the fire-resistant qualities of the Dex-O-Tex traffic bearing roof covering proposed for use on that area of roof of the addition to the Osteopathic Hospital to be used as a sun deck, it appears to meet the requirements for a Class B roof covering and is therefore approved for use on this job as being equivalent to the roof covering required by the Building Code.

Very truly yours,

Albert J. Sears
Director of Building Inspection

AJS/h

AP - 329-395 Brighton Ave.

June 6, 1963

Paul B. McLellan Co.
52 Marginal Way

cc to: Osteopathic Hospital of Maine
335 Brighton Ave.

James Saunders Associates,
562 Congress Street

Gentlemen:

Building permit for construction of a one story and basement addition to hospital at the above named location is issued herewith to contractor based on plans and specifications filed with application for permit and architect's letter of June 4, 1963, but subject to the following conditions:

1. It is understood that the 90 off-street parking spaces required by the Zoning Ordinance are either presently existing or will be provided.
2. Separate permits issuable only to the actual installers are required for the installation of heating and cooking equipment, systems of ventilation, and extension of sprinkler system.

Very truly yours,

Albert J. Sears
Director of Building Inspection

AJS/n

A.P.-329-355 Brighton Ave.

May 10, 1963

James Saunders Associates
562 Congress Street

cc to: Paul B. McCallan Company
52 Marginal Way
cc to: Osteopathic Hospital of Maine
335 Brighton Avenue

Gentlemen:

Check of plans for addition to hospital at above named location discloses the following variances from and questions as to compliance with Zoning Ordinance and Building Code requirements, about which information indicating compliance is needed before issuance of the general construction permit. Details in question are as follows:

1. At least 90 off-street parking spaces are required under Zoning Ordinance specifications for the entire hospital, including the proposed addition. Information is needed that this number of spaces are existing or else a plan needs to be filed showing location of existing and any new parking spaces required. While this information need not necessarily be furnished before issuance of permit, it will need to be furnished as soon thereafter as possible. ?
2. Since this property is located in a Residential Zone, your attention is called to the provisions of Section 16-A-8b of the Ordinance limiting to 15 square feet the area of a general identification sign for the project. O.K.
3. In order to provide the required one-hour enclosure for safe egress of corridor between exit door from new enclosed stairway at ground floor level and the new entrance, self-closing Class "C" fire doors will be needed across corridor #116 at or near its junction with that of the existing building, as well as on opening #103 and at junction of corridors #115 and #116 as indicated in addendum. *copies with the*
4. If room #201 is to be used for assemblage purposes involving more than 20 persons at any one time, it is required to be equipped as for a minor assembly hall, which calls for a second means of egress, exit sign, and vestibule latch sets on doors if they are to have locking devices on them. O.K.
5. Since room #110^{is} apparently to be used for assemblage purposes, it too must be equipped as for a minor assembly hall. This means that white lights on the same circuit as the exit lights will be needed in the stair hall between openings #110 and #114. O.K.
6. Entrance to room #110 from inside the building and the exit door to the outside are not as widely separated as could be desired. Unless there is some good reason why it cannot be done, it is suggested that the steps on landing at opening #109 be placed on the opposite end of landing from that indicated. O.K.

- 7. The 6 inch step down directly outside opening #117 as shown in Section 11 on Sheet 14 needs to be eliminated. *O.K.*
- 8. The following questions concern the type of locking hardware to be used on doors involved in a means of egress:
 - a- Vestibule latch sets or equivalent are required on aluminum doors in opening #104. Apparently there are to be no locks on doors in opening #115.
 - b- Since each leaf of double doors on opening #109 is only 2 feet 6 inches wide, hardware must be such that both doors may be opened at all times from the Auditorium side. A vestibule latch set on the working door and anti-panic bar on the standing door would satisfy this requirement.
 - c- Locks on doors #113, #237, #243 on new stair tower are required to be vestibule latch sets or equivalent, so installed that the doors can always be operated in the direction of exit travel.
 - d- The same applies for doors #239 and #241 and the doors into corridor from former balcony if they are to have locking devices of any kind.
- 9. Any rooms in basement (ground floor) to be used for storage or workshops are required to be equipped with sprinkler heads. *?*
- 10. Automatic alarm system will need to be extended to the addition in a manner approved by the Fire Department. *O.K.*
- 11. If sun deck is to be provided on roof, information is needed as to the fire-resistive qualities of the neoprene composition roofing to meet requirements for Class "A" roofing.
- 12. Oil burner of heater for domestic hot water is required to bear the label of Underwriters' Laboratories, Inc. *-O.K.*
- 13. The wooden construction on walls and ceiling of Room 110, as far as can be determined from plans, is in excess of the amount of combustible construction allowed by Sec. 302-a-1 of the Code applying to First Class Construction. *?*

Hardware contractor has discussed this with me and says he will meet requirements

Arrangement indicated dated 11/11/63 has been approved

May 20, 1963

14. Area of glass or louvers in wall of pent house of elevator shaft apparently does not equal the one-tenth of shaft area required by Section 702-b-1. *Increased - OK*
15. Care will need to be taken to make sure that aggregate area of openings in fire-resistant ceilings for piping, ducts, and electric outlets does not exceed 100 square inches in any 100 square feet of ceiling area, and that all duct openings are protected with approved non-combustible fire dampers. *-OK*
16. A statement of design is needed for affixing to the plans. *-OK*

Very truly yours,

Albert J. Sears
Building Inspection Director

AJS:m

(COPY)



CITY OF PORTLAND, MAINE
Department of Building Inspection

Certificate of Occupancy

Issued to Catholic Hospital of Maine
335 Brighton Ave. LOCATION #329-355 Brighton Avenue
Date of Issue March 26, 1964

This is to certify that the building, premises, or part thereof, at the above location, built—~~altered~~—
~~changed as to use~~ under Building Permit No. 63/608, has had final inspection, has been found to conform
substantially to requirements of Zoning Ordinance and Building Code of the City, and is hereby approved for
occupancy or use, limited or otherwise, as indicated below.

PORTION OF BUILDING OR PREMISES

One story and basement
addition(chronic care unit)
Limiting Conditions:

APPROVED OCCUPANCY
Type A Hospital

This certificate supersedes
certificate issued

Approved:

(Date) Nelson F. Cartwright, Jr.
Inspector

Albert J. Sears
Inspector of Buildings

CS 147

Notice: This certificate identifies lawful use of building or premises, and ought to be transferred from
owner to owner when property changes hands. Copy will be furnished to owner or lessee for one dollar.

R3 RESIDENCE ZONE



APPLICATION FOR PERMIT

Class of Building or Type of Structure
Portland, Maine, May 9, 1963

PERMIT ISSUED JUN 6 1963 CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 335 Brighton Ave. With Fire Limits? Dist. No.
Owner's name and address Osteopathic Hospital of Maine, 335 Brighton Ave. Telephone
Lessee's name and address Telephone
Contractor's name and address Paul McLellan Co., 52 Marginal Way Telephone 2-5951
Architect Specifications Plans YES No. of sheets 21
Proposed use of building Hospital No. families
Last use No. families
Material masonry No. stories 2-b Heat Style of roof Roofing
Other buildings on same lot Fee \$ 436.
Estimated cost \$ 218,000.

General Description of New Work

To construct 2-story masonry addition 59'10" x 147' as per plans

Advance permit for excavation only issued 5/10/63

Permit Issued with Letters

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. PERMIT TO BE ISSUED TO contractor

Details of New Work

Is any plumbing involved in this work? Is any electrical work involved in this work?
Is connection to be made to public sewer? If not, what is proposed for sewage?
Has septic tank notice been sent? Form notice sent?
Height average grade to top of plate Height average grade to highest point of roof
Size, front depth No. stories solid or filled land? earth or rock?
Material of foundation Thickness, top bottom cellar
Kind of roof Rise per foot covering
No. of chimneys Material of chimneys or lining Kind of heat fuel
Framing Lumber-Kind Dressed or full size? Corner posts Sills
Size Girder Columns under girders Size Max. on centers
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
Joists and rafters: 1st floor, 2nd, 3rd, roof
On centers: 1st floor, 2nd, 3rd, roof
Maximum span: 1st floor, 2nd, 3rd, roof
If one story building with masonry walls, thickness of walls? height?

If a Garage

No. cars now accommodated on same lot, to be accommodated number commercial cars to be accommodated
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building?

APPROVED:

Miscellaneous

Will work require disturbing of any tree on a public street? no
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes
Osteopathic Hospital of Maine
Paul McLellan Co.

CS 301

INSPECTION COPY

Signature of owner By:

Paul McLellan

NOTES

6-7-63 ledge excavation
 nearly done *PD*
 9-17-63 basement walls
 & steel up *PD*
 11-20-63 Partitions starting
 Check opening over
 boiler room & elevator
 machinery room *PD*
 12-11-63 Referred to
 architects
 3-25-64 Completed
 except
 Pair fire doors on order
 Grading steps to front
 & rear d.v.s.
 Parking grading in
 front *PD*
 Paddle on inside lock
 Front door. *PD*

Permit No. 63/608
 Location 335 DuPont Ave
 Owner *Waterbury Hygiene & Pharmacy*
 Date of permit 10/6/63
 Notif. closing-in
 Inspn. closing-in
 Final Notif.
 Final Inspn.
 Cert. of Occupancy issued 3/26/64
 Staking Out Notice
 Alarm Check Notice

1st floor #240 opening

R3 RESIDENCE ZONE

APPLICATION FOR PERMIT



Class of Building or Type of Structure Excavation
Portland, Maine, May 9, 1963

PERMIT ISSUED
MAY 10 1963

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 335 Brighton Ave. Within Fire Limits? Dist. No.
Owner's name and address Osteopathic Hospital of Maine, 335 Brighton Ave. Telephone
Lessee's name and address
Contractor's name and address Paul McLellan Co., 32 52 Marginal Way Telephone
Architect Specifications Plans YES No. of sheets
Proposed use of building hospital No. families
Last use " " No. families
Material No. stories Heat Style of roof Roofing
Other buildings on same lot
Estimated cost \$ Fee \$ 2.00

General Description of New Work

To Excavate Only for 2-story brick addition 59'10" x 147'

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. PERMIT TO BE ISSUED TO contractor

Details of New Work

Is any plumbing involved in this work? Is any electrical work involved in this work?
Is connection to be made to public sewer? If not, what is proposed for sewage?
Has septic tank notice been sent? Form notice sent?
Height average grade to top of plate Height average grade to highest point of roof
Size, front depth No. stories solid or filled land? earth or rock?
Material of foundation Thickness, top bottom cellar
Kind of roof Rise per foot Roof covering
No. of chimneys Material of chimneys of lining Kind of heat fuel
Framing Lumber-Kind Dressed or full size? Corner posts Sills
Size Girder Columns under girders Size Max. on centers
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
Joists and rafters: 1st floor, 2nd, 3rd, roof
On centers: 1st floor, 2nd, 3rd, roof
Maximum span: 1st floor, 2nd, 3rd, roof
If one story building with masonry walls, thickness of walls? height?

If a Garage

No. cars now accommodated on same lot, to be accommodated number commercial cars to be accommodated
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building?

APPROVED:

OK-5/10/63 - [Signature]

Miscellaneous

Will work require disturbing of any tree on a public street? no
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? YES

Osteopathic Hospital of Maine
Paul McLellan Co.

CS 301

INSPECTION COPY

Signature of owner By: [Signature]

PH

EMERGENCY

NOTES

6-19-63 Excavation
ledge about done
Con. permit issued

JED

[Handwritten mark]

Permit No. 63/477

Location 335 1/2 Ave. Ave

Owner DeForest H. Hefner & Marie

Date of permit 5/10/63

Notif. closing-in

Inspn. closing-in

Final Notif.

Final Inspn.

Cert. of Occupancy issued

Staking Out Notice

Form Check Notice

MEMORANDUM FROM DEPARTMENT OF BUILDING INSPECTION, PORTLAND, MAINE

September 13, 1963

Gould Farmer Co. of Maine
70 Free St.

Gentlemen:


Location: 335 Brighton Ave.
Before tanks and piping are covered from view, installer is required to notify the Fire Department of readiness for inspection and to refrain from covering up until approved by the Fire Dept.

5000 and
These tanks of 2000 gallons capacity are required to be of steel or wrought iron no less in thickness than #7 gauge and before installation are required to be protected against corrosion, even though galvanized, by two coats of tar, asphaltum, or other suitable rust-resisting paint, and special protection wherein corrosive soil such as cinders or the like.

Pipe lines connected to underground tanks, other than tubing and except fill lines and test wells, must be provided with double swing joints arranged to permit the tank to settle without impairing the efficiency of the pipe connections.

Owner and installer will have to bear the responsibility for the structural capacity of the tank to support loads from above such as heavy motor trucks.

If tank will be so located as to be subjected to the action of tide water or "ground" water, adequate anchorage or weighting must be provided to prevent "floating" when tank is empty or nearly so.



FILL IN AND SIGN WITH INK

APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIPMENT

Portland, Maine, September 13, 1963

PERMIT ISSUED
SEP 17 1963
CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 335 Brighton Ave. Use of Building Hospital No. Stories 2 New Building Existing
 Name and address of owner of appliance Osteopathic Hospital of Maine, 335 Brighton Ave.
 Installer's name and address Gould Farmer Co. of Maine, 70 Free St. Telephone

General Description of Work

To install oil burning equipment in connection with existing hot water heat for new addition.

IF HEATER, OR POWER BOILER

Location of appliance Any burnable material in floor surface or beneath?
 If so, how protected? Kind of fuel?
 Minimum distance to burnable material, from top of appliance or casing top of furnace
 From top of smoke pipe From front of appliance From sides or back of appliance
 Size of chimney flue Other connections to same flue
 If gas fired, how vented? Rated maximum demand per hour
 Will sufficient fresh air be supplied to the appliance to insure proper and safe combustion? Rec'd from Fire Dept. 9/13/63

IF OIL BURNER

Name and type of burner Petro Labelled by underwriters' laboratories? yes
 Will operator be always in attendance? Does oil supply line feed from top or bottom of tank? top
 Type of floor beneath burner concrete Size of vent pipe 2" for each tank
 Location of oil storage outside underground Number and capacity of tanks 1-5000 and 1-2000
 Low water shut off Make No.
 Will all tanks be more than five feet from any flame? yes How many tanks enclosed?
 Total capacity of any existing storage tanks for furnace burners none

IF COOKING APPLIANCE

Location of appliance Any burnable material in floor surface or beneath?
 If so, how protected? Height of Legs, if any
 Skirting at bottom of appliance? Distance to combustible material from top of appliance?
 From front of appliance From sides and back From top of smokepipe
 Size of chimney flue Other connections to same flue
 Is hood to be provided? If so, how vented? Forced or gravity?
 If gas fired, how vented? Rated maximum demand per hour

MISCELLANEOUS EQUIPMENT OR SPECIAL INFORMATION

Tanks to be buried at least 3' below grade, coated with asphaltum; bear Mnd. Lab.

Amount of fee enclosed? 2.00 (\$2.00 for one heater, etc., \$1.00 additional for each additional heater, etc., in same building at same time.)

APPROVED:

APPROVED
Carl P. Johnson
 CHIEF OF FIRE DEPT.
 O.N. 9 17 63
 CS 30C

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? Yes
 Gould Farmer Co. of Maine

Signature of Installer By: *[Signature]*

INSPECTION COPY

Permit No. 335
 Location Brighton Ave
 Over Stapette's Shopette
 Date of Permit 9/17/63

NOTES

1	Full Size	
2	Valve Pipe	
3	Kind of Eent	
4	Barrier Rtd. City & Support	
5	Manhole Label	
6	Stack Control	
7	High Line Control	
8	Manhole Label	
9	Piping Support & Protection	
10	Valve in Shop	
11	Capacity of Tanks	
12	Manhole Significance	
13	Stack Distance	
14	Oil Gauge	
15	Insulation (and)	
16	Low Water Staff	

3-25-64 Completed SW

Large empty lined area for notes, with a large handwritten 'X' in the upper left portion.



FILL IN AND SIGN WITH INK

APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIPMENT

Portland, Maine, January 17, 1963

PERMIT ISSUED
60063
CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location	335 Brighton Ave.	Use of Building	Hospital	No. Stories	NEW Building
Name and address of owner of appliance	Osteopathic Hospital of Maine, 335 Brighton Ave.		Existing "		
Installer's name and address	Portland Gas Light Co., 5 Temple St.	Telephone			

General Description of Work

To install gas-fired Vulcan range #6172-45A

IF HEATER, OR POWER BOILER

Location of appliance basement
 Any burnable material in floor surface or beneath? no
 If so, how protected? Kind of fuel?
 Minimum distance to burnable material, from top of appliance or casing top of furnace
 From top of smoke pipe From front of appliance From sides or back of appliance
 From chimney flue Other connections to same flue
 If gas fired, how vented? Rated maximum demand per hour
 Will sufficient fresh air be supplied to the appliance to insure proper and safe combustion?

IF OIL BURNER

Name and type of burner Labelled by underwriters' laboratories?
 Will operator be always in attendance? Does oil supply line feed from top or bottom of tank?
 Type of floor beneath burner Size of vent pipe
 Location of oil storage Number and capacity of tanks
 Low water shut off Make No.
 Will all tanks be more than five feet from any flame? How many tanks enclosed?
 Total capacity of any existing storage tanks for furnace burners

IF COOKING APPLIANCE

Location of appliance basement
 Any burnable material in floor surface or beneath? no
 If so, how protected? Height of Legs, if any 4"
 Skirting at bottom of appliance? no Distance to combustible material from top of appliance? 3'
 From front of appliance 3' From sides and back 4' From top of smokepipe
 Size of chimney flue Other connections to same flue
 Is hood to be provided? existing If so, how vented? hood
 If gas fired, how vented? to existing hood to existing Forced or gravity? forced
 Rated maximum demand per hour

MISCELLANEOUS EQUIPMENT OR SPECIAL INFORMATION

#6172 P.G.L. Co.

Amount of fee enclosed? 2.00 (\$2.00 for one heater, etc., \$1.00 additional for each additional heater, etc., in same building at same time.)

APPROVED:
 [Signature] 1.17.63 [Signature]

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes
 Portland Gas Light Co.

CS 300

INSPECTION COPY

Signature of Installer By: *Walter A. Lane*

816

STATEMENT OF ELEVATOR TESTS

PORTLAND, MAINE, Mar 29 62

I, G. L. WARD

as an employee of OTIS ELEVATOR COMPANY, PORTLAND, MAINE, have personally supervised the installation or alterations to the elevator, hatchways and enclosures at Osteopathic Hospital, 335 Brighton Ave. under Building Permit _____, and have personally supervised tests of loading capacity and of all brakes, interlocking and all other safety devices, and I do here state that, according to my best knowledge and belief, the elevator will safely carry the maximum rated loading and all brakes, interlocking and other safety devices are in satisfactory condition.

George B. Ward
(Signature)

PORTLAND, MAINE,

STATE OF MAINE

CUMBERLAND, SS:

Personally appeared the above named _____ and made oath the statements by him subscribed are true.

John D. DeLeon
Notary Public Justice of the Peace

APPLICANT'S COPY

STATEMENT OF ELEVATOR TESTS

PORTLAND, MAINE, Mar 29-62

I, G. L. WARD

as an employee of OTIS ELEVATOR COMPANY, PORTLAND, MAINE, have personally supervised the installation or alterations to the elevator, hatchways and enclosures at R. E. Brown, 364 Spring St. as permitted under Building Permit _____, and have personally supervised tests of loading capacity and of all brakes, interlocking and all other safety devices, and I do here state that, according to my best knowledge and belief, the elevator will safely carry the maximum rated loading and all brakes, interlocking and other safety devices are in satisfactory condition.

George B. Ward
(Signature)

PORTLAND, MAINE,

STATE OF MAINE

CUMBERLAND, SS:

Personally appeared the above named _____ and made oath the statements by him subscribed are true.

John D. DeLeon
Notary Public Justice of the Peace

APPLICANT'S COPY

Memorandum from Department of Building Inspection, Portland, Maine

Amend. #2
AP- 335 Brighton Avenue
Jan. 18, 1962

Mr. Galli & Sons
53 Portland Street

cc to: James Saunders Assoc., 562 Congress St.
cc to: Gerald M. Kelley, Admins.
Osteopathic Hospital of Maine
335 Brighton Avenue

Dear Mr. Galli:

Permit to strengthen channel plate in corridor partitions at third floor with (2)-4-inch structural steel channels welded to studs and to strengthen framing around chimney at all floors and roof as per your plan received 1/17/62 is being issued subject to the following conditions:

2-hour fire roofing by use of wire lath and plaster or other means is required around angle iron columns supporting framing around the chimney at the first floor.

OK
1-19-62
mll

Held.

Very truly yours,

Gerald E. Mayberry
Deputy Inspector of Buildings

GEN:m

CS-27

*Granted 6/29/61
6/1/49*

DATE: June 29, 1961

HEARING ON APPEAL UNDER THE ZONING ORDINANCE OF OSTEOPATHIC HOSPITAL OF MAINE
AT 329-335 Brighton Avenue

Public Hearing on the above appeal was held before the Board of Appeals.

BOARD OF APPEALS

VOTE

Franklin G. Hinckley
Harry M. Schwartz
Ralph L. Young

Yes

()
()
()

No

()
()
()

Record of Hearing:

ALBERT J. SEARS
INSPECTOR OF BUILDINGS

CITY OF PORTLAND, MAINE
Department of Building Inspection

43921

AP-329-335 Brighton Avenue

June 15, 1961

Mr. Gerald M. Kelley, Administrator cc to: James Saunders Assoc.
Osteopathic Hospital of Maine 562 Congress Street
335 Brighton Avenue ✓ cc to: Corporation Counsel

Dear Mr. Kelley:

Building permit for construction of a three story and basement addition to hospital at the above named location is not issuable under the Zoning Ordinance because the height is to exceed the maximum of 2½ stories set by Section 4-B-5 of the Ordinance applying to the R-3 Residence Zone in which the property is located.

We understand that you would like to exercise your appeal rights concerning this discrepancy. Accordingly we are certifying the case to the Corporation Counsel, to whose office in Room 208, City Hall, you should go to file the appeal.

Very truly yours,

Ajs/jg

Albert J. Sears
Building Inspection Director

C
O
P
Y

CITY OF PORTLAND, MAINE
BOARD OF APPEALS

June 26, 1961

TO WHOM IT MAY CONCERN:

The Board of Appeals will hold a public hearing in the Council Chamber at City Hall, Portland, Maine, on Thursday, June 29, 1961, at 4:00 P.M. to hear the appeal of the Osteopathic Hospital of Maine requesting an exception to the Zoning Ordinance to permit construction of a three-story and basement addition to the hospital at 329-335 Brighton Avenue.

This permit is presently not issuable because the height is to exceed the maximum of 2½ stories set by Section 4-B-5 of the Ordinance applying to the R-3 Residence Zone in which the property is located.

All persons interested either for or against this appeal will be heard at the above time and place.

BOARD OF APPEALS

Franklin G. Hinckley

Chairman

S



FILL IN AND SIGN WITH INK

APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIPMENT

Portland, Maine, Dec. 26, 1956

PERMIT ISSUED 02257 DEC 26 1956 CITY OF PORTLAND

N-1172

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

329-355

Location 335 Brighton Ave. Use of Building Hospital No. Stories New Building Existing Name and address of owner of appliance Osteopathic Hospital of Maine, 335 Brighton Ave. Installer's name and address E. N. Cunningham Co., 363 Cumberland Ave. Telephone 3-9671

General Description of Work

To install 3 steam boilers, two low pressure and one high pressure (replacement)

IF HEATER, OR POWER BOILER

Location of appliance boiler room Any burnable material in floor surface or beneath? no If so, how protected? Kind of fuel? oil Minimum distance to burnable material, from top of appliance or casing top of furnace * From top of smoke pipe * From front of appliance * From sides or back of appliance * Size of chimney flue 22x25 Other connections to same flue none (3 boilers on same boiler) If gas fired, how vented? Rated maximum demand per hour Will sufficient fresh air be supplied to the appliance to insure proper and safe combustion? yes

IF OIL BURNER by Gould Farmer Co.

Name and type of burner Labelled by underwriters' laboratories? Will operator be always in attendance? Does oil supply line feed from top or bottom of tank? Type of floor beneath burner Size of vent pipe Location of oil storage Number and capacity of tanks Low water shut off Make No. Will all tanks be more than five feet from any flame? How many tanks enclosed? Total capacity of any existing storage tanks for furnace burners

IF COOKING APPLIANCE

Location of appliance Any burnable material in floor surface or beneath? If so, how protected? Height of Legs, if any Skirting at bottom of appliance? Distance to combustible material from top of appliance? From front of appliance From sides and back From top of smokepipe Size of chimney flue Other connections to same flue Is hood to be provided? If so, how vented? Forced or gravity? If gas fired, how vented? Rated maximum demand per hour

MISCELLANEOUS EQUIPMENT OR SPECIAL INFORMATION

*No combustible material

Amount of fee enclosed? \$3.00 (\$2.00 for one heater, etc., 50 cents additional for each additional heater, etc., in same building at same time.)

APPROVED: 12-26-56 O.K. NFE

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

E. N. Cunningham Co.

Signature of Installer by: [Signature]

CITY MAINE PRINTING CO.

UTION COPY

8-16-57 L. ...

Permit No. 562257
Location 335 Brighton Ave.
Owner Catholic Hospital
Date of permit 12/26/58
Approved

Handwritten notes and a large 'X' mark on a lined section of the form.

Large empty table with multiple columns and rows of horizontal lines for data entry.

Osteopathic Hospital
335 Brighton Avenue

May 1, 1972

Consolidated Constructors & Builders, Inc.
616 Congress Street

cc to: Fels Com
Presump

Gentlemen:

Permit to install air conditioning system on roof,
serving third floor operating rooms and part through to second
floor delivery room is hereby issued providing that fire
dampers will be installed in ducts penetrating third floors
if not previously provided in existing ducts.

Very truly yours,

Nelson F. Cartwright
Building Inspector

NFC:m



APPLICATION FOR PERMIT

Class of Building or Type of Structure _____

Portland, Maine, April 27, 1972

PERMIT ISSUED

MAY 2 1972

0471

CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 335 Brighton Ave. Within Fire Limits? _____ Dist. No. _____
 Owner's name and address Osteopathic Hospital of Maine, 335 Brighton Ave. Telephone _____
 Lessee's name and address _____ Telephone _____
 Contractor's name and address Consolidated Constructors & Builders, Inc. Telephone _____
 Architect 616 Congress St. Specifications _____ Plans _____ No. of sheets _____
 Proposed use of building Hospital No. families _____
 Last use _____ " _____ No. families _____
 Material _____ No. stories _____ Heat _____ Style of roof _____ Roofing _____
 Other buildings on same lot _____
 Estimated cost \$ _____ Fee \$ 10.00

General Description of New Work

To install air conditioning system - existing penthouse - and update air conditioning system as per plan

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. **PERMIT TO BE ISSUED TO** contractors

Details of New Work

Is any plumbing involved in this work? _____ Is any electrical work involved in this work? _____
 Is connection to be made to public sewer? _____ If not, what is proposed for sewage? _____
 Has septic tank notice been sent? _____ Form notice sent? _____
 Height average grade to top of plate _____ Height average grade to highest point of roof _____
 Size, front _____ depth _____ No. stories _____ solid or filled land? _____ earth or rock? _____
 Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
 Kind of roof _____ Rise per foot _____ Roof covering _____
 No. of chimneys _____ Material of chimneys _____ of lining _____ Kind of heat _____ fuel _____
 Framing Lumber—Kind _____ Dressed or full size? _____ Corner posts _____ Sills _____
 Size Girder _____ Columns under girders _____ Size _____ Max. on centers _____
 Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
 Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
 On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
 Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
 If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____ number commercial cars to be accommodated _____
 Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will work require disturbing of any tree on a public street? _____
 Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Osteopathic Hospital of Maine
 Consolidated Constructors & Builders

APPROVED:

OK 5-1-72 NFE

with memo

PERMIT ISSUED WITH LETTER

CS 301

INSPECTION COPY

Signature of owner By: Alexander H. Curless

NOTES

5-31-72 To start RD
 June 29th RD
 Shut down opr. rooms. RD
 completed RD
 X

Permit No. 72/0171
 Location 335 Brighton Ave
 Owner Rotespartie Shop of Maine
 Date of permit 5/2/72
 Notif. closing-in
 Inspn closing-in
 Final Notif.
 Final Inspn.
 Cert. of Occupancy issued
~~Seeking-GR Notice~~
 Form Check Notice