

117 Ashmont St.

124-G-18

  
SHAW-WALKER  
# 8503-3R

October 4, 1978

Edward A. & Bernice M. Smith  
117 Ashmont Street  
Portland, Maine 04103

Dear Mr. & Mrs. Smith      Re: 117 Ashmont Street, Portland, Maine      NCP-Oakdale  
124-3-18

The Housing Inspections Division of the Department of Neighborhood Conservation has recently completed an exterior inspection of your property in conjunction with the above referred program.

Congratulations are extended to you for the general condition of your property which was found to meet the standards established by the City's Housing Code. We did, however, note the following items that could cause future problems.

RIGHT WALL - missing gutter.

RIGHT WALL - rotted and missing fascia board.

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely yours,  
Joseph E. Gray, Jr., Director  
Neighborhood Conservation

By Lyle D. Noyes  
Lyle D. Noyes,  
Chief of Housing Inspections

Inspector G. Bartlett  
G. Bartlett

vw

