

70 Ashmont Street

125-G-8



SILVA-WALKER

8503-1R

X
Sept. 15, 1978 ✓

Kenneth E. & Marsha J. Loveitt
70 Ashmont Street
Portland, Maine 04103

Mr. & Mrs. Kenneth Loveitt Re: 70 Ashmont Street, Portland, Maine NCP-Cakdala
125-G-8

The Housing Inspections Division of the Department of Neighborhood Conservation has recently completed an exterior inspection of your property in conjunction with the above referred program.

Congratulations are extended to you for the general condition of your property which was found to meet the standards established by the City's Housing Code. We did, however, note the following items that could cause future problems.

LEFT REAR STEPS- rotted and broken treads.

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely yours,
Joseph E. Gray, Jr., Director
Neighborhood Conservation

By Lyle D. Noyes
Lyle D. Noyes,
Chief of Housing Inspections

Inspector: H. Bartlett
G. Bartlett

vw

