48 Ashmont Street

125-4-10



Sept. 15, 197[illegible]

Alice A. Stillman
48 Ashmont Street
Portland, Maine 04103

Dear Ms. Stillman Re: 48 Ashmont Street, Portland, Maine NCP-Oakdale
125-H-10

The Housing Inspections Division of the Department of Neighborhood Conservation has recently completed an exterior inspection of your property in conjunction with the above referred program.

Congratulations are extended to you for the general condition of your property which was found to meet the standards established by the City's Housing Code. We did, however, note the following items that could cause future problems.

LEFT WALL- rotted gutter.
RIGHT ROOF- worn shingles.

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely yours,
Joseph E. Gray, Jr., Director
Neighborhood Conservation

By Lyle D. Noyes
Lyle D. Noyes,
Chief of Housing Inspections

Inspector G. Bartlett
G. Bartlett

vw

City of Portland

OK-1st EX

NEIGHBORHOOD CONSERVATION

STRUCTURE INSPECTION SCHEDULE

Housing Inspection Division

1) Insp Name BARTLETT

2)Insp.Date	3)Insp.Type	4)Proj.Code	5)Assr's: Chart	6)Bl.	7)Lot	8)Census Tract	9)Blk.	10)Insp.	11)Form NO.
9/11-3		NCP-OAK	125	N	10			6	

12)Hous No.	13)Sec.H.No.	14)Suff.	15)Direct	16)Street Name	17)St.Design.
48				ASHMONT	ST

13)Owner or Agent: ALICE A. STINMAD

19)Status 020 20)Bldg's Rat. 2

21)Address: 48 ASHMONT ST

22)City and State: PTLD. ME Zip Code: 04103

23)D.Units	24)Occ.D.U.s	25)Rm.Units	26)Occ.R.U.s	27)No.Occupants	28)Com'l U.	29)Bldg.Type	30)Stories	31)Const.Mat	32)O.Bs
1	1								

33)C.H.	34)Photo	35)Zoned For	36)Actual Land Use	37)D.D	38)Lks.Ad.Bth.Fac. Yes No	39)Disp.	40)ClosingDate

Viol. No.	Remedy	Cond.	Violation Description	Fl. No.	Loc.	Room Type	Area Type	Resp. Party	Code Sect. Viol.	Viol. Rem.Date
1		RO	GUTTER		LE		WA			
2		WO	SHINGLES		RI		RO			