

20-24 BELMONT ST.

SHANKS & BLAKE
MADE IN U.S.A.



APPLICATION FOR PERMIT

PERMIT ISSUED
RECEIVED
OCT 19 1976
DEPT. OF BLDG. INSP.
CITY OF PORTLAND
0950

B.O.C.A. USE GROUP
B.O.C.A. TYPE OF CONSTRUCTION
ZONING LOCATION R-3 PORTLAND, MAINE, Oct. 15, 1976

To the DIRECTOR OF BUILDING & INSPECTION SERVICES, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect, alter, repair, demolish, move or install the following building, structure, equipment or change use in accordance with the Laws of the State of Maine, the Portland B.O.C.A. Building Code and Zoning Ordinance of the City of Portland with plans and specifications, if any, submitted herewith and the following specifications:

LOCATION 20 Belmont St. Fire District #1 #2
1. Owner's name and address ... Anthony Lombardi - same Telephone 772-9749
2. Lessee's name and address Telephone
3. Contractor's name and address ... State Construction - Box 827, Scarborough Telephone 774-8808
4. Architect Specifications Plans No. of sheets
Proposed use of building garage No. families
Last use No. families
Material No. stories Heat Style of roof Roofing
Other buildings on same lot
Estimated contractual cost \$ 3,600 Fee \$ 16.00

FIELD INSPECTOR—Mr. GENERAL DESCRIPTION
This application is for: @ 775-5451
Dwelling Ext. 234 Permit to construct 2 car garage 22 x24
Garage as per plans, 1 sheet of plans
Masonry Bldg. Stamp of Special Conditions
Metal Bldg.
Alterations
Demolitions
Change of Use
Other

NOTE TO APPLICANT: Separate permits are required by the installers and subcontractors of heating, plumbing, electrical and mechanicals.

PERMIT IS TO BE ISSUED TO 1 2 3 4
Other:

DETAILS OF NEW WORK

Is any plumbing involved in this work? no Is any electrical work involved in this work? no
Is connection to be made to public sewer? If not, what is proposed for sewage?
Has septic tank notice been sent? Form notice sent?
Height average grade to top of plate Height average grade to highest point of roof
Size, front depth No. stories solid or filled land? earth or rock?
Material of foundation Thickness, top bottom cellar
Kind of roof Rise per foot Roof covering
No. of chimneys Material of chimneys of lining Kind of heat fuel
Framing Lumber—Kind Dressed or full size? Corner posts Sills
Size Girder Columns under girders Size Max. on centers
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
Joists and rafters: 1st floor 2nd 3rd roof
On centers: 1st floor ... 16 in 2nd 3rd roof
Maximum span: 1st floor 2nd 3rd roof
If one story building with masonry walls, thickness of walls? height?

IF A GARAGE

No. cars now accommodated on same lot, to be accommodated 2. number commercial cars to be accommodated ...
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building?

APPROVALS BY: DATE
BUILDING INSPECTION—PLAN EXAMINER
ZONING: O.R. M.C. 10/18/76
BUILDING CODE: O.K. E.B. 10/18/76
Fire Dept.:
Health Dept.:
Others:

MISCELLANEOUS
Will work require disturbing of any tree on a public street? no
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Signature of Applicant Anita Chandler Phone # same
Type Name of above Anita Chandler 1 2 3 4
Other
and Address

FIELD INSPECTOR'S COPY

3:25 pm

NOTES

10/21/76

Same Gilbon location

11-15-76 lady at the house said the contractor has 10 more days to the deadline. Fill pit in place.

Location appears OK

Feb 23/77

Same
Mar 30/77 No change - it would appear the owner has lost interest etc. No one answered door.

June 7/77 Margie talked with me about this. The owner called (lady) & thought the garage was not constructed properly.

She thought the ties that are approx 6 ft apart were rafters holding the roof up etc. This was not so, they were ties that act to keep the rafter from spreading. The garage appears to be well constructed.

Tried the door & bell - no one home. Garage completed. The slab of fill was not inspected, this has been dragging along for some time & I was out for a week it was built etc. without us knowing anything about it.

Permit No. 761959
Location 21 Gilman St
Owner Carthage Jewhand
Date of permit 10/21/76
Approved 10-19-76

Barshid v. inc. -



R3 RESIDENCE ZONE

APPLICATION FOR PERMIT

Class of Building or Type of Structure Third Class

Portland, Maine, September 28, 1965

PERMIT ISSUED
SEP 30 1965
CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 20 Belmont Street Within Fire Limits? _____ Dist. No. _____
 Owner's name and address Anthony Lombardi, 20 Belmont Street Telephone _____
 Lessee's name and address _____ Telephone _____
 Contractor's name and address Charles Roberts, Owner Telephone _____
 Architect _____ Specifications _____ Plans no No. of sheets _____
 Proposed use of building Dwelling No. families 1
 Last use " No. families 1
 Material frame No. stories 2 1/2 Heat _____ Style of roof _____ Roofing _____
 Other buildings on same lot _____
 Estimated cost \$ 95. Fee \$ 2.00

General Description of New Work

To change out two existing windows, first floor, to one window 30" x 60" - 4x6 header - This window is in the kitchen and is on side of building.

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. **PERMIT TO BE ISSUED TO** owner

Details of New Work

Is any plumbing involved in this work? _____ Is any electrical work involved in this work? _____
 Is connection to be made to public sewer? _____ If not, what is proposed for sewage? _____
 Has septic tank notice been sent? _____ Form notice sent? _____
 Height average grade to top of plate _____ Height average grade to highest point of roof _____
 Size, front _____ depth _____ No. stories _____ solid or filled land? _____ earth or rock? _____
 Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
 Kind of roof _____ Rise per foot _____ Roof covering _____
 No. of chimneys _____ Material of chimneys _____ of lining _____ Kind of heat _____ fuel _____
 Framing Lumber--Kind _____ Dressed or full size? _____ Corner posts _____ Sills _____
 Size Girder _____ Columns under girders _____ Size _____ Max. on centers _____
 Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
 Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
 On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
 Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
 If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____ number commercial cars to be accommodated _____
 Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

APPROVED:

J. E. M.

Miscellaneous

Will work require disturbing of any tree on a public street? no
 Will there be in-charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

CS 301

INSPECTION COPY

Signature of owner

Paul Anthony Lombardi

PK



FILL IN AND SIGN WITH INK

APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIPMENT

Portland, Maine, Sept. 26, 1958

PERMIT ISSUED
01326
SEP 26 1958
CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 20 Belmont St. Use of Building Dwelling No. Stories 2 New Building Existing "Existing"
 Name and address of owner of appliance H. Warren Paine, 20 Belmont St.
 Installer's name and address Harris Oil Co., 202 Commercial St. Telephone 2-8304

General Description of Work

To install Hot water boiler and oil burning equipment circulating hot water system in place of coal-fired hot water boiler.

IF HEATER, OR POWER BOILER

Location of appliance Basement Any burnable material in floor surface or beneath? none
 If so, how protected? Kind of fuel? oil
 Minimum distance to burnable material, from top of appliance or casing top of furnace 3'
 From top of smoke pipe 2 1/2' From front of appliance over 4' From sides or back of appliance over 3'
 Size of chimney flue 16x24 Other connections to same flue hot water heater
 If gas fired, how vented? Rated maximum demand per hour
 Will sufficient fresh air be supplied to the appliance to insure proper and safe combustion? yes

IF OIL BURNER

Name and type of burner Crane-gumtype Labeled by underwriters' laboratories? yes
 Will operator be always in attendance? Does oil supply line feed from top or bottom of tank? bottom
 Type of floor beneath burner concrete Size of vent pipe 1 1/2"
 Location of oil storage basement Number and capacity of tanks 2-275 gals.
 Low water shut off Make No. none
 Will all tanks be more than five feet from any flame? yes How many tanks enclosed? none
 Total capacity of any existing storage tanks for furnace burners none

IF COOKING APPLIANCE

Location of appliance Any burnable material in floor surface or beneath?
 If so, how protected? Height of Legs, if any
 Skirting at bottom of appliance? Distance to combustible material from top of appliance?
 From front of appliance From sides and back From top of smokepipe
 Size of chimney flue Other connections to same flue
 Is hood to be provided? If so, how vented? Forced or gravity?
 If gas fired, how vented? Rated maximum demand per hour

MISCELLANEOUS EQUIPMENT OR SPECIAL INFORMATION

Amount of fee enclosed? 2.00 (\$2.00 for one heater, etc., 50 cents additional for each additional heater, etc., in same building at same time.)

APPROVED:

[Signature]
9.26.58

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? Yes

Harris Oil Co.

Signature of Installer

by:

[Signature]

CITY MAINE PRINTING CO.

INSPECTION COPY

Fm



(RAA) RESIDENCE ZONE - AA
CITY OF PORTLAND, MAINE
DEPARTMENT OF BUILDING INSPECTION

CS-66

COMPLAINT 126-C-E

INSPECTION COPY

COMPLAINT NO. 57/35

Date Received 5/23/57

Location 20-24
22 Belmont St.

Owner's name and address Warren Paine 38 Spring Use of Building 1-family dwelling
Ruth B. Paine, 20 Belmont St.

Tenant's name and address Telephone 5-2713
Mrs. Hunter, tenant Telephone 27446

Complainant's name and address Beverly E. Telephone
Mrs. Hunter, tenant Telephone

Description: Chimney dangerous above roof

Location: 22 Belmont St.

PH

NOTES: 5-28-57 ~~Full roof sitting over chimney, there
is a hole in the roof, nothing here
that is immediately dangerous.~~ VJm

6-3-57 Mrs. Hunter says neighbors made
complaint. She talked to Warren
Paine last night about replacing porch
and deck. He said he'd call a carpenter
was to have been there Saturday.
She told him the roof was being
worked with he made these repairs.
Mrs. Hunter is trying to find a
different house. VJm

6-20-57 Front porch being replaced. I could
not find any chimney that I would
consider dangerous if only we in this
house. Mrs. Hunter says Mr. Paine would
be here to remove it. I told her to have
the chimney cleaned out and the clean
out door put back in its niche. VJm

923697

Permit # _____ City of Portland BUILDING PERMIT APPLICATION Fee \$80.00 Zone _____ Map # _____ Lot # _____

Please fill out any part which applies to job. Proper plans must accompany form.

Owner: Bennett Bergman Phone # 871-7020
 Address: 20 Belmont St. Ptld
 LOCATION OF CONSTRUCTION 20 Belmont St. Ptld, ME 04103
 Contractor: Kurz Construction Sub: _____
 * Address: P.O. Box 6749 Ptld, Me 04101 Phone # 775-3944
 Est. Construction Cost: 12,000.00 Proposed Use: interior renovations
 Past Use: Single Fam residence
 # of Existing Res. Units _____ # of New Res. Units _____
 Building Dimensions L _____ W _____ Total Sq. Ft. _____
 # Stories: _____ # Bc rooms _____ Lot Size: _____
 Is Proposed Use: Seasonal _____ Condominium _____ Conversion _____
 Explain Conversion interior renovations

For Official Use Only
 Date 5/20/92 Subdivision: _____ Name: _____
 Inside Fire Limits _____
 Bldg Code _____ Ownership: CITY OF PORTLAND
 Time Limit _____
 Estimated Cost _____
 Zoning: _____
 Street Frontage Provided: _____
 Provided Setbacks: Front _____ Back _____ Side _____
 Review Required:
 Zoning Board Approval: Yes _____ No _____ Date: _____
 Planning Board Approval: Yes _____ No _____ Date: _____
 Conditional Use _____ Variance _____ Site Plan _____ Subdivision _____
 Shoreland Zoning Yes _____ No _____ Floodplain Yes _____ No _____
 Special Exception _____
 Other WMA 5-21-92

PERMIT ISSUED
 MAY 27 1992
 CITY OF PORTLAND

Foundation:
 1. Type of Soil: _____
 2. Set Backs - Front _____ Rear _____ Side(s) _____
 3. Footings Size: _____
 4. Foundation Size: _____
 5. Other _____

Floor:
 1. Sills Size: _____ Sills must be anchored.
 2. Girder Size: _____
 3. Lally Column Spacing: _____ Size: _____
 4. Joists Size: _____ Spacing 16" O.C.
 5. Bridging Type: _____ Size: _____
 6. Floor Sheathing Type: _____ Size: _____
 7. Other Material: _____

Exterior Walls:
 1. Studding Size _____ Spacing _____
 2. No. windows _____
 3. No. Doors _____
 4. Header Sizes _____ Span(s) _____
 5. Bracing: Yes _____ No _____
 6. Corner Posts Size _____
 7. Insulation Type _____ Size _____
 8. Sheathing Type _____ Size _____
 9. Siding Type _____ Weather Exposure _____
 10. Masonry Materials _____
 11. Metal Materials _____

Interior Walls:
 1. Studding Size _____ Spacing _____
 2. Header Sizes _____ Span(s) _____
 3. Wall Covering Type _____
 4. Fire Wall if required _____
 5. Other Materials _____

Ceiling:
 1. Ceiling Joists Size: _____ Spacing _____
 2. Ceiling Strapping Size _____ Spacing _____
 3. Type Ceilings: _____ Size _____
 4. Insulation Type _____ Size _____
 5. Ceiling Height: _____
 HISTORIC PRESERVATION
 Not in District nor Landmark.
 Does not require review.
 Requires Review.

Roof:
 1. Truss or Rafter Size _____ Span _____
 2. Sheathing Type _____ Size _____
 3. Roof Covering Type _____
 Action: Approved
 Approved with conditions.

Chimneys:
 Type: _____ Number of Fire Places _____
 Signature: _____

Heating:
 Type of Heat: _____

Electrical:
 Service Entrance Size: _____ Smoke Detector Required Yes _____ No _____

Plumbing:
 1. Approval of soil test if required Yes _____ No _____
 2. No. of Tubs or Showers _____
 3. No. of Flushes _____
 4. No. of Lavatories _____
 5. No. of Other Fixtures _____

Swimming Pools:
 1. Type: _____
 2. Pool Size: _____ x _____ Square Footage _____
 3. Must conform to National Electrical Code and State Law.

Permit Received By _____ Date 5/20/92

Signature of Applicant Bennett Bergman Date 5/20/92

CEO's District 16 MR. ROWE

CONTINUED TO REVERSE SIDE
 Ivory Tag - CEO

White - Tax Assessor



APPLICATION FOR PERMIT
DEPARTMENT OF BUILDING INSPECTIONS SERVICES
ELECTRICAL INSTALLATIONS

Date 6/8/92, 19
 Receipt and Permit number 7765

To the CHIEF ELECTRICAL INSPECTOR, Portland, Maine:

The undersigned hereby applies for a permit to make electrical installations in accordance with the laws of Maine, the Portland Electrical Ordinance, the National Electrical Code and the following specifications:

LOCATION OF WORK: 20 Belmont St.

OWNER'S NAME: Bennett Bergman ADDRESS: _____

	FEES
OUTLETS:	
Receptacles <u>15</u> Switches <u>10</u> Plugmold _____ ft. TOTAL <u>25</u>	5/00
FIXTURES: (number of)	
Incandescent <u>10</u> Fluorescent _____ (not strip) TOTAL <u>10</u>	x 2.00
Strip Fluorescent _____ ft.	
SERVICES:	
Overhead _____ Underground _____ Temporary _____ TOTAL amperes _____	
METERS: (number of)	
MOTORS: (number of)	
Fractional:	
1 HP or over	
RESIDENTIAL HEATING:	
Oil or Gas (number of units)	
Electric (number of rooms)	
COMMERCIAL OR INDUSTRIAL HEATING:	
Oil or Gas (by a main boiler)	
Oil or Gas (by separate units)	
Electric Under 20 kws _____ Over 20 kws _____	
APPLIANCES: (number of)	
Ranges _____ Water Heaters _____	
Cook Tops _____ Disposals _____	
Wall Ovens _____ Dishwashers _____	
Dryers _____ Compactors _____	
Fans _____ Others (denote) _____	
TOTAL	
MISCELLANEOUS: (number of)	
Branch Panels	
Transformers	
Air Conditioners Central Unit	
Separate Units (windows)	
Signs 20 sq. ft. and under	
Over 20 sq. ft.	
Swimming Pools Above Ground	
In Ground	
Fire/Burglar Alarms Residential	
Commercial	
Heavy Duty Outlets, 220 Volt (such as welders) 30 amps and under	
over 30 amps	
Circus, Fairs, etc.	
Alterations to wires <u>X</u>	5.00
Repairs after fire	
Emergency Lights, battery	
Emergency Generators	

INSTALLATION FEE DUE: _____
 FOR ADDITIONAL WORK NOT ON ORIGINAL PERMIT DOUBLE FEE DUE: _____
 FOR REMOVAL OF A "STOP ORDER" (304-16.b)
 TOTAL AMOUNT DUE: 15.00
 minimum fee

INSPECTION:
 Will be ready on 6/9 pm _____ or Will Call _____
 CONTRACTOR'S NAME: T A Napoli, Inc
 ADDRESS: Box 2301 - So Portland
 TEL.: 799-0538
 MASTER LICENSE NO.: #7765 SIGNATURE OF CONTRACTOR: _____
 LIMITED LICENSE NO.: _____

INSPECTOR'S COPY — WHITE
 OFFICE COPY — CANARY
 CONTRACTOR'S COPY — GREEN

923697 923697

Permit # _____ City of Portland BUILDING PERMIT APPLICATION Fee _____ Zone _____ Map # _____ Lot # _____

Please fill out any part which applies to job. Proper plans must accompany form.

Owner: Bennett Bergman Phone # 871-7920

Address: 20 Belmont St. P.tld

LOCATION OF CONSTRUCTION 20 Belmont St. P.tld, ME. 04103

Contractor: Kurz Construction Sub: _____

Address: P.O. Box 6789 P.tld, Me 04101 Phone # 775-3944

Est. Construction Cost: 12,000.00 Proposed Use: interior renovations

Past Use: Single Fam residence

of Existing Res. Units _____ # of New Res. Units _____

Building Dimensions L _____ W _____ Total Sq. Ft. _____

Stories: _____ # Bedrooms _____ Lot Size: _____

Is Proposed Use: Seasonal _____ Condominium _____ Conversion _____

Explain Conversion interior renovations

Foundation:
1. Type of Soil: _____
2. Set Backs - Front _____ Rear _____ Side(s) _____
3. Footings Size: _____
4. Foundation Size: _____
5. Other _____

Floor:
1. Sills Size: _____ Sills must be anchored.
2. Girder Size: _____
3. Lally Column Spacing: _____ Size: _____
4. Joists Size: _____ Spacing 16" O.C.
5. Bridging Type: _____ Size: _____
6. Floor Sheathing Type: _____ Size: _____
7. Other Material: _____

Exterior Walls:
1. Studding Size _____ Spacing _____
2. No. windows _____
3. No. Doors _____
4. Header Sizes _____ Span(s) _____
5. Bracing: Yes _____ No _____
6. Corner Posts Size _____
7. Insulation Type _____ Size _____
8. Sheathing Type _____ Size _____
9. Siding Type _____ Weather Exposure _____
10. Masonry Materials _____
11. Metal Materials _____

Interior Walls:
1. Studding Size _____ Spacing _____
2. Header Sizes _____ Span(s) _____
3. Wall Covering Type _____
4. Fire Wall If required _____
5. Other Materials _____

White - Tax Assessor

Date <u>5/20/92</u>		Subdivision
Inside Fire Limits _____		Name
Bldg Code _____		City of <u>Portland</u>
Time Limit _____		Ownership
Estimated Cost _____		Private

PERMIT ISSUED
MAY 27 1992
CITY OF PORTLAND

Zoning:
Street Frontage Provided: _____
Provided Setbacks: Front _____ Back _____ Side _____ Side _____
Review Required:
Zoning Board Approval: Yes _____ No _____ Date: _____
Planning Board Approval: Yes _____ No _____ Date: _____
Conditional Use: _____ Variance _____ Site Plan _____ Subdivision _____
Shoreland Zoning Yes _____ No _____ Floodplain Yes _____ No _____
Special Exception _____
Other W.A. 5-21-92 (Explain)

Ceiling:
1. Ceiling Joists Size: _____
2. Ceiling Strapping Size _____ Spacing _____
3. Type Ceilings: _____
4. Insulation Type _____ Size _____
5. Ceiling Height: _____

Roof:
1. Truss or Rafter Size _____ Span _____
2. Sheathing Type _____ Size _____
3. Roof Covering Type _____
Action: Approved with conditions

Chimneys:
Type: _____ Number of Fire Places _____ Dots _____

Heating:
Type of Heat: _____

Electrical:
Service Entrance Size: _____ Smoke Detector Required Yes _____ No _____

Plumbing:
1. Approval of soil test if required Yes _____ No _____
2. No. of Tubs or Showers _____
3. No. of Flushes _____
4. No. of Lavatories _____
5. No. of Other Fixtures _____

Swimming Pools:
1. Type: _____
2. Pool Size: _____ x _____ Square Footage _____
3. Must conform to National Electrical Code and State Law.

Permit Received By J. Fees Date 5/20/92

Signature of Applicant Daniel Kurzman Date 5/20/92

CEO's District _____

CONTINUED TO REVERSE SIDE
Ivory Tag - CEO

PLOT PLAN

N



FEES (Breakdown From Front)

Base Fee \$ _____
 Subdivision Fee \$ _____
 Site Plan Review Fee \$ _____
 Other Fees \$ _____
 (Explain) _____
 Late Fee \$ _____

Inspection Record

Type	Date
<i>Done</i>	9.2.93
_____	____/____/____
<i>Al Lowe</i>	____/____/____
_____	____/____/____
_____	____/____/____

COMMENTS

CERTIFICATION

I hereby certify that I am the owner of record of the named property, or that the proposed work is authorized by the owner of record and that I have been authorized by the owner to make this application as has authorized agent and I agree to conform to all applicable laws of this jurisdiction. In addition, if a permit for work described in this application is issued, I certify that the code official or the code official's authorized representative shall have the authority to enter areas covered by such permit at any reasonable hour to enforce the provisions of the code(s) applicable to such permit.

SIGNATURE OF APPLICANT

[Signature]
 RESPONSIBLE PERSON IN CHARGE OF WORK, TITLE

ADDRESS

PHONE NO.

775 3974

PHONE NO.

BERGMAN RESIDENCE
20 BELMONT STREET
PORTLAND

SPECIFICATIONS

1. HALF BATH OFF KITCHEN

- A. REMOVE EXISTING ROCK, FIXTURES, SUB FLOOR, AND TRIM
- B. REPLACE ABOVE WITH NEW

2. MASTER BATH

- A. REMOVE EXISTING FIXTURES AND FLOOR
- B. REPLACE ABOVE WITH NEW/ PEDESTAL SINK IN PLACE OF VANITY

3. SUN ROOM

- A. REPLACE ALL WINDOWS WITH 8 - C4860 PEACHTREE CASEMENT W/
GRILLES AND SCREENS
- B. INSTALL NEW ENTRY DOOR 3' 0" PEACHTREE NEWPORT
- C. INSTALL FRENCH DOORS FROM KITCHEN TO SUN ROOM
- D. DEMO EXISTING CEILING/ STRAP AND ROCK

MISC.

WEATHER STRIP SIDE ENTRY DOOR

REPAIR CRACK IN FOUNDATION

REPAIR BANNISTER AND LATTICE/ FRONT PORCH

ELECTRICAL:

A. FAN IN BOTH BATHS UPSTAIRS

- 1. MASTER - FAN AND SWITCH BY MIRROR
- 2. 2nd - FAN IN PLACE OF RECESSED/SAME SWITCH