

37-59 and FRONT ST. (MODULAR HOMES)  
65-99



SHAW-WALKER

#9203-32







**APPLICATION FOR PERMIT**  
**DEPARTMENT OF BUILDING INSPECTIONS SERVICES**  
**ELECTRICAL INSTALLATIONS**

Date Jan. 30, 1979  
 Receipt and Permit number 42323/

To the CHIEF ELECTRICAL INSPECTOR, Portland, Maine:

The undersigned hereby applies for a permit to make electrical installations in accordance with the laws of Maine, the Portland Electrical Ordinance, the National Electrical Code and the following specifications:

LOCATION OF WORK: 31 Front St.  
 OWNER'S NAME: Portland Housing ADDRESS: \_\_\_\_\_

	FEES
<b>OUTLETS:</b>	
Receptacles <u>30</u> Switches _____ Plugmold _____ ft. TOTAL _____	<u>3.00</u>
<b>FIXTURES:</b> (number of)	
Incandescent _____ Fluorescent _____ (not strip) TOTAL _____	
Strip Fluorescent _____ ft. _____	
<b>SERVICES:</b>	
Overhead _____ Underground _____ Temporary _____ TOTAL amperes _____	
<b>METERS:</b> (number of) _____	
<b>MOTORS:</b> (number of)	
Fractional _____	
1 HP or over _____	
<b>RESIDENTIAL HEATING:</b>	
Oil or Gas (number of units) _____	
Electric (number of rooms) _____	
<b>COMMERCIAL OR INDUSTRIAL HEATING:</b>	
Oil or Gas (by a main boiler) _____	
Oil or Gas (by separate units) _____	
Electric Under 20 kws _____ Over 20 kws _____	
<b>APPLIANCES:</b> (number of)	
Ranges _____	Water Heaters _____
Cook Tops _____	Disposals _____
Wall Ovens _____	Dishwashers _____
Dryers _____	Compactors _____
Fans _____	Others (denote) _____
TOTAL _____	
<b>MISCELLANEOUS:</b> (number of)	
Branch Panels _____	
Transformers _____	
Air Conditioners Central Unit _____	
Separate Units (windows) _____	
Signs 20 sq. ft. and under _____	
Over 20 sq. ft. _____	
Swimming Pools Above Ground _____	
In Ground _____	
Fire/Burglar Alarms Residential _____	
Commercial _____	
Heavy Duty Outlets, 220 Volt (such as welders) 30 amps and under _____	
over 30 amps _____	
Circus, Fairs, etc. _____	
Alterations to wires _____	
Repairs after fire _____	
Emergency Lights, battery _____	
Emergency Generators _____	
	<b>INSTALLATION FEE DUE: <u>3.00</u></b>
FOR ADDITIONAL WORK NOT ON ORIGINAL PERMIT ..... DOUBLE FEE DUE: _____	
FOR REMOVAL OF A "STOP ORDER" (304-16.b) .....	
<b>TOTAL AMOUNT DUE: <u>3.00</u></b>	

**INSPECTION:**  
 Will be ready on noon, 1979; or Will Call \_\_\_\_\_  
 CONTRACTOR'S NAME: Marino Electric  
 ADDRESS: 68 Taft Ave.  
 TEL: 774-3129  
 MASTER LICENSE NO.: 2299 SIGNATURE OF CONTRACTOR: \_\_\_\_\_  
 LIMITED LICENSE NO.: \_\_\_\_\_

INSPECTOR'S COPY — WHITE  
 OFFICE COPY — CANARY  
 CONTRACTOR'S COPY — GREEN



# CITY OF PORTLAND, MAINE

## Application for Permit to Install Wires

Permit No. 55493  
 Issued 11/16/71

Portland, Maine, 1971

To the City Electrician, Portland, Maine:

The undersigned hereby applies for a permit to install wires for the purpose of conducting electric current, in accordance with the laws of Maine, the Electrical Ordinance of the City of Portland, and the following specifications:

*(This form must be completely filled out - Minimum Fee, \$1.00)*

Owner's Name and Address: ~~XXXXXXXXXXXXXXXXXX~~ JACK HORST Tel. \_\_\_\_\_  
 Contractor's Name and Address: 555 Falstaff Rd. Rochester, N.Y. 14609  
 Location: FRONT ST. Portland, Maine Project Use of Building: 50 Apts. + 1 Community Bldg.  
 Number of Families: \_\_\_\_\_ Stores: \_\_\_\_\_ Number of Stories: \_\_\_\_\_  
 Description of Wiring: New Work Additions Alterations

Pipe	Cable	Metal Molding	BX Cable	Plug Molding (No. of feet)	
No. Light Outlets		Plugs	Light Circuits	Plug Circuits	
FIXTURES: No.			Fluor. or Strip Lighting (No. feet)		
SERVICE: Pipe	Cable	Underground	No. of Wires	Size	
METERS: Relocated		Added	Total No. Meters		
MOTORS: Number	Phase	H. P.	Amps	Volts	Starter
HEATING UNITS:	Domestic (Oil)	No. Motors	Phase	H.P.	
	Commercial (Oil)	No. Motors	Phase	H.P.	
	Electric Heat (No. of Rooms)				

APPLIANCES: No. Ranges \_\_\_\_\_ Watts \_\_\_\_\_ Brand Feeds (Size and No.) \_\_\_\_\_  
 Elec. Heaters \_\_\_\_\_ Watts \_\_\_\_\_  
 Miscellaneous \_\_\_\_\_ Watts \_\_\_\_\_ Extra Cabinets or Panels \_\_\_\_\_

Transformers \_\_\_\_\_ Air Conditioners (No. Units) \_\_\_\_\_ Signs (No. Units) \_\_\_\_\_

Will commence \_\_\_\_\_ 19 \_\_\_\_\_ Ready to cover in \_\_\_\_\_ 19 \_\_\_\_\_ Inspection \_\_\_\_\_ 19 \_\_\_\_\_

Amount of Fee \$ 765.00

Signed \_\_\_\_\_

DO NOT WRITE BELOW THIS LINE

SERVICE .. ✓	METER	GROUND ✓
VISITS: 1      2      3      4      5      6		
7      8      9      10      11      12		

REMARKS:

Module Units \$15.00 per Apt. - Total Fee \$765.00  
 INSPECTED BY \_\_\_\_\_ (OVER)

Housing Project

FRONT ST

LOCATION

11/18/71

INSPECTION DATE

11/18/71

WORK COMPLETED

TOTAL NO. INSPECTIONS

REMARKS:

**FEEES FOR WIRING PERMITS EFFECTIVE JULY 31, 1963**

**WIRING**

1 to 30 Outlets	\$ 2.00
31 to 60 Outlets	3.00
Over 60 Outlets, each Outlet	.05

(Each twelve feet or fraction thereof of fluorescent lighting or any type of plug molding will be classed as one outlet).

**SERVICES**

Single Phase	2.00
Three Phase	4.00

**MOTORS**

Not exceeding 50 H.P.	3.00
Over 50 H.P.	4.00

**HEATING UNITS**

Domestic (Oil)	2.00
Commercial (Oil)	4.00
Electric Heat (Each Room)	.75

**APPLIANCES**

Ranges, Cooking Tops, Ovens, Water Heaters, Disposals, Built-in Dishwashers, Dryers, and any permanent built-in appliance — each unit	1.50
---	------

**MISCELLANEOUS**

FRONT STREET HOUSING PROJECT RESUME

11-10-71

The following matters should be considered if and when additional multi-family modular built units are to be constructed in the City of Portland.

While certain conditions not readily evident at the factory became apparent during the assembling of the units on the site, it was found to be too late to do much about it. The following items are those in question.

1. The plans submitted with the application showed a 1 1/2" void space between each unit. Actually however, some units measured close to 4" between modulars, thus causing excessive shear on plate above columns. This plate should have been of metal no less than 1/2" thick and wide enough to engage all four members of the built-up carrying timber. As to the cause of the 4" space as opposed to the 1 1/2" shown, there is no question in my mind but that transporting these modulars 600 miles over the road on flat beds, depositing them on the ground on Presumpscot Street, lifting them back on flat beds, dumping them back on the ground and finally placing them caused the cubes to become out of plumb and out of level. This excessive void space, open from basement to roof line, became nearly impossible to fire stop in a proper manner.
2. The plenum chambers and heat ducts were not covered with 14 lb. asbestos or equivalent as required by the Building Code. I might add here that under Section 119.6 of the BOCA basic Building Code the requirements are even more stringent.
3. In the future we would insist upon corroborating evidence that the forced warm air heating systems, setting on a combustible base in a confined area with a limited amount of air for combustion had been approved by the appropriate agencies, A.G.A., U.L., etc. On Oct. 20, 1971 we received a letter from Sterling Homex which said that "in answer to Point 1 of your letter of the "temporary certificate of occupancy" at the Front Street site in Portland, Sterling Homex Corp. confirmed that the gas-fired heating appliance installation has been approved by all necessary agencies." Evidence of this approval will follow this letter in a few days." The evidence has not been forth coming - - .
4. It should also be borne in mind that double trimmers and double headers must be provided around all openings in the floor joists caused by the passage of plumbing pipes. The floor joists making onto these headers, the headers themselves making onto the trimmers should be provided with strap hangers and not rely on end nailing.
5. Attention should be given to fire stopping around soil stacks, inside chimneys, if any, and around all other pipes and especially pre-fabricated chimneys, such as Metalbertos and VanPacker. In all pre-fabricated chimneys a cleanout must be provided.



6. Concrete block foundations should be reviewed with a jaundiced eye on any future public housing projects. The reason being that blocks are porous and because there really is no effective way to make concrete blocks one hundred percent waterproof. This is due to capillary action of the block itself, the fact that it is hollow and not as dense as a regular poured concrete foundation. You will find that because of the extremely pungent gases given off by the dump on which this whole project is situated, the basements are already accumulating gaseous and pungent odors. Concrete blocks are also easily damaged. At the preliminary closing-in inspection, for instance, I pushed two of the concrete blocks out onto the ground because they were not properly seated in mortar.

7. The yard drains in this project connected to the City of Portland sewers did not have traps installed in them to prevent sewer gases from escaping into the areas directly under the windows of the building to be occupied. It is my understanding this condition has been corrected, but certainly it was an oversight on the part of the contractor who should have known better.

Earle S. Smith  
Plan Examiner

Oct. 29, 1971

Mr. Paul F. Frinsko  
1 Monument Square

cc to: Jack Dexter, Portland Housing  
Authority, 211 Cumberland Ave.  
cc to: Sterling Homex Corp.  
1150 E. River Rd. Avon, New York

Gentlemen

Due to a misunderstanding as to whether the Public Housing Project on Front Street, Portland, Maine was to be a turn key or a straight public housing project paid for by stage payments from the Public Housing Authority, we now find that no fee was ever paid for the building permit.

Based on the cost of the project which was approximately \$1,200,000. ( ) this office requires that Sterling Homex pay a belated fee of \$3600.00 (\$3.00 per thousand), of actual construction cost.

Very truly yours,

R. Lovell Brown  
Director

B:m

(COPY)



CITY OF PORTLAND, MAINE  
Department of Building Inspection

## Certificate of Occupancy

LOCATION 37-59 Front St.  
65-99 Front St.

Date of Issue Oct. 28, 1971

Issued to **Stirling Homex Corp.**

**This is to certify** that the building, premises, or part thereof, at the above location, built—altered—changed as to use under Building Permit No. 71/8, has had final inspection, has been found to conform substantially to requirements of Zoning Ordinance and Building Code of the City, and is hereby approved for occupancy or use, limited or otherwise, as indicated below.

PORTION OF BUILDING OR PREMISES

APPROVED OCCUPANCY

**Entire**

**Community building**

Limiting Conditions:

This certificate supersedes  
certificate issued

Approved:

(Date)

Inspector

Inspector of Buildings

Notice: This certificate identifies lawful use of building or premises, and ought to be transferred from owner to owner when property changes hands. Copy will be furnished to owner or lessee for one dollar.



# APPLICATION FOR PERMIT

Class of Building or Type of Structure Installation

Portland, Maine, Feb. 9, 1971

PERMIT ISSUED

135

CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, any, submitted herewith and the following specifications:

Location 37-59 Front Street Wit' in Fire Limits? \_\_\_\_\_ Dist. No. \_\_\_\_\_  
 Owner's name and address Portland Housing Authority, 211 Cumberland Ave. Telephone \_\_\_\_\_  
 Lessee's name and address \_\_\_\_\_ Telephone \_\_\_\_\_  
 Contractor's name and address Agway Petroleum Corp., 810 Main St., Westbrook Telephone \_\_\_\_\_  
 Architect \_\_\_\_\_ Specifications \_\_\_\_\_ Plans \_\_\_\_\_ No. of sheets \_\_\_\_\_  
 Proposed use of building \_\_\_\_\_ No. families \_\_\_\_\_  
 Last use \_\_\_\_\_ No. families \_\_\_\_\_  
 Material \_\_\_\_\_ No. stories \_\_\_\_\_ Heat \_\_\_\_\_ Style of roof \_\_\_\_\_ Roofing \_\_\_\_\_  
 Other buildings on same lot \_\_\_\_\_  
 Estimated cost \$ \_\_\_\_\_ Fee \$ \_\_\_\_\_

### General Description of New Work

To install 1-300 gal. deisel oil tank for temporary use - approx. 180 days  
Skid tank

Sent to Fire Dept. 2/9/71  
Rec'd from Fire Dept. 2/10/71

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. **PERMIT TO BE ISSUED TO** Agway Petroleum Corp.

### Details of New Work

Is any plumbing involved in this work? \_\_\_\_\_ In any electrical work involved in this work? \_\_\_\_\_  
 Is connection to be made to public sewer? \_\_\_\_\_ If not, what is proposed for sewage? \_\_\_\_\_  
 Has septic tank notice been sent? \_\_\_\_\_ Form notice sent? \_\_\_\_\_  
 Height average grade to top of plate \_\_\_\_\_ Height average grade to highest point of roof \_\_\_\_\_  
 Size, front \_\_\_\_\_ depth \_\_\_\_\_ No. stories \_\_\_\_\_ solid or filled land? \_\_\_\_\_ earth or rock? \_\_\_\_\_  
 Material of foundation \_\_\_\_\_ Thickness, top \_\_\_\_\_ bottom \_\_\_\_\_ cellar \_\_\_\_\_  
 Kind of roof \_\_\_\_\_ Rise per foot \_\_\_\_\_ Roof covering \_\_\_\_\_  
 No. of chimneys \_\_\_\_\_ Material of chimneys \_\_\_\_\_ of lining \_\_\_\_\_ Kind of heat \_\_\_\_\_ fuel \_\_\_\_\_  
 Framing Lumber—Kind \_\_\_\_\_; Dressed or full size? \_\_\_\_\_ Corner posts \_\_\_\_\_ Sills \_\_\_\_\_  
 Size Girder \_\_\_\_\_ Columns under girders \_\_\_\_\_ Size \_\_\_\_\_ Max. on centers \_\_\_\_\_  
 Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.  
 Joists and rafters: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 On centers: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 Maximum span: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 If one story building with masonry walls, thickness of walls? \_\_\_\_\_ height? \_\_\_\_\_

### If a Garage

No. cars now accommodated on same lot \_\_\_\_\_, to be accommodated \_\_\_\_\_ number commercial cars to be accommodated \_\_\_\_\_  
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? \_\_\_\_\_

### Miscellaneous

Will work require disturbing of any tree on a public street? \_\_\_\_\_  
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? Yes

Agway Petroleum Corp.

APPROVED:

David Collins 2-10-71  
2/11/71

CS 301

INSPECTION COPY

Signature of owner By: David Collins

Permit No. 711135

Location 37-59 Front St

Owner *Richard P. Manning*

Date of permit 2/27/71

Notif. closing-in

Inspn. closing-in

Final Notif.

Final Inspn.

Cert. of Occupancy issued

Staking Out Notice

Form Check Notice

NOTES

2/11/71 - P.I.F. *E.I.I.*

Lined area for notes, currently blank.

Lined area for additional information, currently blank.

# PERMIT TO INSTALL PLUMBING

PERMIT NUMBER **154**

Date Issued **2-2-71**  
 Portland Plumbing Inspector  
 By **ERNOLD R. GOODWIN**

Address **29 99 & 65-77 Front St.**  
 Installation Pkt: **Multi**  
 Owner of Bldg: **Multi**  
 Owner's Address: **Marling, New York Corp. (FRA)**  
 Plumber: **The Platte Company** Date: **2-2-71**  
 NEW REPL **299 St. John St.** NO **2-2-71**

App. First Insp.  
 Date **AUG 13 1971**  
 By **ERNOLD R. GOODWIN**  
 App. Final Insp.  
 Date **AUG 25 1971**  
 By **ERNOLD R. GOODWIN**  
 Type of Bldg.

- Commercial
- Residential
- Single
- Multi Family
- New Construction
- Remodeling

NEW	REPL	Description	Quantity	Rate	Total
		SINKS			
		LAVATORIES			
		TOILETS	<b>3</b>	<b>1074</b>	
		BATH TUBS			
		SHOWERS			
		DRAINS FLOOR & SURFACE			
		HOT WATER TANKS			
		TANKLESS WATER HEATERS			
		GARBAGE DISPOSALS			
		SEPTIC TANKS			
		HOUSE SEWERS			
		ROOF LEADERS	<b>19</b>		<b>38.00</b>
		AUTOMATIC WASHERS			
		DISHWASHERS			
		OTHER			
<b>TOTAL</b>				<b>19</b>	<b>38.00</b>

Building and Inspection Services Dept.; Plumbing Inspection



# APPLICATION FOR PERMIT

Third Class

Class of Building or Type of Structure

December 31 1970

Portland, Maine,

PERMIT

JAN 4 1971

City of Portland

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 37-59 Front St. Within Fire Limits? \_\_\_\_\_ Dist. No. \_\_\_\_\_  
 and 65-99 Front St.  
 Owner's name and address Portland Housing Authority, 211 Cumberland Ave. Telephone \_\_\_\_\_  
(c/o George Mulligan) Telephone \_\_\_\_\_  
 Lessee's name and address \_\_\_\_\_ Telephone \_\_\_\_\_  
 Contractor's name and address Stirling Home Corporation, Avon, New York Telephone \_\_\_\_\_  
1150 East River Road  
 Architect \_\_\_\_\_ Specifications \_\_\_\_\_ Plans yes No. of sheets \_\_\_\_\_  
 Proposed use of building Modular Homes No. families 50 units  
 Last use \_\_\_\_\_ No. families \_\_\_\_\_  
 Material \_\_\_\_\_ No. stories \_\_\_\_\_ Heat \_\_\_\_\_ Style of roof \_\_\_\_\_ Roofing \_\_\_\_\_  
 Other buildings on same lot \_\_\_\_\_  
 Estimated cost \$ \_\_\_\_\_ Fee \$ exempt  
no fee

## General Description of New Work

To construct 2-story frame Modular Homes for (50) Units per plans submitted.

**THIS IS A  
MODULAR  
HOME**

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. PERMIT TO BE ISSUED TO Portland Housing Authority

## Details of New Work Jack Dexter

Is any plumbing involved in this work? \_\_\_\_\_ Is any electrical work involved in this work? \_\_\_\_\_  
 Is connection to be made to public sewer? \_\_\_\_\_ If not, what is proposed for sewage? \_\_\_\_\_  
 Has septic tank notice been sent? \_\_\_\_\_ Form notice sent? yes  
 Height average grade to top of plate \_\_\_\_\_ Height average grade to highest point of roof \_\_\_\_\_  
 Size, front \_\_\_\_\_ depth \_\_\_\_\_ No. stories \_\_\_\_\_ solid or filled land? \_\_\_\_\_ earth or rock? \_\_\_\_\_  
 Material of foundation \_\_\_\_\_ Thickness, top \_\_\_\_\_ bottom \_\_\_\_\_ cellar \_\_\_\_\_  
 Kind of roof \_\_\_\_\_ Rise per foot \_\_\_\_\_ Roof covering \_\_\_\_\_  
 No. of chimneys \_\_\_\_\_ Material of chimneys \_\_\_\_\_ of lining \_\_\_\_\_ Kind of heat \_\_\_\_\_ fuel \_\_\_\_\_  
 Framing Lumber--Kind \_\_\_\_\_ Dressed or full size? \_\_\_\_\_ Corner posts \_\_\_\_\_ Sills \_\_\_\_\_  
 Size Girder \_\_\_\_\_ Columns under girders \_\_\_\_\_ Size \_\_\_\_\_ Max. on centers \_\_\_\_\_  
 Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.  
 Joists and rafters: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 On centers: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 Maximum span: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 If one story building with masonry walls, thickness of walls? \_\_\_\_\_ height? \_\_\_\_\_

## If a Garage

No. cars now accommodated on same lot \_\_\_\_\_, to be accommodated \_\_\_\_\_ number commercial cars to be accommodated \_\_\_\_\_  
 Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? \_\_\_\_\_

## Miscellaneous

Will work require disturbing of any tree on a public street? no  
 Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

APPROVED:

Permit Issued with Memo

JAN 4 1971

Portland Housing Authority  
Stirling Homex Corp.

CS 101

INSPECTION COPY

Signature of owner

by:

Handwritten Signature  
FOR STIRLING HOMEX CORP

772-8912

NOTES

2/3/71 - No work started. E.S.D.  
 2/17/71 - Rough excavation being made. Filling in hole with x amount of gravel. E.S.D.  
 2/18/71 - Excavating  
 2/24/71 - Excavating & sewer trench being built. E.S.D.  
 3/30/71 - Several excavations made - 40 one on job. E.S.D.  
 4/14/71 - Same as above. E.S.D.  
 5/10/71 - Same - no progress. E.S.D.  
 6/14/71 - No work started after three days in preparation. E.S.D.  
 7/20/71 - Sewer work being done - no further work done on same. E.S.D.  
 7/30/71 - Unit #1 ready to pour slab. E.S.D.  
 8/3/71 - Unit #1 - walls being laid. Unit #2 poured. Unit #3 being poured. E.S.D.  
 Went over this with G. person of St. Honey. E.S.D.  
 8/5/71 - Checked for all bolts on unit. E.S.D.

Permit No. 71/8  
 Location 3289 - Ford St.  
 Owner [unclear] Housing Dept.  
 Date of permit 1/14/71  
 Notif. closing-in  
 Inspn. closing-in  
 Final Notif.  
 Final Inspn.  
 Cert. of Occupancy issued  
 Submittal-Over-Notice SM 1500  
 Form Check Notice

8/9/71 - I - II - III  
 III blocked & being blocked  
 6-9-8 - poured.  
 10 - ready to pour.  
 17 - ready to pour.  
 E.S.D.  
 8/15/71 - Laying up modules on 1st foundation. E.S.D.  
 9/7/71 - Modules all set.  
 Mod and construction joints in block wall. E.S.D.  
 10/20/71 - plug holes in holes storm ceiling. Factor Columns to floor. Take paper off fiber glass insulation. Take care. (7) Factor Columns at Cantilever. Holes around 2nd floor down. (8) Holes around 2nd floor down. Factor Columns at Cantilever.





**APPLICATION FOR PERMIT**  
**DEPARTMENT OF BUILDING INSPECTION SERVICES**  
**ELECTRICAL INSTALLATIONS**

Date October 17, 1991, 19\_\_  
 Receipt and Permit number 7765

To the **CHIEF ELECTRICAL INSPECTOR, Portland, Maine:**  
 The undersigned hereby applies for a permit to make electrical installations in accordance with the laws of  
 Maine, the Portland Electrical Ordinance, the National Electrical Code and the following specifications:

LOCATION OF WORK: 45 Front St  
 OWNER'S NAME: Portland Housing Authority ADDRESS: 45 Front St

	FEES
<b>OUTLETS:</b>	
Receptacles <u>1</u> Switches _____ Plugmold _____ ft TOTAL _____	.20
<b>FIXTURES:</b> (number of)	
Incandescent <u>1</u> Fluorescent _____ (not strip) TOTAL _____	.20
Strip Fluorescent _____ ft. _____	
<b>SERVICES:</b>	
Overhead _____ Underground <u>1</u> Temporary _____ TOTAL amperes _____	15.00
METERS: (number of) _____	1.00
MOTORS: (number of)	
Fractional _____	
1 HP or over _____	
<b>RESIDENTIAL HEATING:</b>	
Oil or Gas (number of units) _____	
Electric (number of rooms) _____	
<b>COMMERCIAL OR INDUSTRIAL HEATING:</b>	
Oil or Gas (by a main boiler) _____	
Oil or Gas (by separate units) _____	
Electric Under 20 kws _____ Over 20 kws _____	
<b>APPLIANCES:</b> (number of)	
Ranges _____	Water Heaters _____
Cook Tops _____	Disposals _____
Wall Ovens _____	Dishwashers _____
Dryers _____	Compactors _____
Fans _____	Others (denote) _____
TOTAL _____	
<b>MISCELLANEOUS:</b> (number of)	
Branch Panels _____	
Transformers _____	
Air Conditioners Central Unit _____	
Separate Units (windows) _____	
Signs 20 sq. ft. and under _____	
Over 20 sq. ft. _____	
Swimming Pools Above Ground _____	
In Ground _____	
Fire/Burglar Alarms Residential _____	
Commercial _____	
Heavy Duty Outlets 220 Volt (such as welders) 30 amps and under _____	
over 30 amps _____	
Circus, Fairs, etc. _____	
Alterations to wires _____	
Repairs after fire _____	
Emergency Lights, battery _____	
Emergency Generators _____	
FOR ADDITIONAL WORK NOT ON ORIGINAL PERMIT ..... INSTALLATION FEE DUE:	
FOR REMOVAL OF A "STOP ORDER" (304-16.b) ..... DOUBLE FEE DUE:	
TOTAL AMOUNT DUE:	16.40

INSPECTION: Will be ready on ready, 19\_\_; or Will Call \_\_\_\_\_  
 CONTRACTOR'S NAME: Tim Napolitano  
 ADDRESS: \_\_\_\_\_  
 TEL: 799-0538  
 MASTER LICENSE NO.: 7765 SIGNATURE OF CONTRACTOR: [Signature]  
 LIMITED LICENSE NO.: \_\_\_\_\_

INSPECTOR'S COPY — WHITE  
 OFFICE COPY — CANARY  
 CONTRACTOR'S COPY — GREEN

