

1.2 Alba Street 179-G-4,5&6

DRAWING 3

February 11, 1976

Mr. Paul F. Thurlow  
122 Albe Street  
Portland, Maine 04103

Re: 122 Albe Street, Portland, Maine 179-6-19  
Bearing Center 3

Dear Mr. Thurlow:

Your property has been surveyed by the Portland Housing Inspection Division, Health Department, and has met Minimum Code Standards. Congratulations are extended to you for the general condition of your property. Good maintenance is the best way to preserve the useful life of your property and neighborhood.

In order to aid in the preservation of Portland's existing housing inventory, it shall be the policy of this department to inspect each residential building at least once every five years. Although a property is subject to re-inspection at any time during the said five year period, the next regular inspection of this property is scheduled for 1981.

If we can be of further help, please feel free to call on us.

Sincerely yours,  
David C. Stettenbender  
Health Director

Lyla B. Noyes  
Chief of Housing Inspections

Inspector   
A. Kelley

LDN:rl