111 Alba Stree

179-H-5

DRGCTR &



November 21, 1975

Mrs. Thora C. Hamilton 111 Alba Street Fortland, Maine 04103

Dear Mrs. Hamilton:

Ra: 111 Alba Street - 179-H-5 - DC 3

Your property has been surveyed by the Portland Housing Inspection Division, Health Department, and has met Minimum Code Standards. Congratulations are entended to you for the general condition of your property. Good maintenance is the best way to preserve the useful lifeof your property and neighborhood.

In order to aid in the preservation of Fortland's existing housing invantory, it shall be the policy of this department to inspect each residential building at least once every five years. Although a property is subject to reinspection at any time during the said five year period, the next regular inspection of this property is scheduled for Novembe x1980.

If we can be of further help, please Real free to call on us.

Sincerely yours,

David C. Bittenbendar

Health Director

Vis Co.

Chief of Ebusing Inspections

Imspector Mesler Clary

/gg