

59 Bolton Street 186-D-12



August 24, 1979 ✓

Francis C. & Nicolina T. Martinez
125 Hersey Street
Portland, Maine 04102

Re: 59 Polton Street 186-D-12 X
Neighborhood Conservation
N.C.P.-Libbytown

Dear Mr. & Mrs. Martinez:

The Housing Inspections Division of the Department of Neighborhood Conservation has recently completed an exterior inspection of your property in conjunction with the above referred program.

Congratulations are extended to you for the general condition of your property which was found to meet the standards established by the City's Housing Code.

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely yours,
Joseph E. Gray, Jr., Director
Neighborhood Conservation

By Lyle D. Noyes
Lyle D. Noyes,
Chief of Housing Inspections

Inspector M. Bartlett
G. Bartlett

dld

