

August 31, 1979 /

Rama M. Patitpas 69 Bolton Street Portland, Maine 04102

Re: 69 Bolton Street 186-D-14 X

Dear Ma. Petitpss:

The Housing Inspections Division of the Department of Neighborhood Conservation has recently completed an exterior inspection of your property in conjunction with the above referred program.

Congratulations are extended to you for the general condition of your property which was found to meet the standards established by the City's Housing Code. We did, however, note the following items that could cause future problems.

Peeling paint overall walls and trim.

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely yours, Joseph E. Gray, Jr., Director Neighborhood Conservation

Lyle D Noyes,
Chief of Housing Inspections

Inspector Q. Battlett

G. Bartlett

dld

City of Portland

OK-ISTEX

NEIGHBORHOOD CONSERVATION

Housing Inspection Division

1) Irsp. Name BANTUETT STRUCTURE INSPECTION SCHEDULE 3) Insp. Type 4) Proj. Code 5) Assr's: Chart 6) Bl. 7) Lot 8) Census: Tract 9) Blk.

13) S.A. H. No. 14) Suff. 15) Direct. 16) Street Name

Bolto N 10)Insp 2) Insp. Date 8/93/79 12) Hous. No. 51 19)Status 20)Blug's Rat. 18)Owner or Agent 2 90 21)Address: 69 BOLTON ST Zip Code: 09/02 PTUD ME 22)City and State Resp. Code Sect. Party Viol. Viol. Rem. Pate Fl. Pimedy Cond. Violation Description Туре Type OA PE PAINT