

August 24, 1979 /

John M. & Susan O. Bernier 25 Bolton Street Portland, Maine 04102

Re: 25 Bolton Street 186-D-3 Neighborhood Conjervation N.C.F.-Libbytown

Dear Mr. & Mrs. Bernier:

The Housing Inspections Division of the Department of Neighborhood Conservation has recently completed an exterior inspection of your property in conjunction with the above referred program.

Congratulations are extended to you for the general condition of your property which was found to meet the standards established by the City's Housing Code.

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on up if we can be of assistence to you.

Sincerely yours, Joseph E. Gray, Jr., Director Neighborhood Conservation

Lyle 1. Noyes, Chief of Housing Inspections

Inspector\_

d1d

City of Portland

OK-KOTEX

NEIGHBORHOOD CONSERVATION

Housing Inspection Division

STRUCTURE INSPECTION SCHEDULE

1) Insp. Name BAATLETT

2) Insp. Date   3) Insp. T	ype 4)Proj.Code 5)Assr's:Chart 6)Bl. 7)Lot.	(°)Census	:Tract 9	Blk.	16)Ins	p. 11	)Form No.
9129 179	NCP-LBY! 186 2				17)St.		
12) Hous. No. 13) Sec. H.	No. 14)Suff. 15)Direct. 16)Street Name					5T	The Water of the
18)Owner or Agent: JOHN M & SUSAN O. TECHNER.				1	9)Statu		lg'r Rati
					00	)	
21)Address: 25 BOKTON ST					71.	Code: OY/	7.4.3
22)City and State	PTV3,ME		. 00\n1.i-		0) (22)	les 31 Cons	May 132 (0. Bs.
23)D. Units 24)Occ.D.U	s 25)Rm. Units 26)Occ. P. U. s 27)No. Occupants 28	)Com'l U.	29)Blag	.Type	OJSCOL	Les Ji ) Cons	STEEL ST
23) 0 H 24) Photo 35) Z	oped For 36) Actual Land Use 37) D. D. 38) Lks.Ad.	Bth.Fac.	39)Disp.	40)(	losing	Date Same	િ ભારત કરિયા કર્યા કરી છે. જિલ્લા કરિયા કરી છે.
	Yes	No F1.	Room		Resp.	Code Sect.	Viol.
No. Remedy Cond.	Victation Description		Loc. Type	Type		Viol.	Rem.Date
No. Remedy Cond.	7.1						
						- 1,3,4,3	
	/ 1/2					1.77	C. C
		-					the state of the s
	,						
							1
		+ -					

Inspection Services P. Samuel Hoffses Chief



Planning and Urban Development Joseph E. Gray Jr. Director

## CITY OF PORTLAND

APRIL 15, 1997

PERRY DAVID J II 64 MARLU ST WESTBROOK ME 04092

> Re: 25 BOLTON ST CBL: 186 -- D-003-001-01

DU:

Dear Mr. Perry:

The Housing Inspections Division of the Department of Planning and Urban Development has recently completed an overall inspection of the above-referred property.

Congratulations are extended to you for the general condition of your property which was found to meet the standards established by the City's Housing Code. We did, however, note the following items that could cause future problems:

1. EXT - ROOF -CHIMNEY MAY NEED TO BE REPOINTED

108.50

INT - OVERALL -113.50 HARD-WIRED BATTERY-BACK/UP SMOKE DETECTOR'S ARE REQUIRED IN EACH UNIT

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely,

Code Enforcement Officer

Tammy Murison

Code Enfc.Offc./ Field Supv.