

181-183 BOLTON STREET

STAMPALIKER

Full cut 4920n 4 Half cut 4920n 4 Thin cut 4920n 4 Full cut 4920n

**PERMIT TO INSTALL PLUMBING**

**12538**

PERMIT NUMBER

Date Issued 3-1-63  
 PORTLAND PLUMBING INSPECTOR

Address 183 Bolton Street  
 Installation For: Arthur Sears  
 Owner of Bldg. Chlette  
 Owner's Address: 183 Bolton Street Date: 3-1-63  
 Plumber: Reuben Katz

By J. P. Welch  
 APPROVED FIRST INSPECTION

Date Mar 4 1963

By JOSEPH P. WELCH  
 APPROVED FINAL INSPECTION

Date Mar 4 1963

By JOSEPH P. WELCH

- TYPE OF BUILDING
- COMMERCIAL
  - RESIDENTIAL
  - SINGLE
  - MULTI FAMILY
  - NEW CONSTRUCTION
  - REMODELING

NEW	REPL'	PROPOSED INSTALLATIONS	NUMBER	FEE
		SINKS		
		LAVATORIES		
		TOILETS		
		BATH TUBS		
		SHOWERS		
		DRAINS		
		HOT WATER TANKS		
		TANKLESS WATER HEATERS		
		GARBAGE GRINDERS		
		SEPTIC TANKS		
		HOUSE SEWERS		
		ROOF LEADERS (Conn. to house drain)		
1		Washing Machine	1	\$ 2.00

PORTLAND HEALTH DEPT. PLUMBING INSPECTION

TOTAL ▶ \$ 2.00



FILL IN AND SIGN WITH INK

APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIPMENT

Portland, Maine, May 22, 1947

PERMIT 15500  
01093  
MAY 23 1947

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location ... 183 ~~Wilton~~ <sup>Bolton</sup> Street ... Use of Building ... Dwelling ... No. Stories ... <sup>New Building</sup> Existing "  
Name and address of owner of appliance ... Frank Anthony, 183 ~~Wilton~~ <sup>Bolton</sup> St.  
Installer's name and address ... B. G. Pride Co., 543 Main St., Westbrook Telephone

General Description of Work

To install oil burning equipment in connection with existing steam heat

IF HEATER, OR POWER BOILER

Location of appliance or source of heat ... Type of floor beneath appliance ...  
If wood, how protected? ... Kind of fuel ...  
Minimum distance to wood or combustible material, from top of appliance or casing top of furnace ...  
From top of smoke pipe ... From front of appliance ... From sides or back of appliance ...  
Size of chimney flue ... Other connections to same flue ...  
If gas fired, how vented? ... Rated maximum demand per hour ...

IF OIL BURNER

Name and type of burner ... Homease ... Labelled by underwriter's laboratories? ... yes ...  
Will operator be always in attendance? ... Does oil supply line feed from top or bottom of tank? ... bottom ...  
Type of floor beneath burner ... concrete ...  
Location of oil storage ... basement ... Number and capacity of tanks ... 1-275 gal ...  
If two 275-gallon tanks, will three-way valve be provided? ...  
Will all tanks be more than five feet from any flame? ... yes ... How many tanks fire proofed? ...  
Total capacity of any existing storage tanks for furnace burners ... none ...

IF COOKING APPLIANCE

Location of appliance ... Kind of fuel ... Type of floor beneath appliance ...  
If wood, how protected? ...  
Minimum distance to wood or combustible material from top of appliance ...  
From front of appliance ... From sides and back ... From top of smokepipe ...  
Size of chimney flue ... Other connections to same flue ...  
Is hood to be provided? ... If so, how vented? ...  
If gas fired, how vented? ... Rated maximum demand per hour ...

MISCELLANEOUS EQUIPMENT OR SPECIAL INFORMATION

.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....

Amount of fee enclosed? 1.00 (\$1.00 for one heater, etc., 50 cents additional for each additional heater, etc., in same building at same time.)

APPROVED:  
*OK 5-22-47 Bmg*

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? ... yes ...

B. G. Pride Co.

Signature of Installer By: *Byron D. Gillett*

INSPECTION COPY



APPLICATION FOR PERMIT

PERMIT ISSUED 1894

Class of Building or Type of Structure Third Class NOV 3 1936

Portland, Maine, November 5, 1936

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect alter install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 181-185 Bolton Street Ward 8 Within Fire Limits? no Dist. No. \_\_\_\_\_
Owner's or Lessee's name and address Etta Sheehan, 98 Atlantic St. Telephone \_\_\_\_\_
Contractor's name and address Oxford Wrecking Co., 97 Preble St. Telephone 6-5762
Architect's name and address \_\_\_\_\_
Proposed use of building \_\_\_\_\_ No. families \_\_\_\_\_
Other buildings on same lot \_\_\_\_\_
Plans filed as part of this application? no No. of sheets \_\_\_\_\_
Estimated cost \$ \_\_\_\_\_ Fee \$ .50

Description of Present Building to be Altered

Material wood No. stories 1 Heat \_\_\_\_\_ Style of roof \_\_\_\_\_ Roofing \_\_\_\_\_
Last use 1 car garage No. families \_\_\_\_\_

General Description of New Work

To demolish building 10' x 14'

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

Details of New Work

Size, front \_\_\_\_\_ depth \_\_\_\_\_ No. stories \_\_\_\_\_ Height average grade to top of plate \_\_\_\_\_
Height average grade to highest point of roof \_\_\_\_\_
To be erected on solid or filled land? \_\_\_\_\_ earth or rock? \_\_\_\_\_
Material of foundation \_\_\_\_\_ Thickness, top \_\_\_\_\_ bottom \_\_\_\_\_
Material of underpinning \_\_\_\_\_ Height \_\_\_\_\_ Thickness \_\_\_\_\_
Kind of Roof \_\_\_\_\_ Rise per foot \_\_\_\_\_ Roof covering \_\_\_\_\_
No. of chimneys \_\_\_\_\_ Material of chimneys \_\_\_\_\_ of lining \_\_\_\_\_
Kind of heat \_\_\_\_\_ Type of fuel \_\_\_\_\_ Is gas fitting involved? \_\_\_\_\_
Corner posts \_\_\_\_\_ Sills \_\_\_\_\_ Gir: or ledger board? \_\_\_\_\_ Size \_\_\_\_\_
Material columns under girders \_\_\_\_\_ Size \_\_\_\_\_ Max. on centers \_\_\_\_\_
Studs (outside walls and carrying partitions) 2x4-16" O. C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.
Joists and rafters: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_
On centers: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_
Maximum span: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_
If one story building with masonry walls, thickness of walls? \_\_\_\_\_ height? \_\_\_\_\_

If a Garage

No. cars now accommodated on same lot \_\_\_\_\_, to be accommodated \_\_\_\_\_
Total number commercial cars to be accommodated \_\_\_\_\_
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? \_\_\_\_\_

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Signature of owner By Etta Sheehan
By Oxford Wrecking Co.
By H. P. Stapleton

INSPECTION COPY

81028



PERMIT ISSUED

Permit No. 0722

APPLICATION FOR PERMIT TO REPAIR BUILDING

Third Class Building

Portland, Maine, May 28, 1952

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to repair the following described building in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 181-5 Bolton St. Ward 8 Within fire limits? no Dist. No.

Owner's name and address Charles D. Marble, 257 Bradley St. Telephone

Contractor's name and address Brown & Berry, Inc., 22 Kennebec St. Telephone F 4335

Use of building tenement house 3 families

No. stories Height ft., Gross area sq. ft., Style of roof

Type of present roof covering

General Description of New Work

To Repair after fire to former condition. No alterations (rubbish 2d floor)

CERTIFICATE OF OCCUPANCY REQUIREMENT IS WAIVED. replace 2d floor timbers 2x8 16' 00

If Roof Covering is to be Repaired or Renewed

When last repaired? Area then repaired sq. ft.

Are repairs or renewal due to damage by fire? yes If so, what area damaged? sq. ft.

Area of roof to be repaired now? sq. ft.

Type of roofing to be used No. plies

Trade name and grade of roof covering to be used

Estimated cost \$ 100. Fee \$ .50

INSPECTION COPY

Signature of owner Charles D. Marble By Brown & Berry, Inc.

By E. B. Sault

624A



(R) GENERAL RESIDENCE ZONE

Permit No. 5342

# APPLICATION FOR PERMIT **PERMIT ISSUED**

Class of Building or Type of Structure Third Class

Portland, Maine, November 16, 1927 **NOV 19 1927**

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to ~~erect~~ ~~alter~~ ~~install~~ the following building structure ~~equipment~~ in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 181 Bolton Street Ward 8 Within Fire Limits? No Dist. No. \_\_\_\_\_  
 Owner's or Lessee's name and address Charles B. Marble, 181 Bolton St. Telephone \_\_\_\_\_  
 Contractor's name and address Hayden & Dingwell, 192 Brackett St. Telephone FD1497  
 Architect's name and address \_\_\_\_\_  
 Proposed use of building 1 car private garage No. families \_\_\_\_\_  
 Other buildings on same lot 1 family tenement house

### Description of Present Building to be Altered

Material Wood No. stories 1 Heat \_\_\_\_\_ Style of roof \_\_\_\_\_ Roofing \_\_\_\_\_  
 Last use 1 car private garage No. families \_\_\_\_\_

### General Description of New Work

To build addition 8' x 10' to building

CERTIFICATE OF OCCUPANCY  
 REQUIREMENT IS WAIVED.  
 NOTIFICATION BEFORE LATHING  
 OR CLOSING-IN IS WAIVED.

### Details of New Work

Size, front \_\_\_\_\_ depth \_\_\_\_\_ No. stories \_\_\_\_\_ Height average grade to highest point of roof \_\_\_\_\_  
 To be erected on solid or filled land? \_\_\_\_\_ earth or rock? \_\_\_\_\_  
 Material of foundation Corner Posts Thickness, top \_\_\_\_\_ bottom \_\_\_\_\_  
 Material of underpinning \_\_\_\_\_ Height \_\_\_\_\_ Thickness \_\_\_\_\_  
 Kind of roof \_\_\_\_\_ Roof covering Asphalt roll Class 0 Und. Lab.  
 No. of chimneys no Material of chimneys \_\_\_\_\_ of lining \_\_\_\_\_  
 Kind of heat no Type of fuel \_\_\_\_\_ Distance, heater to chimney \_\_\_\_\_  
 If oil burner, name and model \_\_\_\_\_  
 Capacity and location of oil tanks \_\_\_\_\_  
 Is gas fitting involved? no Size of service \_\_\_\_\_  
 Corner posts 4x4 Sills moving doorway out on plank runway Girt or ledger board? \_\_\_\_\_ Size \_\_\_\_\_  
 Material columns under girders \_\_\_\_\_ Size \_\_\_\_\_ Max. on centers \_\_\_\_\_  
 Studs (outside walls and carrying partitions) 2x4-16" O.C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 9 feet. Sills and corner posts all one piece in cross section.  
 Joists and rafters: 1st floor no change, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof 2x4  
 On centers: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 Maximum span: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 If one story building with masonry walls, thickness of walls? \_\_\_\_\_ height? \_\_\_\_\_

### If a Garage

No. cars now accommodated on same lot one, to be accommodated one  
 Total number commercial cars to be accommodated none  
 Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? no

### Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no  
 Plans filed as part of this application? yes No. sheets 1  
 Estimated cost \$ 20. Fee \$ 25  
 Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Charles B. Marble

Signature of owner by

INSPECTION COPY

5351



# City of Portland, Maine

OFFICE HOURS  
10 TO 12 M.  
4 TO 5 M.

## OFFICE OF THE INSPECTOR OF BUILDINGS

4-12-15 191

To the Inspector of Buildings of the City of Portland:

The undersigned respectfully makes application for a permit to erect enlarge a building on (187-183) Bolton street, at number lot 5 to be Three stories high Fifty-five feet long, Twenty-seven feet wide; also an addition to be Three stories high, Twenty-seven feet long, Twenty-seven feet wide, and to be used as a Dwelling.

CELLAR WALL—To be constructed of Concrete to be 16 inches wide on bottom and batter to 12 inches on top.

UNDERPINNING—To be Brick. Height of underpinning from top of cellar wall to bottom of sill 3 ft. 9 inches to be 9 inches in thickness.

EXTERIOR WALLS—To be constructed of Wood. If of Brick, Stone, etc. Total Height of wall 3 ft. 2 inches. Thickness of 1st 2 2d 3 3d 4 4th 5 5th 6 6th story walls. If of reinforced concrete, state mix and reinforcing system to be used.

If wood construction, sills to be 4-8 Girders 8-22 Floor Timbers 2-9 Spaced 16 on Centers Post 4-6 Girts 4-4 Studs 2-4 to be spaced 16 " "

This building will be used for the purposes of Dwelling (If for apartments, tenements, or other family uses state number of families accommodated and number on each floor. If for manufacturing or mercantile purposes state character of business and amount of estimated weight to be carried by the floor.)

Number of families on floor One

Total number of families Three

Manufacturing (state character) \_\_\_\_\_

Estimated load on floors per sq. ft. \_\_\_\_\_

Mercantile business (state character and load per sq. ft.) \_\_\_\_\_

If building is used for tenement house or family use and more than one family, the following provisions of the Building Laws regarding dividing partitions shall be adhered to (Quote Law re. this.)

FIRESTOPS—All bearing and center partitions will have firestops cut in tight on top of each partition cap and between each set of floor timbers. Where ledger board are used there shall be firestops cut in tight against bottom of ledger board, of same size as wall studs. Also wherever the Inspector of Buildings may consider necessary.

STAIRWAYS—No. in build. Two location Front & Rear to be enclosed with \_\_\_\_\_ walls to be lathed with \_\_\_\_\_ lathing.

ROOF—To be constructed of Wood. Rafters to be 2-8 inches to be spaced 16 inches on centers. Roof to be covered with 5 Ply Tar & Gravel.

Gutters to be made of \_\_\_\_\_ Cornices to be made of \_\_\_\_\_

Bay Windows to be made of \_\_\_\_\_ to be covered with \_\_\_\_\_

Dormer Windows to be made of \_\_\_\_\_ to be covered \_\_\_\_\_

Chimneys, Smoke Flues to be lined with Flue Lining and provided with a 10-inch outside collar and an inside collar to go to the inside of the flue.

Estimated Cost of Building: \$6500

INSPECTION—The Inspector of Buildings is to be notified when building is ready for lathing and at least 24 hours before the lathing is begun.

The Building is W. A. Norton Address 229 Brighton Ave.


The Architect is \_\_\_\_\_ Address \_\_\_\_\_

The Owner is Chas. B. Marble Address Waterboro Me

No Deviation will be made from the above application without written permission from the Inspector of Buildings

The above petition was granted the 12 day of April 191 5

Applicant to sign here Chas. B. Marble







# CITY OF PORTLAND

DEPARTMENT OF PLANNING & URBAN DEVELOPMENT  
INSPECTION SERVICES DIVISION

July 9, 1991

Mr. Andrew Berube  
1363 Congress Street  
Portland, ME 04101

DU-3

Re: 13 Bolton Street  
(186-F-005)

Dear Mr. Berube:


We recently received a complaint and an inspection was made by Code Enforcement Officer Mark Mitchell of the property owned by you at 183 Bolton Street, Portland, Maine. As a result of the inspection, you are hereby ordered to correct the following substandard housing conditions:


<u>LOCATION</u>	<u>VIOLATION</u>	<u>CORRECT BY</u>
1. Exterior front porches	Repair or make inaccessible	7-16-91
2. Exterior rear porches	Repair or make inaccessible	7-16-91.

The above mentioned conditions are in violation of Article V of the Municipal Code of the City of Portland, Maine, and must be corrected on or before July 16, 1991 (7 days from notice).

Failure to comply with this order may result in a complaint being filed for prosecution in District Court.

Sincerely yours,  
Joseph E. Gray, Jr., Director of  
Planning & Urban Development

 #6

By   
P. Samuel  
Chief of Inspection Services

Code Enforcement Officer - Mark Mitchell

181-183 Bolton Street 186A-F-5



CERTIFICATE  
OF  
COMPLIANCE

December 11, 1980

CITY OF PORTLAND

Department of Urban Development  
Housing Inspections Division  
Telephone: 775-5451 - Extension 311 - 312

John W. & Nan N. Small  
181 Bolton Street  
Portland, Maine 04103

Re: Premises located at: 181-183 Bolton Street NCP-LBY 186A-F-5

Dear Ms. Small:

A re-inspection of the premises noted above was made on December 10, 1980 by Housing Inspector Gayton Bartlett.


This is to certify that you have complied with our request to correct the violation of the Municipal Codes relating to housing conditions as described in our "Notice of Housing Conditions" dated September 18, 1979.


Thank you for your cooperation and your efforts to help us maintain decent, safe and sanitary housing for all Portland residents.

In order to aid in the preservation of Portland's existing housing inventory, it shall be the policy of this department to inspect each residential building at least once every five years. Although a property is subject to re-inspection at any time during the said five-year period, the next regular inspection of this property is scheduled for December 1985.

Sincerely yours,

Joseph E. Gray, Jr., Director of  
Planning and Urban Development

By   
Lyle D. Noyes  
Housing Code Administrator

Inspector   
Gayton Bartlett

jmr

CITY OF PORTLAND, MAINE  
DEPARTMENT OF NEIGHBORHOOD CONSERVATION  
HOUSING INSPECTIONS DIVISION

NOTICE OF HEARING

OK
BY <u>CS</u>
DATE <u>12/10/80</u>

February 28, 1980

To: John W. & Nan N. Small  
181 Bolton Street  
Portland, Maine 04103

Re: Premises located at 181-183 Bolton Street - NCP-LBY - 186A-F-5

Dear Mr. & Mrs. Small:

Because of your failure to comply with previous NOTICES, you are hereby invited to appear in Room \_\_\_\_\_, City Hall, 389 Congress Street, Portland, Maine at 9:00 A.M. on March 12, 1980, to show cause why legal action should not be taken against you for violations of the Municipal Codes relating to housing conditions at the above referred premises, as described more fully in the attached copy of the original NOTICE received by you on or about September 16, 1979.

FAILURE TO APPEAR MAY RESULT IN PROSECUTION

Please notify this office at once if you have corrected all violations before the above noted hearing date. Telephone 775-5451 Extension 448 - 358.

Joseph E. Gray, Jr., Director  
Neighborhood Conservation

By Lyle D. Noyes  
Lyle D. Noyes, Housing Code Administrator

Requested by  
Inspector G. Bartlett  
G. Bartlett

Enclosure

NOTICE OF HOUSING CONDITIONS

DU 3

City of Portland  
 Department of Neighborhood Conservation  
 Housing Inspections Division  
 Tel. 775-5451 - Ext. 358 - 448

Ch.-Bl.-Lot, 186A-F-5  
 Location: 181-183 Bolton Street  
 Project: NCP-LBY  
 Issued: 9/18/79  
 Expired: 12/18/79

John W. & Nan N. Small  
 181 Bolton Street  
 Portland, Maine 04103  
 774-4917

Dear Mr. & Mrs. Small:

An examination was made of the premises at 181-183 Bolton Street, Portland, Maine, by Housing Inspector Bartlett. Violations of Municipal Codes relating to housing conditions were found as described in detail below.

In accordance with provisions of the above mentioned Codes you are requested to correct these defects on or before 12/18/79. You may contact this office to arrange a satisfactory repair schedule if you are unable to make such repairs within the specified time. We will assume the repairs to be in progress if we do not hear from you within ten days from this date and, on reinspection within the time set forth above, will anticipate that the premises have been brought into compliance with Code Standards. Please contact this office if you have any questions regarding this notice.

Your cooperation will help this Department in its goal to maintain all Portland residents in decent, safe and sanitary housing.

Very truly yours,  
 Joseph E. Gray, Jr., Director  
 Neighborhood Conservation

Inspector G. Bartlett  
 G. Bartlett

By Lyle E. Noyes  
 Lyle E. Noyes,  
 Chief of Housing Inspections

EXISTING VIOLATIONS OF CHAPTER 307 - "MINIMUM STANDARDS FOR HOUSING" -	Section(s)
*1. <del>FIRST FLOOR REAR PORCH - secure loose railing.</del>	<del>6/12/80 CB 3d</del>
*2. <del>FIRST FLOOR REAR PORCH - repair or replace rotted post.</del>	<del>6/12/80 CB 3d</del>
*3. <del>RIGHT PORCH - replace rotted decking.</del>	<del>6/12/80 CB 3d</del>
*4. <del>FIRST FLOOR FRONT STEPS - repair or replace rotted tread and stringers.</del>	<del>6/12/80 CB 3d</del>
<u>THIRD FLOOR AFTER 3:30</u>	
*5. <del>BATHROOM CEILING, LEFT MIDDLE BEDROOM CEILING &amp; KITCHEN CEILING - determine the reason and remedy the condition which causes signs of leakage.</del>	<del>6/12/80 CB 3b</del>
*6. <del>BATHROOM CEILING - secure loose plaster.</del>	<del>6/12/80 CB 3b</del>

WHEN MAKING YOUR REPAIRS, FIRST PRIORITY IS TO BE GIVEN TO ITEMS WITH ASTERISKS, AS THEY CONSTITUTE EXTREME HAZARDS TO THE HEALTH OR SAFETY OF THE OCCUPANTS OF THIS STRUCTURE.

We suggest you contact the City of Portland Building Inspection Department, 389 Congress Street, Tel. 775-5451, to determine if any of the items listed above require a building or alteration permit.

dld

REINSPECTION RECOMMENDATIONS

OK

BY GB

DATE 12/10/80

LOCATION 181-183 BOSTON ST

PROJECT NCP-LBY

OWNER J. SMALL

INSPECTOR BARTLETT

NOTICE OF HOUSING CONDITIONS		HEARING NOTICE		FINAL NOTICE	
Issued	Expired	Issued	Expired	Issued	Expired
<u>9/18/79</u>	<u>12/18/79</u>				

A reinspection was made of the above premises and I recommend the following action:

DATE	RECOMMENDATION
	ALL VIOLATIONS HAVE BEEN CORRECTED Send "CERTIFICATE OF COMPLIANCE" _____ "POSTING RELEASE" _____
<u>3/12/80 GB</u>	SATISFACTORY Rehabilitation in Progress Time Extended To: <u>OTX to 4/15/80</u> Time Extended To: _____ Time Extended To: _____
<u>2/27/80 GB</u>	UNSATISFACTORY Progress <u>March 12 at 9:00</u> Send "HEARING NOTICE" _____ "FINAL NOTICE" _____ NOTICE TO VACATE POST Entire _____ POST Dwelling Units _____
	UNSATISFACTORY Progress "LEGAL ACTION" To Be Taken _____

INSPECTOR'S REMARKS: one violation corrected - unsatisfactory progress - HN

3/12/80 GB AAH - OTX to 4/15/80

4/25/80 GB RE 1/3 - in rehab by owner

6/7/80 GB RE 2/3 - #4 left

10/15/80 GB NOTHING DONE ON FRONT STEPS - CO

12/10/80 GB OK - CoC

INSTRUCTIONS TO INSPECTOR: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_