

450-454 CAPSIC STREET

SHAW-WALKER

MADE IN U.S.A. 100% COTTON

PERMIT TO INSTALL PLUMBING

PERMIT NUMBER **4669**

Date Issued **7-13-76**

Portland Plumbing Inspector
By **ERNOLO R. GARDWIN**

Date

By

Date

By

Type of Bldg.

- Commercial
- Residential
- Single
- Multi Family
- New Construction
- Remodeling

Address **450 Capisic St.**

Installation For **one family**

Owner of Bldg: **David A. Duffey**

Owner's Address: **same**

Date: **7-13-76**

Plumber **The Servage Co.**

Falmouth, Me.

NEW	REPL		NO	FEE	
		SINKS			
		L.VATORIES			
		TOILETS			
		BATH TUBS			
		SHOWERS			
		DRAINS	FLOOR	SURFACE	
		HOT WATER TANKS			
		TANKLESS WATER HEATERS			
		GARBAGE DISPOSALS			
		SEPTIC TANKS			
1		HOUSE SEWERS		2.00	
		ROOF LEADERS			
		AUTOMATIC WASHERS			
		DISHWASHERS		3.00	
		OTHER base fee			
				TOTAL	5.00

ERNOLO R. GARDWIN
 App. First Insp.
JUL 14 1976
 App. Final Insp.

Building and Inspection Services Dept.: Plumbing Inspection



R3 RESIDENCE ZONE
APPLICATION FOR PERMIT

Class of Building or Type of Structure _____
Portland, Maine, May 2, 1972

PERMIT ISSUED
MAY 2 1972
0475
CITY of PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 150 Capisic St. Within Fire Limits? _____ Dist. No. _____
 Owner's name and address Doris Duffy, same Telephone _____
 Lessee's name and address _____ Telephone _____
 Contractor's name and address B. & W. Builders, 259 Bradley St., Saco Telephone 282-3335
 Architect _____ Specifications _____ Plans _____ No. of sheets _____
 Proposed use of building dwelling No. families _____
 Last use _____ " _____ No. families _____
 Material _____ No. stories _____ Heat _____ Style of roof _____ Roofing _____
 Other buildings on same lot _____ Fee \$ 3.00
 Estimated cost \$ 300.

General Description of New Work

To relocate a door in rear of dwelling, to change size of window to 2'6" x 4'6" and to cut in a 4' opening in non-bearing partition. 1x8 header

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. **PERMIT TO BE ISSUED TO Contractor**

Details of New Work

Is any plumbing involved in this work? _____ Is any electrical work involved in this work? _____
 Is connection to be made to public sewer? _____ If not, what is proposed for sewage? _____
 Has septic tank notice been sent? _____ Form notice sent? _____
 Height average grade to top of plate _____ Height average grade to highest point of roof _____
 Size, front _____ depth _____ No. stories _____ solid or filled lan? _____ earth or rock? _____
 Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
 Kind of roof _____ Rise per foot _____ Roof covering _____
 No. of chimneys _____ Material of chimneys _____ of lining _____ Kind of heat _____ fuel _____
 Framing Lumber—Kind _____ Dressed or full size? _____ Corner posts _____ Sills _____
 Size Girder _____ Columns under girders _____ Size _____ Max. on centers _____
 Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
 Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
 On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
 Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
 If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____ number commercial cars to be accommodated _____
 Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will work require disturbing of any tree on a public street? _____
 Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

APPROVED:

O.K. E.S. 5/2/72

CS 301

INSPECTION COPY

Signature of owner By:

B & W Builders
Wm. E. Burke

NOTES

6/23/72

Completed work
for painting of
H

[Crossed out lined area]

Permit No. 72/0475

Location 450 Dupont St

Owner Marie M. Kelly

Date of permit 5/2/72

Notif. closing-in

Inspn. closing-in

Final Notif.

Final Inspn.

Cert. of Occupancy issued

~~Swing Out Notice~~ IRD

Form Check Notice

[Empty lined area]



R3 RESIDENCE ZONE
 CITY OF PORTLAND, MAINE
 DEPARTMENT OF BUILDING INSPECTION
COMPLAINT

Location:
450 Capisic Street


INSPECTION COPY

COMPLAINT NO. 61/16

Date Received April 4, 1961

Location 450 Capisic Street Use of Building _____
 Owner's name and address ^{Doris Hoyt} J. B. Duffey, 450 Capisic St. Telephone SP-4-3424
 Tenant's name and address _____ Telephone _____
 Complainant's name and address neighbor Telephone _____ H
 Description: Several unregistered cars and junked cars on property.

NOTES: 4/6/61 - 4 unregistered car and 1 registered car here
4/17/61 - Letter to owner, which see - AGJ - Allen
4/17/61 - Out - 2 cars & one truck here - Allen
4/27/61 - Lady says there are six cars here today
covered with blankets. PH
4/28/61 - 5 cars here. Three unregistered - Allen
5/3/61 - Second letter to owner, which see - AGJ
5/11/61 - Only one truck here - Allen



Fu-5/11/61 QAS

Cplt. 61/16 - 450 Capisco Street

May 3, 1961

Mrs. Doris H. Duffey
450 Capisco Street

Dear Mrs. Duffey:

In spite of my letter of April 7th to you concerning the unlawful operations being conducted on your property at the above named location, an inspector from this department reports that there has been no improvement in the situation. Under these circumstances, unless this violation is corrected before May 11th, I shall find it necessary to recommend to the Corporation Counsel, without further notice to you, that legal steps be taken to secure compliance with Zoning Ordinance regulations.

Very truly yours,

AJS/JS

Albert J. Sears
Inspector of Buildings

FU - 4/17/61 AAS

61/16 - 450 Capais Street

April 7, 1961

Mrs. Doris H. Duffey
450 Capais Street

Dear Mrs. Duffey:

It has been brought to the attention of this department that the premises outside of your dwelling at the above named location are being used unlawfully under the Zoning Ordinance. The property is located in an R-3 Residence Zone where activities of a business nature are not allowable. While off-street parking of motor vehicles is allowable as an accessory use, it is limited to not more than three vehicles, only one of which may be a commercial motor vehicle. Section 14-5-3 of the Ordinance also stipulates that loading, sales, dead storage, repair or servicing of any kind in connection with motor vehicles shall not be considered as allowable off-street parking.

An inspector from this department reports that at the time of a recent inspection there were at least five motor vehicles on the premises only one of which was licensed. Not only is the dead storage of the unlicensed cars on the premises unlawful, but a total of more than three at any one time is also not permissible. The making of any repairs to such vehicles to put them in shape for resale is also not allowable.

It may be that you are unaware of the restrictions of the Zoning Ordinance applying to your property. Now that the violations have been called to your attention, will you not take steps at once to correct this unlawful condition so that further action by this department may not become necessary? If you have any questions as to the application of the Zoning Ordinance, I shall be glad to go further into the matter upon request. However, it is important that there be no undue delay in correcting the violation.

Very truly yours,

AJS/jg

Albert J. Sears
Inspector of Buildings



APPLICATION FOR AMENDMENT TO PERMIT

Amendment No. 1
Portland, Maine, April 16, 1952

PERMIT ISSUED

APR 18 1952

CITY of PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for amendment to Permit No. 50/2495 pertaining to the building or structure comprised in the original application in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith, and the following specifications:

Location ~~150 Capric Street~~ 361 Woodford St. Within Fire Limits? no Dist. No. _____
Owner's name and address J. E. Duffey, 125 Riverside Street Telephone _____
Lessee's name and address _____ Telephone _____
Contractor's name and address David Baker, 308 Allen Avenue Telephone _____
Architect _____ Plans filed yes No. of sheets 1
Proposed use of building dwelling house No. families 1
Last use " " No. families 1
Increased cost of work _____ Additional fee .25

Description of Proposed Work

To change Contractors to the above.
To finish off three rooms and bath on second floor using 2x3 studs, 16" on centers, covered on both sides sheetrock and ceilings to be of celotex.

Permit Issued with Letter

Amendment to be issued to David Baker Details of New Work

Is any plumbing involved in this work? _____ Is any electrical work involved in this work? _____
Height average grade to top of plate _____ Height average grade to highest point of roof _____
Size, front _____ depth _____ No. stories _____ solid or filled land? _____ earth or rock? _____
Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
Material of underpinning _____ Height _____ Thickness _____
Kind of roof _____ Rise per foot _____ Roof covering _____ of lining _____
No. of chimneys _____ Material of chimneys _____ Dress, or full size? _____
Framing lumber—Kind _____ Sills _____ Girt or ledger board? _____ Size _____
Corner posts _____ Size _____ Columns under girders _____ Size _____ Max. on centers _____
Girders _____ Size _____ Columns under girders _____ Size _____ Max. on centers _____
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
J. E. Duffey

Approved: with letter by ags

Signature of Owner: David Baker
Approved: 4/18/52 W.H.
Inspector of Building

INSPECTION COPY

(R) RESIDENCE ZONE - C

APPLICATION FOR PERMIT



Class of Building or Type of Structure Third Class

Portland, Maine, November 28, 1950

PERMIT ISSUED
02495
DEC 27 1950
CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to ~~erect~~ repair ~~and make alterations~~ the following building ~~structure~~ in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 150 Capisic Street Within Fire Limits? no Dist. No. _____
Owner's name and address J. E. Duffey, 125 Bancroft Street Telephone _____
Lessee's name and address _____ Telephone _____
Contractor's name and address L. A. Mc Mackin, 234 Middle Street Telephone 4-0531
Architect _____ Specifications _____ Plans yes No. of sheets 1
Proposed use of building dwelling house No. families 1
Last use _____ " " _____ No. families 1
Material WOOD No. stories 1 1/2 Heat _____ Style of roof _____ Roofing _____
Other buildings on same lot _____
Estimated cost \$ 4,000. Fee \$ 5.00

General Description of New Work

To repair after ~~repair~~ and make alterations as per plan.

INSPEC NOT COMPLETED

Permit Issued with Letter

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. PERMIT TO BE ISSUED TO L. A. McMackin

Details of New Work

Is any plumbing involved in this work? _____ Is any electrical work involved in this work? _____
Height average grade to top of plate _____ Height average grade to highest point of roof _____
Size, front _____ depth _____ No. stories _____ solid or filled land? _____ earth or rock? _____
Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
Material of underpinning _____ Height _____ Thickness _____
Kind of roof _____ Rise per foot _____ Roof covering _____
No. of chimneys _____ Material of chimneys _____ of lining _____ Kind of heat _____ fuel _____
Framing lumber—Kind _____ Dressed or full size? _____
Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____
Girders _____ Size _____ Columns under girders _____ Size _____ Max. on centers _____
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____ number commercial cars to be accommodated _____
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will work require disturbing of any tree on a public street? _____
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

J. E. Duffey

APPROVED:
with letter by JED

Signature of owner

Lyndon L. McMackin Contractor

INSPECTION COPY

1-25-51 - Checked with Mr. Mulholland, architect that one of the roof supports for the roof may be removed so that maximum span of existing girders can be used and floor will not exceed 9'-6" O.C.

2-27-51 - Mr. Duffly called up for inspection but really wanted to go over his roof construction. He is dissatisfied with the locker pit, it being so large, but pitch etc. checked with plans. Told him he better contact his architect & builder to see if condition can now be changed. No.

5-14-51 - Other work is in a confined space and all that can be done is to bring in steel members up to structural safety and construction detail design requirements as possible. In my mind only the girders as far as framing is concerned. Am doing to take 300 hours to look at WGM

3-17-52 - Sounded over site and they were working on the roof and progress allowing extra 7' of height & can see no other way out to have it replaced with windows and doors which he get in touch with myself. Had recommended and to be someone else furnished. Proceed as originally planned. This has been agreed to do. Told him to notify when he had the door and supports to solid beams. Installation put on a temporary wall. It will be in walls or columns erected. Permission to do this has been given. G.P. 52-52. The building is in yet WGM.

8-10-52 - No one here could get in. WGM. 7-4-52 - No one here WGM. 7-5-52 - Could get in WGM. 9-10-52 - No one here WGM. 10-9-52 - One short joint in floor is in place & will be replaced.

12-15-57 - Same WGM. 1-15-58 - This building is not in my mind only the girders as far as framing is concerned. Am doing to take 300 hours to look at WGM. 3-17-52 - Sounded over site and they were working on the roof and progress allowing extra 7' of height & can see no other way out to have it replaced with windows and doors which he get in touch with myself. Had recommended and to be someone else furnished. Proceed as originally planned. This has been agreed to do. Told him to notify when he had the door and supports to solid beams. Installation put on a temporary wall. It will be in walls or columns erected. Permission to do this has been given. G.P. 52-52. The building is in yet WGM. 7-4-52 - No one here WGM. 7-5-52 - Could get in WGM. 10-9-52 - One short joint in floor is in place & will be replaced. 1-15-58 - This building is not in my mind only the girders as far as framing is concerned. Am doing to take 300 hours to look at WGM.

Permit No.	5012493
Location	1550 - 15th St. N.W.
Owner	E. J. Mulholland
Date of permit	1-27-51
Notif. closing in	2-27-51
Insps. closing in	2-27-51
Final Notif.	2-27-51
Final Inspn.	2-27-51
Cert. of Occupancy Issued	2-27-51

INSPECTION NOT COMPLETED

3-17-52 - Sounded over site and they were working on the roof and progress allowing extra 7' of height & can see no other way out to have it replaced with windows and doors which he get in touch with myself. Had recommended and to be someone else furnished. Proceed as originally planned. This has been agreed to do. Told him to notify when he had the door and supports to solid beams. Installation put on a temporary wall. It will be in walls or columns erected. Permission to do this has been given. G.P. 52-52. The building is in yet WGM.

7-4-52 - No one here WGM.

7-5-52 - Could get in WGM.

10-9-52 - One short joint in floor is in place & will be replaced.

1-15-58 - This building is not in my mind only the girders as far as framing is concerned. Am doing to take 300 hours to look at WGM.

1-15-58 - This building is not in my mind only the girders as far as framing is concerned. Am doing to take 300 hours to look at WGM.



RESIDENCE ZONE - C

APPLICATION FOR PERMIT

Class of Building or Type of Structure: Third Class

Portland, Maine, May 24, 1919

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to ~~erect~~ ~~repair~~ ~~demolish~~ ~~alter~~ ~~the~~ ~~existing~~ ~~building~~ ~~structure~~ ~~equipment~~ in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 458 Canisic Street

Owner's name and address James Duffie, 125 Bancroft Street Within Fire Limits? no Dist. No. _____

Prospective buyer _____ Telephone _____

Lessee's name and address Philip Leonard, 111 State Street Telephone 4-1394

Contractor's name and address Prospective buyer Telephone _____

Architect _____ Specifications _____ Plans yes No. of sheets 3

Proposed use of building Dwelling house No. families 1

Last use vacant No. families _____

Material wood No. stories 1 1/2 Heat _____ Style of roof _____ No. families _____

Other buildings on same lot _____ Roofing _____

Estimated cost \$ 5,000 Fee \$.00

General Description of New Work

To repair after fire and make alterations as per plans.

*applicant
did not to
go ahead in the
work*

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. **PERMIT TO BE ISSUED TO Philip Leonard**

Details of New Work

Is any plumbing involved in this work? _____ Is any electrical work involved in this work? _____

Height average grade to top of plate _____ Height average grade to highest point of roof _____

Size, front _____ depth _____ No. stories _____ solid or filled land? _____ earth or rock? _____

Material of foundation _____ Thickness, top _____ bottom _____ cellar _____

Material of underpinning _____ Height _____ Thickness _____

Kind of roof _____ Rise per foot _____ Roof covering _____

No. of chimneys _____ Material of chimneys _____ of lining _____ Kind of heat _____ fuel _____

Framing lumber—Kind _____ Dressed or full size? _____

Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____

Girders _____ Columns under girders _____ Size _____ Max. on centers _____

Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.

Joists and raft _____ 1st floor _____, 2nd _____, 3rd _____, roof _____

On centers: _____ 1st floor _____, 2nd _____, 3rd _____, roof _____

Maximum span: _____ 1st floor _____, 2nd _____, 3rd _____, roof _____

If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____ number commercial cars to be accommodated _____

Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

APPROVED:

Miscellaneous

Will work require disturbing of any tree on a public street? no

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

James Duffie

INSPECTION COPY

Signature of owner Philip H Leonard

AP 450 Capisic Street

April 18, 1952

Mr. David H. Baker
308 Allen Avenue
Portland, Maine

Copy to Mr. J. H. Duffey
361 Woodward Street

Dear Mr. Baker:

Amendment #1 to Permit 50/2495 covering construction of partitions in and finishing off of the second story of the dwelling at 450 Capisic Street is issued herewith based on the plan filed with the application for amendment.

None of the new partitions, walls or ceiling in the second story and none of the uncovered portions of the first story of the building are to have wall board applied to them until notification has been given this department for an inspection and authorization to do so has been given on a green tag left at the job. The plumbing and electric wiring will need to be installed and approved by the proper inspectors before notification for this inspection is given. All fire-stopping in outside walls, around the chimney, and in all other locations where required should also be done before this notice is given. There are also some details in regard to the framing of walls in the first story, which have previously been taken up with Mr. Duffey, that will want to be completed at that time.

Very truly yours,

Warren McDonald
Inspector of Buildings

AJS/B

AP 450 Capisic : at

December 21, 1950

Mr. L. A. McMackin
234 Middle Street
Portland, Maine

Copy to: Mr. J. E. Duffay
125 Bancroft Street

Dear Mr. McMackin:

Building permit for rebuilding of dwelling damaged by fire at 450 Capisic Street is issued herewith based on the plans filed with the application, but subject to the following:

1. It is understood that all rotted wood is to be removed from the girders in the cellar and 4x8's laid flat provided for bolsters beneath the girders and securely fastened to them. Existing brick piers and cedar posts supporting girders are to remain, but concrete footings extending at least 4" above the cellar floor are to be provided for the cedar posts.
2. Floor framing of first and second floors of main house are to be reinforced with 2x6 timbers placed between the existing floor timbers and properly supported on the carrying girders.
3. Floor timbers in first floor of all are to be reinforced by a new 2x6 girder on spans of about 6'. In order to figure out on this span this 2x6 will need to be full size and the permit is issued on the basis that a full size timber will be used at this location.
4. The walls of the cell in which rafters are supported are to be tied at the plate level by means of the strapping.
5. Extra 2x4 studs are to be provided between the 3x3 studs of the walls of the main house and fastened securely to the outside boarding.
6. There is nothing on plans to indicate how the trusses to which the second floor is to be hung are to be supported. Presumably they will rest on the plates, but 4x6 posts either built up or all one piece in cross section will need to be provided directly beneath each end of the trusses.
7. No wallboard or lath is to be applied to any part of the building until notice for a "closing-in" inspection has been given this department and authorization has been given to do so on a green tag left at the job.

Very truly yours,

Warren McDonald
Inspector of Buildings

AJS/B

file copy
AP 450 Capisic Street-I

December 5, 1950

Mr. L. A. McMackin
234 Middle Street
Portland, Maine

Copy to: Mr. J. E. Duffey
125 Bancroft Street

Dear Mr. McMackin:

A check of the plans filed with the application for a permit for rebuilding of dwelling damaged by fire at 450 Capisic Street and an inspection of the building itself raises the following questions about which more information is needed to show compliance with Building Code requirements before a permit may be issued:

1. What is to be done about the rotted girders in the cellar of the main house? If cedar posts are to remain for support of girders, masonry footings extending at least 6" above cellar floor will need to be provided for these posts.

2. Existing floor timbers in first floor of main house are 4x6, 32" on centers and in second floor are 3x5, 32" on centers. What is to be done about making spacing comply with Building Code requirements? - *Extra timbers between*

3. Floor timbers in first story of ell are on about an 12-foot span, which is too long for the 2x8 timbers. It is apparent that some changes will be made in the framing of this floor by relocation of cellar stairs, but just what is planned cannot be determined unless a framing plan of this floor is furnished.

4. The plan seems to indicate that the second floor timbers of ell are to be run lengthwise of the ell instead of crossways as at present and are to be supported on new bedrock partitions in first story. However, this load would be deposited on the first floor timbers with nothing in the cellar to take care of it. Such an arrangement also raises a question as to how a tie is to be provided across the ell at the plate line. *bracket*

5. The studs in the walls of the main house are 3x5, 30" on centers. What is to be done to provide required wall construction at this location? - *all right between*

6. If the girders supporting second floor construction of the main building are to be carried on trusses as indicated on the plan, such trusses will need to be designed according to standard procedure by someone capable of so doing and a plan showing all details of construction, particularly of the joints, furnished together with the designer's statement of design.

7. Is a new plate to be provided for the building in place of the ledger board construction and how is the building to be tied at the plate line with the second floor joists running at right angles to the rafters? - *yes*

8. Is there to be a platform and steps outside the new front door and if so, what is the construction and foundations to be? - *OK*

Full information as to how all the above details are to be taken care of in compliance with Building Code requirements needs to be shown on revised plans before a permit may be issued. We also would like information as to any plans for use of the old stable on the lot and whether or not any repairs to it are to be made.

Very truly yours,

AJS/G

Inspector of Buildings