

DEPT. OF BUILDING INSPECTION
CITY OF PORTLAND, ME

REPAIR INSPECTION FORM

JAN 9 1995
RECEIVED

Portland High School Repair Project

Project Team Member: P&G WJE Sheet 1 of 1

Room Number on Plan: G074 Building Room Number: G05

Repair Designation/Description: TASKS 1, 2, 3

Engineering Sketches / Calculations Reference: WJE 'ALL REPAIRS'

Contractor: CUG

INSPECTION RECORD

Repair Start Date: ___/___/___ By: ___

Intermediate Inspections:

Date	Time	By	Comment/Photos
1-5-94	9:25	DVP	TASKS 1 & 2 COMPLETE, TASK 3 NOT DONE
1-9-95	10:10	DVP	FIRESTOPPING INSTALLED

Repair Completion Date: 1 / 9 / 95 By: DVP

Final Sign Off: P&G 1-9-95 / WJE 1-9-95 / City of Portland

WJE 942566
WJE/IN

D JAN 9 1995
RECEIVED

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: G069 Building Room Number: G07

Repair Designation/Description: Wall Penetrations TASKS 1, 2

Engineering Sketches / Calculations Reference: _____

Contractor: C.M. CIMINO

INSPECTION RECORD

Repair Start Date: 12 / 2 / 94 By: RBJ

Intermediate Inspections:

Date	Time	By	Comment/Photos
12/2/94		RBJ	FIRE STOPPED SMALL NICK NOT DONE
1-5-95	9:45	DVP	DECIDED TO CHECK ON THICKNESS OF M&S,
1-6-95	0745	RBJ	NOT AN EXISTING OPENING Filled with 8" CMU BLOCK (below) on RIGHT SIDE. REMOVED AND Filled Full DEPTH WITH BRICK.
1-7-95	0735	RBJ	DONE TASK #1

Repair Completion Date: _____ / _____ / _____ By: _____
Final Sign off: DVP 1-9-95, CP 09 JAN 95 [Signature] 9 Jan 95
P&G WJE City of Portland

JAN 9 1995

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G WJE _____ Sheet 1 of 1

Room Number on Plan: G-073 Building Room Number: LAUNDRY

Repair Designation/Description: FLOOR PENETRATION, FIRESTOP

Engineering Sketches / Calculations Reference: _____

Contractor: _____

INSPECTION RECORD

Repair Start Date: _____ / _____ / _____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos
1-5-95	9:20	DKP	NO WORK DONE
1-9-95		DKP	OPENING IN FLOOR FIRESTOPPED

Repair Completion Date: 1 / 9 / 95 By: DKP

Final Sign Off: DKP 1-9-95, CP 0224-95
P&G WJE City of Portland

DEPT. OF BUILDING INSPECTION
CITY OF PORTLAND, ME

REPAIR INSPECTION FORM

JAN 9 1995
RECEIVED

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 6000 Building Room Number: STORAGE

Repair Designation/Description: NO WORK

Engineering Sketches / Calculations Reference: _____

Contractor: _____

INSPECTION RECORD

Repair Start Date: ____/____/____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos

Repair Completion Date: ____/____/____ By: _____

Final Sign Off: DLP 1-6-96 / CP 09 JAN 95
P&G WJE City of Portland

WJE 942546
WJE1416

Portland High School

1/10/35

8:00-11:45

Sam Hoffses/LT. G. McDougall/David Pankham/Richard Jones/Conrad Paulson

Room	Building Plan Number	Decision
220	2041	
220	2040	
220	2042	ok to occupy
221	2044	Check framing on duct work into chase
221	2043	ok to occupy
221	2048-J. Mack	ok to occupy
221	2049	ok to occupy
222	2050	ok to occupy
222	2046	ok to occupy
222	2045	ok to occupy
222	2038	ok to occupy
223	2051	Sprinkler head needs to be dropped
223	2052	ok to occupy
223	2053	ok to occupy
224	2055	ok to occupy
224	2054	ok to occupy
224	2056	ok to occupy
225	2058	ok to occupy
225	2059	ok to occupy
225	2057	ok to occupy
226	2061	ok to occupy
226	2060	ok to occupy
226	2052	ok to occupy
226	2063	ok to occupy

		Fire rate under stairs
226	2063 (under stairs)	
226	2065	ok to occupy
227	2067	ok to occupy
227	2068	ok to occupy
227	2066	ok to occupy
227	2070	ok to occupy
227	2117	ok to occupy
227	2069	ok to occupy

Stair #4 Check treads by calculation

Hallway (2064) check sag in ceiling

Stair #2 ok to occupy

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 2050 Building Room Number: FACULTY HALL

Repair Identification/Description: WALL PENETRATIONS, TASKS 1, 2, 3

Engineering Sketches / Calculations Reference: _____

Contractor: C. M. CIMINO

INSPECTION RECORD

Repair Start Date: 12 / 9 / 94 By: MWC

Intermediate Inspections:

Date	Time	By	Comment/Photos
<u>12/9/94</u>		<u>MWC</u>	<u>Finishing CEILING complete</u>
<u>12/15/94</u>		<u>MWC</u>	<u>SOME PIPE penetrations SEALED WALLS PATCHED</u>
<u>1-10-95</u>		<u>DLP</u>	<u>PELLET PATCHED</u>

INSPECTION
PORTLAND, ME
JAN 11 1995
E I W E

Repair Completion Date: 1 / 10 / 95 By: DLP

Final Sign Off: DLP 1-10-95 CP 10 JAN 95 [Signature] 10/30/95
P&G WJE City of Portland

WJE 942566
WJE 1410

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 2052 Building Room Number: 223

Repair Designation/Description: FIRESTOP CEILING; Plaster CEILING SYSTEM

Engineering Sketches / Calculations Reference: _____

Contractor: C. M. CIMINO

INSPECTION RECORD

Repair Start Date: 12 / 15 / 94 By: M.V.C

Intermediate Inspections:

Date	Time	By	Comment/Photos
<u>12/15/94</u>		<u>M.V.C</u>	<u>WALL PATCHED w/ GWB AND MURDED CEILING w/ plaster</u>
<u>1-10-95</u>		<u>DLP</u>	<u>CEIL. PLASTER PATCHED</u>

INSPECTION
PORTLAND, ME
JAN 11 1995
RECEIVED

Repair Completion Date: 1 / 10 / 95 By: DLP

Final Sign Off: DLP 1-10-95 / CP 10 JAN 95 / [Signature] 1-10-95
P&G WJE City of Portland

WJE 442566
WJE 1416

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 2053 Building Room Number: STORAGE

Repair Designation/Description: NO WORK REQUIRED

Engineering Sketches / Calculations Reference: _____

Contractor: _____

INSPECTION RECORD

Repair Start Date: ____/____/____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos

OFFICE OF BUILDING INSPECTION
CITY OF PORTLAND, ME
JAN 11 1995
E B E I E

Repair Completion Date: ____/____/____ By: _____

Final Sign Off: P&G 1-10-95 / WJE 10 Jan 95 / [Signature] 1-10-95
P&G WJE City of Portland

WJE 942566
WJE1910

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 205 Building Room Number: STORAGE

Repair Designation/Description: NO WORK REQUIRED

Engineering Sketches / Calculations Reference: _____

Contractor: _____

INSPECTION RECORD

Repair Start Date: _____ / _____ / _____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos

INSPECTION
CITY OF PORTLAND, ME.
JAN 11 1995
RECEIVED

Repair Completion Date: _____ / _____ / _____ By: _____

Final Sign Off: WJP 1-10-95 / CD 10-30-95 / [Signature] 1-10-95
P&G WJE City of Portland

WJE 942566
WJE 1412

REPAIR INSPECTION FORM

Portland High School Repair Project:

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: Z055 Building Room Number: 224

Repair Designation/Description: FIRE STAIRWELL, TANKS 142

Engineering Sketches / Calculations Reference: _____

Contractor: C. McCLIMMO

INSPECTION RECORD

Repair Start Date: 12 / 10 / 94 By: RBT

Intermediate Inspections:

Date	Time	By	Comment/Photos
<u>12/10/94</u>	<u>0820</u>	<u>RBT</u>	<u>Small holes in ceiling patched. WIRE MESH FOR LARGE HOLES INSTALLED</u>
<u>12/15/94</u>		<u>MWC</u>	<u>WALLS PATCHED W/ GWB.</u>
<u>1-10-95</u>		<u>DVP</u>	<u>REPAIRS COMPLETE</u>

DEPT. OF BUILDING INSPECTION
 CITY OF PORTLAND, ME
 JAN 11 1995
 RECEIVE

Repair Completion Date: 1 / 1 / 95 By: _____

Final Sign Off: DVP 1-10-95 / WJE 10 JAN 95 / [Signature] 1-10-95
 P&G WJE City of Portland

BY 042566
 WJE 1/10

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 205b Building Room Number: STORAGE

Repair Designation/Description: NEW WALK REZEMBLE

Engineering Sketches / Calculations Reference: _____

Contractor: _____

INSPECTION REPORT

Repair Start Date: ____/____/____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos

INSPECTED BY SECTION
CITY OF PORTLAND, ME
JAN 11 1995
P&G

Repair Completion Date: ____/____/____ By: _____

Final Sign Off: DKP 1-10-95 / OK 10-5-95 / [Signature] 10-5-95
P&G WJE City of Portland

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 2057 Building Room Number: STORAGE

Repair Designation/Description: NO WORK REQUIRED

Engineering Sketches / Calculations Reference: _____

Contractor: _____

INSPECTION RECORD

Repair Start Date: ____/____/____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos

DEPT. OF BUILDING INSPECTION
CITY OF PORTLAND, ME
JAN 11 1995
RECEIVED

Repair Completion Date: ____/____/____ By: _____

Final Sign Off: DWP 1-10-95 CP 1031195 [Signature] 1-10-95
P&G WJE City of Portland

SAM

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G WJE _____ Sheet 1 of 1

Room Number on Plan: 203B Building Room Number: FACULTY

Repair Designation/Description: REPAIR IN WEST WALL, SHEET BOLTS

Engineering Sketches / Calculations Reference: _____

Contractor: CAC

INSPECTION RECORD

Repair Start Date: _____ / _____ / _____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos
1-10-95		DLP	REPAIR COMPLETE, SHEET

DEPT. OF BUILDING INSPECTION
CITY OF PORTLAND, ME
JAN 11 1995
RECEIVED

Repair Completion Date: _____ / _____ / _____ By: _____

Final Sign Off: DLP 1-10-95, CP 10 JAN 95, [Signature] 1-10-95
P&G WJE City of Portland

WJE 042566
WJE 1116

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 2042 Building Room Number: STORAGE

Repair Designation/Description: NO WORK REQUIRED

Engineering Sketches / Calculations Reference: _____

Contractor: _____

INSPECTION RECORD

Repair Start Date: _____ / _____ / _____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos

DEPT. OF BUILDING INSPECTIONS
CITY OF PORTLAND, ME
JAN 11 1995
RECEIVED

Repair Completion Date: _____ / _____ / _____ By: _____

Final Sign Off: DVP 1-10-95 / CP 10 JAN 95 [Signature]
P&G WJE City of Portland

WJE 942566
WJE 1916

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet _____ of _____

Room Number on Plan: 2043 Building Room Number: STORAGE

Repair Designation/Description: NO WORK REQUIRED

Engineering Sketches / Calculations Reference: _____

Contractor: _____

INSPECTION RECORD

Repair Start Date: _____ / _____ / _____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos

DEPT. OF BUILDING INSPECTIONS
CITY OF PORTLAND, ME
JAN 11 1995
RECEIVED

Repair Completion Date: _____ / _____ / _____ By: _____

Final Sign off: P&G 1-10-95 / WJE 10 JAN 95 [Signature] 10/5/95
P&G WJE City of Portland

WJE 942566
WJE 1416

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G WJE _____ Sheet 2 of 2
 Room Number on Plan: ~~2045~~ 2045 Building Room Number: 222 Booth rm.
 Repair Designation/Description: W-5 3/8" P X 16X20 (entire)

Engineering Sketches / Calculations Reference: _____

Contractor: S. M. Cimino

INSPECTION RECORD

Repair Start Date: 12 / 21 / 94 By: TFM

Intermediate Inspections:

Date	Time	By	Comment/Photos
12/21/94	2:30	TFM	started opening
12/21/94	3:00	TFM	Old Masonry Removed to start laying Bricks in AM.
12/22/94	7:15	TFM	Bricking up piers
12/22/94	8:30	TFM	Bricking up piers interlocking bricks almost ready for plate
12/22/94	10:00	TFM	
12/22/94	10:30	TFM	still working on piers
12/22/94	11:00	TFM	Plate in place
12/22/94	1:45	TFM	Plate Grouted

DEPT. OF BUILDING INSPECTION
CITY OF PORTLAND, ME

JAN 11 1995
RECEIVED

Repair Completion Date: 12 / 22 / 94 By: [Signature]
 Final Sign Off: [Signature] P&G [Signature] WJE [Signature] City of Portland 10/Jan/95

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G WJE _____ Sheet 1 of 2

Room Number on Plan: 2045 Building Room Number: WOMEN

Repair Designation/Description: WALL PENETRATION TASK 1

Engineering Sketches / Calculations Reference: W4

Contractor: _____

INSPECTION RECORD

Repair Start Date: 12 / 9 / 94 By: MWC

Intermediate Inspections:

Date	Time	By	Comment/Photos
12/9/94		MWC	Small holes in ceiling patched check one edge between ceiling and wall. Patch req'd
12/15/94		MWC	Walls patched w/ GWP; no work on Lintel

DEPT. OF BUILDING INSPECTION
CITY OF PORTLAND, ME
JAN 11 1995
RECEIVED

Repair Completion Date: 12 / 30 / 94 By: RBS

Final Sign Off: DKP 1-10-95 / CP 10 JAN 95 [Signature] 10/30/95
P&G WJE City of Portland

WJE 942566
WJE1416

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 2046 Building Room Number: MEN

Repair Designation/Description: FIRESTOP, ELECTRICAL

Engineering Sketches / Calculations Reference: _____

Contractor: C. M. CIMINO

INSPECTION RECORD

Repair Start Date: 12 / 15 / 94 By: MWC

Intermediate Inspections:

Date	Time	By	Comment/Photos
12/15/94		MWC	WALLS AND CEILING PATCHED w/ Plaster or GWO

EPT. OF BUILDING INSPECTIONS
CITY OF PORTLAND, ME
JAN 11 1995
RECEIVED

Repair Completion Date: 12 / 30 / 94 By: P&G

Final Sign off: P&G 1-10-95 / WJE 10 Jan 95 City of Portland

WJE 942566
WJE 1410

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 2048-1,2,3 Building Room Number: J. Mack

Repair Designation/Description: W-5 3/8" R 16" X 30, 18, 24"
(WALL AND CEILING PENETRATIONS)

Engineering Sketches / Calculations Reference: W-5

Contractor: C.A. Cimino

DEPT. OF BUILDING INSPECTIONS
CITY OF PORTLAND, ME

INSPECTION RECORD

Repair Start Date: 12 / 21 / 94

By: [Signature] **JAN 11 1995**

Intermediate Inspections:

Date	Time	By	Comment/Photos
12/21/94	10:15	TFM	STARTING ON RIGHT LANTER (2048-3)
12/21/94	11:45	TFM	Plate in & centered - REPLACING BRICK WORK NOT STAGGERED JOINTS OK'D BY RICHARD JONES.
12/21/94	1:15	TFM	STARTING ON 2048-1 STAGGERING BRICK JOINTS
12/21/94	3:05	TFM	BOTH PIERS ON 2048-2 ARE DONE WITH PUT PLATE ON IN AM. GROUT PLATE 2048-3
12/22/94	7:10	TFM	WORKING ON 2048-2
12/22/94	8:25	TFM	BRICKING UP PIERS
12/22/94	9:30	TFM	Ready For Plates 2048-1 & 2
12/22/94	10:05	TFM	2048-2 plate is going in 1/2" clearance
12/22/94	11:05	TFM	GROUTING 2048-1 & 2
12/19/94		MWC	CMC AGREED TO STRIP AND INSTALL 5/8" GWA LAYER OVER EXPOSED FLOOR JOINT ABOVE.
12/15/94		MWC	NO LANTER INSTALLED. WALL PENN PATCHED CEILING opening Patched

Repair Completion Date: 12 / 22 / 94 By: [Signature]

Final Sign Off: [Signature] P&G [Signature] WJE [Signature] City of Portland

WJE 942566
WJE 1416

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 2049 Building Room Number: STORAGE

Repair Designation/Description: NO WORK REQUIRED

Engineering Sketches / Calculation Reference: _____

Contractor: _____

INSPECTION RECORD

Repair Start Date: _____ / _____ / _____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos

DEPT. OF BUILDING INSPECTION
CITY OF PORTLAND, ME
JAN 11 1995
RECEIVED

Repair Completion Date: _____ / _____ / _____ By: _____

Final Sign off: P&G 1-10-95 / WJE CP 10 JAN 95 [Signature] 10/10/95
P&G WJE City of Portland

WJE 9-1-86
WJE 1-86

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 2058 Building Room Number: 225

Repair Designation/Description: Wall Penetrations

Engineering Sketches / Calculations Reference: _____

Contractor: C. M. CIMINO

INSPECTION RECORD

Repair Start Date: 12 / 10 / 94 By: RBT

Intermediate Inspections:

Date	Time	By	Comment/Photos
<u>12/10/94</u>		<u>RBT</u>	<u>CEILING PATCHED WITH PLASTER. SMALL RIB WALL VENT NOT SEALED. WALLS PATCHED w/ GWS</u>
<u>12/14/94</u>		<u>MWC</u>	<u>NOT MUDDED. SMALL CEILING JOBS PATCHED. SIFIT AT CURT SEALED w/ WOOL</u>
<u>1-10-95</u>		<u>DUP</u>	<u>FIRESTOP COMPLETE</u>

DEPT OF BUILDING INSPECTIONS
CITY OF PORTLAND, ME
JAN 11 1995
S. R. V. R.

Repair Completion Date: 1 / 10 / 95 By: DUP

Final Sign Off: DUP 1-10-95 / 10 JAN 95 / [Signature] 1-12-95
P&G WJE City of Portland

WJE 942566
WJE IN 12

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 2059 Building Room Number: STORAGE

Repair Designation/Description: NO WORK REQUIRED

Engineering Sketches / Calculations Reference: _____

Contractor: _____

INSPECTION RECORD

Repair Start Date: _____ / _____ / _____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos

DEPT. OF BUILDING INSPECTION
CITY OF PORTLAND, ME
JAN 11 1995
RECEIVED

Repair Completion Date: _____ / _____ / _____ By: _____

Final Sign Off: P&G 1-10-95 / WJE 10 JAN 95 [Signature] 1-10-95
P&G WJE City of Portland

WJE 012566
WJE 1412

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 2060 Building Room Number: STORAGE

Repair Designation/Description: NO WORK REQUIRED

Engineering Sketches / Calculations Reference: _____

Contractor: _____

INSPECTION RECORD

Repair Start Date: _____ / _____ / _____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos

Repair Completion Date: _____ / _____ / _____ By: _____

Final Sign Off: OLP 1-10-95 / P&G / WJE 10 JAN 95 / WJE 1-10-95
 P&G WJE City of Portland

WJE 942566
 WJE 1916

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 2061 Building Room Number: 226

Repair Designation/Description: WALL PENETRATIONS & FIRE STOPPING

Engineering Sketches / Calculations Reference: _____

Contractor: C. M. CUMINO

INSPECTION RECORD

Repair Start Date: 12 / 9 / 94 By: LB

Intermediate Inspections:

Date	Time	By	Comment/Photos
12/9/94	0820	P&G	TASK #1 Complete
	1317	P&G	TASKS 2 & 3 Complete
12/14/94		MWC	Small holes in wall and ceiling patched w/ plaster or GWA.

CITY OF PORTLAND, ME
 FIRE CODE INSPECTOR
 JAN 11 1995
 E. G. E. I. V. E.

Repair Completion Date: 12 / 14 / 94 By: LB

Final Sign Off: OLP 1-10-95 / CP 1050195 / [Signature] 1-10-95
 P&G WJE City of Portland

WJE 942566
 WJE 1410

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G ✓ WJE _____ Sheet 1 of 1
Room Number on Plan: 2062 Building Room Number: STORAGE
Repair Designation/Description: FIRESTOP CEIL. PENET.

Engineering Sketches / Calculations Reference: _____

Contractor: _____

INSPECTION RECORD

Repair Start Date: 1 / 10 / 95 By: DVP

Intermediate Inspections:

Date	Time	By	Comment/Photos

INSPECTION
OF PORTLAND ME
JAN 11 1995
P&G WJE

Repair Completion Date: 1 / 10 / 95 By: DVP

Final Sign Off: DVP P&G WJE City of Portland 1-10-95

WJE 942566
WJE 1/11/95

6

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1
Room Number on Plan: 2065 Building Room Number: STORAGE
Repair Designation/Description: NO WORK REQUIRED

Engineering Sketches / Calculations Reference: _____

Contractor: _____

INSPECTION RECORD

Repair Start Date: _____ / _____ / _____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos

DEPT. OF BUILDINGS INSPECTION
CITY OF PORTLAND, ME
JAN 11 1995
E. G. FIVE

Repair Completion Date: _____ / _____ / _____ By: _____

Final Sign off: D&P 1-10-95 ICP 10 JAN 95 D. L. Hoff 10 Jan 95
P&G WJE City of Portland

6

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 206G Building Room Number: STORAGE

Repair Designation/Description: PATCH CEIL. PENETRATION

Engineering Sketches / Ca'culations Reference: _____

Contractor: _____

INSPECTION RECORD

Repair Start Date: 1 / 10 / 95 By: DJP

Intermediate Inspections:

Date	Time	By	Comment/Photos
1-10-95	10:55	DJP	PATCH CEIL. COMPLETE

DEPT OF BUILDING INSPECTION
CITY OF PORTLAND, ME
JAN 11 1995
[Stamp]

Repair Completion Date: 1 / 10 / 95 By: DJP

Final Sign Off: DJP 1-10-95 / CP 10 JAN 95
P&G WJE City of Portland

WJE 942566
WJZIN16

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G / WJE Sheet 1 of 1

Room Number on Plan: 2067/2068 Building Room Number: 227

Repair Designation/Description: WALL PENETRATIONS
CEILING PENETRATIONS

Engineering Sketches / Calculations Reference: _____

Contractor: C.M. CIMINI

INSPECTION RECORD

Repair Start Date: 12 / 9 / 94 By: MWC

Intermediate Inspections:

Date	Time	By	Comment/Photos
<u>12/9/94</u>		<u>MWC</u>	<u>DISCLOSED REPAIR of open shaft w/ ANGLONITE LINING. STAIR 16" O.C. APPLY 5/8" GWS STRAU CEILING WATER DRIP PATCHED</u>
<u>12/14/94</u>		<u>MWC</u>	<u>Plaster Patching of ceiling complete. WALL PENETRATIONS PATCHED W/ GWS. SHAFTS TO ATTIC COVERED W/ GWS SCREENING MAT.</u>

DEPT. OF BUILDING INSPECTION
 CITY OF PORTLAND, ME
 JAN 11 1995
 RECEIVED

Repair Completion Date: 12 / 30 / 94 By: [Signature]

Final Sign off: [Signature] P&G / [Signature] WJE / [Signature] City of Portland

WJE 942546
 WJE 1416

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 2019 Building Room Number: STORAGE

Repair Designation/Description: NO WORK REQUIRED

Engineering Sketches / Calculations Reference: _____

Contractor: _____

INSPECTION RECORD

Repair Start Date: _____ / _____ / _____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos

Repair Completion Date: _____ / _____ / _____ By: _____

Final Sign Off: P&G 1-10-95 WJE 10 JAN 95 [Signature] 10/Jan/95
P&G WJE City of Portland

WJE 942546
WJE 1416

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G WJE _____ Sheet 1 of 1

Room Number on Plan: 2070 Building Room Number: OFFICE

Repair Designation/Description: PATCH CEILING & WALLS

Engineering Sketches / Calculations Reference: _____

Contractor: C. M. CUMANO

INSPECTION RECORD

Repair Start Date: 12 / 14 / 94 By: MWC

Intermediate Inspections:

Date	Time	By	Comment/Photos
12/14/94		MWC	CEILING Patched w/Plaster - WALLS with GWS.

DEPT OF BUILDING INSPECTION
CITY OF PORTLAND ME
JAN 11 1995
WJE

Repair Completion Date: 1 / 1 / 95 By: _____
Final Sign Off: WJE 1-10-95 C. M. CUMANO 1-10-95
P&G WJE City of Portland

WJE #42566
WJE1416

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G WJE _____ Sheet 1 of 1

Room Number on Plan: 2117 Building Room Number: CLOSET

Repair Designation/Description: PATCH PENETRATIONS

Engineering Sketches / Calculations Reference: _____

Contractor: _____

INSPECTION RECORD

Repair Start Date: _____ / _____ / _____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos
1-10-95		DUP	PELET. PATCHED

DEPT. OF BUILDINGS INSPECTION
CITY OF PORTLAND, ME

JAN 11 1995

Repair Completion Date: _____ / _____ / _____ By: _____

Final Sign Off: DUP 1-10-95 / CAP 10 JAN 95 [Signature] 10 Jan 95
P&G WJE City of Portland

WJE 042566
WJE 1116

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: STAIR #2 Building Room Number: _____

Repair Designation/Description: NO WORK

Engineering Sketches / Calculations Reference: _____

Contractor: _____

INSPECTION RECORD

Repair Start Date: _____ / _____ / _____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos

JAN 11 1995
INSPECTION DIVISION

Repair Completion Date: _____ / _____ / _____ By: _____

Final Sign Off: DKP 1-10-95 / _____ WJE 10-1-95
P&G City of Portland

WJE 942566
WJE/1414

SAM

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 3039 Building Room Number: NUMBER RM

Repair Designation/Description: NO WORK

Engineering Sketches / Calculations Reference: _____

Contractor: _____

INSPECTION RECORD

Repair Start Date: ____/____/____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos

JAN 19 1995

Repair Completion Date: ____/____/____ By: _____

Final Sign off: DVP 1-18-95 / DFM 1/18/95 / [Signature] 1-18-95
P&G WJE City of Portland

WJE 942566
WJE 1416

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 3041 Building Room Number: PREP RM

Repair Designation/Description: NO WORK

Engineering Sketches / Calculations Reference: _____

Contractor: _____

INSPECTION RECORD

Repair Start Date: ____/____/____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos

JAN 19 1995

Repair Completion Date: ____/____/____ By: _____

Final Sign Off: DUP 1-18-95, DPM 1/18/95
PEG WJE City of Portland

WJE 942546
WJE 1412

REPAIR INSPECTION FORM

Portland High School P Project

Project Team Member: P&G _____ WJE _____ Sheet _____ of _____

Room Number on Plan: 305B Building Room Number: 307

Repair Designation/Description: TASKS 1-2 WALL PENETRATIONS

Engineering Sketches / Calculations Reference: W2

Contractor: C. M. CIMINO

INSPECTION RECORD

Repair Start Date: _____ / _____ / _____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos
1-18-95	9:30	DLP	TASKS 1&2 COMPLETE

JAN 19 1995

Repair Completion Date: _____ / _____ / _____ By: _____

Final Sign Off: DLP 1-18-95 / DFM 1/18/95 / [Signature] 1/18/95
P&G WJE city of Portland

WJE 942566
WJE 1/18/95

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G / WJE Sheet 1 of 1

Room Number on Plan: 3059 Building Room Number: 306

Repair Designation/Description: TASKS 1, 2, 3; WALL PENETRATIONS, CEILING PENETRATIONS FALLING HAZARD

Engineering Sketches / Calculations Reference: W7 + W3

Contractor: C.M. CIMINO

INSPECTION RECORD

Repair Start Date: 11 / 29 / 94 By: RBJ

Intermediate Inspections:

Date	Time	By	Comment/Photos
11/29/94	unknown	RBJ	FIRST COAT OF PLASTER ON WIRE MESH APPLIED FROM ABOVE.
11/30/94	unknown	RBJ	2nd coat of plaster from above and small holes patched down.
1-18-95	9:45	DVP	WALL OPENINGS FILLED (TASK 1 & 2) VARIOUS SMALL PERKETS NOT PATCHED
1-18-95	10:40	DVP	PENETRATIONS PATCHED

JAN 19 1995

Repair Completion Date: / / By:

Final Sign Off: DVP 1-18-95 / DFM 1/18/95 / [Signature] 1-18-95 City of Portland

WJE 942566 WJE 1416

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G WJE _____ Sheet 1 of 1

Room Number on Plan: 3060 Building Room Number: 305/306

Repair Designation/Description: TASKS 273 WALL PENETRATIONS
HOLES IN CEILING.

Engineering Sketches / Calculations Reference: W3

Contractor: C. M. CIMINO

INSPECTION RECORD

Repair Start Date: _____ / _____ / _____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos
1-18-95	10:45	DVP	TASKS COMPLETE

RECEIVED
JAN 19 1995

Repair Completion Date: _____ / _____ / _____ By: _____

Final Sign Off: DVP 1-18-95 / DFM 1/18/95 / [Signature] 1-18-95
P&G WJE City of Portland

WJE 942566
4412146

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 3067 Building Room Number: JAN. CLOSET

Repair Designation/Description: NO WORK PERD

Engineering Sketches / Calculations Reference: _____

Contractor: _____

INSPECTION RECORD

Repair Start Date: _____ / _____ / _____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos

DEPT OF BUILDINGS INSPECTION DIVISION
JAN 19 1995

Repair Completion Date: _____ / _____ / _____ By: _____

Final Sign Off: DUZ 1-18-95 / DFM 1/18/95 / [Signature] 1-18-95
P&G WJE City of Portland

WJE 942566
WJE 1414

JAN

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G WJE _____ Sheet 1 of 1

Room Number on Plan: 2044 Building Room Number: 221

Repair Designation/Description: WALL PENETRATIONS FIRE STOPPING FRAMING TASKS 1-3

Engineering Sketches / Calculations Reference: _____

Contractor: C.M. CIMINO

INSPECTION RECORD

Repair Start Date: 12 / 15 / 94 By: MWC

Intermediate Inspections:

Date	Time	By	Comment/Photos
<u>12/15/94</u>		<u>MWC</u>	<u>1 DRY WALL PATCH NOT MUO 20 CHASE PENETRATIONS SEALED W/ 2 LAYERS GWA</u>
<u>1-10-95</u>		<u>DKP</u>	<u>FRAMING NOT VERIFIED</u>
<u>1-19-95</u>	<u>10:25</u>	<u>DKP</u>	<u>FRAMING VERIFIED, DRYWALL COMPLETE</u>
			<u>NOTE:</u>
			<u>OCCUPANCY IS CONTINGENT ON COMPLETION</u>
			<u>OF FRAMING BELOW TO GROUND FLOOR/</u>
			<u>1ST FLOOR LEVEL <u>(DKP)</u></u>

REPAIR INSPECTION
JAN 19 1995

Repair Completion Date: 1 / 19 / 95 By: DKP

Final Sign Off: DKP 1-19-95 [Signature] 1-19-95 [Signature] 1-19-95
P&G WJE City of Portland

WJE 942566
WJE 1416

JAN 19 1995

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 2041 Building Room Number: 220

Repair Designation/Description: TASKS ITEMS

Engineering Sketches / Calculations Reference: _____

Contractor: C.M. CIMINO

INSPECTION RECORD

Repair Start Date: 12 / 9 / 94 By: RBJ

Intermediate Inspections:

Date	Time	By	Comment/Photos
<u>12/9/94</u>		<u>RBJ</u>	<u>Small Holes in Ceiling Patched</u>
<u>12/19/94</u>		<u>MWC</u>	<u>Small Holes in Wall Patched. Do some pipe penetrations need to be caulked. Suspended ceiling supply wire not attached.</u>
<u>1-9-95</u>	<u>8:20</u>	<u>DLP</u>	<u>DUCT INTO CHASE NEEDS FIRESTOP.</u>
<u>1-19-95</u>	<u>10:30</u>	<u>DLP</u>	<u>PATCH COMPLETE</u>
NOTE:			NOTE: FINAL SIGN OFF IS CONTINGENT
<u>OCCUPANCY IS CONTINGENT</u>			<u>UPON REPLACING SHIRT WALL</u>
<u>ON COMPLETION OF FRAMING</u>			<u>WITH WOOD OR STEEL STUD BRG.</u>
<u>BELOW TO GROUND FLOOR /</u>			<u>WALL FOLLOWING CLOSE OF SCHOOL</u>
<u>1ST FLOOR LEVEL <u>(DLP)</u></u>			<u>IN 6-95 <u>(DLP)</u></u>

Repair Completion Date: 1 / 19 / 95 By: DLP

Final Sign Off: DLP 1-19-95 P&G _____ WJE _____ City of Portland
(Signature) 1-19-95 (Signature) 1-19-95

WJE 942566
WJE 1414
JAN 19 1995
RECEIVED

REPAIR INSPECTION FORM JAN 19 1995

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 2
Room Number on Plan: _____ Building Room Number: Stammell across
Repair Designation/Description: from room 222

Engineering Sketches / Calculations Reference: _____

Contractor: _____

INSPECTION RECORD

Repair Start Date: 1/18/95 By: A. Rowe

Intermediate Inspections:

Date	Time	By	Comment/Photos
1/18/95	9:20 AM	AR/MC	slat rock to be used to support bottom of piece - sprinkler head below ceiling
1/18/95	10:40 AM	AR	work continues
1/18/95	11:10 AM	AR/MC	sprinkler head has been dropped correctly - slat rock work continues
1/18/95	12:30	KC	TAPING JOINTS
1-18-95	2:30	DJ	Taping in progress 1st coat / new Fire Sprinkler head installed in ceiling
1/19/95	9:45 AM	AR	Looks done

Repair Completion Date: _____ By: _____

Final Sign Off: DKP 1-19-95 [Signature] 1-19-95 [Signature] 1-19-95
City of Portland

WJE 942566
WJE 1414

JAN 19 1995
RECEIVED

DEPT. OF BUILDING INSPECTION
PORTLAND, ME

JAN 19 1995

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 2 of 2

Room Number on Plan: 2463 Building Room Number: STORAGE

Repair Designation/Description: GNB ENCLOSURE REPAIR @ BACK
OF STAIRS

Engineering Sketches / Calculations Reference: _____

Contractor: CAC/DIRIGO

INSPECTION RECORD

Repair Start Date: 1 / 17 / 95 By: DKP

Intermediate Inspections:

Date	Time	By	Comment/Photos
1-17-95	PM	DKP	TRACKS INSTALLED, QUESTIONED FASTENERS

JAN 19 1995

Repair Completion Date: 1 / 19 / 95 By: DKP

Final Sign Off: DKP 1-19-95 / [Signature] 1-19-95 / [Signature] 1-19-95
P&G WJE City of Portland

WJE 942566
WJE 1416

DEPT. OF BUILDING INSPECTION
CITY OF PORTLAND, ME

JAN 19 1995

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 3019 Building Room Number: DARK ROOM

Repair Designation/Description: WALL & CEILING PENETRATIONS

Engineering Sketches / Calculations Reference: _____

Contractor: C. M. CIMINO

INSPECTION RECORD

Repair Start Date: 12 / 8 / 94 By: MWC

Intermediate Inspections:

Date	Time	By	Comment/Photos
<u>12/8/94</u>	<u>unknown</u>	<u>MWC</u>	<u>SMALL HOLES PATCHED</u>
<u>12/12/94</u>	<u>unknown</u>	<u>MWC</u>	<u>GWO PATCHING OF WALL OPENING</u>
<u>12/13/94</u>	<u>unknown</u>	<u>MWC</u>	<u>SIG LIGHT NOT REINFORCE OR FIRE RATED</u>
<u>1-19-95</u>	<u>11:35</u>	<u>DKP</u>	<u>EXH. REPAIR ALMOST COMPLETE</u>

INSPECTION
CITY OF PORTLAND, ME

JAN 19 1995

Repair Completion Date: 1 / 19 / 95 By: DKP

Final Sign Off: DKP 1-19-95 / [Signature] 1-19-95 / [Signature] 1-19-95
P&G WJE City of Portland

WJE 942566
WJE 1412

DEPT. OF BUILDING INSPECTION
PORTLAND, ME

JAN 19 1995

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 3020/3022 Building Room Number: TEACHER'S WORK RM

Repair Designation/Description: PATCH CEILING AND WALL PENETRATIONS
TABS 1-2

Engineering Sketches / Calculations Reference: _____

Contractor: C. M. CIMINO

INSPECTION RECORD

Repair Start Date: 12 / 9 / 94 By: MWC

Intermediate Inspections:

Date	Time	By	Comment/Photos
<u>12/9/94</u>	<u>unkn</u>	<u>MWC</u>	<u>CEILING HOLES PATCHED COMPLETE</u> <u>GWB PATCH OF WALLS IN PROGRESS</u>
<u>12/12/94</u>	<u>unkn</u>	<u>MWC</u>	<u>GWB PATCHING COMPLETE NEED TO</u> <u>FIRE COLLAR CASE RE-INSTALL</u>

BUILDING INSPECTION
PORTLAND, ME

JAN 19 1995

EC

Repair Completion Date: _____ By: _____

Final Sign off: 1-19-95 DWP J. [Signature] 1-19-95 [Signature] 1-19-95
P&G WJE City of Portland

WJE 942566
WJE 1414

DEPT. OF BUILDING INSPECTION
CITY OF PORTLAND, ME

JAN 19 1995

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 3029 Building Room Number: LIBRARY

Repair Designation/Description: NO WORK REQUIRED,
3 CONDITIONS INVESTIGATED

Engineering Sketches / Calculations Reference: _____

Contractor: _____

INSPECTION RECORD

Repair Start Date: _____ / _____ / _____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos

DEPT. OF BUILDING INSPECTION
PORTLAND, ME

JAN 19 1995

Repair Completion Date: _____ By: _____

Final Sign Off: DKP 1-19-95 [Signature] 1-19-95 [Signature]
P&G WJE City of Portland

WJE 942566
WJE 1/1/85

DEPT. OF BUILDING INSPECTION
CITY OF PORTLAND, ME

JAN 19 1995

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 3030 Building Room Number: 322

Repair Designation/Description: CEILING AND WALL PENETRATIONS

Engineering Sketches / Calculations Reference: _____

Contractor: C. McCIMINGO

INSPECTION RECORD

Repair Start Date: 12 / 13 / 94 By: MWC

Intermediate Inspections:

Date	Time	By	Comment/Photos
<u>12/13/94</u>	<u>4:25</u>	<u>MWC</u>	<u>WALL PATCHED GWO, CEILING HOLES PATCHED.</u>

DEPT. OF BUILDING INSPECTION
CITY OF PORTLAND, ME

JAN 19 1995

WJE

Repair Completion Date: 1 / 19 / 95 By: _____

Final Sign Off: dup 1-19-95 P&G, [Signature] WJE, [Signature] City of Portland

WJE 942566
WJE/KIA

REPAIR INSPECTION FORM

JAN 19 1995

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 3032 Building Room Number: 323

Repair Designation/Description: CEILING AND WALL PENETRATION

Engineering Sketches / Calculations Reference: _____

Contractor: C. McCUMMAD

INSPECTION RECORD

Repair Start Date: 12 / 13 / 94 By: MWC

Intermediate Inspections:

Date	Time	By	Comment/Photos
<u>12/13/94</u>	<u>unkn</u>	<u>MWC</u>	<u>Holes in walls patched w/ GUMB water in ceiling patched</u>

T. OF BUILDING INSPECTOR
OF PORTLAND, ME

JAN 19 1995

Repair Completion Date: _____ By: _____

Final Sign Off: WJE 1-19-95 / P&G 1-19-95 P&G 1-19-95
P&G WJE City of Portland

WJE 942566
WJE 1916

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 2009 Building Room Number: _____

Repair Designation/Description: NO WORK REQUIRED

Engineering Sketches / Calculations Reference: _____

Contractor: _____

INSPECTION RECORD

Repair Start Date: _____ / _____ / _____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos

DEPT. OF BUILDING INSPECTION
CITY OF PORTLAND, OREGON
JAN 23 1995

Repair Completion Date: _____ By: _____

Final Sign Off: DVP 1-20-95 / [Signature] 1-20-95 / [Signature]
P&G WJE City of Portland

WJE 942566
WJE 1410

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 2008 Building Room Number: _____

Repair Designation/Description: NO WORK REQUIRED

Engineering Sketches / Calculations Reference: _____

Contractor: _____

INSPECTION RECORD

Repair Start Date: _____ / _____ / _____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos

DEPT OF BUILDINGS INSPECTION
CITY OF PORTLAND, ME
JAN 23 1995

Repair Completion Date: _____ / _____ / _____ By: _____

Final Sign Off: WJE 1-20-95 / [Signature] 1-20-95 / [Signature] 1-20-95
P&G WJE City of Portland

WJE 942566
WJE 1416

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G | WJE Sheet 1 of 1

Room Number on Plan: 2007 Building Room Number: _____

Repair Designation/Description: TASKS 1-2 WALL PENETRATION

Engineering Sketches / Calculations Reference: _____

Contractor: _____

INSPECTION RECORD

Repair Start Date: ____/____/____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos

DEPT OF BUILDINGS INSPECTION
CITY OF PORTLAND, ME
JAN 23 1995

Repair Completion Date: 1 / 20 / 95 By: RBJ

Final Sign Off: 1-20-95 OLP / J. Brown 1-20-95 City of Portland

WJE 942566
WJE 1410

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 2006 Building Room Number: _____

Repair Designation/Description: NO WORK REQUIRED

Engineering Sketches / Calculations Reference: _____

Contractor: _____

INSPECTION RECORD

Repair Start Date: _____ / _____ / _____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos

DEPT. OF BUILDINGS INSPECTION
CITY OF PORTLAND, ME.
JAN 23 1995

Repair Completion Date: _____ By: _____

Final Sign off: P&G 1-20-95 / WJE 1-20-95 / City of Portland 1-20-95

WJE 942566
WJE 1416

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G WJE _____ Sheet 1 of 1

Room Number on Plan: 2005 Building Room Number: 203

Repair Designation/Description: VARIES - W3, W4, W7 TASKS 1-3

Engineering Sketches / Calculations Reference: _____

Contractor: _____

INSPECTION RECORD

Repair Start Date: 12 / 29 / 94 By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos
<u>12/29/94</u>	<u>1:15</u>	<u>MWC</u>	<u>STARTING FULL DEPTH MASONRY INFILL AT OPENING IN WEST CLASSROOM WALL</u>
<u>1/20/95</u>	<u>3:00</u>	<u>DVP</u>	<u>LOOSE TILE REMOVED</u>

DEFECT BUILDERS ASSOCIATION
 CITY OF PORTLAND, ME
 JAN 23 1995

Repair Completion Date: 1/20/95 By: DVP

Final Sign Off: DVP 1-20-95 WJE 1-20-95 [Signature] 1-20-95
 P&G WJE City of Portland

WJE 942566
 WJE 1/1/94

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 2116 Building Room Number: STORAGE

Repair Designation/Description: NO VISIBLE DEFECTS

Engineering Sketches / Calculations Reference: _____

Contractor: _____

INSPECTION RECORD

Repair Start Date: _____ / _____ / _____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos

DET. OF BUILDING INSPECTIONS
JAN 23 1995

Repair Completion Date: _____ By: _____

Final Sign Off: okp 1-20-95 / [Signature] 1-20-95 / [Signature] 1-20-95
P&G WJE City of Portland

WJE 942566
WJE 1416

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 2001 Building Room Number: 205

Repair Designation/Description: WALL PENETRATIONS TASKS 1, 2, 3

Engineering Sketches / Calculations Reference: S/WI, W4, W2

Contractor: C. M. CIMINO

INSPECTION RECORD

Repair Start Date: 12 / 30 / 74 By: RBJ

Intermediate Inspections:

Date	Time	By	Comment/Photos
12/30/74	0725	RBJ	TASKS 2/3 complete Removing BRICK FR- TASK 1
	0830	RBJ	STARTED BRICKING @ SIDE of FIRE DAMPER @ 400' DIA
	0940	RBJ	Lintel's Installed Work complete TASK 1

DEPT OF BUILDINGS INSPECTION
 CITY OF PORTLAND, ME
 JAN 23 1995
 R. E. ...

Repair Completion Date: 12 / 31 / 74 By: RBJ

Final Sign Off: DVP 1-20-75 P&G [Signature] WJE [Signature] City of Portland 1-20-75

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 2108 Building Room Number: STORAGE

Repair Designation/Description: DUCT OPENING THROUGH ARCH
TASK 1 ; WALL PENETRATION TASK 2

Engineering Sketches / Calculations Reference: W2

Contractor: C. M. CIMINO ; KIS

INSPECTION RECORD

Repair Start Date: _____ / _____ / _____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos
<u>1-20-95</u>	<u>1:45</u>	<u>DLP</u>	<u>FIRESTOP COMPLETE</u>

DEPT OF BUILDING INSPECTION
CITY OF PORTLAND, ME
JAN 23 1995

Repair Completion Date: 1 / 20 / 95 By: DLP

Final Sign Off: DLP 1-20-95 / [Signature] 1-20-95 / [Signature] 1-20-95
P&G WJE City of Portland

WJE 942566
WJE/MLG

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 2109 Building Room Number: OFFICE

Repair Designation/Description: SOFFIT, HOLE TILE AND CEILING

Engineering Sketches / Calculations Reference: _____

Contractor: CMC

INSPECTION RECORD

Repair Start Date: 1 / 20 / 95 By: DLP

Intermediate Inspections:

Date	Time	By	Comment/Photos
<u>1-20-95</u>	<u>2:00</u>	<u>DLP</u>	<u>FIRESTOP COMPLETE</u>

REPAIR INSPECTION
JAN 23 1995

Repair Completion Date: 1 / 20 / 95 By: _____

Final Sign Off: DLP 1-20-95 [Signature] 1-20-95 [Signature] 1-20-95
P&G WJE City of Portland

WJE 942566
WJE 1410

REPAIR INSPECTION FORM

Portland High School Repair Project

Project Team Member: P&G _____ WJE _____ Sheet 1 of 1

Room Number on Plan: 2110 Building Room Number: OFFICE

Repair Designation/Description: NO WORK REQUIRED

Engineering Sketches / Calculations Reference: _____

Contractor: _____

INSPECTION RECORD

Repair Start Date: _____ / _____ / _____ By: _____

Intermediate Inspections:

Date	Time	By	Comment/Photos

REPAIR INSPECTION
CITY OF PORTLAND
JAN 20 1995

Repair Completion Date: _____ By: _____

Final Sign Off: P&G 1-20-95 WJE 1-20-95 City of Portland 1-20-95

WJE 6-2566
WJE 1410