

Res 88 Allen Avenue

April 5, 1972

Mrs. Ethel Brown, 88 Allen Avo.

Door Mrs. Browns

Sometime ago a demolition permit was applied for to demolish existing frame barn on your property at 88 Allen Avenue.

Our inspector reports he has inspected the property several times but is confused about the building to be demolished.

Would you please call Mr. Irving at this office that we may determine if it is the garage barn that exists or is it another building that has been removed.

Very truly yours,

R. Lovell Brown Director

HI/c

æ

104-166 Blu ford

CITY OF PORTLAND, MAINE DEPARTMENT OF BUILDING INSPECTION

Mrs. Ethel Brown 88 Allen Avenue

Sept. 24, 1971

With relation to permit applied for to demolish a building or it is unlawful portion of building at 88 Allen (barn) to commence demolition work until a permit has been issued from this department.

Section 6 of the Ordinance for rodent and vermin control provides: "It shall be unlawful to demolish any building or structure unless provision is made for rodent and vermin eradication. No permit for the demolition of a building or structure shall be issued by the Building Inspection Department until and unless provisions for rodent and vermin eradication have been carried out under supervision of a pest control operator registered with the Health Department.

The building permit for demolition cannot be issued until the provisions of this section have been satisfied. It is the obligation of owner or demolition contractor or both to take up with the Health Department the matter of complying with this section, being prepared to inform that department what registered pest control operator is to be employed.

Very truly yours,

R. Lovell Brown Director

Eradication of this building has been completed.

Contractor:

Robert Landry

Wells, Maine

Sent to Health Dept / 24/7/ Reo'd from Houlth Dopt, 9/28/74

9-27-81 NO EVINENCE OF ROBENT ACTIVITY AT TIME OF INSPECTION
Bu Keen

CITY OF PORTLAND, MAINE DEPARTMENT OF BUILDING INSPECTION

Mrs. Ethel Brown 88 Allen Avenue

August 20,1971

With relation to permit applied for to demolish a building or portion of building at 88 Allen Avenue (barn) it is unlawfu to commence demolition work until a permit has been issued from this department. it is unlawful

Section 6 of the Ordinance for rodent and vermin control provides: "It shall be unlawful to demolish any building or structure unless provision is made for rodent and vermin eradication. No permit for the demolition of a building or structure shall be issued by the Building Inspection Department until and unless provisions for rodent and vermin eradication have been carried out under subervision of a pest control operator registered with the Health Department.

The building permit for demolition cannot be issued until the provisions of this section have been satisfied. It is the obligation of owner or demolition contractor or both to take up with the Health Department the matter of complying with this section, being prepared bepartment the matter of complying with this section, being prepared to inform that department what registered pest control operator is to be employed.

Very truly yours,

R. Lovell Brown

Eradication of this building has been completed.

A Josell Brown

Contractor:

Robert Landry

Wells, Maine

August 23, 1970

Ins ection this date revealed VES rodent activity.

Units: When Signs, Regulars balturg.

Remy Red



APPLICATION FOR PERMIT

Clus of Building or Type of Structure

PERMIT ISSUED SEP 30 1971

To the INSPECTOR OF BUILDINGS,	Mand, Maine, August 20, 1971	PTTV (178
The west of the second	FORTLAND, MAINE	Total de la company de la comp
in accordance with the Laws of the State of a specifications, if any, submitted herewith and Location 88 Allen Avs . rear	PORTLAND, MAINE permit to erect alter repair demolish install t. Maine, the Building Code and Zoning Ordi	ne following building structure equipment
Location 88 Allen Arm	specifications:	ony of Fortiand, plans and
Location 88 Allen Ave . rear Owner's name and address Ethe Lessee's name and address Contractor's name and address	Nithin Fire I	imits? Diet No
Lessee's name and address	down, oo Allen Ave.	Telephone 1.6/1 -1.1/17
Architect Proposed use of building Last use barn Material	Specifications Pla	ns N
Last use barn Material No. stories Other buildings on some let		No. 6 - ::
Material No. stories Other buildings on same lot	HeatStyle of roof	Post-
Other buildings on same lot		
Gen	eral Description of New Work	Fee \$_5.00
To demolish existing frame barn		
To leave the land vacant		
		/-
		Ser.i to Hacith Dopt. 9/24/7
		Ser.l to Heclih Dept 9/28/
		Roa'd from Health Dept.
		X/ .// F
It is and about it is a	Sent	
It is und Astood that this permit does not include the name of the heating antractor. PERMIT	e installation of heating abband	fr.m Health Dant 8 23/7/
the name of the heating nkractor. PERMIT	TO BE ISSUED TO OWNER	to be taken out separately by and in
Is any plumbing involved in this work?	Details of New Work	
Sconnection to be made to public sewer?	If not sub-	ed in this work?
Is connection to be made to public sewer? Has septic tank notice been sent? Height average grade to top of plate Size, front	Form Form	sewage?
rieight average grade to top of plate	Height	
Height average grade to top of plate	ories and treight average grade to highest	point of roof
Material of foundation	Thickness (see Solid or filled land?	earth or rock?
No. of chimneys	Roof covering	
Framing Lumber-Kind Dressed or	full stand	of heat
Framing Lumber—Kind	Corner posts	Sille
Size Girder Columns under gir Studs (outside walls and carrying partitions) 2xe Joists and rafters: 1st floor	Gers Size	Max. on centers
Joists and rafters:	-16" O. C. Bridging in every floor and fl	at roof span over 8 fact
On centers:	, 2nd , 3rd , 3rd , 3rd	roof
one story building with mass was a state of the story building with mass was a state of the story building with mass was a state of the story building with mass was a state of the story building with mass was a state of the story building with mass was a state of the story building with mass was a state of the story building with mass was a state of the story building with mass was a state of the story building with mass was a state of the story building with mass was a state of the story building with mass was a state of the story building with mass was a state of the story building with mass was a state of the story building with mass was a state of the story building with mass was a state of the	, 2nd, 3rd, 3rd	, rooi
Tone story building with mascary walls, thickne	ss of walls?	hat 1.2
No. com	II a Garage	neight?
Will and accommodated on same lot to l		
No. cars now accommodated on same lot, to l Will automobile repairing be done other than mind	or repairs to some half to a	cars to be accommodated
	cars nabitually stored in the	proposed building?
0.16. E.S.S. 9/28/7/	i Wiscellane	:One
- 1/28/7/	Will work require disturbing of any tr	00.00.00.00.00.00
	Will there be in charge of the at-	e on a public street?
and the second s	Will there be in charge of the above see that the State and City require	work a person competent to
	see that the State and City require observed? yes	ments pertaining thereto are
C.C. C.C.	Strol Dans	

INSPECTION COPY

Signature of owner By: Etho S. From

Owner Child Date of permit Notif. closing-in Inspn. closing-in Final Nctif. Cert. of Occupancy issued Final Inspn. Form Check Nonce NOTES g

CITY OF PORTLAND DEPARTMENT OF PUBLIC WORKS DEMOLITION OF BUILDINGS

A building will be demolished at # 88 Allen Avenue

Street on August 30, 1971

The Contractor is Robert Landry, Wells, Maine

8/30/71 The Contractor and the hower division have been notified of sealing the house drain before the building can be demolished.

DEPARTMENT OF PUBLIC WORKS

PHILIP MULLIN

- --

j.

i

l

ſ

ч



APPLICATION FOR PERMIT

PERMIT ISSUED JUL 10(1882)

Third Class Class of Building or Type of Structure.

PORTLAND, MAINE, July 1, 1960

To the INSPECTOR OF BUILDINGS, Portland, Me.

The undersign, wereby applies for a permit to repair or renew roof covering of the following described building in accordance with the last of Maine, the Building Code of the City of Portland, and the following specifications:

Location 88 Allen Ave. Owner's name and address George C Brown, 88 Allen Ave. Contractor's name and address_owner Use of building Present Dwolling Plo. of Stories 12 Style of roof pitch 'Type of present roof covering. As that t Type and Grade of roofing to be used Asphalt Class C Und. Lab.

GENERAL DESCRIPTION OF NEW WORK

To cover portion of roof.

Signature of Owner by: Heavy C Brown
The S. Brown

INSPECTION COPY

FILL IN ANY SIGN WITH INK 3 1 1931

PERMIT ISSUEL

APPLICATION FOR PERMIT FOR
HEATING, COOKING OR POWER EQUIPMENT

TITY of PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, ME. The undersigned hereby applies for a per uit to install the following caring, cooking or power equipment in accord-Location 88 Allen Ave. Use of Building 1-family dwelling .. No. Stories Name and address of owner of appliance ... George G. Brown, 88 Allen Ave. Installer's name and address Randall & McAllister, 84 Commercial St. Telephone ...3-2941 General Description of Work To install ... oil burning equipment in connection with existing forced hot water heating system (conversion) IF HEATER, OR POWER BOILER Any burnable material in floor surface or beneath? Minimum distance to hurnable material, from top of appliance or casing top of furnace From top of smoke pipeFrom front of appliance From sides or back of appliance Size of chimney flue Other connections to same flue Will sufficient fresh air be supplied to the appliance to insure proper and safe combustion? IF OIL BURNER Will operator be always in attendance?...... Does oil supply line feed from top or bottom of tank? ...hot.tom...... Type of floor beneath burnerconcrets Size of vent pipe Location of oil storage ______basement _____ Number and capacity of tanks ____1-275_gal.____ Will all tanks be more than five feet from any flame? How many tanks enclosed? Total capacity of any existing storage tanks for futnace burners . none...... . IF COOKING APPLIANCE Skirting at bottom of appliance? Distance to combustible material from top of appliance? From front of appliance From sides and back From top of smokepipe Is hoon to be provided? If so, how vented? Forced or gravity? MISCELLANEOUS EQUIPMENT OR SPECIAL INFORMATION Amount of fee enclosed? ... 2.00 for one heater, etc., 50 cents additional for each additional heater, etc., in same building at same time.) Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? ..yes Randall & M6Allister

INSPECTION COPY

Signature of Installerby

C17-254-131 MARKS

5

**



Class of Building or Type of Structure Trans Glass

The state of the s	STREET, 20 1924
To the INS TOTOR OF BUILDINGS, PORTLAND, ME.	Portland, Maine, September 23, 1954
The undersigned hereby applies for a permit to erect uccordance with the Lawrence of the second and the second area.	+alter instati the following building assessment
any, submitted herewith and the following specifications:	d 9 Within Fire Limits 100 Within Fire Limits 100 Within Fire Limits 100 Telephone Telephone
War	d Within Fire Limits ,130 Dist. No.
Owner sor bessee's name and address Trank 7. Robert	St. 122 Cummercial St. Telephone
that actual control	
i de supplication:	No. of sheets
	D in th
Description of Present	Building to be Altered
Marchai M	,
General Descript	on of New Work
To rebuild rear chimney knowstratesburgers	
	-51C4
	CETTATICITE OF OCCUPANCE
	CERTIFICATION IN
•	History.
It is understood that this permit does not include installation of heating the heating contractor.	Apparatus urbion is all toward
Details of I	Vary Worls
	T+
Size, frontdepthNo, stories	
	armatic
Material of underpinning He Kind of Roof Pico dea factors	ightThickness
TVISC DEC 1007	ant manager
No. of chinneys 2 Material of chinneys Kind of heat	inrick of lining 1118
Type	
Cart or ledger boar	· · · · · · · · · · · · · · · · · · ·
span over 8 rect. Sills and covers partitions) 2x4-16" O. C. (Max. on centers Girders 6x8 or larger. Bridging in every floor and flat roof section.
Joists and rafters: 1st floor	section.
, wild	3rdranf
Maximum span: lst floor	, 3rd, roof
If one story building with processes and	, 3rd, roof
walls?	- Indiate 2
No. cars now accompage and an accompage to the control of the cont	age
No. cars now accommod ted on same lot Total number commercial cars to be accommodated	, to be accommodated
, and the recommunity of the rec	7
oc done other man minor repairs to c	ars habitually stored in the proposed building?
wiscenar	leous
Will above work require removal or disturbing of any shade tree Will there be in charge of the above work a pairse removal.	on a public street? no
and above was a person competent to	see that the State and City requirements pertaining thereto
Fr.	nk F. Roberts
INSPECTION COPY Signature of owner By	- AB

Patrons Co-operative Corporation, Wholesale Grocers.

Dealers in Flour, Grain and Provisions 122-124 Commercial St.

Warren Mc Bonald, Building Inspector, Portland, Maine.

Weer Sir:-

I take great pleasure in writing you that a mason will immediately, at 88 Alleu Avenue, Portland, Maine, extend the chimney down as requested by you.

Thank you very kindly for calling my attention to the dangerous ecndition of the present temporary arrangement which I hoped would be satisfactory until Spring.

yrw/ffr

29/2037 R-1/28/30-Rm pecember 26, 1929 Mr. Frank F. Roberts Brices Straet Wasterook, Maine In Docember 13th, we wrote you conserming the condition Dear Shr: of the smoke pipe and chisney in the building which you are reported to own at RA aller and chisney in the building which you are reported to own at 88 Allen Avenue, relating in part as follows: "It is necessary that you extend your chimey flue downwards to a good foundation at or about the cellar floor level, providing at the bettom of the flue a cast iron cleanout door and frame, and thus give the heating comments and account the connect the smoke thus give the heating co-racter an opportunity to connect the smoke pipe through the verifical state of the change which is the usual pipe through the vertical side of the chimney which is the usual The condition referred to above is considered unrafe, and practice," you have not only not paid any attention to our roquest above referred to, but have indicated that you do not plan to do anything about it, at least for the present. You are bereby directed to have this condition corrected ined shows on an artistic and the condense of the con You are hereby directed to have this condition corrected as outlined above on or before January 27, 1930. This order to given as authorized and directed by section 28 and mostions being Chapter 30. Revised Statutes of Maine, hopy of these sections being attached beratu. attached beratu. very truly yourse Inspictor of Bulldings. TH/EC

December 13, 1929 29/2037 ar. Frank F. Roberts Bridge Street restbrook, Mains upon examination of the warm air furnace which the upon examination of the warm air furnace which the portland Stove moundry is installing in your building at the Alien Avonue, we find that the smoke pipe from the these has been connected to the entency by means of entering the has been connected to the entency by means of entering the Dear Siri do allen Avoine, se tain the the smoke pape from the first the has been connected to the chimney by means of entering the has been connected to the chimney by means or entering the bottom or the chimney rive through the arch which apparently This is not considered a safe and adequate muthod as This is not considered a safe and adequate muthod as the cleaned of the chimney is not in the chimney itself, but the cleaned of the chimney is not in the scot that is cleaned in the scoke page, and naturally enter the scoke page first out of the chimney must naturally enter the scoke page. supports the chimney. It is necessary that you extend your chimney flus downwards to a good foundation at or about the cellar ricer aleand level. Providing at the bottom of the heating contractor and thus give the heating contractor and thus give the heating contractor. level. providing at the bottom of the fine a cast from olean-out door and frame, and thus give the heating contractor, and opportunity to connect the smoke pipe through the vertical opportunity to connect the smoke pipe through the vertical side of the chimney which is the usual practice. please have this work done without delay, and notify this office when the same has been completed so, that another increasion may be made. inspection may be made. Aona tenta acons Inspector of Amildings. Kaynu CC- Portlerd Stove T andry Company

FILL IN COMPLETELY AND SIGN WITH THE Permit No.... LICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIPMENT Portland, Maine,

Portland, Maine,

Portland, Maine,

Portland, Me.

To the INSPECTOR OF BUILDINGS, Portland, Me.

The undersigned hereby applies for a permit to install the following heating, cooking or The undersigned hereby applies for a permit to install the following code of the City of Portland, power equipment in accordance with the laws of Maine, the Building Code of the City of Portland, and the following specifications: Use of Building Wweller Location 88 allesso Name and address of owner Frank Jr Roberts Telephone 34 Portlang Stre Jidy Go General Description of Work Contractor's name and address... Kann IF HEATER, POWER BOILER OR COOKING DEVICE To install. Is heater or source of hear to be in cellar? _______ If not, which story ______ Kind of Fuel. Material of supports of heater or equipment (concrete floor or what kind)..... Minimum distance to wood or combustible material; from top of boiler or casing top of furnace, __/5_" from top of smokepipe from from from tof heater from sides or back of heater. Approved by Underwriters' Laboratories? Name and type of burner. TO LIM to one lessen was an end a finite state. in while Littling it was the



APPLICATION FOR PERMIT Class of Building or Type of Structure____ Portland, Maine, December 6, 1929 To the INSPECTOR OF BUILDINGS, PORTLAND, ME. The undersignd hereby applies for a permit to erect after install the following wilkling structure equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications: Location .. 88 Allen Avenue. Ward 91 Within Fire Limits? no Dist. No. ____ Owner's for lesser's name and address Frank F. Roberts Bridge St, Westbrook, Ma Telephone Contractor's name and address Portland Stove Foundry Ca. 39 Kennedge St. Telephone F 6500 Architect's name and address_____ Proposed use of building dwolling house Other buildings on same lot... Description of Present Building to be Altered No. stories _____Heat _____Style of roof _____Roofing_ General Description of New Work To install Warm Lir Furnace Details of New Work depth _____No. stories ____ Height average grade to highest point of roof_ To be erected on solid or filled land? _____earth or rock? Material of foundation _______ Thickness,, top_______bottom_____ Material of underpinning _____ Height ____ Thickness ____ _____Roof covering _____ Kind of roof _____ ____of lining _____ Kind of heat _______ Type of fuel ______ Distance, heater to chimney______ If oil burner, name and model Capacity and location of oil tanks______ Is gas fitting involved?______Size of service_____ Corner posts Sills Girt or ledger board? Size Material colunns under girders______Size_____Max. on centers _____ Studs (outside walls and carrying partitions) 2x4-16" O.C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section. 1st floor ______, 2nd ______, 3id ______, roof _____ Joists and rafters: 1st floor ______, 2nd ______, 3rd ______, roof ____ On centers: 1st floor _______, 2nd _______, 3rd _______, roof ______ Maximum span: If one story building with masonry walls, thickness of walls? ______ height? _____ If a Garage No. cars now accommodated on same lot ______, to be accommodated _____ Total number commercial cars to be accommodated_____ Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? Miscellaneous Fee \$ 1.00 Estimated cost \$____ Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed?____yos

INSPECTION COPY

Signature of owner.....

Final Notif. al Inspn. f. permit closing-in of Occupancy issued
NOTES /3/30 1/23/30 4:10 EM not get in a constant of the land of the l of all to



APPLICATION FOR PERMIT

DEPARTMENT OF BUILDING INSPECTIONS SERVICES ELECTRICAL INSTALLATIONS

CODE

Date Sept. 3, 1986 Receipt and Permit number <u>D24503</u>

To the CHIEF ELECTRICAL INSPECTOR, Portland, In The undersigned hereby applies for a permit to make	e electrical installations in accordance with the	he laws of
1 D- 1 - Planting Clastrical (Irdinance Inc National	Migriffical Code and the Johnson J.	
LOCATION OF WORK: 88 Allen Ave.		
LOCATION OF WORK: 88 Allen Ave. OWNER'S NAME: Ethel Brown	ADDF.ESS: same	FEES
OUTLETS:	ld ft. TOTAL	
* 1 Flourescent (not	strip) TOTAL	
Strip Flourescent ft		
Overhoud v Underground Tempo	orary TOTAL amperes 200	1.00_
METERS: (number of) 2		
MOTORS: (number of) Fractional		
1 HP o. over		
Oil on Con (number of units)		
Electric (number of rooms)		
CONTROL OF INDUSTRIAL HEATING.		
Oil - Cas (he a main vilor)		
O'l C- (he conorate units)		
Electric Under 20 kws Over 20 kw	'S	
APPLIANCES: (rumber of)	Water Heaters	
Ranges	Disposals	
Cook Tops Wail Ovens	Dishwashers	
	Compactors	
Mana .	Others (denote)	
TOTAL		
Deep b Panais		
Was aformers		
Air Conditioners Central Unit	•••••	
Separate Units (windows)		
Signs 20 sq. ft. and under	****	
Over 20 sq. ft. Swimming Pools Above Ground	****	
You Channel		
Fire/Bi.rglar Aiarnis Residential		
Commercial		
Heavy Duty Outlets, 220 Volt (such as welder	s) 30 amps and under	
	over 30 amps	
Circus, Fairs, etc.		
Alterations to wires		
Repairs after fire		
Emergency Lights, battery		
_	INSTALLATION FEE DUE:	
FOR ADDITIONAL WORK NOT ON ORIGINAL PH	ERMIT DOUBLE FEE DUE	
FOR REMOVAL OF A "STOP ORDER" (304-16.b)	TOTAL AMOUNT DUE:	5.00
	* *	
INSPECTION:		
Will be ready on, 19;	or Will Call	
CONTRACTOR'S NAME: R. D. Electric		
ADDRESS: 94 Allen Ave., P	ortland, Me. 04103	
TEL.: 797-6195	- Carlos Carlos Carlos Carlos	
MASTER LICENSE NO.: 2812	-/(`\begin{align*} \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
LIMITED LICENSE NO.:	- 1000	

INSPECTOR'S COPY — WHITE
OFFICE COPY — CANARY
CONTRACTOR'S COPY — GREEN

EvaPECTIONS:	Service called in To C. M.P 4:00 PM 9/8/80 Ins
PROGRESS INS	Closing-in by Spection Register Page No.
	ALLATIONS—
DATE: 9/8/80	Service Completed.



APPLICATION FOR PERMIT CEPARTMENT OF BUILDING INSPECTIONS SERVICES ELECTRICAL INSTALLATIONS

	Date <u>Aug 29</u> , 19 8 Receipt and Permit number D2448	<u>3</u> 6 38	
To the CHIEF ELECTRICAL INSPECTOR, Portland, Maine: The undersigned hereby applies for a permit to make electrical installations in accordance with the laws of Maine, the Portland Electrical Ordinance, the National Electrical Code and the following specifications:			
TOCATION OF WORK: 88 Allen Avenue		_	
OWNER'S NAME: Ethel S Brown	ADDRESS: <u>lives there</u> FEES	-	
OUTLETS: Receptacles Switches Plugmold	ft. TOTAL <u>1-30</u> 3.00	_	
FIXTURES: (number of) Incandescent X Flourescent X (not	strip) TOTAL <u>1-10</u>		
Strip Flourescent ft		_	
Overhead Underground Tempor	ary TOTAL amperes 50	-	
METERS: (number of) 1			
Fractional			
THE PROPERTY AND A STATE OF THE PARTY OF THE		_	
RESIDENTIAL HEATING:			
Oil or Gas (number of units)	3,00	_	
COMMEDCIAL OF INDISTRIAL HEATING.			
Oil on Con (by a regin boiler)		_	
Oil or Gas (by separate units)			
Electric Under 20 kws Over 20 kws			
APPLIANCES: (number of)	1		
1941,500	Water Heaters 1		
Otoh rops	Disposals		
Wall Overing	Dishwashers		
21,010	Compactors		
Fans	Others (denote) 3.00		
TOTAL		-	
MISCELLANEOUS: (number of) Branch Panels1	<u> 1,00</u>		
Transformers			
Air Conditioners Central Unit			
Separate Units (windows)			
Signs 20 .q. ft. and under			
Over 20 sq. ft.			
Swimming Pools Above Ground			
In Ground			
Fire/Burglar Alarms Residential			
Commercial		<u>.</u>	
Heavy Duty Outlets, 220 Volt (such as welders)	30 amps and under	<u>.</u>	
	over 30 amps		
Circus, Fairs, etc.			
Alterations to wires		 ,	
Regains after fire			
Emergency Lights, battery	, , , , , , , , , , , , , , , , , , ,		
Emergency Generators FOR ADDITIONAL WORK NOT ON ORIGINAL PER	INSTALLATION FEE DUE:	_	
FOR REMOVAL OF A "STOP ORDER" (304-16.b)			
1 ON IMPROVIDED IN STOL OUDDIN (001-100)	TOTAL AMOUNT DUE: 13.50		
	20.00		
INSPECTION:			
Will be ready on, 19_; or	Will Call XX		
CONTRACTOR'S NAME: R D ELectric			
ADDRESS: 94 Allen Aver	nue		
TEL.: 797-6195	\sim		
MASTER LICENSE NO.: 2812	SIGNATURE OF CONTRACTOR:		
LIMITED LICENSE NO.:	Kolon Wyullen		

[INSPECTOR'S COPY — WHITE OFFICE COPY — CANARY CONTRACTOR'S COPY --- GREEN

finds interest to have

INSPECTIONS:	Service called in 7/2/86 by Musso	Permit Number Location Location Cowner Date of Permit Final Inspection By Inspector By Inspector
TROOKLOS	////	ELECTRICAL INSTALLATIONS— Permit Number 2 948 C Location 5 Quence 2 Quence
DATE:	REMARKS:	
9/2/86	needs permit for service	S MARKETELL
77-7-0	conned about crowning aron	nded weres
	<i>f</i> /	was to specify the
12/29/87	This office was not contacted	for fend Orapeitin
77070		V V in the state of the state o
		A STATE
		1997
,		· 李马克克
		· · · · · · · · · · · · · · · · · · ·
		53