

222 Sherwood Street 428-K-5



SEAWALKER  
42503-1R

✓ August 24, 1979 X

Leslie G. Lamkin  
222 Sherwood Street  
Portland, Maine 04103

Re: 222 Sherwood Street 428-K-5  
Neighborhood Conservation  
N.C.P. - East Oering Ext.

Dear Ms. Lamkin:

The Housing Inspections Division of the Department of Neighborhood Conservation has recently completed an exterior inspection of your property in conjunction with the above referred program.

Congratulations are extended to you for the general condition of your property which was found to meet the standards established by the City's Housing Code. We did, however, note the following items that could cause future problems.

Missing siding right exterior wall.

Peeling paint overall exterior trim.

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely yours,  
Joseph E. Gray, Jr., Director  
Neighborhood Conservation

By Lyle D. Noyes  
Lyle D. Noyes,  
Chief of Housing Inspections

Inspector M. Wing  
M. Wing

dld