

ISLAND AVE
ISLAND LOT 93-B-21 Long

214
1-579
LITTLE



APPLICATION FOR PERMIT
 DEPARTMENT OF BUILDING INSPECTIONS SERVICES
 ELECTRICAL INSTALLATIONS

Date Sept. 16, 1976 19__
 Receipt and Permit number 7894

To the CHIEF ELECTRICAL INSPECTOR, Portland, Maine:
 The undersigned hereby applies for a permit to make electrical installations in accordance with the laws of Maine, the Portland Electrical Ordinance, the National Electrical Code and the following specifications:

LOCATION OF WORK: 93-B-21 Island Ave. Long Island
 OWNER'S NAME: William P. Sieg ADDRESS: _____

OUTLETS: (number of) _____ FEES _____
 Lights _____
 Receptacles _____
 Switches _____
 Plugmold _____ (number of feet) _____
 TOTAL _____

FIXTURES: (number of) _____
 Incandescent _____
 Fluorescent _____ (Do not include strip fluorescent)
 TOTAL _____
 Strip Fluorescent, in feet _____

SERVICES: _____
 Permanent, total amperes 200 _____
 Temporary _____ **3.00**

METERS: (number of) 1 _____ **.50**

MOTORS: (number of) _____
 Fractional _____
 1 HP or over _____

RESIDENTIAL HEATING: _____
 Oil or Gas (number of units) _____
 Electric (number of rooms) _____

COMMERCIAL OR INDUSTRIAL HEATING: _____
 Oil or Gas (by a main boiler) _____
 Oil or Gas (by separate units) _____
 Electric (total number of kws) _____

APPLIANCES: (number of) _____
 Ranges _____ Water Heaters _____
 Cook Tops _____ Disposal's _____
 Wall Ovens _____ Dishwashers _____
 Dryers _____ Compactors _____
 Fans _____ Others (denote) _____
 TOTAL _____

MISCELLANEOUS: (number of) _____
 Branch Panels _____
 Transformers _____
 Air Conditioners _____
 Signs _____
 Fire/Burglar Alarms _____
 Circus, Fairs, etc. _____
 Alterations to wires _____
 Repairs after fire _____
 Heavy Duty, 220v outlets _____
 Emergency Lights, battery _____
 Emergency Generators _____

INSTALLATION FEE DUE: _____
 FOR ADDITIONAL WORK NOT ON ORIGINAL PERMIT DOUBLE FEE DUE: _____
 FOR REMOVAL OF A "STOP ORDER" (304-16.b) _____
 FOR PERFORMING WORK WITHOUT A PERMIT (304-9) _____
 TOTAL AMOUNT DUE: **3.50**

INSPECTION: Will be ready on _____, 19__; or Will Call _____

CONTRACTOR'S NAME: Harry Pappkeo
 ADDRESS: Island Ave. Long Island
 TEL.: 766-2202

MASTER LICENSE NO.: _____
 LIMITED LICENSE NO.: _____
 SIGNATURE OF CONTRACTOR: Harry Pappkeo

INSPECTOR'S COPY



APPLICATION FOR PERMIT
DEPARTMENT OF BUILDING INSPECTIONS SERVICES
ELECTRICAL INSTALLATIONS

Date Dec. 10 1976
 Receipt and Permit number A2031

To the CHIEF ELECTRICAL INSPECTOR, Portland, Maine.
 The undersigned hereby applies for a permit to make electrical installations in accordance with the laws of Maine, the Portland Electrical Ordinance, the National Electrical Code and the following specifications:

LOCATION OF WORK: 93-B-22 Island Ave. Long Island, Me.
 OWNER'S NAME: William Sieg ADDRESS: same

OUTLETS: (number of)
 Lights _____
 Receptacles _____
 Switches _____
 Plugmold _____ (number of feet)
 TOTAL _____

FIXTURES: (number of)
 Incandescent _____
 Fluorescent _____ (Do not include strip fluorescent)
 TOTAL _____
 Strip Fluorescent, in feet _____

SERVICES:
 Permanent, total amperes _____
 Temporary _____

METERS: (number of) _____

MOTORS: (number of)
 Fractional _____
 1 HP or over _____

RESIDENTIAL HEATING:
 Oil or Gas (number of units) _____
 Electric (number of rooms) 5 5.00

COMMERCIAL OR INDUSTRIAL HEATING:
 Oil or Gas (by a main boiler) _____
 Oil or Gas (by separate units) _____
 Electric (total number of kws) _____

APPLIANCES: (number of)

Ranges _____	Water Heaters _____
Cook tops _____	Disposals _____
Washers _____	Dishwashers _____
Dryers _____	Compactors _____
Fans _____	Others (denote) _____
TOTAL _____	

MISCELLANEOUS: (number of)
 Branch Panels _____
 Transformers _____
 Air Conditioners _____
 Signs _____
 Fire/Burglar Alarms _____
 Circus, Fairs, etc. _____
 Alterations to wires _____
 Repairs after fire _____
 Heavy Duty, 220v outlets _____
 Emergency Lights, battery _____
 Emergency Generators _____

FOR ADDITIONAL WORK NOT ON ORIGINAL PERMIT ... INSTALLATION FEE DUE: _____
 FOR REMOVAL OF A "STOP ORDER" (304-16.b) ... DOUBLE FEE DUE: _____
 FOR PERFORMING WORK WITHOUT A PERMIT (304-9) ... TOTAL AMOUNT DUE: 5.00

INSPECTION:
 Will be ready on 12-10, 1976 or Will Call _____

CONTRACTOR'S NAME: Harry G. Papke
 ADDRESS: Island Ave. Long Island, Me.
 TEL.: Fx 766-2002

MASTER LICENSE NO.: 105
 LIMITED LICENSE NO.: _____

SIGNATURE OF CONTRACTOR:
Harry G. Papke

INSPECTOR'S COPY

Cottage Alteration - Long Island

4-10-15

100-100-100

Frank A. Libbey, owner Long Island

Alteration and strengthening of cottage, rather than conversion to dwelling as per application.

I went over this work with Mr. Libbey on location and he plans this for "long season" rather than year round work. His plans considerable repair and strengthening, a large part of which, under the circumstances, will not concern us. It is the usual cottage construction with interior partitions of sheathing.

There is a laid in mortar stone foundation, outlined in a plan, the sections outside of this are piers and one story additions sitting on posts. This structural condition could not be seen but is to be repaired as necessary by the owner.

Proper support of the rear wall of the main cottage (and of second floor over living room) are the two matters calling for special attention.

Guides include drawings of main cottage. Proposed 12' x 11'0" with 4 posts (5 spans @ 4')

27.7
1100
27700
277
304700

6x6 deaced 27.7 x 1100 = $\frac{304700}{48} = 6347.9 \times 2 = 12695.8$

1 WK	ST
W x 15 x 15	2 x 110
22.50 = 12 x 1100	
W = $\frac{1200}{22.50}$	
1200	26.67
2.04	
596	
22.5 x 26	

It is easy to cut down to 2 posts (3 spans) at 7' spans. good for about 2900# which seems ample as cl. below no flat roof load is involved.

Mr. Libbey plans wood posts which should have proper footings.


Second floor over living room
2 x 6's 18' h.c. 15'0" span - via 4x4 or 11'0" of cor. in line
 $12 \times 11.00 = 13200 \times 8 = 105600$ (30# floor joists)

12	13200
130	1200
150	12
150	13200
	105600
150	105600 (354)
	900
	1530
	1840

Rear wall is to be reinforced with 4x4 posts at end of span. The ground is soft so that the whole might be a bit in danger.

^{east from living room}
Second Floor 2x6-18" o.c. 11'-6" span
Good for 47¢

It would require a large girder to bring the floor over the
living room up to even 40¢



FRONT

RECEIVED
 APR 10 1945
 DEPT. OF BLD'G. INSP.
 CITY OF PORTLAND

8'4" Box

AP Island Ave.,
Long Island-I

ATH
RMT
PH
AJS
BS

April 12, 1945

Mr. Clark A. Libbey
RFD #2
So. Portland, Maine

Subject: Building permit for alterations of the
cottage of Clark A. Libbey on Island Avenue,
Long Island

Dear Sir:


Permit for the above work is enclosed, subject to the following:

1. I understand that you have no intention of occupying this cottage through the winter months as a year round dwelling. If that should be your intention, you should refrain from starting the work, return the permit card at once and give us additional information on a new application for the permit as to how you intend to strengthen the building, especially the framing on the floors to take care of the ordinary loads of a year round dwelling.
2. Some of the structural parts of the building and of the foundation cannot be seen at the present time, but it is my understanding that you intend to go over them all thoroughly and make permanent repairs of any defects found.
3. Proper support of the rear wall of the main cottage is one of the matters of major importance. I understand that you propose to use a 6x6 girder underneath this wall with four posts under the girder equally spaced thus making the span of the girder about four feet--this in place of an existing 2x8 laid flat supported by piers. This proposed construction appears satisfactory. Any part of the posts if below the surface of the ground ought to be of cedar or else the posts above the ground ought to be supported upon suitable masonry piers no less than eight inches square at the surface of the ground and no less than ten inches square at the bottom of the pier, the pier to extend at least 6 inches above surface of ground.
4. It is my understanding that you do not propose any finished ceilings in the cottage either now or in the future. The second floor framing over the living room--2x6 joists, 18 inches from center to center on spans of 15 feet--is such too light anyway without allowing any additional load of even the lightest ceiling. Although these joists on the long span have a 4x4 beam beneath them, the 4x4 is of little consequence by way of adding strength to the floor system. If you were ever to use the cottage for a year round dwelling, very substantial strengthening would be required for this second floor framing over the living room.

Very truly yours,

Inspector of Buildings

RMH/S



APARTMENT HOUSE ZONE
APPLICATION FOR PERMIT

PERMIT ISSUED
Permit No. 281

Class of Building or Type of Structure Third Class

Portland, Maine, April 9, 1945 APR 12 1945

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect alter install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location Island Avenue, Long Island Within Fire Limits? no Dist. No. RD #2, South Portland
Owner's or Lessee's name and address Clark A. Libbey, Long Island Telephone _____
Contractor's name and address Owner Telephone _____
Architect _____ Plans filed no No. of sheets _____
Proposed use of building Smelling Cottage No. families 1
Other buildings on same lot none
Estimated cost \$ 250. Fee \$ 1.00

Description of Present Building to be Altered

Material frame No. stories 1 1/2 Feet _____ Style of roof _____ Roofing _____
Last use Cottage No. families _____

General Description of New Work

- To demolish side and rear piazza
- To close up existing door in corner of kitchen and cut in new window
- To relocate existing door in front of building and
- To replace existing door opening with window
- To partition off rear entry - 2x3 studs, 16" O.C., Celotex
- To finish off outside walls with insulation and Galvex - entire cottage
- To cover roof of kitchen portion of building

FOR OR FOR Casco Bay Lt. & Power Co

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

Details of New Work

Is any plumbing work involved in this work? _____
Is any electrical work involved in this work? _____ Height average grade to top of plate _____
Site, front _____ depth _____ No. stories _____ Height average grade to highest point of roof _____
To be erected on solid or filled land? _____ earth or rock? _____
Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
Material of underpinning _____ Height _____ Thickness _____
Kind of roof _____ Rise per foot _____ Roof covering _____
No. of chimneys _____ Material of chimneys _____ of lining _____
Kind of heat _____ Type of fuel _____ Is gas fitting involved? _____
Framing lumber—Kind _____ Dressed or full size? _____
Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____
Material columns under girders _____ Size _____ Max. on centers _____
Studs (outside walls and carrying partitions) 2x4-16" O. C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.
Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____
Total number commercial cars to be accommodated _____
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Signature of owner Clark A. Libbey

~~INSPECTION NOT COMPLETED~~

Location Island Ave, Long Isl

Owner Charles J. Libby

Date of permit 4/12/45

Notif. closing-in

Inspn. closing-in

Final Notif.

Final Inspn.

Cert. of Occupancy issued

Notes of 7-3-45 NOTES

93 B-1

7/3/45 work called for
cessment in Palace
etc