

BEACH AVENUE - LONG ISLAND
94-B-23-24-25-27

SHAW-WALKER
Faint, illegible text and markings, possibly a stamp or bleed-through from the reverse side of the page.



R3 RESIDENCE ZONE

APPLICATION FOR PERMIT

PERMIT ISSUED

00234

MAR 13 1959

CITY OF PORTLAND

Class of Building or Type of Structure March 6, 1959
Portland, Maine

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location Beach Ave., Long Island 94-B-23 Within Fire Limits? _____ Dist. No. _____
 Owner's name and address Delores DelRe, 30 West St. Telephone _____
 Lessee's name and address William Floyd, 303 Preble St., So. Portland Telephone _____
 Contractor's name and address owner Telephone _____
 Architect _____ Specifications _____ Plans _____ No. of sheets _____
 Proposed use of building _____ No. families _____
 Present use Dwelling No. families 1
 Material frame _____ No. stories 2 Heat _____ Style of roof _____ Roofing _____
 Other buildings on same lot _____
 Estimated cost \$ _____ Fee \$ 1.00

General Description of New Work

To demolish existing 2 story frame building
 (the interior to be demolished at the present time)
 some of building to be remodeled later)
 Land to be left vacant

Graduation letter sent 3/9/59

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. **PERMIT TO BE ISSUED TO** William Floyd

Details of New Work

Is any plumbing involved in this work? _____ Is any electrical work involved in this work? _____
 Is connection to be made to public sewer? _____ If not, what is proposed for sewage? _____
 Has septic tank notice been sent? _____ Form notice sent? _____
 Height average grade to top of plate _____ Height average grade to highest point of roof _____
 Size, front _____ depth _____ No. stories _____ solid or filled land? _____ earth or rock? _____
 Material of foundation _____ Thickness, top _____ bottom _____ cell? _____
 Material of underpinning _____ Height _____ Thickness _____
 Kind of roof _____ Rise per foot _____ P of covering _____
 No. of chimneys _____ Material of chimneys _____ of lining _____ Kind of heat _____ fuel _____
 Framing Lumber—Kind _____ Dressed or full size? _____ Corner posts _____ Sills _____
 Size Girder _____ Columns under girders _____ Size _____ Max. on centers _____
 Kind and thickness of outside sheathing of exterior walls? _____
 Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
 Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
 On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
 Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
 If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____ number commercial cars to be accommodated _____
 Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

APPROVED:

Miscellaneous

Will work require disturbing of any tree on a public street? no
 Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Signature of owner William Floyd

INSPECTION COPY

PH

RECEIVED

NOTES

11/19/60 - Books as if
 in the lot stopped here.
 Remove it to the store
 Jeff

Permit No. 52/234

Location: Grand Canyon

Owner: McBride, Walter

Date of permit: 3/13/59

Notif. closing-in: _____

Inspn. closing-in: _____

Final Notif. _____

Final Inspn. _____

Cert. of Occupancy Issued _____

Staking 'C' at Notice _____

Form Check Notice _____

IT

Foot covering
 10' high
 10' wide
 10' deep
 10' long
 10' high
 10' wide
 10' deep
 10' long
 10' high
 10' wide
 10' deep
 10' long

IT is understood that the permit was not issued until the
 following conditions were met:

1. A minimum of 10' high in the work
 in connection to be made to public ways
 If a public way notice been made
 Permit expires 10' to highest point in work
 10' high
 10' wide
 10' deep
 10' long
 10' high
 10' wide
 10' deep
 10' long

CITY OF PORTLAND, MAINE
DEPARTMENT OF BUILDING INSPECTION

March 9, 1959

William Floyd
303 Preble St.
South Portland Maine

Dear Sir:

With relation to permit applied for to demolish a building or portion of building at Beach Ave. Long Island it is unlawful to commence demolition work until a permit has been issued from this department. (This is a partial demolition)

Section 6 of the ordinance for rodent and vermin control provides: "It shall be unlawful to demolish any building or structure unless provision is made for rodent and vermin eradication. No permit for the demolition of a building or structure shall be issued by the Building Inspector until and unless provisions for rodent and vermin eradication have been carried out under supervision of a pest control operator registered with the Health Department.

The building permit for demolition cannot be issued until the provisions of this section have been satisfied. It is the obligation of owner or demolition contractor or both to take up with the Health Department the matter of complying with this section, being prepared to inform that department what registered pest control operator is to be employed.

Very truly yours!

Warren McDonald

Warren McDonald
Inspector of Buildings

WMcD/H

Erasmus W. Brown

Eradication of this building has been completed.

O/K
TW
3/12/59

Memorandum from Department of Building Inspection, Portland, Maine

Bocch Ave., Long Island (Catherine Sheridan & Mary Hughes)—Reconstruction of side platform of cottage by William Sheridan, builder, for Catherine Sheridan and Mary Hughes, owners—8/23/46

To Owners & Builder:

When filing application, builder did not seem very familiar with Building Code requirements as to framing. He should note that the 4x6 sills shown on the application are to be set with the six inch dimension upright and run along the three exposed edges of the platform with the bottom of sills no less than six inches above the ground; that the 2x5 floor joists are to be supported upon the sills by bearing upon the tops of the sills or let down on no less than 2x3 nailing strips spiked to the side of the sill.

W McD/D

(Signed) Warren McDonald

CC: Catherine Sheridan & Mary Hughes



(A) APARTMENT HOUSE ZONE
APPLICATION FOR PERMIT

PERMIT ISSUED

01580
APR 23 1916

Class of Building or Type of Structure Third Class

Portland, Maine, August 24, 1916

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect alter repair demolish or sell the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location Beach Avenue, Long Island Within Fire Limits? no Dist. No. _____
 Owner's name and address Catherine Sheridan, & Mary Hughes, Long Island Telephone _____
 Lessee's name and address _____ Telephone _____
 Contractor's name and address William Sheridan, Long Island Telephone _____
 Architect _____ Specifications _____ Plans no No. of sheets _____
 Proposed use of building Cottage No. families _____
 Last use _____ No. families _____
 Material Frame No. stories 2 Heat _____ Style of roof _____ Roofing _____
 Other buildings on same lot _____
 Estimated cost \$ 100. Fee \$ 50

General Description of New Work

To demolish existing 6'x4' side platform and to reconstruct same size.

Permit Issued with Memo

NOTIFICATION BEFORE LATHING
OR CLOSING-IN IS WAIVED

CERTIFICATE OF OCCUPANCY
REQUIREMENT IS WAIVED

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately, by and in the name of the heating contractor.

Details of New Work

Is any plumbing work involved in this work? _____ Is any electrical work involved in this work? _____
 Height average grade to top of plate _____ Height average grade to highest point of roof _____
 Size, front _____ depth _____ No. stories _____ solid or filled land? _____ earth or rock? _____
 Material of foundation cedar posts at least 4' below grade or to ledge _____ Thickness, top _____ bottom _____ cellar _____
 Material of underpinning _____ 6" O.C. _____ Height _____ Thickness _____
 Kind of roof none Rise per foot _____ Roof covering _____
 No. of chimneys _____ Material of chimneys _____ of lining _____ Kind of heat _____ fuel _____
 Framing lumber Kind hemlock Dressed or full size? dressed
 Corner posts _____ Sills 2x6 Girt or ledger board? _____ Size _____
 Girders _____ Size _____ Columns under girders _____ Size _____ Max. on centers _____
 Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
 Joists and rafters: 1st floor 2x6 2nd _____ 3rd _____ roof none
 On centers: 1st floor 16" 2nd _____ 3rd _____ roof _____
 Maximum span: 1st floor 6' 2nd _____ 3rd _____ roof _____
 If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____ to be accommodated _____ number commercial cars to be accommodated _____
 Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will work require disturbing of any tree on a public street? no
 Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

APPROVED: _____

Signature of owner William P. Sheridan

INSPECTION NOT COMPLETED

Permit No. 46/1580

Location Beach Dr, Long Beach

Owner Catharine Reed Long

D. permit 46/1580

Notif. closing-in

Inspn. closing-in

Final Notif.

Final Inspn.

Cert. of Occupancy issued

NOTIFICATION FOR PERMIT
REPAIRMENT HOUSE

NOTES
Use of permanent
outletting system
Use of permanent
outletting system
Use of permanent
outletting system

No.	Date	Description	Inspector	Remarks
1	10/21/46	Initial inspection
2	10/21/46
3	10/21/46
4	10/21/46
5	10/21/46
6	10/21/46
7	10/21/46
8	10/21/46
9	10/21/46
10	10/21/46
11	10/21/46
12	10/21/46
13	10/21/46
14	10/21/46
15	10/21/46
16	10/21/46
17	10/21/46
18	10/21/46
19	10/21/46
20	10/21/46
21	10/21/46
22	10/21/46
23	10/21/46
24	10/21/46
25	10/21/46
26	10/21/46
27	10/21/46
28	10/21/46
29	10/21/46
30	10/21/46
31	10/21/46
32	10/21/46
33	10/21/46
34	10/21/46
35	10/21/46
36	10/21/46
37	10/21/46
38	10/21/46
39	10/21/46
40	10/21/46
41	10/21/46
42	10/21/46
43	10/21/46
44	10/21/46
45	10/21/46
46	10/21/46
47	10/21/46
48	10/21/46
49	10/21/46
50	10/21/46
51	10/21/46
52	10/21/46
53	10/21/46
54	10/21/46
55	10/21/46
56	10/21/46
57	10/21/46
58	10/21/46
59	10/21/46
60	10/21/46
61	10/21/46
62	10/21/46
63	10/21/46
64	10/21/46
65	10/21/46
66	10/21/46
67	10/21/46
68	10/21/46
69	10/21/46
70	10/21/46
71	10/21/46
72	10/21/46
73	10/21/46
74	10/21/46
75	10/21/46
76	10/21/46
77	10/21/46
78	10/21/46
79	10/21/46
80	10/21/46
81	10/21/46
82	10/21/46
83	10/21/46
84	10/21/46
85	10/21/46
86	10/21/46
87	10/21/46
88	10/21/46
89	10/21/46
90	10/21/46
91	10/21/46
92	10/21/46
93	10/21/46
94	10/21/46
95	10/21/46
96	10/21/46
97	10/21/46
98	10/21/46
99	10/21/46
100	10/21/46

APPROVED
[Signature]

ON OCTOBER 18 4 1946
RECEIVED BY THE CITY ENGINEER

September 14, 1932

Mrs. Mary Hughes et al
Beach Avenue, Long Island
Portland, Maine

Dear Madam:

Enclosed is the building permit covering alterations of the cottage owned by you and Mrs. Sheida at Long Island. The blank written in long hand which you sent to the office is still not complete, but since the job is a small one, we do not desire to withhold the permit longer, and I am therefore issuing the permit with the following suggestions as to the construction of the platform.

The sills of the platform should be at least 4x6 in size and all one piece in cross section. That is it should be a solid piece of lumber rather than built up of more than one piece. The sills should be set with the six inch dimension vertical on top of the posts. At the same level as the sills other 4x8s should run across the platform dividing the length of twenty feet into at least two parts. The floor joists of the platform should be at least 2x6 and should be supported upon the end sill and the center 4x6. These joists should be set no more than eighteen inches from center to center, and it would be well to bridge them with cross bridging no less than 1x3. It is assumed, of course, that you will provide substantial boarding for the floor and a substantial railing around the platform.

Please be governed accordingly.

Very truly yours,

Inspector of Buildings.

YH/HB
Enc.



(A) APARTMENT HOUSE ZONE

APPLICATION FOR PERMIT

PERMIT ISSUED

1996

SEP 14 1992

Class of Building or Type of Structure Third Class

Portland, Maine, September 8, 1992

To the INSPECTOR OF BUILDINGS, ME.

The undersigned hereby applies for permit to erect alter install the following building structure within in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location Beach Avenue, Long Island 10771 Within Fire Limits? no Dist. No. _____

Owner's or Lessee's name and address Rory Hughes, et al Beach Ave, Long Is. Telephone _____

Contractor's name and address Orner Telephone _____

Architect's name and address _____ Telephone _____

Proposed use of building Cottage No. families _____

Other buildings on same _____

Plans filed as part of this application yes No. of sheets 1

Estimated cost \$ 34 Fee \$ 80

Description of Present Building to be Altered

Material wood No. stories 2 Heat _____ Style of roof _____ Roofing _____

Last use Cottage No. families _____

General Description of New Work:

~~To erect open platform~~

To remove about 20' of roof of existing one story open side
To erect open platform on rear of building about 20' x 12'

NOTIFICATION BEFORE LATHING
OR CLOSING-IN IS WAIVED.
CERTIFICATE OF OCCUPANCY
BEFORE PERMIT

It is understood that this permit does not include installation of heating apparatus which is to be taken out scope of this permit and in the name of the heating contractor.

Details of New Work

Height average grade to top of plate _____

Size front 23' depth 51' No. stories 1 Height average grade to highest point of roof 60' 30"

To be erected on solid or filled land? solid earth or rock? earth

Material of foundation Cedar post Thickness, top _____ bottom _____

Material of underpinning _____ Height _____ Thickness _____

Kind of Roof _____ Rise per foot _____ Roof covering _____

No. of chimneys _____ Material of chimneys _____ of lining _____

Kind of heat _____ Type of fuel _____ Is gas fitting involved _____

Corner posts _____ Size _____ Girt or ledger board? _____ Size _____

Material columns under girders _____ Size _____ Max. on centers _____

Studs (outside walls and carrying partitions) 2x4-16" O. C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.

Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof no roof

On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____

Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____

If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____

Total number commercial cars to be accommodated _____

Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Signature of owner _____

INSPECTION COPY

4th Pomer
Ward 1 Permit No. 321-396

Location Berwick

Owner Maxima

Date of permit 9/14/33

No. of closing-in

Insp. closing-in 9-19-33

Final Notif.

Final Inspn 5/17/33

Cert. of Occupancy issued None

5/17/33 NOTES
Construction called
for in attached letter
has not been followed,
and is rather differ-
ent from usual manner
of work. Paving
Paving is well shown
and seems firm and
solid, but should be O.K.
O.K.