

BEACH AVENUE - LONG ISLAND  
97-1-8

SCHEDULE	
NO.	DESCRIPTION
1	...
2	...
3	...
4	...
5	...
6	...
7	...
8	...
9	...
10	...
11	...
12	...
13	...
14	...
15	...
16	...
17	...
18	...
19	...
20	...
21	...
22	...
23	...
24	...
25	...
26	...
27	...
28	...
29	...
30	...
31	...
32	...
33	...
34	...
35	...
36	...
37	...
38	...
39	...
40	...
41	...
42	...
43	...
44	...
45	...
46	...
47	...
48	...
49	...
50	...
51	...
52	...
53	...
54	...
55	...
56	...
57	...
58	...
59	...
60	...
61	...
62	...
63	...
64	...
65	...
66	...
67	...
68	...
69	...
70	...
71	...
72	...
73	...
74	...
75	...
76	...
77	...
78	...
79	...
80	...
81	...
82	...
83	...
84	...
85	...
86	...
87	...
88	...
89	...
90	...
91	...
92	...
93	...
94	...
95	...
96	...
97	...
98	...
99	...
100	...



**APPLICATION FOR PERMIT**  
**DEPARTMENT OF BUILDING INSPECTIONS SERVICES**  
**ELECTRICAL INSTALLATIONS**

Date Sept. 7, 1976, 19  
 Receipt and Permit number A 7851

To the CHIEF ELECTRICAL INSPECTOR, Portland, Maine:

The undersigned hereby applies for a permit to make electrical installations in accordance with the laws of Maine, the Portland Electrical Ordinance, the National Electrical Code and the following specifications:

LOCATION OF WORK: 97-I-8 Beach Ave., Long Island  
 OWNER'S NAME: Anne Clark ADDRESS: same

OUTLETS: (number of) 1

Lights	_____	
Receptacles	_____	
Switches	_____	
Plugmold	_____ (number of feet)	
TOTAL	_____	

FEES

FIXTURES: (number of)

Incaidescant	_____	
Fluorescent	_____ (Do not include strip fluorescent)	
TOTAL	_____	
Strip Fluorescent, in feet	_____	

SERVICES:

Permanent, total amperes	<u>100</u>	
Temporary	_____	<u>3.00</u>

METERS: (number of) 1 .50

MOTORS: (number of)

Fractional	_____	
1 HP or over	_____	

RESIDENTIAL HEATING:

Oil or Gas (number of units)	_____	
Electric (number of rooms)	_____	

COMMERCIAL OR INDUSTRIAL HEATING:

Oil or G. (by a main boiler)	_____	
Oil or Gas (by separate units)	_____	
Electric (total number of kws)	_____	

APPLIANCES: (number of)

Ranges	_____	Water Heaters	_____
Cook Tops	_____	Disposals	_____
Wall Ovens	_____	Dishwashers	_____
Dryers	_____	Compactors	_____
Fans	_____	Others (denote)	_____
TOTAL	_____		

MISCELLANEOUS: (number of)

Branch Panels	_____	
Transformers	_____	
Air Conditioners	_____	
Signs	_____	
Fire/Burglar Alarms	_____	
Circus, Fairs, etc.	_____	
Alterations to wires	_____	
Repairs after fire	_____	
Heavy Duty, 220v outlets	_____	
Emergency Lights, battery	_____	
Emergency Generators	_____	

INSTALLATION FEE DUE:	_____
FOR ADDITIONAL WORK NOT ON ORIGINAL PERMIT	..... DOUBLE FEE DUE:
FOR REMOVAL OF A "STOP ORDER" (304-16.b)	.....
FOR PERFORMING WORK WITHOUT A PERMIT (304-9)	.....
TOTAL AMOUNT DUE:	<u>3.50</u>

INSPECTION: Will be ready on \_\_\_\_\_, 19\_\_\_\_; or Will Call XX

CONTRACTOR'S NAME: Harry Papkee  
 ADDRESS: Island Ave., Long Island  
 TFL.: 756-2002

MASTER LICENSE NO.: 1714 SIGNATURE OF CONTRACTOR: [Signature]  
 LIMITED LICENSE NO.: \_\_\_\_\_

INSPECTOR'S COPY



CITY OF PORTLAND  
HEALTH DEPARTMENT  
HOUSING DIVISION



Loc. ~~12345~~ L. I.  
Loc w/1 S ~~12345~~  
Bldg # Fire # Elec # Other  
Issued December 14, 1960  
Expires January 16, 1961

Mr. Brian Rich  
Maine Avenue  
Long Island, Maine

97-I-8

Dear Mr. Rich:

On November 2, 1960 an examination was made of the premises located at 12345 Main Street, Long Island, Maine. Non-compliance with the ordinances relating to housing conditions was found as detailed below.

In accordance with the provisions of the above ordinance, you are hereby ordered to correct these defects according to specifications within the time limits allowed. Failure to comply with this notice will necessitate legal action.

Some repairs or improvements required will necessitate permits which are to be obtained from the Building Inspector, Health, Fire or other City Departments. These must be obtained before the work is started.

If any additional information is desired, visit or telephone the Housing Supervisor at this Office, Spruce 4-8221, extension 226. Kindly notify this office as soon as all corrections have been completed.

Very truly yours,  
Douglas H. Brown, M. D.  
Health Director

By \_\_\_\_\_  
Housing Supervisor

### VIOLATIONS & SPECIFICATIONS

/// Responsibility of Owner or Agent      \*\* Responsibility of Occupant

- | NO. | VIOLATION  | RESPONSIBILITY |
|-----|--|----------------|
| 1.  | Repair or replace the deteriorated floor boards on the front porch.  | ///            |
| 2.  | Repair or replace the defective and missing tax paper on all sides of the structure.   | ///            |
| 3.  | Repair or replace the broken gutter in the front of the structure.   | ///            |
| 4.  | Repair or replace the missing drain pipe.  | ///            |
| 5.  | Repair, replace, or demolish the dilapidated barn.   | ///            |
| 6.  | Repair or replace the cracked, loose, or missing plaster on the walls in the kitchen and bathroom of the 2nd floor.                                | ///            |
| 7.  | Finish off the unfinished room on the 2nd floor.   | ///            |
| 8.  | Determine the reason and remedy the condition which now causes signs of leakage in the dining room and bedroom of the 1st floor.                   | ///            |
| 9.  | Repair or replace the cracked, loose, or missing plaster on the ceilings of the kitchen, living room, and rear entrance hall.                      | ///            |
| 10. | Replace the broken window panes in the 2nd floor bathroom and in the rear entrance hall.   | ///            |
| 11. | Repair or replace the cracked, loose, or missing plaster on the walls along the stairway to the 2nd floor.   | ///            |
| 12. | Replace the missing railing around the opening to the 2nd floor.   | ///            |
| 13. | Repair or replace the dilapidated floor in the rear entrance hall.   | ///            |
| 14. | Repair and have repaired all defective electric wiring and electrical equipment throughout the structure.  | **             |
| 15. | Our inspection reveals that the wiring is defective throughout the structure and should be thoroughly checked by a competent licensed electrician. | **             |
| 16. | Determine the reason and remedy the condition which now causes the short circuits in the kitchen.  | **             |
| 17. | Repair or replace the defective fixtures in the 2nd floor bathroom and in the unfinished room.   | ///            |

(over)

REPAIRS

has and have repaired all defective plumbing and plumbing fixtures throughout the structure.

- a. Install a private head and flush toilet conveniently located within the structure and connect it to a private tank and filter not approved by this Department.
- b. A recent test of your present water shows that the water is contaminated and unfit for drinking purposes and for cooking fishes.

Therefore, you are hereby ordered to dig a new well at least 100 feet away from the sewage house drainage system.

- c. Replace the missing trap under the kitchen sink.
- d. Repair or replace the defective pump in the kitchen.

REPAIRS AND TEMPORARY MEASURES:

- a. accomplish a general clean-up of the house by removing and properly disposing of all brush, filth, litter, and debris.

REPAIRS

- a. Replace the missing bricks and point up the loose joints in the front chimney above the roof line.

The above mentioned conditions are in violation of Chapter 107 of the Municipal Code of the City of Portland, and must be corrected on or before January 16, 1961.

86940  
 Permit # \_\_\_\_\_ City of Portland BUILDING PERMIT APPLICATION Fee \$25. Zone \_\_\_\_\_ Map # \_\_\_\_\_ Lot# \_\_\_\_\_

Please fill out any part which applies to job. Proper plans must accompany form.

Owner: John W. Norcross Phone # 766-5027  
 Address: Beach Ave.; Long Island, ME 04050  
 LOCATION OF CONSTRUCTION: Beach Ave; Long Is. 97-1-8  
 Contractor: OWNER Sub: \_\_\_\_\_  
 Address: \_\_\_\_\_ Phone # \_\_\_\_\_  
 Est. Construction Cost: \_\_\_\_\_ Proposed Use: 1-fam w shed  
 Past Use: 1-fam  
 # of Existing Res. Units \_\_\_\_\_ # of New Res. Units \_\_\_\_\_  
 Building Dimensions L \_\_\_\_\_ W \_\_\_\_\_ Total Sq. Ft. \_\_\_\_\_  
 # Stories: \_\_\_\_\_ # Bedrooms \_\_\_\_\_ Lot Size: \_\_\_\_\_  
 Is Proposed Use: Seasonal \_\_\_\_\_ Condominium \_\_\_\_\_ Conversion \_\_\_\_\_  
 Explain Conversion: Construct shed; 12'x20'

For Official Use Only  
 Date 5/25/90 Subdivision \_\_\_\_\_  
 Inside Fire Limits \_\_\_\_\_ Name \_\_\_\_\_  
 Bldg Code \_\_\_\_\_ Lot JUN 4 1990  
 Time Limit \_\_\_\_\_ Ownership: \_\_\_\_\_ Public \_\_\_\_\_  
 Estimated Cost: \$1,000 Private \_\_\_\_\_  
 City of Portland  
 Zoning: Long Island Residence  
 Street Frontage Provided: \_\_\_\_\_  
 Provided Setbacks: Front \_\_\_\_\_ Back \_\_\_\_\_ Side \_\_\_\_\_  
 Review Required:  
 Zoning Board Approval: Yes \_\_\_\_\_ No \_\_\_\_\_ Date: \_\_\_\_\_  
 Planning Board Approval: Yes \_\_\_\_\_ No \_\_\_\_\_ Date: \_\_\_\_\_  
 Conditional Use: \_\_\_\_\_ Variance \_\_\_\_\_ Site Plan \_\_\_\_\_ Subdivision \_\_\_\_\_  
 Shoreland Zoning Yes \_\_\_\_\_ No \_\_\_\_\_ Floodplain Yes \_\_\_\_\_ No \_\_\_\_\_  
 Special Exception \_\_\_\_\_  
 Other (Explain) OK WDA 5-30-90

**Foundation:**

1. Type of Soil: \_\_\_\_\_
2. Set Backs - Front \_\_\_\_\_ Rear \_\_\_\_\_ Side(s) \_\_\_\_\_
3. Footings Size: \_\_\_\_\_
4. Foundation Size: \_\_\_\_\_
5. Other: \_\_\_\_\_

**Floor:**

1. Sills Size: \_\_\_\_\_ Sills must be anchored.
2. Girder Size: \_\_\_\_\_
3. Lally Column Spacing: \_\_\_\_\_ Size: \_\_\_\_\_
4. Joists Size: \_\_\_\_\_ Spacing 16" O.C.
5. Bridging Type: \_\_\_\_\_ Size: \_\_\_\_\_
6. Floor Sheathing Type: \_\_\_\_\_ Size: \_\_\_\_\_
7. Other Material: \_\_\_\_\_

**Exterior Walls:**

1. Studding Size \_\_\_\_\_ Spacing \_\_\_\_\_
2. No. window \_\_\_\_\_
3. No. Doors \_\_\_\_\_
4. Header Sizes \_\_\_\_\_ Span(s) \_\_\_\_\_
5. Bracing: Yes \_\_\_\_\_ No \_\_\_\_\_
6. Corner Posts Size \_\_\_\_\_
7. Insulation Type \_\_\_\_\_ Size \_\_\_\_\_
8. Siding Type \_\_\_\_\_ Size \_\_\_\_\_
9. Siding Type \_\_\_\_\_ Weather Exposure \_\_\_\_\_
10. Masonry Materials \_\_\_\_\_
11. Metal Materials \_\_\_\_\_

**Interior Walls:**

1. Studding Size \_\_\_\_\_ Spacing \_\_\_\_\_
2. Header Sizes \_\_\_\_\_ Span(s) \_\_\_\_\_
3. Wall Covering Type \_\_\_\_\_
4. Fire Wall if required \_\_\_\_\_
5. Other Materials \_\_\_\_\_

**Ceiling:**

1. Ceiling Joists Size: \_\_\_\_\_
2. Ceiling Strapping Size \_\_\_\_\_ Spacing \_\_\_\_\_
3. Type Ceilings: \_\_\_\_\_
4. Insulation Type \_\_\_\_\_ Size \_\_\_\_\_
5. Ceiling Height: \_\_\_\_\_

**Roof:**

1. Truss or Rafter Size \_\_\_\_\_ Span \_\_\_\_\_
2. Sheathing Type \_\_\_\_\_ Size \_\_\_\_\_
3. No. of Covering Type \_\_\_\_\_

**Chimneys:**

- Type: \_\_\_\_\_ Number of Fire Places \_\_\_\_\_

**Heating:**

- Type of Heat: \_\_\_\_\_

**Electrical:**

- Service Entrance Size: \_\_\_\_\_ Smoke Detector Required Yes \_\_\_\_\_ No \_\_\_\_\_

**Plumbing:**

1. Approval of soil test if required Yes \_\_\_\_\_ No \_\_\_\_\_
2. No. of Tubs or Showers: \_\_\_\_\_
3. No. of Flushes: \_\_\_\_\_
4. No. of Lavatories: \_\_\_\_\_
5. No. of Other Fixtures: \_\_\_\_\_

**Swimming Pools:**

1. Type: \_\_\_\_\_
2. Pool Size: \_\_\_\_\_ Square Footage \_\_\_\_\_
3. Must conform to National Electrical Code and State Law.

Permit Received By Louise E. Chase

Signature of Applicant John W. Norcross Date 5/25/90

Signature of CEO \_\_\_\_\_ Date \_\_\_\_\_

Inspection Dates \_\_\_\_\_

White-Tax Assessor

Yellow-GPCOG

White Tag-CEO

© Copyright GBZCO 1989

Mr. Adderley

Permit # 40045 City of Portland BUILDING PERMIT APPLICATION Fee 525. Zone \_\_\_\_\_ Map # \_\_\_\_\_ Lot# \_\_\_\_\_  
 Please fill out any part which applies to job. Proper plans must accompany form.

Owner: John W. Horcross Phone # 766-5027  
 Address: Beach Ave.; Long Island, 4E 04050  
 LOCATION OF CONSTRUCTION Beach Ave; Long Is. 97 1-3  
 Contractor: OWAAC Sub: \_\_\_\_\_  
 Address: \_\_\_\_\_ Phone # \_\_\_\_\_  
 Est. Construction Cost: \_\_\_\_\_ Propose Use: 1-fam w shed  
 Past Use: 1-fam  
 # of Existing Res. Units \_\_\_\_\_ # of New Res. Units \_\_\_\_\_  
 Building Dimensions L \_\_\_\_\_ W \_\_\_\_\_ Total Sq. Ft. \_\_\_\_\_  
 # Stories: \_\_\_\_\_ # Bedrooms \_\_\_\_\_ Lot Size: \_\_\_\_\_  
 Is Proposed Use:  Seasonal \_\_\_\_\_  Condominium \_\_\_\_\_  Conversion \_\_\_\_\_  
 Explain Conversion Construct shed; 12'x20'

**For Official Use Only**

**PERMIT ISSUED**

Date: 5/25/90 Subdivision Name \_\_\_\_\_  
 Inside Fire Limits \_\_\_\_\_  
 Bldg Code \_\_\_\_\_ Ownership City of Portland  
 Time Limit \_\_\_\_\_ Private \_\_\_\_\_  
 Estimated Cost: \$1000.

Zoning: R-1  
 Street Frontage Provided: \_\_\_\_\_  
 Provided Setbacks: Front \_\_\_\_\_ Back \_\_\_\_\_ Side \_\_\_\_\_  
 Review Required:  
 Zoning Board Approval: Yes \_\_\_\_\_ No \_\_\_\_\_ Date: \_\_\_\_\_  
 Planning Board Approval: Yes \_\_\_\_\_ No \_\_\_\_\_ Date: \_\_\_\_\_  
 Conditional Use \_\_\_\_\_ Variance \_\_\_\_\_ Site Plan \_\_\_\_\_ Subdivision \_\_\_\_\_  
 Shoreland Zoning Yes \_\_\_\_\_ No \_\_\_\_\_ Floodplain Yes \_\_\_\_\_ No \_\_\_\_\_  
 Special Exception \_\_\_\_\_  
 Other (Explain) See attached 5-30-90

**Foundations**

- Type of Soil: \_\_\_\_\_
- Set Backs - Front \_\_\_\_\_ Rear \_\_\_\_\_ Side(s) \_\_\_\_\_
- Footings Size: \_\_\_\_\_
- Foundation Size: \_\_\_\_\_
- Other \_\_\_\_\_

**Floor:**

- Sills Size: \_\_\_\_\_ Sills must be anchored.
- Girder Size: \_\_\_\_\_
- Lally Column Spacing: \_\_\_\_\_ Size: \_\_\_\_\_
- Joists Size: \_\_\_\_\_ Spacing 16" O.C.
- Bridging Type: \_\_\_\_\_ Size: \_\_\_\_\_
- Floor Sheathing Type: \_\_\_\_\_ Size: \_\_\_\_\_
- Other Material: \_\_\_\_\_

**Exterior Walls:**

- Studding Size \_\_\_\_\_ Spacing \_\_\_\_\_
- No. windows \_\_\_\_\_
- No. Doors \_\_\_\_\_
- Header Sizes \_\_\_\_\_ Span(s) \_\_\_\_\_
- Bracing: Yes \_\_\_\_\_ No \_\_\_\_\_
- Corner Posts Size \_\_\_\_\_
- Insulation Type \_\_\_\_\_ Size \_\_\_\_\_
- Sheathing Type \_\_\_\_\_ Size \_\_\_\_\_
- Siding Type \_\_\_\_\_ Weather Exposure \_\_\_\_\_
- Masonry Materials \_\_\_\_\_
- Metal Materials \_\_\_\_\_

**Interior Walls:**

- Studding Size \_\_\_\_\_ Spacing \_\_\_\_\_
- Header Sizes \_\_\_\_\_ Span(s) \_\_\_\_\_
- Wall Covering Type \_\_\_\_\_
- Fire Wall if required \_\_\_\_\_
- Other Materials \_\_\_\_\_

**Ceiling:**

- Ceiling Joists Size: \_\_\_\_\_ Spacing \_\_\_\_\_
- Ceiling Strapping Size \_\_\_\_\_ Spacing \_\_\_\_\_
- Tyee Ceiling \_\_\_\_\_
- Insulation Type \_\_\_\_\_ Size \_\_\_\_\_
- Ceiling Height: \_\_\_\_\_

**Roof:**

- Truss or Rafter Size \_\_\_\_\_ Span \_\_\_\_\_
- Sheathing Type \_\_\_\_\_ Size \_\_\_\_\_
- Roof Covering Type \_\_\_\_\_

**Chimneys:**  
 Type: \_\_\_\_\_ Number of Fire Places \_\_\_\_\_

**Heating:**  
 Type of Heat: \_\_\_\_\_

**Electrical:**  
 Service Entrance Size: \_\_\_\_\_ Smoke Detector Required Yes \_\_\_\_\_ No \_\_\_\_\_

**Plumbing:**

- Approval of soil test if required Yes \_\_\_\_\_ No \_\_\_\_\_
- No. of Tubs or Showers \_\_\_\_\_
- No. of Flushes \_\_\_\_\_
- No. of Lavatories \_\_\_\_\_
- No. of Other Fixtures \_\_\_\_\_

**Swimming Pools:**

- Type \_\_\_\_\_
- Pool Size: \_\_\_\_\_ x \_\_\_\_\_ Square Footage \_\_\_\_\_
- Must conform to National Electrical Code and State Law.

Permit Received By Louise E. Chase  
 Signature of Applicant John W. Horcross Date 5/25/90  
 Signature of CEO John W. Horcross Date \_\_\_\_\_  
 Inspection Dates \_\_\_\_\_

PLC PLAN



FEES (Breakdown From Front)		Type	Inspection Record	Date
Base Fee \$	<u>25-</u>	_____	_____	____/____/____
Subdivision Fee \$	_____	_____	_____	____/____/____
Site Plan Review Fee \$	_____	_____	_____	____/____/____
Other Fees \$	_____	_____	_____	____/____/____
(Explain)	_____	_____	_____	____/____/____
Late Fee \$	_____	_____	_____	____/____/____

COMMENTS

---

---

---

---

---

---

---

---

---

---

---

Signature of Applicant \_\_\_\_\_



Date \_\_\_\_\_



RECEIVED

MAY 21 1990

CLPT OF BUSH'S BRISTOL  
CITY OF PORTLAND




19	2 x 6 x 12	41.20	21.69	51.01	399
68	2 x 4 x 8	149	118.5	201	155
14	2 x 4 x 12	217.2	300	215.4	215.4
8	2 x 4 x 8	159.9	199.9	12.22	156.9
30	2 x 11 x 8	695	769	559	160
		555.62	624.39	658.88	512.79
		522.36			


WILKES 772-2884  
FOX 797-7131  
Hillside 766-3926  
GROSSMANS 797-6816  
Rufus Doremus 772-6505

789.00

2x3 1.15



Wall	2	14	8	44	Floor	2	16	2	= 17
Wall	2	14	8	44					
Floor	3	4	8	= 8					
Wall	1	4	8	= 16					



IR-1

Beach Ave

RECEIVED

MAY 25 1990

DEPT OF PLANNING AND  
COMMUNITY DEVELOPMENT  
CITY OF PORTLAND